

HUNTER POWER PROJECT HAZOP REPORT

| Document Information | | | | | |
|----------------------|-----------------------------------|-------------------|-----------|----------|----------|
| Title | Hunter Power Project HAZOP Report | | | | |
| Number | HPP-SHL-SYS-PT-GEN-REP-0001 | | | | |
| Revision | 0 | | | | |
| Revision Information | | | | | |
| Revision | Date | Description | Author | Reviewer | Approver |
| A | 23 August 2022 | Issued for Review | E Bayliss | I Smith | M Bokil |
| 0 | 10 October 2022 | Issue for Use | E Bayliss | I Smith | M Bokil |
| | | | | | |

Table of Contents

| | |
|---|----|
| Executive Summary | 4 |
| 1 Introduction | 7 |
| 1.1 Aim of the Report | 7 |
| 2 Glossary and Abbreviations | 8 |
| 3 Summary of Main Findings and Recommendations | 9 |
| 4 Scope and Objectives | 11 |
| 4.1 Applying Snowy Hydro's Company Values | 11 |
| 4.2 Duty under the NSW Work Health and Safety Act | 11 |
| 4.3 Satisfy Consent Condition B12(b) | 12 |
| 4.4 Scope of the Study | 12 |
| 4.5 Excluded Scope and Other Studies | 13 |
| 5 Description of the Facility | 14 |
| 5.1 Power Island | 15 |
| 5.2 Closed Cooling Water System | 15 |
| 5.3 Balance of Plant | 16 |
| 6 HAZOP Team Members | 17 |
| 6.1 Facilitator Selection | 17 |
| 7 HAZOP Methodology | 18 |
| 8 Study Details | 20 |
| 8.1 General | 20 |
| 8.2 HAZOP Study Management | 20 |
| 8.3 Study Language | 22 |
| 8.4 Study Preparation | 22 |
| 8.5 Study Environment | 23 |
| 8.6 Power Island and Balance of Plant Interface | 23 |
| 8.7 Kurri Kurri Gas Lateral Interface | 23 |
| 9 Guide Words | 24 |
| 10 Plant Overview | 25 |
| 11 Analysis of Main Findings | 26 |
| 11.1 Summary and Discussion of the HAZOP Results | 26 |
| 11.1.1 Power Island | 26 |
| 11.1.2 Closed Cooling Water System | 27 |
| 11.1.3 Balance of Plant | 27 |
| 12 Action Arising from the HAZOP | 28 |
| 12.1 Plan to Manage HAZOP Recommendations | 28 |
| 13 References | 29 |
| | |
| Appendix A – NSW Department of Planning, Industry and Environment Letters of Facilitator Acceptance and Facilitator Credentials | |
| Appendix B – Power Island Detail HAZOP Report | |
| Appendix C – Power Island Closed Cooling Water System Detail HAZOP Report | |
| Appendix D – Balance of Plant Detail HAZOP Report | |

Appendix E – HAZOP Recommendations Completion Schedule by Project Phase

Appendix F – Current HAZOP Recommendations Status

Executive Summary

Snowy Hydro Limited (Snowy Hydro) is developing a Gas Turbine Peaking Power Station at Loxford in the Hunter Valley, NSW – the “Project”. Mitsubishi Heavy Industries (MHI) together with its associated company, Mitsubishi Electric Corporation (MELCO) and AECOM Australia Limited are providing the facility design. The Project has been declared Critical State Significant Infrastructure (CSSI) under Section 5.13 of the NSW Environmental Planning and Assessment Act 1979.

The Conditions of Consent (Ref.4), Consent Condition B12(b), for the Project requires preparation and submission of a HAZOP study of the design. This report contains a summary and details of the HAZOP study performed on the Project.

For the purposes of this HAZOP study, the Project was defined by its physical property boundary (the Site) and its terminal points such as the gas connection point at the Gas Receiving Station, the diesel unloading point, the water supply, stormwater and sewerage service connection points to the Hunter Water network at the property boundary and the electrical connection within the Switching Station to the Ausgrid 132kV electricity network.

The NSW Government, Department of Planning and Environment (DPE) has a key objective to pursue the orderly development of industry and the protection of community safety. DPE manages risk assessment and land use safety planning processes that account for both the technical and the broader locational safety aspects of potentially hazardous industry. These processes are implemented as part of the environmental impact assessment procedures under the Environmental Planning and Assessment Act 1979 (Ref.3). HAZOP study of the Project design is one of the key procedures in this process and DPE’s requirements for it are described in NSW *Hazardous Industry Advisory Paper 8* (HIPAP-8) (Ref.6). The project completed the hazard and operability study (HAZOP) over the period January to May 2022.

The design being implemented by Snowy Hydro does not involve any unproven, novel technology or methods. The hazards and risks associated with operation of the design are well understood. The Project has been developed to be hydrogen ready meaning that it will be capable of co-firing natural gas with hydrogen in the future. However, this method of operation was not assessed in detail during this HAZOP study. It will be assessed in a future HAZOP as required when the logistics of hydrogen delivery to the Site are established.

Certain Project design interfaces between 3rd parties (i.e., the AECOM balance of plant and MELCO hydrogen seal oil systems, Fire and Gas systems) were mostly but not fully developed at the time of the HAZOP study. Design completion of the 3rd party interfaces will need to be managed carefully. Should the design or system interface change, it would be best practice to HAZOP those sections of plant again. Snowy Hydro has recorded an action to review whether this additional study is required prior to construction, and this is further underpinned by Snowy Hydro’s technical change management process.

Two experienced facilitators were used to complete the HAZOP study, given the size of the project and different design organisations involved.

The HAZOP study teams were selected to achieve a diverse range of relevant organisational roles, technical disciplines and experience representing operations management, production, maintenance, engineering, design and project management. The design teams were comprised of the responsible mechanical engineers, process engineers, electrical, control and instrument engineers.

Snowy Hydro’s selection of operations representatives was drawn primarily from its senior operations personnel at its existing Gas Turbine Generating plants to ensure relevant plant experience was available to the study.

The HAZOP session for the natural gas reticulation system on site considered the impact of disturbances on the Project site from the APA natural gas supply infrastructure, being the Gas Receiving Station, which is connected to the Kurri Kurri Gas Lateral and as emphasized in NSW Department of Planning, Industry and Environment letter to SHL, dated 22nd December 2021 (Ref.5). The potential for impacts on the Gas Receiving Station were also noted. The Engineering Manager and Lead Process Engineer from APA participated in this session.

The HAZOP study participants were able to review the proposed design in a satisfactory manner under the guidance of the experienced HAZOP study facilitators. Adequate information was available, and the HAZOP study participants had a sound range of relevant design and production experience.

The hazards identified in the Power Island and Closed Cooling Water System were assessed for likelihood and consequence level using Snowy Hydro’s risk matrix as shown below.

| | | | | | | | | | |
|------------|----------|------------|--------|----------|---------|---------|--------------|-------------------|---------------------|
| Likelihood | Certain | Low | Medium | High | Extreme | Extreme | Extreme | > 0.9 | 1 yr /event |
| | Likely | Low | Medium | High | High | Extreme | Extreme | 0.5 - 1 | 1 - 2 yrs / event |
| | Possible | Low | Medium | Medium | High | High | Extreme | 0.1 - 0.5 | 2 - 10 yrs /event |
| | UnLikely | Low | Low | Medium | Medium | High | High | 0.02 - 0.1 | 10 - 50 yrs / event |
| | Rare | Low | Low | Low | Medium | Medium | High | < 0.02 | > 50 yrs /event |
| | | Negligible | Minor | Moderate | Major | Severe | Catastrophic | Consequence Level | |

Process hazards with the potential to have severe hazardous effects well beyond the immediate area of a *process incident* were identified as:

- High pressure natural gas
- High pressure hydrogen
- Bulk diesel fuel storage

Plant hazards with the potential for localised but severe hazardous effects *resulting from a process incident* are:

- High kinetic energy rotodynamic machinery
- Pressure equipment

A “severe” hazardous effect is defined in Snowy Hydro’s Risk Matrix for a safety hazard as:

Single fatality or permanent significant disability, long term impairment or illness significantly affecting the quality of life for an employee, contractor or member of the public.

These systems were given focus for the HAZOP to check that the risks associated with these hazards were suitably managed.

Whilst not within the scope of the HAZOP, the “product” of the facility, being high voltage electricity, is a significant hazard with the potential for localised severe hazardous effects. The risks associated with high voltage electricity are well understood and their management is implemented through application of standards made mandatory through regulation.

The above hazards are highlighted in the context of DPE’s stated objective to pursue protection of community safety. There are a range of other process and plant hazards typical of every industrial facility which tend to have hazardous effects local to the source of the hazard e.g., hot surfaces, noise, electrical equipment, equipment at height, etc. Hazards in addition to those highlighted and associated with the process are detailed in the HAZOP study records in the appendices to this report.

The HAZOP study did not reveal any hazards with extreme risk that would compromise the safety or integrity of the Project with respect to the safety of site personnel or the public, which could not be managed. In the opinion of the Facilitators, the Project can proceed, subject to satisfactory resolution of the HAZOP recommendations by the required timeframes.

A summary of the results of the risks assessed are shown below.

| | | |
|----------------------|--------|-----|
| Inherent Risk | Low | 157 |
| | Medium | 68 |
| | High | 24 |
| Residual Risk | Low | 168 |
| | Medium | 79 |
| | High | 2 |

In this HAZOP, there were no hazards identified with a high inherent risk and low residual risk which indicates that there is not an over-reliance on the safety protection layers.

Two hazards were identified as having a high residual risk. Both hazards were for the Generator DC Seal Oil System where the generator uses H₂ as a cooling medium with “Loss of H₂ containment” being the consequence. The residual risk takes into consideration the existing safety protection layers but not the HAZOP recommended action. As part of the closing out of HAZOP recommendations, actions have now been taken to address these two high residual risk items.

The remainder of the high-risk items were assessed as being mitigated to medium risk, as defined the Snowy Hydro’s risk matrix when considering the safety protection layers.

The schedule for completion of HAZOP recommendations is summarised in Appendix E. There were 335 recommendations made in total. Most of the recommendations have been scheduled for completion prior to issuing construction drawings. Of the recommendations to be completed in subsequent project implementation phases, 34 recommendations are scheduled for completion prior to commissioning and 6 recommendations are scheduled for completion prior to handover to operations for beneficial operation. No recommendations are scheduled for completion after beneficial operation commences.

1 Introduction

Snowy Hydro Limited (Snowy Hydro) is developing a new Gas Turbine Peaking Power Station at Loxford in the Hunter Valley, NSW – the Project. The Project will be comprised of 2 x 330MW open cycle gas turbines (OCGT) with natural gas as the primary fuel and diesel as the backup.

The design being implemented by Snowy Hydro does not involve any unproven, novel technology or methods. The Project has been developed to be hydrogen ready meaning that it will be capable of co-firing natural gas with hydrogen in the future. However, this method of operation was not assessed in detail during this HAZOP study. It will be assessed in a future HAZOP as required when the logistics of hydrogen delivery to the Site are established.

The Project has been declared Critical State Significant Infrastructure (CSSI) under Section 5.13 of the NSW Environmental Planning and Assessment Act 1979 (Ref.3). The Conditions of Consent (Ref.4), Consent Condition B12(b), for The Project requires preparation and submission of a HAZOP study of the design. This report contains a summary and details of the HAZOP study performed on the Project.

The HAZOP was conducted over several sessions between 20 January 2022 and 5 May 2022 and attended by experienced representatives from both the Owner and Contractors' teams. Given the COVID-19 health orders in place at the time of conducting the HAZOP, the sessions were all held virtually.

The HAZOP study scope was divided into three parts and conducted by two facilitators, who each prepared separate HAZOP study reports. The scope was split in this way as that was the logical division between the main contracting parties and representatives from each party were present for each part of the study. This document is structured as follows:

- Report Body – summarises the HAZOP study
- Appendix A – contains the credentials of the HAZOP study facilitators.
- Appendix B – contains the detailed HAZOP study report for the Power Island. (MHI & Pantac)
- Appendix C – contains the detailed HAZOP study report for the Closed Cooling Water System. (AECOM & Pantac)
- Appendix D – contains the detailed HAZOP study report for the Balance of Plant. (AECOM & RiskCon)
- Appendix E – contains the HAZOP Recommendations Completion Schedule by Project Phase developed at the time of the HAZOP
- Appendix F – contains the updated status of the recommendations at the time of submitting this report

1.1 Aim of the Report

The aim of this report is to address Consent Condition B12(b) by summarising the findings of the overall HAZOP study and provide sufficient context, information, and cross references to enable the outcomes to be understood and managed to closure.

2 Glossary and Abbreviations

A glossary and list of abbreviations used in the body of this report is shown in Table 1. Each HAZOP study report contained in Appendices B, C and D includes its own glossary and list of abbreviations as there is potential for differences between them because of the different design organisations involved.

Table 1 - Glossary and Abbreviations

| Term | Definition |
|--------------|---|
| AECOM | AECOM Australia Ltd |
| AS | Australian Standard |
| BoP | Balance of Plant – a contractual division of plant design – primarily covers services and utilities |
| CSSI | Critical State Significant Infrastructure (NSW) |
| DPE | NSW Department of Planning and Environment |
| GT | Gas Turbine |
| GTG | Gas Turbine Generator |
| HAZOP | Hazard and Operability Study |
| HIPAP | Hazardous Industry Advisory Paper (NSW) |
| H&S | Health and Safety |
| IEC | International Electrotechnical Commission |
| km | kilometre |
| kV | kilovolt |
| MELCO | Mitsubishi Electric Corporation |
| MHI | Mitsubishi Heavy Industries |
| MW | megawatt |
| NSW | New South Wales |
| OCGT | Open Cycle Gas Turbine |
| P&ID | Piping and Instrument Diagram |
| Power Island | A contractual division of plant design – primarily covers the core turbine and generation equipment |
| RACI | Responsible, accountable, consulted, and informed matrix or chart |
| Snowy Hydro | Snowy Hydro Ltd |
| SPL | Safety Protection Layer |
| WHS | NSW Work Health and Safety Act 2011 No 10 |

3 Summary of Main Findings and Recommendations

The HAZOP study participants were able to review the proposed design in a satisfactory manner, including the impact of disturbances from the Kurri Kurri Gas Lateral on the Project, under the guidance of experienced HAZOP study facilitators. Adequate information was available, and the HAZOP study participants had a sound range of relevant design and production experience.

Snowy Hydro has reviewed and accepts the finding of the HAZOP and has actions in place to steward the closure of the recommendations as required under its obligations under the NSW Work Health and Safety Act by applying its H&S policy in a timely manner on the Project and satisfying Consent Condition B12(b) in the Infrastructure Approval.

The HAZOP study did not reveal any hazards with extreme risk that would compromise the safety or integrity of the Project with respect to the safety of site personnel or the public, which could not be managed. In the opinion of the Facilitators, the Project can proceed, subject to satisfactory resolution of the HAZOP recommendations by the required timeframes.

The hazards identified in the Power Island and Closed Cooling Water System were assessed using Snowy Hydro’s risk matrix as shown below.

Figure 1 - Snowy Hydro Risk Matrix

| | | | | | | | | | |
|------------|----------|------------|--------|----------|---------|---------|--------------|-------------------|---------------------|
| Likelihood | Certain | Low | Medium | High | Extreme | Extreme | Extreme | > 0.9 | 1 yr /event |
| | Likely | Low | Medium | High | High | Extreme | Extreme | 0.5 - 1 | 1 - 2 yrs / event |
| | Possible | Low | Medium | Medium | High | High | Extreme | 0.1 - 0.5 | 2 - 10 yrs /event |
| | UnLikely | Low | Low | Medium | Medium | High | High | 0.02 - 0.1 | 10 - 50 yrs / event |
| | Rare | Low | Low | Low | Medium | Medium | High | < 0.02 | > 50 yrs /event |
| | | Negligible | Minor | Moderate | Major | Severe | Catastrophic | Consequence Level | |

In the initial assessment, the ‘Likelihood’ and ‘Severity’ represented the possibility and consequence of a hazard without taken credit for the safety protection layer (SPL). This is summarised below as the Inherent Risk.

‘Likelihood with SPL’ and ‘Severity with SPL’ represent the possibility and consequence of a hazard having taken credit for the correct operation of the SPL. The consequence remains the same, only the frequency was modified. This is summarised below as the Residual Risk.

The descriptions of the different types of consequence levels are provided in Appendix B Power Island HAZOP Report in Appendix 3.

A summary of the results of the risks identified are shown below.

Table 2 - Summary of the Risks

| | | |
|----------------------|--------|-----|
| Inherent Risk | Low | 157 |
| | Medium | 68 |
| | High | 24 |
| Residual Risk | Low | 168 |
| | Medium | 79 |
| | High | 2 |

In general, when a hazard is assessed as having a high inherent risk and a low residual risk, this can indicate an over-reliance on the protection measures. In this HAZOP, there were no hazards identified with a high inherent risk and low residual risk.

During the HAZOP, two hazards were identified as having a high residual risk. Both hazards were for the Generator DC Seal Oil System where the generator uses H2 as a cooling medium with “Loss of H2 containment” being the consequence. The residual risk takes into consideration the existing safety protection layers but not the HAZOP recommended action. As part of the closing out of HAZOP recommendations, actions have now been taken to address these two high residual risk items. The

items as recorded in the HAZOP are shown below along with the current HAZOP recommendation status.

Figure 2 - High Residual Risk HAZOP Records

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments |
|--|---|------------------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|--|
| NODE No. 53 - Generator - DC seal oil system Dwg A13C870 - Generator seal oil diagram for GT | | | | | | | | | | |
| Pressure Low | DC Pump fault | Loss of H2 containment | Unlikely | Severe | High | | Unlikely | Severe | High | There is no safeguard for DC pump failure. No DC pump discharge pressure sensor. Pump is tested monthly. Proof test procedure with pressure limits and response time to be confirmed on site. No method for automatic H2 venting system. |
| Pressure Low | Oversized DC pressure relief valve RV-2 passing | Loss of H2 containment | Unlikely | Severe | High | | Unlikely | Severe | High | Note monthly testing regime |

| Recommendations | Owner | Required Completion Phase | Type | Does it relate to a SHL OI / procedure to be drafted? | Status |
|---|-------|---|--|---|--|
| | | 1 - Prior to design completion 2 - Prior to commissioning 3 - Prior to handover | Firm action / recommendation A verification check Further Study For consideration | | |
| Change DC pressure PI-5 to pressure transmitter for DC pump test run and linking to H2 automatic venting system. MELCO team suggest change is technically possible but may cause delays. MELCO will consider changing DC pressure indicator PI-5 to pressure transmitter. | MELCO | 2 | Verify | No | The existing pressure indicator will be changed to a pressure transmitter. Snowy Hydro has also instructed the Supplier to develop a suitable venting design to reduce this risk and are currently working with the Supplier to implement this design. |
| MELCO team to confirm DC pump recirc line size. The large size valve passing may result in very low DC seal oil pressure | MELCO | 1 | Verify | No | CLOSED |

The remainder of the high-risk items were assessed as being mitigated to medium or lower risk when considering the implementation of the mitigating actions.

The schedule for completion of the HAZOP recommendations is summarised in Appendix E. There were 335 recommendations made. Most of the recommendations have been scheduled for completion prior to issuing construction drawings. Of the recommendations to be completed in subsequent project implementation phases, 34 recommendations are scheduled for completion prior to commissioning and 6 recommendations are scheduled for completion prior to handover to operations for beneficial operation. No recommendations are scheduled for completion after beneficial operation commences.

Further discussion and analysis of the results is provided in Section 11 Analysis of Main Findings.

4 Scope and Objectives

The HAZOP for the new 660MW OCGT power station development was undertaken for the following main objectives:

1. Ensure the Company Values, as articulated in the Snowy Hydro Group Health and Safety Policy (H&S Policy) (Ref.1), are applied in a timely manner to the Project
2. Discharge Snowy Hydro's duty under the NSW Work Health and Safety Act 2011 No 10 (WHS Act) (Ref.2)
3. Satisfy Consent Condition B12(b) in the Infrastructure Approval document from the NSW Government, Department of Planning, Industry and Environment, dated 17th December 2021 (Ref.4)

Snowy Hydro will own and operate the Hunter Power Station for its operating life. The target of the HAZOP Objectives is a design that is safe to build and operate and does not pose risk to the community.

These objectives are discussed in the following sections.

4.1 Applying Snowy Hydro's Company Values

Snowy Hydro identifies its values as:

- Safety – Safety is always our number one priority
- Teamwork – We help each other succeed through support and trust
- Ownership – We take pride in our work and own our choices
- Agility – We are adaptable and embrace change
- Decency – We treat others the way we'd like to be treated
- Courage – We speak up and act for what's important

The organisational value of safety is further enumerated in Snowy Hydro' H&S Policy (Ref.1). Key extracts from the Policy include:

The fundamental belief of the Snowy Hydro Group is that all injuries can be prevented.

The purpose of this Policy is to outline the Group's commitment to managing its operations to provide safe and healthy working conditions for the prevention of injury or ill health to all workers (including contractors), visitors and members of the public.

...

Our minimum expectation is that we meet or exceed legislative and other requirements;

...

Managers and supervisors must take steps to provide for the health and safety of workers by: Maintaining work premises and facilities, plant, systems, and working environments where risks to health and safety are understood and actively managed;

This HAZOP study is one of the processes undertaken during the project development and design phase to review and demonstrate the safety of the new gas turbine power station for its future operation.

4.2 Duty under the NSW Work Health and Safety Act

In ensuring the project team follows the Snowy Hydro H&S Policy (Ref.1) and enabling procedures, Snowy Hydro can ensure it discharges its safety duties under the WHSA (Ref.2) and the Project Conditions of Consent (Ref.4). The objectives of the WHSA (Ref.2) and DPE are highlighted below.

The objective of the WHSA (Ref.2) is stated in Division 2, Clause 3 as:

The main object of this Act is to provide for a balanced and nationally consistent framework to secure the health and safety of workers ...

4.3 Satisfy Consent Condition B12(b)

DPE has a key objective to pursue the orderly development of industry and the protection of community safety, which aligns well with Snowy Hydro's H&S Policy (Ref.1). This is described in the Executive Summary of *Hazardous Industry Advisory Paper 8 (HIPAP-8)* (Ref.6), maintained by DPE, as follows:

The orderly development of industry and the protection of community safety necessitate the assessment of hazards and risks. The Department of Planning has formulated and implemented risk assessment and land use safety planning processes that account for both the technical and the broader locational safety aspects of potentially hazardous industry. These processes are implemented as part of the environmental impact assessment procedures under the Environmental Planning and Assessment Act 1979.

The Department has developed an integrated assessment process for safety assurance of development proposals, which are potentially hazardous. The integrated hazards-related assessment process comprises:

- a preliminary hazard analysis undertaken to support the development application by demonstrating that risk levels do not preclude approval;*
- a hazard and operability study, fire safety study, emergency plan and an updated hazard analysis undertaken during the design phase of the project;*
- a construction safety study carried out to ensure facility safety during construction and commissioning, particularly when there is interaction with existing operations;*
- implementation of a safety management system to give safety assurance during ongoing operation; and*
- regular independent hazard audits to verify the integrity of the safety systems and that the facility is being operated in accordance with its hazards-related conditions of consent.*

Section 1.2 of HIPAP-8, also identifies the following objective for HAZOP study reports submitted to a consent authority:

a report should be able to satisfy a consent authority as to the competence of the examining team and that the potential hazards involved in the enterprise have been addressed.

The Project has completed the hazard and operability study (HAZOP) element of this integrated hazards-related assessment process.

4.4 Scope of the Study

For the purposes of this HAZOP study, the Project was defined by its physical property boundary (the Site) and its terminal points such as the gas connection point at the Gas Receiving Station, the diesel unloading point, the water supply, stormwater, and sewerage service connection points to the Hunter Water network at the property boundary and the electrical connection within the Switching Station to the Ausgrid 132kV electricity network.

A summary of the plant systems covered in the HAZOP study is given in Table 3 below.

Table 3 - Plant Systems Covered in HAZOP Study

| System | Main Project Division of Design |
|---------------------------------------|---------------------------------|
| Fuel Oil (Diesel) | Power Island |
| Fuel Gas (Natural Gas) | Power Island |
| Air & Flue Gas | Power Island |
| GT Lube Oil | Power Island |
| GT Control Oil | Power Island |
| Package Enclosure Ventilation | Power Island |
| Gas Turbine Casing Cooling | Power Island |
| Gas Turbine Blade Washing | Power Island |
| Evaporative Cooler (Inlet Air Filter) | Power Island |
| Purge Air | Power Island |

| | |
|---|------------------|
| Cooling water | Power Island |
| Generator CO2 | Power Island |
| Generator H2 | Power Island |
| Generator Lube Oil | Power Island |
| Generator Seal Oil | Power Island |
| Diesel Systems | Balance of Plant |
| Natural Gas Systems | Balance of Plant |
| Hydrogen Systems, CO2 systems, Nitrogen Systems | Balance of Plant |
| Instrument Air Systems, Services Air Systems | Balance of Plant |
| Potable Water Systems, Services Water Systems, Demineralised Water Systems, chemical dosing systems | Balance of Plant |
| Fire water systems, oily water systems | Balance of Plant |
| Blade washing systems, trade waste and sewer systems | Balance of Plant |

4.5 Excluded Scope and Other Studies

Non-process systems infrastructure (such as telecommunication, electrical transmission connections, etc), tasks and activities are not within the scope of the HAZOP study. Aspects of these relevant to DPE's objective of *orderly development of industry and the protection of community safety* are addressed by other elements in DPE's integrated hazards-related assessment process.

The Project has also completed various other safety and design studies during the development and design phase which include:

- Preliminary Hazard Analysis
- Final Hazard Analysis
- Safety in Design workshops (for both the AECOM balance of plant design and the Mitsubishi Power Island design);
- Layers of Protection Analysis (LOPA) workshops for the Mitsubishi Power Island design;
- Safety integrity level (SIL) assessment;
- Fire Safety Study; and
- Maintainability and Operational study

5 Description of the Facility

A detailed project description is included in Section 2 of the *Hunter Power Project Environmental Impact Statement (ref 9)*. For convenience, a summary of the main aspects of the Project are described below.

The intent of establishing a peaking power station in the Hunter Valley is to enable Snowy Hydro to increase its dispatchable generating capacity in NSW. The facility will be able to supply electricity to the grid at short notice during periods of high electricity demand including during low supply periods from intermittent renewable sources or during supply outages or shortages at other base load power stations.

The Project Site is located at Hart Road, Loxford, about one kilometre (km) east of the M15 Hunter Expressway and about three km's north of the town of Kurri Kurri as shown in **Error! Reference source not found..** An overview of the power station layout is shown in Figure 2.

Figure 3 - Project Location





Figure 4 - Plant Layout



The power station will be a dual fuel (gas and diesel), “peak load” generation facility supplying electricity at a capacity of up to approximately 660 MW, which will be generated via two heavy-duty open cycle gas turbines (OCGTs). The gas turbines are model M701F units supplied new by Mitsubishi Heavy Industries (MHI) and manufactured in Japan.

The Project involves the construction and operation of the power station together with other associated infrastructure. The major supporting infrastructure required for the Project is a 132kV electrical Switching Station located adjacent to the main power generation footprint but within the Project Site. The Project will connect into the existing 132kV Ausgrid electricity transmission infrastructure located near the Project Site. A new gas lateral pipeline is being developed by a third party to supply gas to the power station and will terminate at the Gas Receiving Station, at which point it will connect to the Project infrastructure.

Snowy Hydro has engaged two main organisations to perform the overall process design for the Project with the following division of design responsibility:

- Power Island - Mitsubishi Heavy Industries (MHI)
- Balance of Plant and Closed Cooling Water System – AECOM Australia Ltd

These systems are described in more detail below.

5.1 Power Island

The power island consists of two dual fuel, MHI M701F series gas turbines (GT) with water injection for fuel oil low NOx control and two hydrogen cooled generators. The GT intakes are equipped with an evaporative cooling system to increase output performance. The power island also includes the following auxiliary plant infrastructure:

- Generator circuit breaker
- power/distribution transformers,
- Static frequency converter and associated equipment
- Excitation transformer and associated equipment
- Electrical equipment and I&C
- Fuel gas control
- Fuel oil control
- Oil systems (control, lubrication, and gas sealing)
- Turbine enclosure air cooling
- Fire detection system
- Gas fire suppression systems
- Firewater deluge systems
- Turbine blade washing facility
- Emergency diesel generator

Refer to the individual HAZOP report for the Power Island in Appendix B for further details on the system.

5.2 Closed Cooling Water System

The Closed Cooling Water System forms part of the Balance of Plant system design and circulates cooling water throughout the power island to cool the various oil, air and process gas systems. It comprises the following main components:

- Fin fan coolers
- Helper cooler and booster pump
- Expansion tank
- Cooling water pumps
- GT HP purge air coolers
- GTG H2 air coolers
- GT control oil coolers
- GT lube oil coolers

Refer to the individual HAZOP report for the Closed Cooling Water System in Appendix C for further details on the system.

5.3 Balance of Plant

The Balance of Plant infrastructure includes:

- Natural Gas Supply – from the main gas supply provider at the power station boundary to the GT enclosure, including metering systems, knock out drums, filter/coalescers, cartridge filters, condensate tank and associated pipework
- Diesel Fuel Supply – including diesel truck fuel unloading and reloading, diesel storage tanks, forwarding pumps and associated delivery pipework from the tanks to the GT enclosure
- Process Gas – Hydrogen gas systems including gas cylinders (trailers) and delivery pipework to the generator for each GT
- Process Gas – Carbon Dioxide (CO₂) gas systems including cylinders and delivery pipework to the generator for each GT
- Process gas - Nitrogen gas systems including cylinders and delivery pipework to the natural gas supply line to the GT
- Compressed Air and Instrument air systems supplying air services to the site and to the GT equipment
- Water Supply – potable water supply to the service water tank and site users, including service water tank, service water pumps and associated pipework to users
- Water Supply – service water systems including pumps to Reverse Osmosis (RO) plant, RO plant, demineralised (demin.) water tanks, pumps, filters and chemical dosing systems
- Water Supply – fire water and fire services systems, including fire water tanks, pumps and pipework
- Waste-Water Systems – Oily water collection and treatment systems, Demin plant and blade washing wastewater systems, chemical dosing systems for the trade waste system and sewer systems.
- Fire-fighting system including water storage, pumps, hydrants and deluge systems
- Emergency diesel generator with associated internal fuel storage
- Electrical Switch Rooms and associated power distribution cabling
- Stormwater drainage system
- Administration Building incorporating a Local Control Room and amenities
- Integrated Workshop and Warehouse
- Chemical Store
- Yards for outdoor laydown
- Roads, car parks and security fencing

Refer to the individual HAZOP report for the Balance of Plant in the Appendix D for further details on the balance of plant equipment including process descriptions, pressures and flows and the P&IDs.

6 HAZOP Team Members

The HAZOP study teams were selected to achieve a diverse range of relevant organisational roles, technical disciplines and experience representing operations management, production, maintenance, engineering, design and project management. The design teams were comprised of the responsible mechanical engineers, process engineers, electrical, control and instrument engineers.

Snowy Hydro's selection of operations representatives was drawn primarily from its senior operations personnel at its existing Gas Turbine Generating plants to ensure relevant plant experience was available to the study.

The MHI design team representatives had extensive experience in design of OCGT plant having delivered many other projects across the world.

The AECOM design team representatives have extensive experience in auxiliary plant designs of the type required for the OCGT plant, having delivered many projects.

The study team participants also had prior HAZOP experience.

Snowy Hydro believes the combination of participants with relevant operations and design experience and prior HAZOP method experience managed by experienced facilitators achieves the objective of deploying a competent examination team.

Full details of the study teams are included in the individual HAZOP reports contained in Appendices B, C and D.

6.1 Facilitator Selection

To cover the entire process, Snowy Hydro engaged two HAZOP facilitators:

- Power Island – Paul van Dyk, who has 30 years of professional experience and 10 years of HAZOP experience
- Balance of Plant – Steve Sylvester, who has over 45 years of professional experience and over 25 years of HAZOP experience

The facilitators were selected for their:

- depth of engineering experience and experience in facilitating HAZOP studies
- knowledge of the technologies being deployed in the Project
- independence of the design teams on the Project

Refer to Appendix A for the Department of Planning and Environment's approval of the HAZOP Chairpersons as listed above.

7 HAZOP Methodology

The basic approach used for the Hunter Power Project HAZOP complies with and was that as described in HIPAP-8 (Ref.6). This process is further standardised in Australian Standard, AS/IEC 61882:2017 (Ref.7), which depicts it as shown in Figure 5.




Figure 5 - Flow Chart of the Workshop Examination Procedure, as per AS IEC 61882:2017

During the HAZOP study, the study team identified hazardous conditions or operational issues in the design by considering how the design responds to process deviations, synthesized through application of the guidewords to the process. The study team also played out the hazardous condition or operational issue to further understand the potential consequences thus identifying a complete risk scenario. Planned safeguards for the risk scenario were identified and evaluated for effectiveness in

treating the risk and a decision then taken as to whether additional risk treatment measures were required. As the HAZOP study team is not collectively responsible for the design, it makes “recommendations” to the responsible designers for follow-up risk treatment action.

A specific form of additional risk treatment was immediately recorded as a study team recommendation when it:

- was obvious
- would not introduce other risks
- was strongly endorsed by the study team, which includes the responsible designers.

Further investigation and analysis by the responsible designers were recorded as a study team recommendation when:

- the form of additional risk treatment was not obvious
- multiple alternatives were available
- identified risk treatments had the potential to introduce other risks or operational difficulties.

In this latter case, where possible options for risk treatment were identified they were recorded “for consideration” as part of the follow-up investigation and analysis by the responsible designer.

The detail of the risk scenarios, planned safeguards, study team recommendations and organisational assignment for recommendations are documented in the HAZOP study worksheets appended to the individual HAZOP reports contained in Appendices B, C and D. The study team recommendations and required project completion phase are also summarised in Appendix E.

8 Study Details

8.1 General

Due to the size of the plant and different design teams associated with the overall design, the HAZOP study was conducted in separate sessions over the period from January to May 2022. Details regarding the individual HAZOP studies are included in the HAZOP reports contained in Appendices B, C and D which cover:

- Meeting location, timing and participants
- Guidewords selection
- Drawings and node selection
- Description of the plant systems
- Relevant supporting design documents
- HAZOP study results.

8.2 HAZOP Study Management

The key management steps in implementing a HAZOP study are enumerated in the following RACI matrix. The RACI matrix identifies the division of accountability (“A”) and responsibility (“R”) for performance of the work. In this context, responsibility is distinguished from accountability by meaning the party performing a task. Additionally, the RACI matrix identifies when related parties need to be consulted (“C”) during performance of a task in order to properly complete the task and when related parties only need to be informed (“I”) of the outcome of a task. Separate RACI matrices are given for the division of design responsibility introduced in Section 3 Summary of Main Findings and Recommendations

The HAZOP study participants were able to review the proposed design in a satisfactory manner, including the impact of disturbances from the Kurri Kurri Gas Lateral on the Project, under the guidance of experienced HAZOP study facilitators. Adequate information was available, and the HAZOP study participants had a sound range of relevant design and production experience.

Snowy Hydro has reviewed and accepts the finding of the HAZOP and has actions in place to steward the closure of the recommendations as required under its obligations under the NSW Work Health and Safety Act by applying its H&S policy in a timely manner on the Project and satisfying Consent Condition B12(b) in the Infrastructure Approval.

The HAZOP study did not reveal any hazards with extreme risk that would compromise the safety or integrity of the Project with respect to the safety of site personnel or the public, which could not be managed. In the opinion of the Facilitators, the Project can proceed, subject to satisfactory resolution of the HAZOP recommendations by the required timeframes.

The hazards identified in the Power Island and Closed Cooling Water System were assessed using Snowy Hydro’s risk matrix as shown below.

Figure 1 - Snowy Hydro Risk Matrix

| | | | | | | | | | |
|------------|----------|------------|--------|----------|---------|---------|--------------|-------------------|---------------------|
| Likelihood | Certain | Low | Medium | High | Extreme | Extreme | Extreme | > 0.9 | 1 yr /event |
| | Likely | Low | Medium | High | High | Extreme | Extreme | 0.5 - 1 | 1 - 2 yrs / event |
| | Possible | Low | Medium | Medium | High | High | Extreme | 0.1 - 0.5 | 2 - 10 yrs /event |
| | UnLikely | Low | Low | Medium | Medium | High | High | 0.02 - 0.1 | 10 - 50 yrs / event |
| | Rare | Low | Low | Low | Medium | Medium | High | < 0.02 | > 50 yrs /event |
| | | Negligible | Minor | Moderate | Major | Severe | Catastrophic | Consequence Level | |

In the initial assessment, the 'Likelihood' and 'Severity' represented the possibility and consequence of a hazard without taken credit for the safety protection layer (SPL). This is summarised below as the Inherent Risk.

'Likelihood with SPL' and 'Severity with SPL' represent the possibility and consequence of a hazard having taken credit for the correct operation of the SPL. The consequence remains the same, only the frequency was modified. This is summarised below as the Residual Risk.

The descriptions of the different types of consequence levels are provided in Appendix B Power Island HAZOP Report in Appendix 3.

A summary of the results of the risks identified are shown below.

Table 2 - Summary of the Risks

| | | |
|----------------------|--------|-----|
| Inherent Risk | Low | 157 |
| | Medium | 68 |
| | High | 24 |
| Residual Risk | Low | 168 |
| | Medium | 79 |
| | High | 2 |

and repeated below:

- Power Island – Mitsubishi Heavy Industries (MHI) (**Error! Reference source not found.**)
- Balance of Plant – AECOM Australia Ltd (**Error! Reference source not found.**)

The HAZOP study for the Power Island was co-ordinated by Evan Bayliss and Sara Roder, Snowy Hydro Limited and the HAZOP study for the Balance of Plant was co-ordinated by David Lockley, AECOM.

Table 4 - Power Island HAZOP Study RACI Matrix

| Activity | SHL Project Manager | Power Island HAZOP Coordinator | BoP HAZOP Coordinator | Facilitator Paul van Dyk | Power Island Lead Plant Engineer |
|--|---------------------|--------------------------------|-----------------------|--------------------------|----------------------------------|
| Review Power Island Plant Systems for HAZOP | A | C | | R | |
| Establish a preliminary Power Island Plant HAZOP session schedule | A | C | | R | |
| Prepare template HAZOP Terms of Reference | A | C | | R | |
| Prepare template HAZOP Report | A | | R | | |
| Review Power Island Plant design drawings and intent with Lead Process Engineer and select nodes | A | | | R | C |
| Review and refine Power Island Plant HAZOP session schedule | A | C | | R | C |
| Detail and publish Power Island Plant HAZOP Terms of Reference to participants | A | C | | R | C |
| Facilitate Study sessions | A | | | R | |
| Detail Formal Power Island Plant HAZOP Report | A | | | R | |

| Activity | SHL Project Manager | Power Island HAZOP Coordinator | BoP HAZOP Coordinator | Facilitator Paul van Dyk | Power Island Lead Plant Engineer |
|---|---------------------|--------------------------------|-----------------------|--------------------------|----------------------------------|
| Review Formal Power Island Plant HAZOP Report | A | R | C | | C |
| Finalise Formal Power Island Plant HAZOP Report | A | C | I | R | I |
| Issue Formal Power Island Plant HAZOP Report | A | R | I | I | I |

Table 5 - Balance of Plant HAZOP Study RACI Matrix

| Activity | SHL Project Manager | BoP HAZOP Coordinator | Facilitator Steve Sylvester | Lead BoP Process Engineer |
|---|---------------------|-----------------------|-----------------------------|---------------------------|
| Review Balance of Plant (BoP) Systems for HAZOP | A | R | | C |
| Establish a preliminary BoP HAZOP session schedule | A | R | | C |
| Prepare template HAZOP Terms of Reference | A | R | | I |
| Prepare template HAZOP Report | A | R | | I |
| Review BoP design drawings and intent with Lead Process Engineer and select nodes | A | | R | C |
| Review and refine BoP HAZOP session schedule | A | I | R | C |
| Detail and publish BoP HAZOP Terms of Reference to participants | A | I | R | C |
| Facilitate Study sessions | A | | R | |
| Detail Formal BoP HAZOP Report | A | | R | |
| Review Formal BoP HAZOP Report | A | R | | C |
| Finalise Formal BoP HAZOP Report | A | C | R | I |
| Issue Formal BoP HAZOP Report | A | R | I | I |

8.3 Study Language

As the Power Island design is being performed by MHI in Japan, the HAZOP sessions were bilingual i.e., English and Japanese. A translator was selected, who is experienced in the technical language used for this type of project.

8.4 Study Preparation

Preliminary work by the facilitators included review of the P&IDs and supporting explanatory design documents followed by clarification of the design intent with the design teams to enable preliminary identification of study nodes and guidewords. The facilitators' preliminary study nodes and guidewords were discussed with Snowy Hydro and the respective design team to confirm that they appropriately reflected the proposed design and operations. Refinements were made as appropriate.

Prior to the study commencement, the P&IDs were provided in electronic format to the study participants to allow them an opportunity for private study of the design.

8.5 Study Environment

Owing to the diverse geographic location of the HAZOP study participants (reaching across Australia, New Zealand and Japan) and complications associated with COVID-19 rules all study sessions were conducted as a hybrid of small in-person groups connected via video conference.

It was recognized that this hybrid approach and bilingual language is demanding on the study participants. To manage fatigue, the sessions were scheduled to limit consecutive study days to provide adequate rest days. Within each session, rest breaks were implemented.

This is discussed in more detail by the facilitators in the individual HAZOP reports contained in Appendices B, C and D.

8.6 Power Island and Balance of Plant Interface

As indicated previously, Snowy Hydro has entered into two main contracts covering the design of the power station, which created a major design interface. To ensure scenarios were properly examined irrespective of the physical location of the contractual interface for design, design representatives from each of the two major design contract teams i.e., MHI and AECOM, participated in each other's HAZOP sessions.

8.7 Kurri Kurri Gas Lateral Interface

The HAZOP session for the natural gas reticulation system on the Site considered the impact of disturbances on the Project from the APA supply infrastructure, being the Gas Receiving Station, which is connected to the Kurri Kurri Gas Lateral; this is good HAZOP practice and was also emphasized in the NSW Department of Planning, Industry and Environment letter to SHL, dated 22nd December 2021 (Ref.5). The potential for impacts on the Gas Receiving Station were also noted. The Engineering Manager and Lead Process Engineer from APA participated in this session. The full Kurri Kurri Gas Lateral and Gas Receiving Station HAZOP is to be undertaken by the separate project developing that infrastructure.

From the HAZOP study there were 8 recommendations regarding the emergency shut down and safe venting of the fuel gas system including to perform a dynamic study of the system based on closure times of the valves considering all system shutdown (trip) scenarios.

The detail pertaining to this interface is in the individual HAZOP report contained in Appendix D in Table 11 (Node 2.1).

9 Guide Words

The guide words for each portion of the HAZOP scope were selected to be the most appropriate given the nature of the systems being studied.

The guide words are located as described below:

- Power Island portion are in Appendix B, Section 6.1
- Closed Cooling Water System portion are in Appendix C, Section 6.1
- Balance of Plant portion are in Appendix D, Section 2.2 – Table 2

10 Plant Overview

In addition to the line-by-line guideword analysis conducted during the HAZOP study, the following general conditions and situations likely to result in a hazardous outcome, were also considered for the various HAZOP sections.

Power Island:

- Start up
- Shut down
- Utility failure
- Fire

Closed Cooling Water System:

- Start up
- Shut down
- Utility failure
- Fire
- Maintenance

Balance of Plant:

- Toxicity
- Physical Damage
- Fire/Explosion
- Environmental Impact
- Material of Construction
- Access
- Utilities and Services
- Commissioning
- Start Up
- Shut down
- Safety Equipment
- Natural Hazards
- Inspection and Testing
- Procedures – e.g. maintenance, emergency
- Quality Control

Any issues or recommended actions from the plant overview portion of the HAZOP studies were recorded in the HAZOP reports contained in Appendices B, C and D.

11 Analysis of Main Findings

The results of the HAZOP, giving deviations, consequences and actions required are recorded in the detailed individual HAZOP reports in Appendices B, C and D.

Actions were taken based on consensus of the HAZOP participants on whether the hazard was adequately addressed in the design. Where the recommended inclusion or change to the design was clear, the specific change was recorded. Where further investigation was required, the action was recorded for the action owner to “review” or “confirm” the design with the context of the hazard provided.

For those events on which the decision of no action was made, these are also listed in the HAZOP results, along with the events for which consequence or risk analysis was considered necessary.

A summary and discussion of the main findings of the HAZOP is given in the following section.

11.1 Summary and Discussion of the HAZOP Results

Process hazards for the Project with the potential to have severe hazardous effects well beyond the immediate area of a *process incident* were identified as:

- High pressure natural gas
- High pressure hydrogen
- Bulk diesel fuel storage

Plant hazards for the Project with the potential for localised but severe hazardous effects *resulting from a process incident* are:

- High kinetic energy rotodynamic machinery
- Pressure equipment

A “severe” hazardous effect is defined in Snowy Hydro’s Risk Matrix for a safety hazard as:

Single fatality or permanent significant disability, long term impairment or illness significantly affecting the quality of life for an employee, contractor or member of the public.

These systems were given focus for the HAZOP to check that the risks associated with these hazards were suitably managed.

Whilst not within the scope of the HAZOP study, the “product” of the facility, being high voltage electricity, is a significant hazard with the potential for localised severe hazardous effects. The risks associated with high voltage electricity are well understood and their management is implemented through application of standards made mandatory through regulation.

The above hazards are highlighted in the context of DPE’s stated objective to pursue protection of community safety. There are a range of other process and plant hazards typical of every industrial facility which tend to have hazardous effects local to the source of the hazard e.g., hot surfaces, noise, electrical equipment, equipment at height, etc. Hazards in addition to those highlighted and associated with the process are detailed in the HAZOP study records in the appendices to this report.

The types of hazards commonly identified, and noteworthy observations for each section are discussed below to provide a summary and context to the HAZOP study.

11.1.1 Power Island

One of the main design observations that was uncovered during the HAZOP study was that the original generator hydrogen seal oil system design relied heavily on administrative controls (Operator response to alarms), which is the second lowest category in the Hierarchy of Controls.

There were several action items related to the hydrogen generator system design with respect to single points of failure and remote operational requirements.

The workshop identified that the proposed MHI M701F class gas turbine generator plant design was more typically installed in fully attended plants. As the Hunter Power Station is planned to operate remotely and can be unattended, there were some aspects identified that were not consistent with the attended operation design philosophy. This is particularly relevant to the hydrogen generator plant and the general higher reliance on operator alarm and response measures. 20 alarm response instances

were recorded in the study records. So, this was one part of the design that resulted in several recommendations for change.

Certain Project design interfaces between 3rd parties (i.e., the AECOM balance of plant design and the MELCO hydrogen seal oil systems, Fire and Gas systems) were mostly but not fully developed at the time of the HAZOP study. Design completion of the 3rd party interfaces will need to be managed carefully. Should the design or system interface change it would be best practice to HAZOP those sections of plant again. Snowy Hydro has recorded an action to review whether this additional study is required prior to construction, and this is further underpinned by Snowy Hydro's technical change management process

Although the turbine control and protection systems appeared to be robust, generally SIL rated and well documented, the Snowy Hydro project team will need to ensure that AS3814 compliance is demonstrated and a suitable AS3814 Type B compliance dossier is created. The technical regulator approval approach is not unique to gas / combustion safety and the approval process effort should be consistent with the generator protection, governor and voltage control modelling, fire and gas detection and suppression compliance requirements. This was another area of the HAZOP study that resulted in some recommendations.

11.1.2 Closed Cooling Water System

One of the main considerations uncovered was that the closed cooling water system design relies on a cooling water system discharge pressure that is greater than the generator hydrogen pressure to prevent any hydrogen leakage or accumulation in the water system in the event of an exchanger leak. There is an action to review the cooling water system discharge pressure control in light of this requirement.

It was also uncovered that the high-pressure air compressors interlocks and protection was not well understood at the time of the HAZOP study and thus an action item was assigned to MHI to confirm with their 3rd party supplier. It was identified that this section of the plant will need to be reviewed again on completion of design and when suitable interlock and protection information becomes available. An action has been recorded to check that this review has been completed.

11.1.3 Balance of Plant

There are no novel technologies being used as part of the overall Balance of Plant design. The hazards and recommendations are considered typical for each of these systems. The types of hazards and recommendations generally identified in the HAZOP study for each system are provided below:

| System | Main Findings |
|--|---|
| Diesel Systems | Nothing unusual identified, to be dealt with through normal design processes |
| Natural Gas Systems | The main recommendations are regarding the review of the emergency shut down and venting requirements around the terminal point with the gas supply from the Gas Receiving Station. |
| Hydrogen Systems, CO2 systems, Nitrogen Systems | Nothing unusual identified, to be dealt with through normal design processes |
| Instrument Air Systems, Services Air Systems | Nothing unusual identified, to be dealt with through normal design processes |
| Potable Water Systems, Services Water Systems, chemical dosing systems | Nothing unusual identified, to be dealt with through normal design processes |
| Demineralised Water Systems | Demineralised water is mildly hazardous as it is slightly acidic and must be neutralised prior to release to the environment. It can also cause corrosion of the metals it comes in contact with. The demineralised water system is used infrequently with the possible consequence of it not working when required. There is also the possibility of damage to RO plant caused by biocide added to the service water used to feed the system. There are also 6 recommendations regarding the integration of the demineralised water control system into the overall plant PLC. |
| Fire water systems, oily water systems | Nothing unusual identified, to be dealt with through normal design processes |
| Blade washing systems, trade waste and sewer systems | Nothing unusual identified, to be dealt with through normal design processes |

12 Action Arising from the HAZOP

Snowy Hydro will manage the close out of the HAZOP recommendations according to the plan outlined in the following section.

12.1 Plan to Manage HAZOP Recommendations

The HAZOP study recommendations and required project completion phase timelines are listed in Appendix E.

Where a recommendation has been made, the project timing for its resolution is indicated in the HAZOP study record according to the following project implementation phases in order of priority:

1. Prior to Construction
2. Prior to Commissioning
3. Prior to Handover for Beneficial Operation
4. Within 12 months of Beneficial Operation

The responsibility for processing a given recommendation during the HAZOP study was assigned at responsible organization level either by company name or company project manager name (or delegate) in the HAZOP study record.

The HAZOP recommendations will be transferred from each HAZOP study record to a master project issues and actions management register, where the recommendations will be assigned to specific individuals with specific target dates for completion commensurate with the remaining project schedule. HAZOP recommendations for the major project implementation participants beyond design will be transferred to the respective entity for incorporation into its management and operational readiness plans. Snowy Hydro retains overall accountability for ensuring that all HAZOP recommendations are resolved in accordance with the required project phase.

Snowy Hydro will continue to provide the co-ordination between the project parties as required to ensure the HAZOP recommendations are resolved. The Snowy Hydro Project Technical Director will provide the project governance by periodically reviewing the status of the HAZOP recommendations and checking that they are suitably addressed prior to progressing to the next phase of the Project.

13 References

1. Snowy Hydro Ltd. 2020, *Policy Number 002: Snowy Hydro Group Health and Safety Policy - 16 December 2020*
2. NSW Government 2011, *Work Health and Safety Act No 10*
3. NSW Government 1979, *Environmental Planning and Assessment Act*
4. NSW Government, Department of Planning, Industry and Environment 2021, *Infrastructure Approval - 17th December 2021*
5. NSW Government, Department of Planning, Industry and Environment 2021, *HAZOP Chairperson Approval – 22nd December 2021*
6. NSW Government, Department of Planning 2011, *Hazardous Industry Advisory Paper 8 (HAZOP Guidelines)*
7. Standards Australia 2017, *AS IEC 61882:2017 – Hazard and Operability Studies (HAZOP studies) – Application Guide*
8. Jacobs Group (Australia) Pty Ltd 2021, *Hunter Power Project Environmental Impact Statement*

Appendix A

DPE Letters of Facilitator Acceptance and Facilitator Credentials



Ian Smith
Approvals Manager – Hunter Project
Snowy Hydro Limited
PO Box 332
Cooma, NSW, 2630

22/12/2021

Dear Mr. Smith

**Hunter Power Project (SSI-12590060)
HAZOP Chairperson Approval**

I refer to your request (SSI-12590060-PA-15) for the Secretary's approval of suitably qualified persons to undertake the role of HAZOP Chairperson for the Hunter Power Project (SSI-12590060).

The Department has reviewed the nominations and information you have provided and is satisfied that these experts are suitably qualified and independent. Consequently, I can advise that the Secretary approves the appointment of David Lockley of AECOM to undertake the role of the HAZOP Chairperson, assisted by Steven Sylvester of Riskcon Engineering.

Please note, the HAZOP study should consider the operating conditions arising from the Kurri Kurri Lateral Pipeline (SSI-22338205) and provide recommendations as necessary.

If you wish to discuss the matter further, please contact Wayne Jones on (02) 6575 3406.

Yours sincerely

A handwritten signature in black ink, appearing to be 'S O'Donoghue'.

Stephen O'Donoghue
Director Resource Assessments

As nominee of the Secretary

Our ref: SSI-12590060-PA-44

Ian Smith
Approvals Manager – Hunter Power Project
Snowy Hydro Limited
PO Box 332
Cooma, NSW 2630

27/09/2022

Dear Mr Smith

**Hunter Power Project (SSI-12590060)
HAZOP Chairperson Approval**

I refer to your request (SSI-12590060-PA-44) for the Secretary's approval of a suitably qualified person to undertake the role of HAZOP Chairperson for the Hunter Power Project (SSI-1259006).

The Department has reviewed the nomination and information you provided and is satisfied the expert is suitably qualified and independent. Consequently, I can advise that the Secretary approves the appointment of Paul van Dyk of Pantac Control to undertake the role of HAZOP Chairperson.

Please note, the HAZOP study should consider the operating conditions arising from the Kurri Kurri Lateral Pipeline (SSI-22338205) and provide recommendations as necessary.

If you wish to discuss the matter further, please contact Jack Turner on 9995 5387.

Yours sincerely

A handwritten signature in black ink, appearing to be "SOD", written over a light blue circular stamp.

Stephen O'Donoghue
Director
Resource Assessments
As nominee of the Planning Secretary

Appendix B

Power Island HAZOP Study Report



0.

HAZOP STUDY

SnowyHydro – Hunter Power Station
Mitsubishi Heavy Industries
M701G Gas turbine generators
SHL Purchase Work Order No. 314502



ABSTRACT

Hazard and Operability (HAZOP) Study of the Hunter Power Station gas turbine generator process design

Pantac System Control

Risk Assessment Doc No 21081700-001-R0

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 1 of 13 |

Contents

| | |
|---|----|
| Revision History..... | 2 |
| 1. Executive Summary | 3 |
| 2. Background | 4 |
| 3. Process description..... | 4 |
| 4. Scope..... | 5 |
| 5. Objectives..... | 5 |
| 6. Methodology..... | 5 |
| 6.1 Guide words and Deviations | 6 |
| 7. Participants | 6 |
| Appendix 1: HAZOP Nodes and drawings..... | 7 |
| Appendix 2: Study records..... | 8 |
| Appendix 3: SnowyHydro Risk Matrix | 9 |
| Appendix 4: HAZOP action items | 10 |
| Appendix 5: Safeguards | 11 |
| Appendix 6: Participants..... | 12 |
| Appendix 7: Acronyms..... | 13 |

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 2 of 13 |

Revision History

| Date | Rev | Description |
|--------------|-----|-----------------------------|
| 20 Apr. 2022 | 0 | Draft – Issued for comments |

| Revision | Prepared By | Reviewed by | Approved By |
|----------|--------------|-----------------|--------------|
| 0 | Paul van Dyk | Reinier van Dyk | Paul van Dyk |

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 3 of 13 |

1. Executive Summary

This report covers the findings of the HAZOP study workshop for the SnowyHydro Hunter Power Station gas turbine generator process design. Due to COVID travel restrictions, the workshop was performed remotely via google meet with client, vendor, translation services and specialist representation. The scope and focus of the study are limited to the gas turbine generator Process and Instrumentation Design (P&IDs) systems.

The workshop was performed according to the agreed scope as outlined in Section 4, using the methodology described in Section 6. It is considered that the stated objectives listed in Section 5 were satisfactorily met, subject to implementation of the recommendations generated.

The workshop generated:

83 recommendations tabled in appendix 4 and identified

50 Safeguards tabled in appendix 5

It is worth noting the following:

- The generator hydrogen seal oil system design relies heavily on administrative controls (Operator response to alarms), which is the second lowest category in the Hierarchy of Controls. Refer Hierarchy of Controls note 1 below.

There are several action items related to the hydrogen system design with respect to single points of failure and remote operational requirements.

Note 1 - There are five levels in the Hierarchy of Controls:

1. Elimination
2. Substitution
3. Engineering controls
4. Administrative controls
5. Personal protective equipment.

The hierarchy is arranged beginning with the most effective controls and proceeds to the least effective.

- The workshop identified that the MHI M701F class gas turbine generator plant is typically installed in fully attended combined cycle plants. Hunter Power Station is planned to operate remotely and unattended, which is not consistent with the attended operation design.

This is particularly relevant to the hydrogen plant and the generally high reliance on Operator alarm response. 20 alarm response instances were recorded in the study records, refer appendix 5 Safeguards instances

- Due to the complexity of the systems, the English Japanese language barrier and the number of people required to attend the web-based sessions, this HAZOP study ran for eleven days

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 4 of 13 |

spread out over seven weeks. Design interfaces between 3rd parties (AECOM balance of plant, MELCO hydrogen seal oil systems, Fire and Gas systems, were mostly but not fully developed.

3rd party interfaces will need to be managed carefully to define scope and deliverables. Should the design or system interface change it would be best practice to HAZOP those sections of plant again.

- MHI is not familiar with the Australian gas fired appliance standard AS3814 approval process. Although the turbine control and protection systems appear to be robust, SIL rated and well documented, the SnowyHydro project team will need to ensure that AS3814 compliance can be demonstrated and a suitable AS3814 Type B compliance dossier is created. Technical regulator approval approach is not unique to gas / combustion safety and the approval process effort should be consistent with the generator protection, governor and voltage control modelling, fire and gas detection and suppression compliance requirements.

2. Background

This new gas turbine peaking plant will be commissioned on liquid fuel in 2023 to provide power to the New South Wales electricity spot market. Natural gas firing will follow 6 to 12 months after that.

The plant will be owned and operated by SnowyHydro Ltd.

Hydrogen blending with natural gas for combustion is not included at the time of this study.

3. Process description

Hunter Power Station will be a dual fuel (high speed diesel and natural gas fired), Open Cycle Gas Turbine Power Station with a rated output of approximately 2 x 330 MW. The plant consists of two dual fuel, MHI M701G series gas turbines with water injection for fuel oil low NOx control, two hydrogen cooled generators, associated lube and seal oil and gas systems, electrical equipment and I&C, emergency diesel generator, power/distribution transformers, closed circuit cooling system, firefighting and detection systems and HVAC. The GT intakes are equipped with an evaporative cooling system to increase output performance.

The station is designed for peak load operation with fast start-up and loading (approximately 5 minutes to synchronising and 15 MW/min normal load rate {TBC}) but has a predicted operating regime of only 48 fired hours per year {TBC} with 25 starts {TBC}.

The plant may be dispatched and operated remotely for much of the time. Site staffing will be minimal.

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 5 of 13 |

4. Scope

The scope of the HAZOP workshop was limited to the gas turbine generator Process and Instrumentation Design systems and any associated control requirements to maintain machine protection and minimise environmental excursions in accordance with the targets defined in the SnowyHydro corporate Risk Matrix, refer appendix 3.

5. Objectives

The objective of the HAZOP workshop is to

- Review the proposed design
- Generate action items for any areas of concern brought to the meeting
- Identify potential hazards and operability problems, to examine safeguards and to make recommendations to address identified problems
- Ensure that all applicable recommendations related to the hierarchical controls are recorded

6. Methodology

The HAZOP examination procedure systematically questions every part of a process or operation to discover qualitatively how deviations from normal operation can occur and whether further protective measures, altered operating procedures or design changes are required.

The examination procedure uses a full description of the process which will, almost invariably, include a P&ID or equivalent, and systematically questions every part of it to discover how deviations from the intention of the design can occur and determine whether these deviations can give rise to hazards.

The questioning is sequentially focused on guide words which are derived from method study techniques. The guide words ensure that the questions posed to test the integrity of each part of the design will explore ways in which operation could deviate from the design intention.

Some of the causes may be so unlikely or trivial, that they need not be considered further, however there may be some deviations with causes that are conceivable and consequences that are potentially serious. The potential problems are then noted for remedial action.

The immediate solution to a problem may not be obvious and could need further consideration either by a team member or perhaps a specialist. All decisions taken are recorded.

The main advantage of this technique is its systematic thoroughness in failure case identification. The method may be used at the design stage, when plant alterations or extensions are to be made, or applied to an existing facility.

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 6 of 13 |

6.1 Guide words and Deviations

The following deviations were applied to each study node

| No | Deviation | Notes |
|----|--|--|
| 1 | Pressure High | |
| 2 | Pressure Low | |
| 3 | Pressure No or not | |
| 4 | Pressure Vacuum | |
| 5 | Temperature High | Include Fire |
| 6 | Temperature Low | |
| 7 | Temperature – No or not | |
| 8 | Flow / Level – High | |
| 9 | Flow / Level – Low | |
| 10 | Flow / Level – No or not | |
| 11 | Flow / Level – Reverse | |
| 12 | Vibration – High Low or not | |
| 13 | As well as - concentration / two phase | |
| 14 | Other then - impurities / contamination | |
| 15 | Timing / Sequence - Early / Late | Start up, shutdown, Auto / manual valves |
| 16 | Timing / Sequence - Fast / Slow | |
| 17 | Utility failure - instr. air / oil / power | Fail safe? |
| 18 | Volts / Amps High | |
| 19 | Volts / Amps Low | |
| 20 | Volts / Amps - No or Not | |

7. Participants

Study attendance is normally recorded and listed here in the body of the document but due to large number of attendees over the 11 day period, the participants are listed in Appendix 6

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 7 of 13 |

Appendix 1: HAZOP Nodes and drawings

The nodes and drawings should be read in conjunction with the system descriptions listed below

Turbine and generator interlocks – 6327H78_6000_D3-H0250_000_Interlocks.pdf

Governor control model – 6327H78_6000_D3-H0251_000_Governor diagram.pdf

Turbine control – 6327H78_6000_D4-H4790_000_Control descriptions.pdf

Hydrogen and seal oil – ABH-Y1379_TURBINE GENERATOR H2 & CO2 GAS SYSTEM DESCRIPTION.pdf

Seal oil systems – ABH-Y2273_TURBINE GENERATOR SEAL OIL SYSTEM DESCRIPTION.pdf



| | Node | Dwg | Dwg Title |
|----|--|--------------------------|---|
| 1 | Fuel Oil - High pressure Pump | A-21045 | Fuel oil system 5 of 5 |
| 2 | Fuel Oil - Manifold pressure control | A-21042 | Fuel oil system 2 of 5 |
| 3 | Fuel Oil - Pilot flow control | A-21042 | Fuel oil system 2 of 5 |
| 4 | Fuel Oil - Main flow control | A-21042 | Fuel oil system 2 of 5 |
| 5 | Fuel Oil - Flow divider | A-21043 | Fuel oil system 3 of 5 |
| 6 | Fuel Oil - Burners | A-21044 | Fuel oil system 4 of 5 |
| 7 | Fuel Oil - Drain tank | A-21045 | Fuel oil system 5 of 5 |
| 8 | Fuel Oil - Water injection | A-21043 | Fuel oil system 3 of 5 |
| 9 | Fuel Oil - Purge credit block valves | A-21046 | Fuel oil purge credit system |
| 10 | Fuel Gas - Supply | A-21061 | Fuel gas system 1 of 7 |
| 11 | Fuel Gas - Supply pressure control | A-21062 | Fuel gas system 2 of 7 |
| 12 | Fuel Gas - Flow control | A-21063 | Fuel gas system 3 of 7 |
| 13 | Fuel Gas - Pilot and Main B burners | A-21064 | Fuel gas system 4 of 7 |
| 14 | Fuel Gas - Top Hat and Main A burners | A-21065 | Fuel gas system 5 of 7 |
| 15 | Fuel Gas - Combustor drain valves | A-21066 | Fuel gas system 6 of 7 |
| 16 | Fuel Gas - Burners | A-21066 | Fuel gas system 6 of 7 |
| 17 | Fuel Gas - GT sweep (purge air) | A-21067 | Fuel gas system 7 of 7 |
| 18 | Fuel Gas - Flow meter | A-21068 | Fuel gas flow meter |
| 19 | Fuel Gas - Filter and purge credit | A-21069 | Fuel gas filter and purge credit system |
| 20 | Fuel Gas - Calorie meter | A-21070 & MYP127-DWG-002 | Fuell gas Calorie meter package |
| 21 | Air & Flue Gas - Seal air | A-21081 | Air & Flue gas 1 of 5 |
| 22 | Air & Flue Gas - GT LP Bleed valve | A-21081 | Air & Flue gas 1 of 5 |
| 23 | Air & Flue Gas - GT MP Bleed valve | A-21082 | Air & Flue gas 2 of 5 |
| 24 | Air & Flue Gas - GT HP Bleed valve | A-21083 | Air & Flue gas 3 of 5 |
| 25 | Air & Flue Gas - Inlet duct flow | A-21084 | Air & Flue gas 4 of 5 |
| 26 | Air & Flue Gas - Air compressor | A-21084 | Air & Flue gas 4 of 5 |
| 27 | Air & Flue Gas - Combustor and Exhaust | A-21084 | Air & Flue gas 4 of 5 |
| 28 | Air & Flue Gas - GT Cooling air supply | A-21085 | Air & Flue gas 5 of 5 |
| 29 | Lube Oil - Tank, pumps, prv | A-21021 | Lube oil system 1 of 4 |
| 30 | Lube Oil - GT bearings | A-21022 | Lube oil system 2 of 4 |
| 31 | Lube Oil - Temp control | A-21023 | Lube oil system 3 of 4 |
| 32 | Lube Oil - Mist extraction fans | A-21024 | Lube oil system 4 of 4 |

| | Node | Dwg | Dwg Title |
|----|---|--------------------|--|
| 33 | Lube Oil - Generator bearing seal oil | A-13C870 | Refer nodes 50 - 54 |
| 34 | Control Oil - Tank, pumps, temp control | A-21031 | Control oil system 1 of 3 |
| 35 | Control Oil - Fuel valve position control | A-21032 | Control oil system 2 of 3 |
| 36 | Control Oil - Fuel valve trip solenoids & Inlet Guide Vanes | A-21033 | Control oil system 3 of 3 |
| 37 | Package Enclosure Ventilation | A-21088 | Protection system P&ID |
| 38 | Air & Flue Gas - Inlet filter | A-21084 | Protection system P&ID |
| 39 | Gas Turbine - Casing cooling | A-21090 | GT Casing cooling system |
| 40 | Gas Turbine - Blade washing device | A-21086 | GTW Washing and drain system 1 of 2 |
| 41 | Gas Turbine - Blade washing and drain system | A-21087 | GTW Washing and drain system 2 of 2 |
| 42 | Evaporative Cooler - pump and tank unit | C-50011 | Evaporative cooler system |
| 43 | Burner nozzle purge air supply and control | A-21100 & A-21042B | Purge air system |
| 44 | Generator cooling water | A13C868 | Cooling water P&ID |
| 45 | Generator CO2 gas supply | AS29623 | Generator H2 & CO2 gas supply diagram for GT |
| 46 | Generator H2 gas supply | AS29623 | Generator H2 & CO2 gas supply diagram for GT |
| 47 | Generator CO2 | A13C869 | H2 and CO2 for P&ID for GT |
| 48 | Generator H2 | A13C869 | H2 and CO2 for P&ID for GT |
| 49 | Generator H2 drying system | A13C869 | H2 and CO2 for P&ID for GT |
| 50 | Generator - Lube oil system | A13C870 | Generator seal oil diagram for GT |
| 51 | Generator - Seal oil vacuum pump and tank | A13C870 | Generator seal oil diagram for GT |
| 52 | Generator - AC seal oil system | A13C870 | Generator seal oil diagram for GT |
| 53 | Generator - DC seal oil system | A13C870 | Generator seal oil diagram for GT |
| 54 | Generator - Gland seal oil system | A13C870 | Generator seal oil diagram for GT |

Node 6


CAD (PI)
 R-0
 -Internal issue.
 R-1
 2021.12.10
 Y.Tsukuda, Y.Oshiro, N.Sumimura, T.Hatada
 -Issue for customer.

FOR INFORMATION



GAS TURBINE

20 COMBUSTORS



出図
 2021.12.14

NOTE
 1. HEAT TRACING WILL BE PROVIDED BY EPC CONTRACTOR.

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
 THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

Employer: **snowyhydro**

Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST FEES | ARRANGE | WELDING | SPARE | PIPE | TOTAL | REMARKS |
|------|--|----------|-----------|---------|----------|-------|-----------|----------|---------|
| | NO. | | | MENTS | QUANTITY | PIECE | SIZE (mm) | WGT (kg) | |
| | Hunter Power Project | | | | | | | | |
| | M701F GAS TURBINE | | | | | | | | |
| | FUEL OIL SYSTEM (4 OF 5) (GT PACKAGE) P&ID DIAGRAM | | | | | | | | |
| DATE | 2021.9.10 | DESIGNER | | | | | | | |
| DATE | 2021.9.10 | CHECKER | | | | | | | |
| DATE | 2021.9.10 | OWNER | | | | | | | |

OWNER: snowhydro

PROJECT: TAKASAGO POWER PLANT ENGINEERING SECTION

DATE: 2021.9.10

PROJECT NO: A-21044-B

JOB NO: S3-80411

REVISION: R-1

OWNER: snowhydro

PROJECT: TAKASAGO POWER PLANT ENGINEERING SECTION


DATE: 2021.9.10

PROJECT NO: A-21044-B


JOB NO: S3-80411

REVISION: R-1

FIG. NO. A-21044-B
 SHEET NO. 33-80411
 (1/12) (NO. 11)
 E. 1
 S. 2
 ECT
 GTCC BUSINESS DIVISION
 TAKASAGO POWER PLANT ENGINEERING DEPARTMENT
 TAKASAGO POWER PLANT ENGINEERING SECTION



出図
2021.12.17



NOTE
1 DISCHARGE LEVEL OF OILY DRAIN PIPING SHOULD BE HIGHER THAN HIGHEST LEVEL OF OILY DRAIN PIT.


Employee: **snowyhydro** LIMITED
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST | APPROVE | WORK | SPARE | FOR | TOTAL | REMARKS |
|----------------------|---|---------------------------------|------------------------|---------|--------|--------|------|-------|---------|
| TYPE | SYMBOL | CC CODE | PIECE | MENTS | PIECES | PIECES | MASS | NO | |
| Hunter Power Project | | | | | | | | | |
| Date | Y.Tsukuda | Title | M701F GAS TURBINE | | | | | | |
| Checked | N.Sumimura | FUEL OIL SYSTEM (5 OF 5) (MFOP) | | | | | | | |
| Approved | T.Hatabu | FUEL OIL DRAIN TANK | | | | | | | |
| Scale | 2021.9.10 | Sheet | A-21045-B S3-80412 R-1 | | | | | | |
| OWNER | MITSUBISHI HEAVY INDUSTRIES Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | |

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND IS NOT TO BE REPRODUCED, COPIED, OR TRANSMITTED IN ANY MANNER WITHOUT THE EXPRESS WRITTEN PERMISSION OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY, BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

| | | | | | | |
|--------|-----------|----------|-----|---|-----|---|
| 1/1001 | A-21045-B | S3-80412 | R-1 | 2 | EOT | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION |
|--------|-----------|----------|-----|---|-----|---|



出図
2021.12.14

FOR INFORMATION

CAD (P)
PLAN RECORD
R-0
-Internal Issue-
R-1
2021.12.14
Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu
-Issue for customer-

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment/instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

NOTE
1. HEAT TRACING WILL BE PROVIDED BY EPC CONTRACTOR.

Employer: **snowyhydro** LIMITED
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST FEES | ARRANGE -MENTS | QUANTITY | REMARKS |
|-----------|--|----------|-----------|----------------|-----------|----------|
| | Hunter Power Project | | | | | |
| | M701F GAS TURBINE | | | | | |
| | FUEL OIL SYSTEM (2 OF 5) (FUEL OIL UNIT) P&ID DIAGRAM | | | | | |
| DATE | BY | CHECKED | | | | |
| 2021.9.10 | Y.Tsukuda | | | | | |
| | N.Sumimura | | | | | |
| | T.Hatabu | | | | | |
| DATE | BY | CHECKED | | | | |
| 2021.9.10 | | | | | | |
| OWNER | GTEC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | PA CODE | A-21042-B | ISSUE NO. | S3-80409 |
| | | | REV. | R. 1 | | |

A-21042-B
 S3-80409
 R. 1
 2
 GTEC BUSINESS DIVISION
 TAKASAGO PLANT ENGINEERING DEPARTMENT
 TAKASAGO POWER PLANT ENGINEERING SECTION
 DRAWN
 MBS CODE
 C. CODE



This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| | |
|--|--------------------|
| CAD (P) | PLAN RECORD |
| R-0 | Internal Issue |
| R-1 | Issue for customer |
| 2021.12.10 Y.Tsukuda, Y. Ohno, N. Sumimura, T. Hatabu | |

FOR INFORMATION

出図
2021.12.14

| | | |
|----------|---|----------|
| Employer | snowyhydro | |
| Supplier | MITSUBISHI HEAVY INDUSTRIES | |
| DATE | 2021.9.10 | REV |
| OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | |
| PROJECT | Hunter Power Project | |
| UNIT | M701F GAS TURBINE | |
| SYSTEM | FUEL OIL SYSTEM (3 OF 5) (FLOW DIVIDER UNIT) | |
| NO. | A-21043-B | S3-80410 |
| SCALE | 1:1 | R-1 |
| DATE | 2021.9.10 | REV |
| OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | |
| PROJECT | Hunter Power Project | |
| UNIT | M701F GAS TURBINE | |
| SYSTEM | FUEL OIL SYSTEM (3 OF 5) (FLOW DIVIDER UNIT) | |
| NO. | A-21043-B | S3-80410 |
| SCALE | 1:1 | R-1 |
| DATE | 2021.9.10 | REV |


| | | | |
|---------|---------------------------------------|------|--|
| DATE | 2021.12.14 | REV | 1 |
| OWNER | GTCC BUSINESS DIVISION | DATE | 2021.12.14 |
| PROJECT | TAKASAGO PLANT ENGINEERING DEPARTMENT | UNIT | TAKASAGO POWER PLANT ENGINEERING SECTION |
| SYSTEM | FUEL OIL SYSTEM (3 OF 5) | NO. | A-21043-B |
| SCALE | 1:1 | REV | R-1 |
| DATE | 2021.9.10 | REV | 1 |
| OWNER | GTCC BUSINESS DIVISION | DATE | 2021.9.10 |
| PROJECT | TAKASAGO PLANT ENGINEERING DEPARTMENT | UNIT | TAKASAGO POWER PLANT ENGINEERING SECTION |
| SYSTEM | FUEL OIL SYSTEM (3 OF 5) | NO. | A-21043-B |
| SCALE | 1:1 | REV | R-1 |
| DATE | 2021.9.10 | REV | 1 |

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

| CAD | | PLAN RECORD | |
|-----|---|-------------|-----------------------|
| REV | DATE | REV | DATE |
| R-0 | | R-0 | |
| R-1 | | R-1 | |
| | 2021.12.10 | | 2021.12.10 |
| | Y.Tsukuda, Y. Gahra, N. Sumimura, T. Hatabu | | |
| | | | - Issue for customer. |

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.


FOR INFORMATION



出図
2021.12.14

| | | | |
|-----------|---|-----------|----------------------|
| Employer: | snowyhydro | | |
| Supplier: | MITSUBISHI HEAVY INDUSTRIES | | |
| DATE: | 2021.9.10 | PROJECT: | Hunter Power Project |
| OWNER: | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | DATE: | 2021.9.10 |
| PROJECT: | M701F GAS TURBINE | DATE: | 2021.9.10 |
| PACKAGE: | FUEL OIL SYSTEM (3 OF 5) (FLOW DIVIDER UNIT) | DATE: | 2021.9.10 |
| DWG NO.: | A-21043-B | REV. NO.: | R-1 |
| OWNER: | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | DATE: | 2021.9.10 |
| PROJECT: | M701F GAS TURBINE | DATE: | 2021.9.10 |
| PACKAGE: | FUEL OIL SYSTEM (3 OF 5) (FLOW DIVIDER UNIT) | DATE: | 2021.9.10 |
| DWG NO.: | A-21043-B | REV. NO.: | R-1 |

| | |
|-----------|---|
| DATE: | 2021.12.14 |
| PROJECT: | M701F GAS TURBINE |
| PACKAGE: | FUEL OIL SYSTEM (3 OF 5) (FLOW DIVIDER UNIT) |
| DWG NO.: | A-21043-B |
| REV. NO.: | R-1 |
| DRAWN: | |
| CHECKED: | |
| APPROVED: | |



Node 10 HAZOP
completed by AECOM

AECOM 2 x 100%
coalescer filters here

node 18

node 19

出図
2021.12.14

FOR INFORMATION

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

- NOTE
1. PIPING MATERIAL AND THICKNESS SHALL BE DETERMINED BY EPC IN CONSIDERATION OF H₂S CONTENT IN FUEL GAS.
 2. PIPING SIZE OUT OF GT PKG SHALL BE DETERMINED BY EPC IN CONSIDERATION OF CUSTOMER'S REQ.
 3. SHORT SPOOL FOR CLEANING OF PIPING.
 4. FLANGED CONNECTION SHALL BE PROVIDED FOR FLOW METER INSPECTION.


| PLAN RECORD | |
|-------------|---|
| R-0 | -Internal Issue. |
| R-1 | 2021.12.10 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu -Issue for customer. |

| | |
|-------------|---------------------|
| FILE NO. | A-21061-B |
| PROJECT NO. | S3-80417 |
| REV. | R-1 |
| DATE | 2021.12.14 |
| BY | Y.Tsukuda |
| CHECKED | N.Sumimura |
| APPROVED | T.Hatabu |
| SCALE | 1/1 |
| SECTION | ENGINEERING SECTION |

| | | | | | | | | | |
|---|-----------------------------|----------|-----------|---------|-------------------|-------|-----------|-------|------------|
| Employer | snowhydro | | | | | | | | |
| Supplier | MITSUBISHI HEAVY INDUSTRIES | | | | | | | | |
| MARK | DESCRIPTION | MATERIAL | TEST | ARRANGE | WELD | SPARE | DEL. DATE | TOTAL | REMARKS |
| | | | PIECE | MENTS | NO. | PIECE | DATE | PIECE | |
| Hunter Power Project | | | | | | | | | |
| OWNER | Y.Tsukuda | DATE | 2021.9.8 | PROJECT | M701F GAS TURBINE | NO. | 1 | DATE | 2021.12.14 |
| FUEL GAS SYSTEM (1 OF 7) P&I DIAGRAM | | | | | | | | | |
| OWNER | GTEC BUSINESS DIVISION | PROJECT | A-21061-B | NO. | S3-80417 | REV. | R-1 | DATE | 2021.12.14 |
| MITSUBISHI HEAVY INDUSTRIES | | | | | | | | | |
| Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | | |

| | |
|------------------------|------------------------|
| OWNER | GTEC BUSINESS DIVISION |
| PROJECT | TAKASAGO PLANT |
| ENGINEERING DEPARTMENT | ENGINEERING DEPARTMENT |
| ENGINEERING SECTION | ENGINEERING SECTION |
| DATE | 2021.9.8 |
| PROJECT | A-21061-B |
| NO. | S3-80417 |
| REV. | R-1 |
| DATE | 2021.12.14 |
| BY | Y.Tsukuda |
| CHECKED | N.Sumimura |
| APPROVED | T.Hatabu |
| SCALE | 1/1 |
| SECTION | ENGINEERING SECTION |

| | | | |
|------------------------|----------|--|------------------|
| FOR INFORMATION | CAD (PI) | PLAN RECORD | |
| | | R-0 | -Internal Issue. |
| | | R-1 | 2021.12.8 |
| | | Y.Tsukuda,Y.Oshiro,N.Sumimura,T.Hatabu -Issue for customer. | |



出図
2021.12.13

Employer: **snowyhydro**
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| NO. | DESCRIPTION | MATERIAL | TEST FEED | AMOUNT | UNIT | SHAPE | FEED | TOTAL | REMARKS | S/F |
|---|-------------|---|-----------|--------|------|-------|------|-------|---------|-----|
| Hunter Power Project | | | | | | | | | | |
| 2021.9.8 | Y.Tsukuda | Title M701F GAS TURBINE | | | | | | | | |
| 2021.9.8 | N.Sumimura | FUEL GAS SYSTEM (2 OF 7) (SUPPLY UNIT) P&I DIAGRAM | | | | | | | | |
| 2021.9.8 | T.Hatabu | PA CODE: A-21062-B DRG NO: S3-80418 R-1 | | | | | | | | |
| 2021.9.8 | OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | |
| MITSUBISHI HEAVY INDUSTRIES Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | | | |

| | | | |
|---|-----------|-------------|------------|
| PROJECT NO. | A-21062-B | DRAWING NO. | S3-80418 |
| REVISION | R-1 | DATE | 2021.12.13 |
| DESIGNER | Y.Tsukuda | CHECKER | N.Sumimura |
| APPROVER | T.Hatabu | DATE | 2021.9.8 |
| GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | |
| 出図 2021.12.13 | | | |
| NO. | 1 | DESCRIPTION | 変更 |
| NO. | 2 | DESCRIPTION | 変更 |
| NO. | 3 | DESCRIPTION | 変更 |
| NO. | 4 | DESCRIPTION | 変更 |
| NO. | 5 | DESCRIPTION | 変更 |
| NO. | 6 | DESCRIPTION | 変更 |
| NO. | 7 | DESCRIPTION | 変更 |
| NO. | 8 | DESCRIPTION | 変更 |
| NO. | 9 | DESCRIPTION | 変更 |
| NO. | 10 | DESCRIPTION | 変更 |
| NO. | 11 | DESCRIPTION | 変更 |
| NO. | 12 | DESCRIPTION | 変更 |
| NO. | 13 | DESCRIPTION | 変更 |
| NO. | 14 | DESCRIPTION | 変更 |
| NO. | 15 | DESCRIPTION | 変更 |
| NO. | 16 | DESCRIPTION | 変更 |
| NO. | 17 | DESCRIPTION | 変更 |
| NO. | 18 | DESCRIPTION | 変更 |
| NO. | 19 | DESCRIPTION | 変更 |
| NO. | 20 | DESCRIPTION | 変更 |
| NO. | 21 | DESCRIPTION | 変更 |
| NO. | 22 | DESCRIPTION | 変更 |
| NO. | 23 | DESCRIPTION | 変更 |
| NO. | 24 | DESCRIPTION | 変更 |
| NO. | 25 | DESCRIPTION | 変更 |
| NO. | 26 | DESCRIPTION | 変更 |
| NO. | 27 | DESCRIPTION | 変更 |
| NO. | 28 | DESCRIPTION | 変更 |
| NO. | 29 | DESCRIPTION | 変更 |
| NO. | 30 | DESCRIPTION | 変更 |
| NO. | 31 | DESCRIPTION | 変更 |
| NO. | 32 | DESCRIPTION | 変更 |
| NO. | 33 | DESCRIPTION | 変更 |
| NO. | 34 | DESCRIPTION | 変更 |
| NO. | 35 | DESCRIPTION | 変更 |
| NO. | 36 | DESCRIPTION | 変更 |
| NO. | 37 | DESCRIPTION | 変更 |
| NO. | 38 | DESCRIPTION | 変更 |
| NO. | 39 | DESCRIPTION | 変更 |
| NO. | 40 | DESCRIPTION | 変更 |
| NO. | 41 | DESCRIPTION | 変更 |
| NO. | 42 | DESCRIPTION | 変更 |
| NO. | 43 | DESCRIPTION | 変更 |
| NO. | 44 | DESCRIPTION | 変更 |
| NO. | 45 | DESCRIPTION | 変更 |
| NO. | 46 | DESCRIPTION | 変更 |
| NO. | 47 | DESCRIPTION | 変更 |
| NO. | 48 | DESCRIPTION | 変更 |
| NO. | 49 | DESCRIPTION | 変更 |
| NO. | 50 | DESCRIPTION | 変更 |
| NO. | 51 | DESCRIPTION | 変更 |
| NO. | 52 | DESCRIPTION | 変更 |
| NO. | 53 | DESCRIPTION | 変更 |
| NO. | 54 | DESCRIPTION | 変更 |
| NO. | 55 | DESCRIPTION | 変更 |
| NO. | 56 | DESCRIPTION | 変更 |
| NO. | 57 | DESCRIPTION | 変更 |
| NO. | 58 | DESCRIPTION | 変更 |
| NO. | 59 | DESCRIPTION | 変更 |
| NO. | 60 | DESCRIPTION | 変更 |
| NO. | 61 | DESCRIPTION | 変更 |
| NO. | 62 | DESCRIPTION | 変更 |
| NO. | 63 | DESCRIPTION | 変更 |
| NO. | 64 | DESCRIPTION | 変更 |
| NO. | 65 | DESCRIPTION | 変更 |
| NO. | 66 | DESCRIPTION | 変更 |
| NO. | 67 | DESCRIPTION | 変更 |
| NO. | 68 | DESCRIPTION | 変更 |
| NO. | 69 | DESCRIPTION | 変更 |
| NO. | 70 | DESCRIPTION | 変更 |
| NO. | 71 | DESCRIPTION | 変更 |
| NO. | 72 | DESCRIPTION | 変更 |
| NO. | 73 | DESCRIPTION | 変更 |
| NO. | 74 | DESCRIPTION | 変更 |
| NO. | 75 | DESCRIPTION | 変更 |
| NO. | 76 | DESCRIPTION | 変更 |
| NO. | 77 | DESCRIPTION | 変更 |
| NO. | 78 | DESCRIPTION | 変更 |
| NO. | 79 | DESCRIPTION | 変更 |
| NO. | 80 | DESCRIPTION | 変更 |
| NO. | 81 | DESCRIPTION | 変更 |
| NO. | 82 | DESCRIPTION | 変更 |
| NO. | 83 | DESCRIPTION | 変更 |
| NO. | 84 | DESCRIPTION | 変更 |
| NO. | 85 | DESCRIPTION | 変更 |
| NO. | 86 | DESCRIPTION | 変更 |
| NO. | 87 | DESCRIPTION | 変更 |
| NO. | 88 | DESCRIPTION | 変更 |
| NO. | 89 | DESCRIPTION | 変更 |
| NO. | 90 | DESCRIPTION | 変更 |
| NO. | 91 | DESCRIPTION | 変更 |
| NO. | 92 | DESCRIPTION | 変更 |
| NO. | 93 | DESCRIPTION | 変更 |
| NO. | 94 | DESCRIPTION | 変更 |
| NO. | 95 | DESCRIPTION | 変更 |
| NO. | 96 | DESCRIPTION | 変更 |
| NO. | 97 | DESCRIPTION | 変更 |
| NO. | 98 | DESCRIPTION | 変更 |
| NO. | 99 | DESCRIPTION | 変更 |
| NO. | 100 | DESCRIPTION | 変更 |

FOR INFORMATION

| PLAN RECORD | |
|-------------|---|
| CAD (PI) | R-0 |
| | -Internal Issue- |
| | R-1 |
| | 2021.12.8 |
| | Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu |
| | -Issue for customer- |



出図
2021.12.13

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.












CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| | | | | | | | | | |
|---|---|--|-------------------|-------------|------------------|------------------|-------|---------|-----|
| Employer | | snowyhydro LIMITED | | | | | | | |
| Supplier | | MITSUBISHI HEAVY INDUSTRIES | | | | | | | |
| MARK | DESCRIPTION | MATERIAL | TEST PRICE | ADVANCE AMT | WARRANTY PERCENT | SHIPPING PERCENT | TOTAL | REMARKS | S/L |
| TYPE | SYMBOL | QC CODE | | | | | | | |
| Hunter Power Project | | | | | | | | | |
| Drawn | Y. Tsukuda | Title | M701F GAS TURBINE | | | | | | |
| Checked | N. Sumimura | FUEL GAS SYSTEM (3 OF 7) (CONTROL UNIT) P&ID DIAGRAM | | | | | | | |
| Issued | T. Hatabu | Scale | PA CODE | A-21063-B | OWL NO | S3-80419 | Rev. | R-1 | |
| Department | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | |
| OWNER | | MITSUBISHI HEAVY INDUSTRIES | | | | | | | |
| Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | | |

| | |
|-------------|---|
| PROJECT NO. | A-21063-B |
| SKETCH NO. | S3-80419 |
| REV. | R-1 |
| DATE | 2021.12.13 |
| DESIGNER | Y. Tsukuda |
| CHECKER | N. Sumimura |
| ISSUER | T. Hatabu |
| DEPARTMENT | GTCC BUSINESS DIVISION |
| PLANT | TAKASAGO PLANT |
| SECTION | TAKASAGO POWER PLANT ENGINEERING SECTION |
| SCALE | 1/1 |
| DATE | 2021.12.13 |
| PROJECT | Hunter Power Project |
| UNIT | M701F GAS TURBINE |
| SYSTEM | FUEL GAS SYSTEM (3 OF 7) (CONTROL UNIT) P&ID DIAGRAM |
| SCALE | 1/1 |
| DATE | 2021.12.13 |
| OWNER | MITSUBISHI HEAVY INDUSTRIES |
| DEPARTMENT | Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. |

FOR INFORMATION

| | |
|-------------|--|
| PLAN RECORD | |
| R-0 | -Internal issue. |
| R-1 | 2021.12.8 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Halabu -Issue for customer. |



node 13



NOTE) 1) N2 PURGE FOR MAINTENANCE (e.g. filter cleaning).

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

Employer: **snowyhydro**

Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| DATE | DESCRIPTION | MATERIAL | TEST | ARRANGE | ISSUE | REMARKS |
|-----------|-------------|----------|------|---------|-------|---------|
| 2021.9.8 | Y. Tsukuda | | | | | |
| 2021.12.8 | N. Sumimura | | | | | |
| 2021.12.8 | T. Halabu | | | | | |

| | | | |
|--------------|--------------------------------------|--------------|--|
| DATE | 2021.9.8 | DATE | |
| BY | Y. Tsukuda | BY | |
| CHECKED | N. Sumimura | CHECKED | |
| APPROVED | T. Halabu | APPROVED | |
| DATE | 2021.9.8 | DATE | |
| PROJECT | Hunter Power Project | PROJECT | |
| DESCRIPTION | M701F GAS TURBINE | DESCRIPTION | |
| TYPE | FUEL GAS SYSTEM (4 OF 7) P&I DIAGRAM | TYPE | |
| PROJECT CODE | A-21064-B | PROJECT CODE | |
| ORDER NO. | S3-80420 | ORDER NO. | |
| REV. | R-1 | REV. | |

MPA, celsius

CPD NG

GT PACKAGE







T/C: A-21064-B
 S3-80420
 R-1
 2
 ECT
 T/ASAGO POWER PLANT ENGINEERING SECTION

| | | | |
|--------------|--------------------------------------|--------------|--|
| DATE | 2021.9.8 | DATE | |
| BY | Y. Tsukuda | BY | |
| CHECKED | N. Sumimura | CHECKED | |
| APPROVED | T. Halabu | APPROVED | |
| DATE | 2021.9.8 | DATE | |
| PROJECT | Hunter Power Project | PROJECT | |
| DESCRIPTION | M701F GAS TURBINE | DESCRIPTION | |
| TYPE | FUEL GAS SYSTEM (4 OF 7) P&I DIAGRAM | TYPE | |
| PROJECT CODE | A-21064-B | PROJECT CODE | |
| ORDER NO. | S3-80420 | ORDER NO. | |
| REV. | R-1 | REV. | |

FOR INFORMATION

| | |
|---|------------------|
| CAD (PI) | PLAN RECORD |
| | R-0 |
| | -Internal issue. |
| | R-1 |
| 2021.12.8 | |
| Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu | |
| -Issue for customer. | |

node 14



NOTE)
1) N₂ PURGE FOR MAINTENANCE (e.g filter cleaning).



GT PACKAGE

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| | | | |
|---|---------------------------------------|---|-------------------|
| Employer | | snowyhydro LIMITED | |
| Supplier | | MITSUBISHI HEAVY INDUSTRIES | |
| DATE | 2021.9.8 | DESIGNER | Y.Tsukuda |
| DATE | 2021.9.8 | CHECKER | N.Sumimura |
| DATE | 2021.9.8 | APPROVER | T.Hatabu |
| PROJECT | Hunter Power Project | PLANT | M701F GAS TURBINE |
| DESCRIPTION | FUEL GAS SYSTEM (5 OF 7) P&ID DIAGRAM | PL CODE | A-21065-B |
| DATE | 2021.9.8 | FIG. NO. | 83-80421 |
| SCALE | | REV. | R-1 |
| GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | MITSUBISHI HEAVY INDUSTRIES Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | |


| | |
|----------|--|
| FIG. NO. | A-21065-B |
| REV. | R-1 |
| DATE | 2021.12.13 |
| DESIGNER | Y.Tsukuda |
| CHECKER | N.Sumimura |
| APPROVER | T.Hatabu |
| PROJECT | TAKASAGO POWER PLANT ENGINEERING SECTION |

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| PLAN RECORD | |
|-------------|--|
| CAD (PI) | R-0 |
| | -Internal Issue- |
| | R-1 |
| | 2021.12.8 |
| | Y. Tsukuda, Y. Ozuno, N. Sumimura, T. Hataku |
| | -Issue for customer- |


This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

FOR INFORMATION



出図
2021.12.13


node 15



Add leak test point? Probably not, more for gas

also 2.2 MPA

Air compressor CPD = 2.2 MPA. Drain valve permissive is below 1200 rpm




| | | | | | | | | | | |
|---|-----------------------------|----------|--------------------------------------|----------|----------|-------|------|-------|---------|---|
| Employer | snowyhydro | | | | | | | | | |
| Supplier | MITSUBISHI HEAVY INDUSTRIES | | | | | | | | | |
| MARK | DESCRIPTION | MATERIAL | TEST | ARRANGE | QUANTITY | SPARE | PER | TOTAL | REMARKS | S |
| TYPE | SYMBOL | QC CODE | FEZE | MEYTS | QUANTITY | PIECE | MASS | KG | | |
| Hunter Power Project | | | | | | | | | | |
| Date | Y. Tsukuda | Titb | M701F GAS TURBINE | | | | | | | |
| Drawn | N. Sumimura | | FUEL GAS SYSTEM (6 OF 7) P&I DIAGRAM | | | | | | | |
| Checked | T. Hatabu | | | | | | | | | |
| Date | 2021. 9. 8 | PA/DOE | A-21066-B | ENG. NO. | S3-80422 | Rev. | R-1 | | | |
| GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | | | |
| Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | | | |

TAKASAGO POWER PLANT ENGINEERING SECTION
 TAKASAGO PLANT ENGINEERING DEPARTMENT
 S3-80422
 R-1
 2021.12.13
 Y. Tsukuda, Y. Ozuno, N. Sumimura, T. Hataku
 出図
 2021.12.13

FOR INFORMATION

| | | |
|----------|---|------------------|
| CAD (PI) | PLAN RECORD | |
| | R-0 | -Internal issue. |
| | R-1 | |
| | 2021.12.8 Y.Tsukuda,Y.Oshino,N.Sumimura,T.Hatabu -issue for customer. | |

GT PACKAGE



MPA, celsius

Typ. CPD temp 425 - 480 C and 2.0 - 2.2 MPA at full load but less at part load for fuel transfer

出図
2021.12.13

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

Employer: **snowyhydro** LIMITED


Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| WH# | DESCRIPTION | MATERIAL | TEST | ARRANGE | YOUNG | SPARE | TEST | TOTAL | REMARKS | S | F |
|------------|--|---|-------|---------|-----------|-----------|----------|-------|---------|---|---|
| TYPE | SYMBOL | QC CODE | PIECE | MENTS | NO. | NO. | PIECE | NO. | | | |
| | Hunter Power Project | | | | | | | | | | |
| Design | Y.Tsukuda | Title M701F GAS TURBINE | | | | | | | | | |
| Client | N.Sumimura | FUEL GAS SYSTEM (7 OF 7) (PURGE AIR UNIT) P&ID DIAGRAM | | | | | | | | | |
| Approved | T.Hatabu | | | | | | | | | | |
| Date | 2021.9.8 | Drawn | | PA CODE | A-21067-B | Drawn No. | S3-80423 | Rev. | 1 | | |
| Department | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | | | |
| OWNER | Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | | | |

| | | | | | | | | | | | | | |
|--------------|---|--------------|----------|-------|-----|------|------------|----------|-----------|---------|------------|----------|----------|
| FIGURE | A-21067-B | REVISION NO. | S3-80423 | SCALE | 1:1 | DATE | 2021.12.13 | DESIGNER | Y.Tsukuda | CHECKER | N.Sumimura | APPROVER | T.Hatabu |
| PROJECT NAME | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | | | | | |

FOR INFORMATION

| PLAN RECORD | |
|-------------|---|
| R-0 | -Internal issue. |
| R-1 | 2021.12.9 Y.Tsukuda,Y.Oahino,N.Sumimura,T.Hatabu -Issue for customer. |



Node 18

GT FUEL GAS FLOW METER SKID

Coriolis mass flow meter to be removed for blow down construction work. Commissioning spool required

出図
2021.12.13

Employer **snowyhydro LIMITED**
Supplier **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST RECD | AVANCE AMT | QTY | PRICE | SPACE | PCS | TOTAL | REMARKS | S/F |
|------|-------------|----------|-----------|------------|-----|-------|-------|-----|-------|------------------------------------|-----|
| | | | | | | | | | | Hunter Power Project | |
| | | | | | | | | | | M701F GAS TURBINE | |
| | | | | | | | | | | FUEL GAS FLOW METER P&I DIAGRAM | |
| | | | | | | | | | | A-21068-B | |
| | | | | | | | | | | S3-80424 | |
| | | | | | | | | | | R-1 | |
| | | | | | | | | | | MITSUBISHI HEAVY INDUSTRIES | |

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| FIGURE | ISSUE NO. | DATE | BY | CHKD | REV | DESCRIPTION |
|-----------|-----------|------------|-----------|------------|-----|---------------------|
| A-21068-B | S3-80424 | 2021.12.13 | Y.Tsukuda | N.Sumimura | 1 | Issue for customer. |


| NO. | DATE | BY | CHKD | REV | DESCRIPTION |
|-----|------------|-----------|------------|-----|---------------------|
| 1 | 2021.12.13 | Y.Tsukuda | N.Sumimura | 1 | Issue for customer. |

| NO. | DATE | BY | CHKD | REV | DESCRIPTION |
|-----|------------|-----------|------------|-----|---------------------|
| 1 | 2021.12.13 | Y.Tsukuda | N.Sumimura | 1 | Issue for customer. |


FOR INFORMATION

| | | |
|----------|-------------|--|
| CAD (PI) | PLAN RECORD | |
| | R-0 | -Internal issue. |
| | R-1 | 2021.12.9 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu -Issue for customer. |
| | | |

Node 19



Add instrument tapping point for Nitrogen entry for valve leak testing, with smaller volume than upstream line



- NOTE
1. FLANGED CONNECTION SHALL BE PROVIDED FOR PIPING CLEANING.
 2. THIS PIPING ARRANGEMENT SHALL BE INSTALLED BY "P" IN ORDER TO CAPTURE INCOMING FOREIGN PARTICLE.
 3. THIS PIPING ARRANGEMENT SHALL BE APPLIED AS FIG. 1.

NOTICE
The business operations and employees of Mitsubishi Power, Ltd. involved in design, manufacture, sale, installation and engineering have been transferred to Mitsubishi Heavy Industries, Ltd. (MHI) as of October 1, 2021. Therefore, please note that the word "Mitsubishi Power" (and/or Mitsubishi Hitachi Power Systems (M-PS)) should be read as "Mitsubishi Heavy Industries (MHI)" in this drawing (or document), unless otherwise notified.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.



Employer: **snowyhydro**
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST | ARRANGE | MANUFACTURE | INSTALL | REPAIR | TOTAL | REMARKS |
|----------------------|---|----------|----------|---------|---|---------|--------|-------|---------|
| TYPE | SYMBOL | QC CODE | PIECE | MENTS | PEACE | PEACE | PEACE | PIECE | |
| Hunter Power Project | | | | | | | | | |
| Drawn | Y. Tsukuda | | Title | | M701F GAS TURBINE | | | | |
| Checked | N. Sumimura | | Project | | FUEL GAS FILTER & PURGE CREDIT SYSTEM P&I DIAGRAM | | | | |
| Approved | T. Hatabu | | Date | | 2021.9.8 | | | | |
| DATE | 2021.9.8 | | JOB CODE | | S3-80425 | | REV. 1 | | |
| OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | |


DRAWING NO. A-21069-B
 DRAWN BY S3-80425 (10/10/21)
 CHECKED BY R-1
 DATE 2021.12.13
 TMS-1000 POWER PLANT ENGINEERING SECTION
 TMS-1000 POWER PLANT ENGINEERING SECTION
 TMS-1000 POWER PLANT ENGINEERING SECTION

FIELD

GAS LAB Q2 ENCLOSURE

OUTSIDE Q2 ENCLOSURE

Node 20



Please inform this point pipe length.
(BY EPC CONTRACTOR)

| BILL OF MATERIAL | | |
|------------------|----------|---------------------------------|
| ITEM NO | QUANTITY | DESCRIPTION |
| 1 | 1 EA | HEATED PRESSURE REGULATOR |
| 2 | 1 EA | GAS COOLER |
| 3 | 5 EA | ISOLATION BALL VALVE 1/4" OD |
| 4 | 1 EA | SINGLE STAGE PRESSURE REGULATOR |
| 5 | 1 EA | PRESSURE RELIEF VALVE |
| 6 | 1 EA | PARTICULATE FILTER |
| 7 | 1 EA | GAS LAB Q2 |
| 8 | 1 EA | FILTER |
| 9 | 1 EA | VOLTEX COOLER |
| 10 | 1 EA | POPPET CHECK VALVE |
| 11 | 1 EA | FLOW METER |
| 12 | 1 EA | CHECK VALVE |
| 13 | 2 EA | DUAL STAGE PRESSURE REGULATOR |
| 14 | 5 EA | PRESSURE GAUGE, 0-10 BARG |
| 15 | 2 EA | PRESSURE GAUGE, 0-250 BARG |

LEGEND:



NOTES :
 1. ALL DIMENSION ARE IN MILLIMETRES UNLESS OTHERWISE NOTED.
 2. CALIBRATION GAS CYLINDERS SUPPLIED BY EPC CONTRACTOR.

CLIENT : MITSUBISHI HEAVY INDUSTRIES

VENDOR : elster Honeywell Instronet

PROJECT : HUNTER POWER, AUSTRALIA (CALORIE METER PACKAGE)


TITLE : P&ID

SCALE : AS SHOWN SIZE : A3 UNIT : MM CAD FILE : MYP127-DWG-002

JOB NO. : MYP127 SHEET : 1 OF 1 DRAWING NO. : MYP127-DWG-002 REV. : A

THIS REPRODUCTION IS SOLE PROPERTY OF ELSTER-INSTRONET AND IS SUBJECT TO THE CONDITIONS THAT IT OR ANY INFORMATION CONTAINED THEREIN WILL NOT BE USED IN ANY WAY DETRIMENTAL TO OUR INTEREST AND THAT ALL COPIES WILL BE RETURNED IMMEDIATELY ON DEMAND.

| REFERENCE DWG. NO. | DESCRIPTION | REV. | DESCRIPTION | DATE | DRAWN | CHKD. | APPD. | CHKD. | APPD. | CONSULTANT | CLIENT |
|--------------------|-------------|------|---------------------|----------|-------|-------|-------|-------|-------|------------|--------|
| - | - | A | ISSUED FOR APPROVAL | 04.01.22 | SAM | TS | DK | - | - | | |



Node 20
refer dwg MYP127-DWG-002

| | |
|-------------|-----------------|
| CAD (PI) | PLAN RECORD |
| | R-0 |
| | -Internal Issue |
| | R-1 |

2021.12.10
Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu
-Issue for customer

出図
2021.12.14

- NOTE
1. INSTALL THE CALORIE METER NEAR THE FUEL GAS MAIN PIPING AS CLOSE AS POSSIBLE.
 2. DRAIN TRAP AT VENT LINE SHALL BE SUPPLIED BY EPC CONTRACTOR IF DRAIN WILL BE EXPECTED TO OCCUR.
 3. SPAN GAS AND NITROGEN WILL BE USED AT MAINTENANCE.

FOR INFORMATION

Employer: **snowyhydro**

Supplier: **MITSUBISHI HEAVY INDUSTRIES**

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and lag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| MARK | DESCRIPTION | MATERIAL | TEST | ARRANGE | MOOD | SPARE | TOTAL | REMARKS |
|---|---|----------|------|---------|------------|-------|-----------|------------------|
| | SYMBOL | | PECE | HEATS | SIZE | PIECE | PIECE | |
| Hunter Power Project | | | | | | | | |
| M701F GAS TURBINE | | | | | | | | |
| FUEL GAS CALORIE METER P&ID DIAGRAM | | | | | | | | |
| Drawn | Y.Tsukuda | | | Check | N.Sumimura | | | |
| Approved | T.Hatabu | | | | | | | |
| Date | 2021.9.8 | | | Scale | FA CODE | | A-21070-B | DWG No. S3-80426 |
| OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | |
| Energy Transition & Power headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | |

| | | | |
|-------|------------|------------|--------------------|
| NO. 1 | Y.Tsukuda | 2021.12.10 | Issue for customer |
| NO. 2 | N.Sumimura | 2021.12.10 | Issue for customer |
| NO. 3 | T.Hatabu | 2021.12.10 | Issue for customer |

| | |
|--------------|---|
| Project No. | A-21070-B |
| Project Name | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION |
| Drawn | Y.Tsukuda |
| Checked | N.Sumimura |
| Approved | T.Hatabu |

| | | |
|-----------------|---------|---|
| FOR INFORMATION | CAD (P) | PLAN RECORD |
| | R-0 | -Internal issue- |
| | R-1 | 2021.12.14 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu -Issue for customer- |



出図
2021.12.15

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment/instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


Employer: **snowyhydro**
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MR. | DESCRIPTION | MATERIAL | TEST | ARRANGE | WARRANTY | SPARE | PER | TOTAL | REMARKS | S | F |
|---|---|--|----------|---------|----------|-----------|----------|----------|---------|-----|---|
| TYPE | SYMBOL | QC CODE | | | | | PRICE | QTY | | | |
| | Hunter Power Project | | | | | | | | | | |
| 2021.9.7 | Y.Tsukuda | M701F GAS TURBINE | | | | | | | | | |
| 2021.9.7 | N.Sumimura | AIR & FLUE GAS SYSTEM (1 OF 5) P&I DIAGRAM | | | | | | | | | |
| 2021.9.7 | T.Hatabu | | | | | | | | | | |
| 2021.9.7 | Date | | 2021.9.7 | Scale | PI CODE | A-21081-B | DWG. No. | SG-80427 | Rev. | R-1 | |
| OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | | | |
| | | | | | | | | | | | |
| Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | | | | |

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY, BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| | |
|------------|--|
| PI CODE | A-21081-B |
| ISSUE NO. | SG-80427 |
| DATE | 2021.12.15 |
| REV. | R-1 |
| CLASS | EC1 |
| SECTION | ENGINEERING SECTION |
| DEPARTMENT | GTCC BUSINESS DIVISION |
| PLANT | TAKASAGO PLANT |
| SECTION | TAKASAGO POWER PLANT ENGINEERING SECTION |
| NO. | 1 |
| REV. | |
| DATE | |
| BY | |
| CHECKED | |
| APPROVED | |

| | | | |
|-----------------|---|------------------|--|
| FOR INFORMATION | CAD (PI) | PLAN RECORD | |
| | | R-0 | |
| | | -Internal Issue. | |
| | | R-1 | |
| | 2021.12.14 | | |
| | Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu | | |
| | -Issue for customer. | | |



出図
2021.12.15

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

Employer: **snowyhydro**
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| NO. | DESCRIPTION | MATERIAL | TEST FECE | ARRANGE MEHTS | WORLD NO | SPARE QUANTITY | FOR PRICE MASS | TOTAL MASS | REMARKS | S | F |
|-----|--|---|-----------|---------------|----------|----------------|----------------|------------|---------|---|---|
| 1 | Hunter Power Project | | | | | | | | | | |
| 2 | M701F GAS TURBINE | | | | | | | | | | |
| 3 | AIR & FLUE GAS SYSTEM (2 OF 5) P&I DIAGRAM | | | | | | | | | | |
| 4 | DATE | 2021.9.7 | | | | | | | | | |
| 5 | DRW | Y.Tsukuda | | | | | | | | | |
| 6 | CHECK | N.Sumimura | | | | | | | | | |
| 7 | APPROVE | T.Hatabu | | | | | | | | | |
| 8 | DATE | 2021.9.7 | | | | | | | | | |
| 9 | PI CODE | A-21082-B | | | ENR NO. | S3-80428 | | REV. | R-1 | | |
| 10 | OWNER | snowyhydro | | | | | | | | | |
| 11 | OWNER | TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | | |

| | | | | | | | | | | | | | | |
|-------------|-----------|-------------|----------|------|----------|------|---|----------|-----------|------------|---|-------------|----------|--|
| PROJECT NO. | A-21082-B | DRAWING NO. | S3-80428 | REV. | 1 | DATE | 2021.12.15 | DRAWN BY | Y.Tsukuda | CHECKED BY | N.Sumimura | APPROVED BY | T.Hatabu | |
| | JOB NO. | | 01 | | JOB NAME | | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | |
| | | | JOB CODE | | | | 01 | | JOB TITLE | | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | |
| | | | | | | | JOB NAME | | | | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | |
| | | | | | | | | | | | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | |

| | | |
|-----------------|----------|---|
| FOR INFORMATION | CAD (PI) | PLAN RECORD |
| | R-0 | -Internal Issue. |
| | R-1 | 2021.12.14 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu -Issue for customer. |
| | | |



This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment/instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

出図
2021.12.15

Employer **snowyhydro**
Supplier **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST PECE | ARRANGE AGENTS | WGT. (KG) | QTY | PRICE (JPY) | TOTAL (JPY) | REMARKS | S | F |
|--|-------------|--|-----------|----------------|-----------|----------|-------------|-------------|---------|------|-----|
| Hunter Power Project | | | | | | | | | | | |
| OWNER | Y. Tsukuda | Title M701F GAS TURBINE | | | | | | | | | |
| OWNER | N. Sumimura | AIR & FLUE GAS SYSTEM (3 OF 5) P&I DIAGRAM | | | | | | | | | |
| OWNER | T. Hatabu | DATE: 2021.9.7 | | | | | | | | | |
| OWNER | | JOB CODE | | A-21083-B | | DWG. NO. | | S3-80429 | | REV. | R-1 |
| <p>OWNER: GTCC BUSINESS DIVISION, TAKASAGO PLANT ENGINEERING DEPARTMENT, TAKASAGO POWER PLANT ENGINEERING SECTION</p> <p>EMPLOYER: Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd.</p> | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | |
|-----------|-----------|-------------|----------|------|-----|------|------------|---------|---|-------|-----|--------|-----|----------|--|---------|--|------|--|
| FILE CODE | A-21083-B | DRAWING NO. | S3-80429 | REV. | R-1 | DATE | 2021.12.15 | SECTION | 2 | SCALE | 1:1 | STATUS | EC7 | DESIGNER | | CHECKER | | DATE | |
|-----------|-----------|-------------|----------|------|-----|------|------------|---------|---|-------|-----|--------|-----|----------|--|---------|--|------|--|



FOR INFORMATION CAD (PI) PLAN RECORD
 R-0 -Internal issue.
 R-1
 2021.12.14
 Y.Tsukuda,Y.Oshino,N.Sumimura,T.Hatabu
 -Issue for customer.

node 25

Node 27

node 26

casing temp /
expansion
monitoring

casing pressure
control

#1 Brg

出図
2021.12.15

CONFIDENTIAL
 THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD.
 AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE
 OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY
 INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY
 INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO
 A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL
 LEAD TO LEGAL ACTION.

This P&ID Diagram is prepared based on
 MITSUBISHI HEAVY INDUSTRIES, LTD.
 standard design. Therefore, number
 of equipment, instruments, valves,
 and tag numbers shall not be
 changed without authorization of
 MITSUBISHI HEAVY INDUSTRIES, LTD.

| MARK | DESCRIPTION | MATERIAL | TEST PIECE | APPROVE MENTS | WARRANTY PERIOD | SPECIAL PRETREAT | NET WEIGHT | TOTAL WEIGHT | REMARKS | S F |
|--|-------------|----------|---------------|------------------|--|---------------------|---------------|-----------------|---------|--------|
| | | | | | | | | | | |
| Hunter Power Project | | | | | | | | | | |
| M701F GAS TURBINE | | | | | | | | | | |
| AIR & FLUE GAS SYSTEM (4 OF 5) P&ID DIAGRAM | | | | | | | | | | |
| DATE | 2021.9.7 | DESIGNER | Y.Tsukuda | TITLE | M701F GAS TURBINE | | | | | |
| DATE | 2021.9.7 | DESIGNER | N.Sumimura | TITLE | AIR & FLUE GAS SYSTEM (4 OF 5) P&ID DIAGRAM | | | | | |
| DATE | 2021.9.7 | DESIGNER | T.Hatabu | TITLE | AIR & FLUE GAS SYSTEM (4 OF 5) P&ID DIAGRAM | | | | | |
| OWNER | snowyhydro | | | PA CODE | A-21084-B | DRW NO. | S3-80430 | REV | R-1 | |

PROJECT: A-21084-B
 DRAWING NO.: S3-80430
 REV: R-1
 SHEET: 2 OF 5
 SECTION: ECT
 DATE: 2021.12.14
 DRAWN BY: Y.Tsukuda
 CHECKED BY: N.Sumimura
 APPROVED BY: T.Hatabu
 DEPARTMENT: GTCC BUSINESS DIVISION
 ENGINEERING DEPARTMENT
 TAKASAGO POWER PLANT ENGINEERING SECTION
 MITSUBISHI HEAVY INDUSTRIES, LTD.
 Energy Transition & Power Headquarters, Energy Systems
 Mitsubishi Heavy Industries, Ltd.

Node 28

#17 outlet

#14 outlet

FOR INFORMATION

| PLAN RECORD | |
|-------------|---|
| R-0 | -Internal Issue |
| R-1 | 2021.12.18 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu -Issue for customer. |

Dry instrument air for anti-corrosion when shutdown

2.2 MPA

出図
2021.12.17

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipments, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRACTION OF ANY KIND WILL LEAD TO LEGAL ACTION.

Employer: **snowyhydro** LIMITED


Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| REV | DATE | DESCRIPTION | MATERIAL | TEST | ARRANGE | WORK | ISSUE | TOTAL | REMARKS |
|-----|----------|-------------|----------|------|---------|------|-------|-------|---------|
| 1 | 2021.9.7 | Y.Tsukuda | | | | | | | |
| 2 | 2021.9.7 | N.Sumimura | | | | | | | |
| 3 | 2021.9.7 | T.Hatabu | | | | | | | |

| | |
|-----------|---|
| Project | Hunter Power Project |
| Client | M701F GAS TURBINE |
| Design | AIR & FLUE GAS SYSTEM (5 OF 5) P&I DIAGRAM |
| Scale | A-21085-B |
| Sheet No. | S3-80431 |
| Rev. | R-1 |


| | | | |
|-----|------------|------------|------------|
| 1/3 | Y.Tsukuda | 2021.12.18 | Y.Tsukuda |
| 2/3 | N.Sumimura | 2021.12.18 | N.Sumimura |
| 3/3 | T.Hatabu | 2021.12.18 | T.Hatabu |

| | | | |
|---|------------|------------|------------|
| 1 | Y.Tsukuda | 2021.12.18 | Y.Tsukuda |
| 2 | N.Sumimura | 2021.12.18 | N.Sumimura |
| 3 | T.Hatabu | 2021.12.18 | T.Hatabu |



PLAN RECORD
 R-0
 -Internal Issue-
 R-1
 3021.12.17
 Y. Tsukuda, Y. Oshino, N. Sumimura, T. Hatabu
 -Issue for customer-

Node 29



出図
 2021.12.21


FOR INFORMATION

| | | |
|------------|---|---|
| Employer: | snowyhydro | |
| Supplier: | MITSUBISHI HEAVY INDUSTRIES | |
| MARK | DESCRIPTION | REMARKS |
| TYPE | SYMBOL | QC CODE |
| 2021.9.6 | Y. Tsukuda | M701F GAS TURBINE |
| 6327/175 | N. Sumimura | LUBE OIL SYSTEM (1 OF 4) P&I DIAGRAM |
| 6000 | T. Hatabu | |
| 2021.9.6 | | |
| SNOWYHYDRO | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | PL CODE: A-21021-B Dwg No: S3-80401 Rev: R-1 |
| | | MITSUBISHI HEAVY INDUSTRIES Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. |

CONFIDENTIAL
 THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

FIG. CODE: A-21021-B
 SHEET NO.: S3-80401
 SHEET: R-1
 OF: 2
 ECT
 DATE: 2021.12.21
 DRAWN BY: Y. Tsukuda
 CHECKED BY: N. Sumimura
 APPROVED BY: T. Hatabu
 GTCC BUSINESS DIVISION
 TAKASAGO PLANT ENGINEERING DEPARTMENT
 TAKASAGO POWER PLANT ENGINEERING SECTION



Node 31

FOR INFORMATION

| CAD (PI) | PLAN RECORD | |
|----------|-------------|--|
| | R-0 | Internal issue |
| | R-1 | 2021.12.18 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu Issue for customer. |
| | | |

| | | | | |
|------------------------|---------------------------------------|--|---|-----|
| 1/1023-B | 3/30403 | R-1 | 2 | EOT |
| GTCC BUSINESS DIVISION | TAKASAGO PLANT ENGINEERING DEPARTMENT | TAKASAGO POWER PLANT ENGINEERING SECTION | | |

出図
2021.12.17

Employer: **snowyhydro** LIMITED
Supplier: **MITSUBISHI HEAVY INDUSTRIES**


This P&ID Diagram is prepared based on Mitsubishi Power standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of Mitsubishi Power.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI POWER LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI POWER LTD OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI POWER LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| NO. | DESCRIPTION | MATERIAL | UNIT PRICE | QUANTITY | AMOUNT | REMARKS |
|--|-------------|----------|------------|----------|--------|---------|
| Hunter Power Project | | | | | | |
| M701F GAS TURBINE | | | | | | |
| LUBE OIL SYSTEM (3 OF 4) P&ID DIAGRAM | | | | | | |
| DATE | 2021.9.6 | DRW | Y.Tsukuda | | | |
| DATE | 2021.9.6 | CHK | N.Sumimura | | | |
| DATE | 2021.9.6 | APP | T.Hatabu | | | |
| OWNER | snowyhydro | PROJECT | 6327R15 | 6000 | | |
| OWNER | | PROJECT | | | | |

GTCC BUSINESS DIVISION
TAKASAGO PLANT ENGINEERING DEPARTMENT
TAKASAGO POWER PLANT ENGINEERING SECTION

Energy Transition & Power Headquarters, Energy Systems
Mitsubishi Heavy Industries, Ltd.



Node 32

FOR INFORMATION

| | | |
|----------|---|------------------|
| CAD (Pi) | PLAN RECORD | |
| | R-0 | -Internal issue. |
| | R-1 | |
| | 2021.12.16 Y.Tsukuda, Y.Oshino, N.Sumimura, T.Hatabu -issue for customer. | |


出図
2021.12.17

Employer: **snowyhydro** LIMITED
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST FEES | ARRANGE MENTS | WORK TIME | APPROVAL | PER. PREC.B. | TOTAL | REMARKS | S. V. |
|---|---|----------|-----------|---------------|-----------|----------|--------------|-------|---------|-------|
| | Hunter Power Project | | | | | | | | | |
| | M701F GAS TURBINE | | | | | | | | | |
| | LUBE OIL SYSTEM (4 OF 4) P&I DIAGRAM | | | | | | | | | |
| 2021.9.6 | Y.Tsukuda | | | | | | | | | |
| 2021.9.6 | N.Sumimura | | | | | | | | | |
| 2021.9.6 | T.Hatabu | | | | | | | | | |
| 3327H75 | 6000 | | | | | | | | | |
| OWNER | snowyhydro | | | | | | | | | |
| | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | | |
| | A-21024-B | | S3-80404 | | R-1 | | | | | |
| Energy Transition & Power Headquarters, Energy Systems. | | | | | | | | | | |

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

PROJECT: A-21024-B
 DRAWING NO.: S3-80404
 (10/14 M.F.)
 SHEET: 2
 ECT
 GTCC BUSINESS DIVISION
 TAKASAGO PLANT ENGINEERING DEPARTMENT
 TAKASAGO POWER PLANT ENGINEERING SECTION
 DATE: 2021.12.17
 DRAWN BY: Y.Tsukuda
 CHECKED BY: N.Sumimura
 APPROVED BY: T.Hatabu
 SCALE: 1:1
 SHEET: 2 OF 4
 PROJECT: HUNTER POWER PROJECT
 UNIT: M701F GAS TURBINE
 SYSTEM: LUBE OIL SYSTEM (4 OF 4)
 DIAGRAM TYPE: P&I DIAGRAM
 OWNER: snowhydro



LEGEND

| | | | | | |
|--|--|--|--|--|---|
| | VALVE (NORMALLY OPENED) | | NEEDLE VALVE | | PRESSURE INDICATOR |
| | VALVE (NORMALLY CLOSED) | | FLOAT VALVE | | TEMPERATURE INDICATOR |
| | VALVE (NORMALLY THROTTLED) | | BALL VALVE | | TEMPERATURE INDICATOR WITH SWITCH |
| | CHECK VALVE WITH LOCK DEVICE (NORMALLY OPENED) | | STRAINER | | LEVEL SWITCH |
| | CHECK VALVE WITH LOCK DEVICE (NORMALLY CLOSED) | | ORIFICE | | LEVEL INDICATOR |
| | CHECK VALVE | | ELECTRICAL WIRING | | PRESSURE SWITCH |
| | CHECK VALVE WITH LOCK DEVICE | | FLEXIBLE PIPING | | DIFF. PRESSURE TRANSMITTER WITH INDICATOR |
| | BELLOWS VALVE | | BARRIER | | DIFF. PRESSURE SWITCH |
| | RELIEF VALVE | | PLUG | | DIFF. PRESSURE INDICATOR |
| | FIVE WAYS MANIFOLD | | REDUCER | | THERMOCOUPLE |
| | TWO WAYS MANIFOLD | | GENERATOR CONTROL AND PROTECTION RELAY PANEL | | TEMPERATURE ELEMENT |
| | SOLENOID VALVE | | GAS TURBINE CONTROL SYSTEM | | |
| | GLOBE VALVE | | FLOW SIGHT GLASS | | |

CHARACTER

| SYMBOL | No. | RANGE | SET VALUE | SYMBOL | No. | RANGE | SET VALUE | SYMBOL | No. | SET VALUE |
|--------|-----|--------------|-----------|--------|--------|-------------------|---------------|--------|---------|---------------------|
| PI | 1 | 0~10 barg | - | TIS | 1 | 0~100 °C | 60 °C | LS | 1 | 450 cm ³ |
| | 2 | 0~10 barg | - | | 2 | 0~100 °C | 60 °C | | 2 | 450 cm ³ |
| | 3 | 0~25 mbarg | - | LI | 1 | -120mm~+120mm | - | | 3 | NL+100mm |
| | 4 | -1~0~15 barg | - | | 2 | -120mm~+120mm | - | | 4 | NL-100mm |
| | 5 | 0~15 barg | - | DPTI | 1 | 0~2 bar / 4~20 mA | - | | 5 | NL+100mm |
| | 6 | 0~10 barg | - | | 2 | TYPE-E | - | | 6 | NL-100mm |
| TI | 1 | 0~6 barg | - | TC | 1 | TYPE-E | - | DPS | 1 | 0.45 bar (NOTE7) |
| | 2 | 0~1 barg | - | | 2 | TYPE-E | - | | 2 | 0.5 bar |
| | 3 | 0~15 barg | - | 3 | TYPE-E | - | 3 | | 0.5 bar | |
| PS | 1 | 0~100 °C | - | TE | 1 | 0~100°C | P1100Q at 0°C | RV-1 | 1 | 8 barg |
| | 2 | 0~100 °C | - | | 2 | 0~100 °C | - | | RV-2 | 11.5 barg |
| | 3 | 0~100 °C | - | | | | | | | |

- ALARMS**
- 1T GEN. DRAIN OIL LEVEL (TURB. SIDE) ----- HIGH (≥ 450 cm³)
 - 1T GEN. DRAIN OIL LEVEL (SLIP. SIDE) ----- HIGH (≥ 450 cm³)
 - 2 GEN. SEAL OIL DIFF. PRESS. ----- LOW (≤ 0.45 bar)
 - EMERGENCY SEAL OIL PUMP RUNNING
 - TURNING STARTING INTERLOCK
 - 3 GEN. SEAL OIL DIFF. PRESS. ----- HIGH (≥ 1.5 bar MORE THAN 5 SECONDS)
 - 4 GEN. SEAL OIL PUMP OUTLET PRESS. ----- LOW (≤ 8 barg)
 - EMERGENCY SEAL OIL PUMP RUNNING
 - 5H GEN. DRAIN REGULATOR OIL LEVEL ----- HIGH (≥ NL+100 mm)
 - 5L GEN. DRAIN REGULATOR OIL LEVEL ----- LOW (≤ NL-100 mm)
 - 6H GEN. SEAL OIL VACUUM TANK OIL LEVEL ----- HIGH (≥ NL+100 mm)
 - SEAL OIL VACUUM PUMP STOP INTER LOCK
 - 6L GEN. SEAL OIL VACUUM TANK OIL LEVEL ----- LOW (≤ NL-100 mm)
 - 7 GEN. SEAL OIL SUPPLY TEMP. ----- HIGH (≥ 60°C)
 - 8 GEN. SEAL OIL FILTER DIFF.PRESS. ----- HIGH (≥ 0.5 bar)
 - 9 GEN. GLAND SEAL FLOAT OIL FILTER DIFF.PRESS. ----- HIGH (≥ 0.5 bar)



- NOTES**
- ALL PIPING MATERIAL SUPPLIED BY MELCO (IN THIS DRAWING) IS STPT EXCEPT OTHERWISE NOTED. PIPING INSIDE EQUIPMENTS WILL BE SELECTED IN ACCORDANCE WITH MANUFACTURER'S STANDARD.
 - STPT...STPT370-S CARBON STEEL PIPES FOR HIGH TEMPERATURE SERVICE (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3456.
 - SCH NO IS 40 EXCEPT OTHERWISE NOTED.
 - SUS...SUS304TP-S STAINLESS STEEL PIPES (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3459.
 - SCH NO IS 40 EXCEPT OTHERWISE NOTED.
 - TERMINAL POINTS BETWEEN EPC AND MELCO ARE BASED ON ANSI STANDARD. TERMINAL POINTS BETWEEN MHI AND MELCO ARE BASED ON ANSI STANDARD.
 - SCOPE OF SUPPLY SHOWN IN THIS DRAWING IS AS FOLLOWS.
 - (EPC) | (MELCO) (MHI) | (MELCO)
 - SUPPLIED BY EPC SUPPLIED BY MELCO SUPPLIED BY MHI SUPPLIED BY MELCO
 - ALL PIPES SHALL BE LAID WITH GRADIENT OF MORE THAN 1/50 TO PREVENT ACCUMULATION OF OIL OR MAKING AIR POCKET IN THE PIPES.
 - THE SCREEN FOR GENERATOR MAIN BEARING TEMPORARY OIL STRAINERS ARE USED AT FLUSHING AND SHALL BE TAKEN AWAY IN GENERATOR RUNNING. STRAINER MATERIAL SHALL BE STAINLESS STEEL.
 - VENT DIRECTION OF GENERATOR LOOP SEAL TANK SHALL BE TOWARD TO THE SAFE AREA SUCH AS NO PASSAGEWAY, NO ELECTRICAL EQUIPMENT, AND SO ON.
 - VENT POINT OF GENERATOR LOOP SEAL TANK SHALL BE MORE THAN 2m ABOVE ROOF.
 - VENT POINT OF GENERATOR LOOP SEAL TANK SHALL BE AS FAR AS POSSIBLE FROM AIR INTAKE OF GAS TURBINE.
 - DIFF. PRESS. BETWEEN SEAL OIL AND GAS AT SEAL RING 0.35bar + DIFF. ELEVATION HEAD BETWEEN SEAL OIL SIDE AND GAS SIDE 0.01MPa = 0.45bar

Employer: **snowyhydro LIMITED**

Supplier: **MITSUBISHI ELECTRIC**

Company Proprietary NOT TO BE REPRODUCED OR DISCLOSED WITHOUT SPECIFIC WRITTEN PERMISSION OF MITSUBISHI ELECTRIC CORPORATION

Employer's DWG Number: **HPP-MEL-MEC-OS-GEN-DRG-0001**

CHANGE CAY6-03

出図先 ()

| | | | |
|-------------|--------------|-------------|------------------|
| 作成日 DATE | 2021-12-10 | 検査 APPROVED | |
| 作成 DRAWN | R.Goto, R.Mm | 検査 CHECKED | T.Emura, N.Obana |
| 設計 DESIGNED | K.Obana | 設計 CHECKED | T.Obada |

MITSUBISHI ELECTRIC CORPORATION

Hunter Power Project

TITLE: GENERATOR SEAL OIL DIAGRAM FOR GT

DWG.NO: A13C870

Node 34

CAD (PI)
 PLAN RECORD
 R-0
 -Internal issue
 R-1
 2021.12.17
 Y.Tsukuda,Y.Oshino,N.Sumimura,T.Hatabu
 -Issue for customer

Low pressure starts standby pump

piston pumps c/w internal pressure relief back to tank

Design to be confirmed - wall ?



FOR INFORMATION

CONFIDENTIAL THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR IN ANY MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDLED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY, BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment/instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.


Employer: **snowyhydro**
 Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | UNIT | ARRANGE | WORK | SPARE | TOTAL | REMARKS | S |
|------|-------------|----------|------|---------|------|-------|-------|---------|---|
| | | | | | | | | | |

| DATE | BY | CHK | APPR | WORK NO. | REV. |
|----------|------------|-----|------|--|------|
| 2021.9.8 | Y.Tsukuda | | | M701F GAS TURBINE | 1 |
| 2021.9.8 | N.Sumimura | | | CONTROL OIL SYSTEM (1 OF 3) P&ID DIAGRAM | 1 |
| 2021.9.8 | T.Hatabu | | | | 1 |
| 2021.9.8 | | | | | 1 |
| 2021.9.8 | | | | | 1 |

| OWNER | PROJECT | NO. | REV. | DATE | DESCRIPTION |
|------------|----------------------|-----------|------|----------|--|
| snowyhydro | Hunter Power Project | A-21031-B | 001 | 2021.9.6 | CONTROL OIL SYSTEM (1 OF 3) P&ID DIAGRAM |


OWNER: **MITSUBISHI HEAVY INDUSTRIES**
 Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd.



Vertical title block on the right side of the page, containing project and drawing information.

Node 35

| PLAN RECORD | |
|-------------|--|
| R-0 | -Internal issue. |
| R-1 | 2021.12.17 Y.Tsukuda, Y.Oshino, Sumimura, T.Hatibu -Issue for customer |



出図
2021.12.21

FOR INFORMATION

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment/instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

Employer: **snowyhydro** LIMITED
Supplier: **MITSUBISHI HEAVY INDUSTRIES**

| MARK | DESCRIPTION | MATERIAL | TEST | APPROVE | WELD | WELD | PER | TOTAL | REMARKS |
|----------------------|-------------|----------|-------------|---------|---|-------------|-----------|----------|----------|
| TYPE | INSTRUMENT | DC CODE | | | | | | | |
| Hunter Power Project | | | | | | | | | |
| DATE | 2021.9.6 | DESIGNER | Y. Tsukuda | TITLE | M701F GAS TURBINE | | | | |
| DATE | 2021.12.21 | DESIGNER | N. Sumimura | TITLE | CONTROL OIL SYSTEM (2 OF 3) P&ID DIAGRAM | | | | |
| DATE | 2021.9.6 | DESIGNER | T. Hatibu | SCALE | | PROJECT NO. | A-21032-B | FIG. NO. | S3-80406 |
| OWNER | snowyhydro | | | OWNER | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT ENGINEERING SECTION | | | | |
| OWNER | snowyhydro | | | OWNER | MITSUBISHI HEAVY INDUSTRIES Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | |

| | |
|----------|------------|
| FIG. NO. | A-21032-B |
| MARK NO. | S3-80406 |
| DATE | 2021.12.21 |
| REV. | 1 |
| REV. | 2 |
| REV. | 3 |
| REV. | 4 |
| REV. | 5 |
| REV. | 6 |
| REV. | 7 |
| REV. | 8 |
| REV. | 9 |
| REV. | 10 |
| REV. | 11 |
| REV. | 12 |
| REV. | 13 |
| REV. | 14 |
| REV. | 15 |
| REV. | 16 |
| REV. | 17 |
| REV. | 18 |
| REV. | 19 |
| REV. | 20 |
| REV. | 21 |
| REV. | 22 |
| REV. | 23 |
| REV. | 24 |
| REV. | 25 |
| REV. | 26 |
| REV. | 27 |
| REV. | 28 |
| REV. | 29 |
| REV. | 30 |
| REV. | 31 |
| REV. | 32 |
| REV. | 33 |
| REV. | 34 |
| REV. | 35 |
| REV. | 36 |
| REV. | 37 |
| REV. | 38 |
| REV. | 39 |
| REV. | 40 |
| REV. | 41 |
| REV. | 42 |
| REV. | 43 |
| REV. | 44 |
| REV. | 45 |
| REV. | 46 |
| REV. | 47 |
| REV. | 48 |
| REV. | 49 |
| REV. | 50 |
| REV. | 51 |
| REV. | 52 |
| REV. | 53 |
| REV. | 54 |
| REV. | 55 |
| REV. | 56 |
| REV. | 57 |
| REV. | 58 |
| REV. | 59 |
| REV. | 60 |
| REV. | 61 |
| REV. | 62 |
| REV. | 63 |
| REV. | 64 |
| REV. | 65 |
| REV. | 66 |
| REV. | 67 |
| REV. | 68 |
| REV. | 69 |
| REV. | 70 |
| REV. | 71 |
| REV. | 72 |
| REV. | 73 |
| REV. | 74 |
| REV. | 75 |
| REV. | 76 |
| REV. | 77 |
| REV. | 78 |
| REV. | 79 |
| REV. | 80 |
| REV. | 81 |
| REV. | 82 |
| REV. | 83 |
| REV. | 84 |
| REV. | 85 |
| REV. | 86 |
| REV. | 87 |
| REV. | 88 |
| REV. | 89 |
| REV. | 90 |
| REV. | 91 |
| REV. | 92 |
| REV. | 93 |
| REV. | 94 |
| REV. | 95 |
| REV. | 96 |
| REV. | 97 |
| REV. | 98 |
| REV. | 99 |
| REV. | 100 |


| | |
|---------|--|
| CAD (P) | PLAN RECORD |
| R-0 | -Internal issue |
| R-1 | 2021.12.17 Y.Tsukuda, Y.Oshino, H.Sumimura, T.Hatabu -Issue for customer |

TRIP VALVE UNIT
Node 36

Fail open de-energize to trip. This drawing shows operating state of gas operation, therefore fuel oil is shown tripped. 1oo1 solenoid to trip fuel, common cause factor and hardware fault tolerance for SIL rating to be confirmed

Used for solenoid trip testing only. Indicates intermediate pressure. Unit wont trip when only 1 solenoid is operated

Fail open de-energize to trip. Solenoids shown in normal operating state (not de-energized state). 2oo4 to trip



出図
2021.12.21

Employer
snowyhydro Limited
Supplier
MITSUBISHI HEAVY INDUSTRIES


| MARK | DESCRIPTION | MATERIAL | TEST | APPROVE | YIELD | QTY | UNIT | TOTAL | REMARKS |
|-------------|---|----------|------------|---------|-------------|----------|-----------|-------|------------|
| | Hunter Power Project | | | | | | | | |
| | M701 GAS TURBINE | | | | | | | | |
| | CONTROL OIL SYSTEM (3 OF 3) P&I DIAGRAM | | | | | | | | |
| DATE | 2021. 9. 6 | DESIGNER | Y. Tsukuda | CHECKER | N. Sumimura | APPROVER | T. Hatabu | DATE | 2021. 9. 6 |
| DEPARTMENT | GTCC-BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | | |
| PROJECT NO. | A-21033-B | DRAW NO. | S3-80407 | REV. | R-1 | | | | |
| OWNER | Energy Transition & Power Headquarters, Energy Systems, Mitsubishi Heavy Industries, Ltd. | | | | | | | | |

This P&I Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipments, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

GTCC-BUSINESS DIVISION
 TAKASAGO PLANT ENGINEERING DEPARTMENT
 TAKASAGO POWER PLANT ENGINEERING SECTION
 R-1
 S3-80407
 2021.12.17
 Y. Tsukuda, Y. Oshino, H. Sumimura, T. Hatabu
 -Issue for customer

Node 42



CODE: MPTA(C001)
 C-50011
 DRAWING NO. M4-H9043-41
 R. 0
 SECURITY LEVEL 2
 ECT
 POWER SYSTEMS PROJECT ENGINEERING DEPARTMENT
 GAS TURBINE APPLICATION ENGINEERING SECTION

PRELIMINARY
SOME MODIFICATION WILL BE CONSIDERED ON DETAILED DESIGN STAGE.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI POWER, LTD. AND CONFIDENTIAL. IT MUST NEITHER BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI POWER OR WITH A PRIOR WRITTEN CONSENT OF MITSUBISHI POWER. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.


| MARK | DESCRIPTION | MATERIAL | TEST PIECE | ARRANGE -MENTS | WORK -SIC | SPARE -PARTS | PERF. QUANTITY | TOTAL QUANTITY | REMARKS | S/F |
|---|-------------|----------|------------|----------------|-----------|--------------|----------------|----------------|---------|-----|
| | | | | | | | | | | |
| Snowy Hydro / Kurri Kurri Gas-fired Power Station | | | | | | | | | | |
| Title M701F GAS TURBINE P&I DIAGRAM | | | | | | | | | | |
| EVAPORATIVE COOLER SYSTEM (PUMP/TANK UNIT) | | | | | | | | | | |
| Scale ~ PA CODE C-50011 DWG. No. M4-H9043-41 Rev. R- 0 | | | | | | | | | | |
| | | | | | | | | | | |
| Project Management Division, Engineering Headquarters, Mitsubishi Power, Ltd. | | | | | | | | | | |

| | |
|------------|---|
| CAD (P) | PLAN RECORD |
| | R-0 -Internal Issue |
| | R-1 2021.12.9 Y.Tsukuda, Y.Ohno, N.Sumimura, T.Hatabu -Issue for customer. |
| | |

FOR INFORMATION

Node 43A

Detail design not available yet. To be completed later



出図
2021.12.14

Employer: **snowyhydro**


Supplier: **MITSUBISHI POWER**

This P&ID Diagram is prepared based on MITSUBISHI HEAVY INDUSTRIES, LTD. standard design. Therefore, number of equipment, instruments, valves, and tag numbers shall not be changed without authorization of MITSUBISHI HEAVY INDUSTRIES, LTD.

CONFIDENTIAL
THIS DOCUMENT IS THE PROPERTY OF MITSUBISHI HEAVY INDUSTRIES, LTD. AND CONFIDENTIAL. IT MUST NOT BE COPIED NOR USED FOR ANY PURPOSE OR MANNER OTHER THAN EXPRESSLY PERMITTED BY MITSUBISHI HEAVY INDUSTRIES, LTD. NEITHER IS IT TO BE HANDED OVER NOR COMMUNICATED TO A THIRD PARTY IN ANY WAY. BREACH OR INFRINGEMENT OF ANY KIND WILL LEAD TO LEGAL ACTION.

| MARK | DESCRIPTION | MATERIAL | TEXT | ARRANGE | QUANTITY | PRICE | TOTAL | REMARKS |
|--------------|---|----------|-----------|---------|------------|-------|-----------|---------|
| | Hunter Power Project | | | | | | | |
| | M701F GAS TURBINE | | | | | | | |
| | PURGE AIR SYSTEM P&I DIAGRAM | | | | | | | |
| DATE | 2021.9.10 | BY | Y.Tsukuda | CHKD | N.Sumimura | DATE | 2021.9.10 | NO. |
| OWNER | snowyhydro | | | | | | | |
| DEPARTMENT | GTCC BUSINESS DIVISION TAKASAGO PLANT ENGINEERING DEPARTMENT TAKASAGO POWER PLANT ENGINEERING SECTION | | | | | | | |
| PROJECT CODE | A-21100-B | | | | | | | |
| FIGURE NO. | S3-80414 | | | | | | | |
| REVISION | R-1 | | | | | | | |
| PROJECT NAME | Project Management Division, Engineering Headquarters, Mitsubishi Power, Ltd. | | | | | | | |

| | |
|--------------|---|
| FIG. NO. | A-21100-B |
| FIG. NAME | S3-80414 |
| REV. | R-1 |
| DATE | 2021.12.14 |
| BY | Y.Tsukuda |
| CHKD | N.Sumimura |
| DATE | 2021.12.14 |
| PROJECT CODE | A-21100-B |
| FIGURE NO. | S3-80414 |
| REVISION | R-1 |
| PROJECT NAME | Project Management Division, Engineering Headquarters, Mitsubishi Power, Ltd. |




- LEGEND**
- VALVE (NORMALLY OPENED)
 - VALVE (NORMALLY CLOSED)
 - VALVE (NORMALLY THROTTLED)
 - BUTTERFLY VALVE (NORMALLY OPENED)
 - BUTTERFLY VALVE (NORMALLY THROTTLED)
 - GLOBE VALVE

- NOTES**
- ALL PIPING MATERIAL SUPPLIED BY MELCO (IN THIS DRAWING) IS STPT EXCEPT OTHERWISE NOTED.
 ·STPT...STPT370-S CARBON STEEL PIPES FOR HIGH TEMPERATURE SERVICE (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3456.
 SCH.NO IS 4.0 EXCEPT OTHERWISE NOTED.
 PIPING INSIDE EQUIPMENTS WILL BE SELECTED IN ACCORDANCE WITH MANUFACTURER'S STANDARD.
 - TERMINAL POINTS BETWEEN OTHERS AND MELCO ARE BASED ON ANSI STANDARD.
 - SCOPE OF SUPPLY SHOWN IN THIS DRAWING IS AS FOLLOWS.

← (EPC) | (MELCO) →
 SUPPLIED BY EPC SUPPLIED BY MELCO

FOR APPROVAL




| | |
|-----------------------|-----------------------------|
| Employer | snowyhydro LIMITED |
| Supplier | MITSUBISHI ELECTRIC |
| Employer's DWG Number | HPP-MEL-MEC-CL-GEN-DRG-0001 |

COMPANY PROPRIETARY
 NOT TO BE REPRODUCED OR DISCLOSED
 WITHOUT SPECIFIC WRITTEN PERMISSION
 OF MITSUBISHI ELECTRIC CORPORATION

| | | | | | | |
|---------|---------------------------------|--|------------|-------------|----------------------|-------------------|
| 出図先 () | MITSUBISHI ELECTRIC CORPORATION | 作成日付 DATE | 2021-12-10 | 校核 APPROVED | Hunter Power Project | |
| | | 尺数 SCALE | | 作成 DRAWN | | R.Goto, K.Masa |
| | | | | 检查 CHECKED | | T.Eura, H.Hanawa |
| | | | | 設計 DESIGNED | | K.Takano, T.Osada |
| TITLE | | GENERATOR COOLING WATER DIAGRAM FOR GT | | | DWG.NO | |
| | | A13C868 | | | | |

変更 CHANGE
 CAY6-03



LEGEND

| | | | |
|--|----------------------------|--|--------------------|
| | VALVE (NORMALLY OPENED) | | PRESSURE INDICATOR |
| | VALVE (NORMALLY CLOSED) | | FILTER |
| | VALVE (NORMALLY THROTTLED) | | PLUG |
| | GLOBE VALVE | | |
| | BELLOWS VALVE | | |
| | NEEDLE VALVE | | |
| | RELIEF VALVE | | |
| | PRESSURE CONTROL VALVE | | |

CHARACTER

| SYMBOL | No. | RANGE | SET VALUE |
|--------|-----|------------|-----------|
| | 1 | 0~250 barg | - |
| | 2 | 0~16 barg | - |
| | 3 | 0~6 barg | - |


| SYMBOL | No. | SET VALUE |
|--------|------|-----------|
| | RV-1 | 9 barg |
| | RV-2 | 5 barg |
| | CV-1 | 7 barg |

NOTES

- ALL PIPING MATERIAL SUPPLIED BY MELCO (IN THIS DRAWING) IS STPT EXCEPT OTHERWISE NOTED.
 · STPT STPT370-S CARBON STEEL PIPES FOR HIGH TEMPERATURE SERVICE (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3456.
 SCH.NO IS 40 EXCEPT OTHERWISE NOTED.
 · SUS SUS304TP-S STAINLESS STEEL PIPES (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3459.
 SCH.NO IS 40 EXCEPT AS NOTED.
 PIPING INSIDE EQUIPMENTS WILL BE SELECTED IN ACCORDANCE WITH MANUFACTURE'S STANDARD.
 2.TERMINAL POINTS BETWEEN OTHERS AND MELCO ARE BASED ON ANSI STANDARD.
 3.SCOPE OF SUPPLY SHOWN IN THIS DRAWING IS AS FOLLOWS.

SUPPLIED BY EPC SUPPLIED BY MELCO

FOR APPROVAL



| | |
|-----------------------|-----------------------------|
| Employer | snowyhydro LIMITED |
| Supplier | MITSUBISHI ELECTRIC |
| Employer's DWG Number | HPP-MEL-MEC-HY-GEN-DRG-0002 |

COMPANY PROPRIETARY
NOT TO BE REPRODUCED OR DISCLOSED
WITHOUT SPECIFIC WRITTEN PERMISSION
OF MITSUBISHI ELECTRIC CORPORATION

| | | | | |
|--|-------------------------|---|---------------------------------|--|
| 出 図 先 (A) 1 2 3 4 5 6 7 8 9 10 | mm 尺 度 SCALE 1:20 | MITSUBISHI ELECTRIC CORPORATION 作成日付 DATE 2021-12-10 作 成 DRAWN R.Goto, K.1000 関 査 CHECKED T.Ewara, N.Chanura 設 計 DESIGNED K.Tokuse | 検 査 認 可 APPROVED T.Osada | Hunter Power Project TITLE GENERATOR H2 & CO2 GAS SUPPLY SYSTEM DIAGRAM FOR GT DWG No. AS29623 |
|--|-------------------------|---|---------------------------------|--|

CHANGE
CAY6-03

A13C869

LEGEND


| | | | | | |
|--|----------------------------|--|---------------------------------|--|--|
| | VALVE (NORMALLY OPENED) | | PRESSURE INDICATOR | | MOTOR |
| | VALVE (NORMALLY CLOSED) | | PRESSURE SWITCH | | BLOWER |
| | VALVE (NORMALLY THROTTLED) | | DIFFERENTIAL PRESSURE INDICATOR | | PLUG |
| | BELLOWS VALVE | | FLOW INDICATOR | | REDUCER |
| | BALL VALVE | | LEVEL SWITCH | | FILTER |
| | THREE WAY BALL VALVE | | LIMIT SWITCH | | FILTER & REGULATOR |
| | FOUR WAY SOLENOID VALVE | | PRESSURE TRANSMITTER | | AIR LINE |
| | PRESSURE REDUCING VALVE | | TEMPERATURE INDICATOR | | BARRIER |
| | FLOW CONTROL VALVE | | TEMPERATURE SWITCH | | GENERATOR CONTROL AND PROTECTION RELAY PANEL |
| | SPRING RETURN VALVE | | GAS PURITY DETECTOR | | GAS TURBINE CONTROL PANEL |
| | NEEDLE VALVE | | GAS PURITY MONITOR | | |

NOTES

- ALL PIPING MATERIAL SUPPLIED BY MELCO (IN THIS DRAWING) IS STPT EXCEPT OTHERWISE NOTED.
 STPT... STPT370-S CARBON STEEL PIPES FOR HIGH TEMPERATURE SERVICE (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3456.
 SCH.NO IS 40 EXCEPT OTHERWISE NOTED.
- SUS... SUS304TP-S STAINLESS STEEL PIPES (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3459.
 SCH.NO IS 40 EXCEPT AS NOTED.
- PIPING INSIDE EQUIPMENTS WILL BE SELECTED IN ACCORDANCE WITH MANUFACTURE'S STANDARD.
- "A" IS A FLEXIBLE TUBE WHICH SHOULD BE CONNECTED TO THE REMOVABLE LINK WHEN PURGING CARBON DIOXIDE GAS BY AIR. THE FLEXIBLE TUBE SHALL BE DISCONNECTED AND CLOSED BY BLIND FLANGE DURING GENERATOR OPERATION.
- CONNECTION OF TERMINAL POINT IS BASED ON ANSI STANDARDS 150LB RF FLANGE EXCEPT OTHERWISE NOTED.
- SCOPE OF SUPPLY SHOWN IN THIS DRAWING IS AS FOLLOWS.

SUPPLIED BY EPC SUPPLIED BY MELCO

- PIPES MARKED SHALL BE SLOPED AT THE RATE OF MINIMUM 1/50 NOT TO MAKE DRAIN SUMP IN THE PIPELINE.
- GAS VENT DIRECTION SHALL BE TOWARD TO THE SAFE AREA SUCH AS NO PASSAGEWAY, NO ELECTRICAL EQUIPMENT, AND SO ON.
- GAS VENT POINT SHALL BE MORE THAN 2m ABOVE ROOF.
- GAS VENT POINT SHALL BE AS FAR AS POSSIBLE FROM AIR INTAKE OF GAS TURBINE.



CHARACTER

| SYMBOL | No. | RANGE | SET VALUE | SYMBOL | No. | RANGE | SET VALUE |
|--------|-----|----------------|-----------|--------|------------------|---------------------|-----------|
| PI | 1 | 0~10 barg | - | AI | 1 | H2 in Air 85~100% | - |
| | 2 | 0~16 barg | - | | H2 in CO2 0~100% | - | |
| | 3 | 0~10 barg | - | | | | |
| | 4 | 0~0.5 barg | - | | | | |
| PT | 1 | 0~10 barg | - | LS | 1 | 450 cm ³ | - |
| DPI | 1 | 0~100 mbar | - | | 2 | 450 cm ³ | - |
| FI | 1 | 200~2000ml/min | - | PS | 1 | 6 barg | - |
| | 2 | 200~2000ml/min | - | TS | 1 | 250℃ | - |
| | 3 | 5~50ml/min | - | CV-1 | 1 | 5 barg | - |
| TI | 1 | 0~300℃ | - | CV-2 | 1 | 0.1~0.3 barg | - |



- ALARMS**
- 1 H2 GAS PURITY ----- LOW (≦ 90%)
 - 2A/2B H2 GAS PRESSURE ----- HIGH OR LOW (≧ 5.35barg/≦ 4.8barg)
 - 2C H2 GAS PRESSURE ----- LOW (FOR DRAIN REGULATOR OIL LEVEL HIGH ALARM INTER LOCK) (≦ 1.5barg)
 - 3 GAS PURITY MONITOR ----- ABNORMAL
 - 4A/4B WATER DETECTOR LEVEL ----- HIGH (≧ 450cm³)
 - 5 H2 GAS SUPPLY PRESSURE ----- LOW (≦ 6 barg)

NOTE 6

WIRE NET (40MESH) MATERIAL: STAINLESS

vent with earth lead

TO EARTH



FOR APPROVAL

ENERGY SYSTEMS CENTER

DEC. 17, 2021


MITSUBISHI ELECTRIC CORP. JAPAN

Employer **snowyhydro** LIMITED

Supplier **MITSUBISHI ELECTRIC**

Employer's DWG Number HPP-MEL-MEC-HY-GEN-DRG-0001

COMPANY PROPRIETARY NOT TO BE REPRODUCED OR DISCLOSED WITHOUT SPECIFIC WRITTEN PERMISSION OF MITSUBISHI ELECTRIC CORPORATION



LEGEND

| | | | | | |
|--|--|--|--|--|---|
| | VALVE (NORMALLY OPENED) | | NEEDLE VALVE | | PRESSURE INDICATOR |
| | VALVE (NORMALLY CLOSED) | | FLOAT VALVE | | TEMPERATURE INDICATOR |
| | VALVE (NORMALLY THROTTLED) | | BALL VALVE | | TEMPERATURE INDICATOR WITH SWITCH |
| | CHECK VALVE WITH LOCK DEVICE (NORMALLY OPENED) | | STRAINER | | LEVEL SWITCH |
| | CHECK VALVE WITH LOCK DEVICE (NORMALLY CLOSED) | | ORIFICE | | LEVEL INDICATOR |
| | CHECK VALVE | | ELECTRICAL WIRING | | PRESSURE SWITCH |
| | CHECK VALVE WITH LOCK DEVICE | | FLEXIBLE PIPING | | DIFF. PRESSURE TRANSMITTER WITH INDICATOR |
| | BELLOWS VALVE | | BARRIER | | DIFF. PRESSURE SWITCH |
| | RELIEF VALVE | | PLUG | | DIFF. PRESSURE INDICATOR |
| | FIVE WAYS MANIFOLD | | REDUCER | | THERMOCOUPLE |
| | TWO WAYS MANIFOLD | | GENERATOR CONTROL AND PROTECTION RELAY PANEL | | TEMPERATURE ELEMENT |
| | SOLENOID VALVE | | GAS TURBINE CONTROL SYSTEM | | |
| | GLOBE VALVE | | FLOW SIGHT GLASS | | |

CHARACTER


| SYMBOL | No. | RANGE | SET VALUE | SYMBOL | No. | RANGE | SET VALUE | SYMBOL | No. | SET VALUE |
|--------|--------------|-----------|-----------|--------|---------------|-------------------|------------------|---------|----------|---------------------|
| PI | 1 | 0~10 barg | - | TIS | 1 | 0~100 °C | 60 °C | LS | 1 | 450 cm ³ |
| | 2 | 0~10 barg | - | | 2 | 0~100 °C | 60 °C | | 2 | 450 cm ³ |
| | 3 | 0~25 mbar | - | LI | 1 | -120mm~+120mm | - | | 3 | NL+100mm |
| 4 | -1~0~15 barg | - | 2 | | -120mm~+120mm | - | 4 | | NL-100mm | |
| TI | 1 | 0~15 barg | - | DPTI | 1 | 0~2 bar / 4~20 mA | - | | 5 | NL+100mm |
| | 2 | 0~10 barg | - | | 2 | TYPE-E | - | | 6 | NL-100mm |
| | 3 | 0~6 barg | - | | DPS | 1 | 0.45 bar (NOTE7) | - | 1 | 0.45 bar |
| 4 | 0~1 barg | - | 2 | TYPE-E | | - | 2 | 0.5 bar | | |
| 5 | 0~15 barg | - | 3 | TYPE-E | | - | 3 | 0.5 bar | | |
| PS | 1 | 0~100 °C | - | TC | 1 | 0~100 °C | P1100Q at 0°C | RV-1 | 1 | 9.5 barg |
| | 2 | 0~100 °C | - | | 2 | 0~100 °C | - | | 2 | 11.5 barg |
| | 3 | 0~100 °C | - | DPI | 1 | 0~1 bar | - | | | |
| | | | 2 | | 0~1 bar | - | | | | |

ALARMS

| | | |
|----|--|--------------------------------------|
| 1T | GEN. DRAIN OIL LEVEL (TURB. SIDE) | HIGH (≥ 450 cm ³) |
| 1S | GEN. DRAIN OIL LEVEL (SLIP. SIDE) | HIGH (≥ 450 cm ³) |
| 2 | GEN. SEAL OIL DIFF. PRESS. | LOW (≤ 0.45 bar) |
| | -EMERGENCY SEAL OIL PUMP RUNNING | |
| | -TURNING STARTING INTERLOCK | |
| 3 | GEN. SEAL OIL DIFF. PRESS. | HIGH (≥ 1.5 bar MORE THAN 5 SECONDS) |
| 4 | GEN. SEAL OIL PUMP OUTLET PRESS. | LOW (≤ 8 barg) |
| | -EMERGENCY SEAL OIL PUMP RUNNING | |
| 5H | GEN. DRAIN REGULATOR OIL LEVEL | HIGH (≥ NL+100 mm) |
| 5L | GEN. DRAIN REGULATOR OIL LEVEL | LOW (≤ NL-100 mm) |
| 6H | GEN. SEAL OIL VACUUM TANK OIL LEVEL | HIGH (≥ NL+100 mm) |
| | -SEAL OIL VACUUM PUMP STOP INTER LOCK | |
| 6L | GEN. SEAL OIL VACUUM TANK OIL LEVEL | LOW (≤ NL-100 mm) |
| 7 | GEN. SEAL OIL SUPPLY TEMP. | HIGH (≥ 60°C) |
| 8 | GEN. SEAL OIL FILTER DIFF.PRESS. | HIGH (≥ 0.5 bar) |
| 9 | GEN. GLAND SEAL FLOAT OIL FILTER DIFF.PRESS. | HIGH (≥ 0.5 bar) |

- NOTES**
- ALL PIPING MATERIAL SUPPLIED BY MELCO (IN THIS DRAWING) IS STPT EXCEPT OTHERWISE NOTED. PIPING INSIDE EQUIPMENTS WILL BE SELECTED IN ACCORDANCE WITH MANUFACTURER'S STANDARD.
 - STPT...STPT370-S CARBON STEEL PIPES FOR HIGH TEMPERATURE SERVICE (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3456.
 - SCH NO IS 40 EXCEPT OTHERWISE NOTED.
 - SUS...SUS304TP-S STAINLESS STEEL PIPES (SEAMLESS) CONFORMING TO JAPANESE INDUSTRIAL STANDARD JIS G3459.
 - SCH NO IS 40 EXCEPT OTHERWISE NOTED.
 - TERMINAL POINTS BETWEEN EPC AND MELCO ARE BASED ON ANSI STANDARD. TERMINAL POINTS BETWEEN MHI AND MELCO ARE BASED ON ANSI STANDARD.
 - SCOPE OF SUPPLY SHOWN IN THIS DRAWING IS AS FOLLOWS.
 - (EPC) | (MELCO) | (MHI) | (MELCO)
 - SUPPLIED BY EPC | SUPPLIED BY MELCO | SUPPLIED BY MHI | SUPPLIED BY MELCO
 - ALL PIPES SHALL BE LAID WITH GRADIENT OF MORE THAN 1/50 TO PREVENT ACCUMULATION OF OIL OR MAKING AIR POCKET IN THE PIPES.
 - THE SCREEN FOR GENERATOR MAIN BEARING TEMPORARY OIL STRAINERS ARE USED AT FLUSHING AND SHALL BE TAKEN AWAY IN GENERATOR RUNNING. STRAINER MATERIAL SHALL BE STAINLESS STEEL.
 - VENT DIRECTION OF GENERATOR LOOP SEAL TANK SHALL BE TOWARD TO THE SAFE AREA SUCH AS NO PASSAGEWAY, NO ELECTRICAL EQUIPMENT, AND SO ON.
 - VENT POINT OF GENERATOR LOOP SEAL TANK SHALL BE MORE THAN 2m ABOVE ROOF.
 - VENT POINT OF GENERATOR LOOP SEAL TANK SHALL BE AS FAR AS POSSIBLE FROM AIR INTAKE OF GAS TURBINE.
 - DIFF. PRESS. BETWEEN SEAL OIL AND GAS AT SEAL RING 0.35bar + DIFF. ELEVATION HEAD BETWEEN SEAL OIL SIDE AND GAS SIDE 0.01MPa = 0.45bar

FOR APPROVAL



Employer: **snowyhydro LIMITED**

Supplier: **MITSUBISHI ELECTRIC**

Employer's DWG Number: **HPP-MEL-MEC-OS-GEN-DRG-0001**

COMPANY PROPRIETARY NOT TO BE REPRODUCED OR DISCLOSED WITHOUT SPECIFIC WRITTEN PERMISSION OF MITSUBISHI ELECTRIC CORPORATION

出図先 ()

MITSUBISHI ELECTRIC CORPORATION

作成日 DATE: 2021-12-10

作成 DRAWN: R.Goto, R.Mun

チェック CHECKED: T.Ewara, N.Hanawa

設計 DESIGNED: K.Hanawa

承認 APPROVED: T. Otsuda

Hunter Power Project

TITLE: GENERATOR SEAL OIL DIAGRAM FOR GT

DWG.NO: A13C870

変更 CHANGE: CAY6-03

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 8 of 13 |

Appendix 2: Study records

Note on study records

Column 4 'Likelihood' and column 5 'Severity' represent the possibility and consequence of a hazard without taken credit for the safety protection layer (SPL).

Column 8 'Likelihood with SPL' and column 9 'Severity with SPL' represent the possibility and consequence of a hazard taken credit for the correct operation of the SPL. The consequence remains the same, only the frequency is modified.

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|-------------------------------------|--------------------------------|------------|-------------|--------------|---------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 1 - Fuel Oil - High pressure Pump Dwg A-21045 - Fuel oil system 5 of 5 | | | | | | | | | | | |
| Pressure High | FO forwarding pump deadhead | FO release | Certain | Negligible | Low | | Rare | Minor | Low | 1 MPA line rating, supply side | 1. Confirm forwarding pump deadhead pressure and prv |
| | FO blocked in thermal expansion | FO release | Unlikely | Minor | Low | | Unlikely | Minor | Low | 1 MPA line rating, supply side | 2. Review bunding requirements around FO pumps |
| | Blocked filter | Unit trip - loss of production | Unlikely | Minor | Low | PS MBN12CP211 | Unlikely | Minor | Low | Duplex filter with manual change over | 3. Confirm \$ cost per unit trip / 1 hr outage |
| Pressure Low | No forwarding supply / AC power out | Unit trip - loss of production | Unlikely | Minor | Low | PS MBN12CP211 | Unlikely | Minor | Low | | 4. All ball valves to be lockable 5. SHL to review who supplies instrumentation at MHI interfaces |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Forwarding pipework designed for 50 C. Locked Open MBN12AA124 | |
| Temperature Low | Ambient temperature | Unit fail to start | Possible | Minor | Medium | | Possible | Minor | Medium | Increased viscosity, low flow high pressure. Combustion problem potential. Design -5 C, site has experience -6 C. 11 C | 6. AECOM to consider heat tracing for FO dwg 2of 5. Start up temperature should be 11 deg C. Alternative may be an enclosure for the pump and piping |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | Manual valves out of position | | | | | | | | | Lockable valves | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | Winding temperatures are monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------------|--------------------------------|------------|-------------|--------------|---------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 2 - Fuel Oil - Manifold pressure control Dwg A-21042 - Fuel oil system 2 of 5 | | | | | | | | | | | |
| Pressure High | BPCS - Control loop failure | | | | | | | | | Flow control valves, would compensate | |
| Pressure Low | BPCS - Control loop failure | Unit trip - loss of production | Unlikely | Minor | Low | PT MBN12CP118, MBN12CP119 | Unlikely | Minor | Low | | |
| Pressure No or not | BPCS - Instrument failure | Unit trip - loss of production | Unlikely | Minor | Low | | Unlikely | Minor | Low | MHI to check logic | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | Rare | Minor | Low | | Rare | Minor | Low | | |
| Temperature Low | | | | | | | | | | Refer pump node. Screw pump | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Control loop failure | Unit trip - loss of production | Unlikely | Minor | Low | PT MBN12CP118, MBN12CP119 | Unlikely | Minor | Low | | |
| Flow / Level - Low | | | | | | | | | | | 7. The screw pump has no min flow bypass return line. The HP pump only starts when burners are to be lit. When no burner flow the manifold pressure control valve acts as the min flow control. MHI to confirm forwarding pump flow rate through HP screw pump when shutdown |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other than - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | MHI to check if forwarding pumps can recirculate through the screw pump. FYI only | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|-----------------------------------|---|------------|-------------|--------------|-------------------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 3 - Fuel Oil - Pilot flow control Dwg A-21042 - Fuel oil system 2 of 5 | | | | | | | | | | | |
| Pressure High | BPCS - Control loop failure | Excessive start fuel, machine damage, exh temp hi hi, overspeed | Unlikely | Major | Medium | Blade path temperature | Rare | Minor | Low | | |
| | | | | | | Overspeed protection | | | | | |
| | | Excessive start fuel, machine damage, exh temp hi hi | Unlikely | Minor | Low | PDIT MBN12CP521 MBN12CP522 | Rare | Minor | Low | Not large enough to create catastrophic failure | |
| Pressure Low | BPCS - Control loop failure | Unit trip - loss of production | Unlikely | Minor | Low | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | Ambient temperature | Unit fail to start | Possible | Minor | Medium | | Possible | Minor | Medium | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Same as high pressure | |
| Flow / Level - Low | | | | | | | | | | Same as low pressure | |
| Flow / Level - No or not | | | | | | | | | | Can lose 1, both = trip | |
| Flow / Level - Reverse | Loss of purge air when gas firing | Nozzle over temp, maintenance cost minor | Unlikely | Minor | Low | Limit switch alarm | Rare | Minor | Low | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Same as high pressure | |
| Utility failure - instr. air / oil / power | | Unit trip - loss of production | Unlikely | Minor | Low | | Unlikely | Minor | Low | Instant fail close | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------------------|---|------------|-------------|--------------|-------------------------------|---------------------|----------------------|-----------------------|--|---------|
| NODE No. 4 - Fuel Oil - Main flow control Dwg A-21042 - Fuel oil system 2 of 5 | | | | | | | | | | | |
| Pressure High | BPCS - Control loop failure | Excessive start fuel, machine damage, exh temp hi hi, overspeed | UnLikely | Severe | High | Blade path temperature | Rare | Severe | Medium | Compressor surge, only on run up, not on over fuelling | |
| Pressure Low | BPCS - Control loop failure | Excessive start fuel, machine damage, exh temp hi hi | UnLikely | Minor | Low | PDIT MBN12CP521 MBN12CP522 | Rare | Minor | Low | | |
| Pressure No or not | BPCS - Control loop failure | Unit trip - loss of production | UnLikely | Minor | Low | | UnLikely | Minor | Low | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | Ambient temperature | Unit fail to start | Possible | Minor | Medium | | Possible | Minor | Medium | | |
| Flow / Level - High | | | | | | Overspeed protection | | | | Same as high pressure | |
| Flow / Level - Low | | | | | | | | | | Same as high pressure | |
| Flow / Level - No or not | | | | | | | | | | Same as low pressure | |
| Flow / Level - Reverse | | | | | | | | | | Can lose 1, both = trip | |
| Vibration - High Low or not | Loss of purge air when gas firing | Nozzle over temp, maintenance cost minor | UnLikely | Minor | Low | Limit switch alarm | Rare | Minor | Low | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Slow response on fouling / varnish common problem with E/H. Valve position is monitored, alarms and trips unit | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Same as high pressure | |
| Volts / Amps High | | Unit trip - loss of production | UnLikely | Minor | Low | | UnLikely | Minor | Low | Instant fail close | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--|--------------------------------|------------|-------------|--------------|------------------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 5 - Fuel Oil - Flow divider Dwg A-21043 - Fuel oil system 3 of 5 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | MBN13BR310 out of position on start up | Unit trip - loss of production | UnLikely | Minor | Low | Blade path temperature | UnLikely | Minor | Low | | |
| | MBN13AA901 out of position, drain valves | | | | | | | | | All manual ball valves to be lockable | 8. MHI manual ball valves should all be lockable type, i.e. flow divider drain valves. SHL to discuss requirements with MHI |
| Pressure No or not | | | | | | | | | | Flow divider has no speed indication but has never shown to be a problem. Would be fail to start scenario | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Flow is controlled before divider. Divider just splits it into 20 equal streams | |
| Flow / Level - Low | | | | | | | | | | Same as low pressure | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Air ingress not considered possible | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Slow fail to start | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Fail open valves. Confirm limit switches qty | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------------|---|------------|-------------|--------------|-------------------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 6 - Fuel Oil - Burners Dwg A-21044 - Fuel oil system 4 of 5 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Refer high flow | |
| Pressure Low | | | | | | | | | | Refer low flow | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS - Control loop failure | Exhaust gas temp Hi Hi - machine damage | Unlikely | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| Temperature Low | Flame out | Flame out, potential reignition explosion | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Control loop failure | Exhaust gas temp Hi Hi - machine damage | Unlikely | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| Flow / Level - Low | Flame out | Flame out, potential reignition explosion | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | No flame detectors only blade path temperature. New improved design | 9. Pantac to review blade path flameout voting logic. One or multiple burners, adjacent burners, single or duplex t/c. No optical flame detectors |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | Refer purge air, low consequence | |
| Vibration - High Low or not | High frequency combustion | Machine damage - burner tubes | Possible | Major | High | Combustion pressure monitoring trip | Unlikely | Major | Medium | Combustion humming sensors, high frequency combustion will trip the unit. Low frequency is monitored. Is humming more serious for gas fuel? | 10. MHI to advise combustion frequency sensor criticality. Commissioning tool or protection |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | No history of fuel quality minerals, silica's causing problems at Colongra. Diesel run times expected to be quite short, insufficient to see major damage to first stage buckets | 11. SHL investigating additional diesel fuel quality reports |
| Timing / Sequence - Early / Late | | | | | | | | | | No purge precombustion as part of the run up. | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|--|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 7 - Fuel Oil - Drain tank Dwg A-21045 - Fuel oil system 5 of 5 | | | | | | | | | | | |
| Pressure High | Potential oil surge from oil to drain volume / velocity | Backflow through atmospheric vent, oil escapes | | | | | | | | Overflow open to atmosphere and pit. Backflow unlikely with 15 m tall vent line | |
| Pressure Low | | | | | | | | | | Overflow open to atmosphere and pit | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | Overflow open to atmosphere and pit | |
| Temperature High | | | | | | | | | | Diesel fuel may be heat traced but not considered a hazard, 60 Deg C max, design 80 C. Typical operation 10 - 20 C | |
| Temperature Low | | | | | | | | | | Minus 6 C is the lowest temp on site recorded. Tank is gravity fed, so low or below ground level | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Level control failure | Potential overflow to oily water system | Possible | Negligible | Low | | Possible | Negligible | Low | MBN13AA701 FO Pilot drain valve is fail closed valves and if fail open, unit would fail to start. Drain tank bund drains to oil drain pit | 12. MHI to confirm if there is a drain tank Hi level start permissive. Unit wont start with high level |
| Flow / Level - Low | BPCS - Level control failure | Pump runs dry, damage pump | Possible | Negligible | Low | | Possible | Negligible | Low | | |
| Flow / Level - No or not | | | | | | | | | | Loss of LT = no pump start | |
| Flow / Level - Reverse | | | | | | | | | | Refer high pressure, vent height. Double check valves to prevent return flow into drain tank. Forwarding pumps and tank head upstream pressure | 13. SHL to confirm with operations to see if small lines have been problematic with non-return valves failing / passing pressure |
| Vibration - High Low or not | | | | | | | | | | | 14. AECOM to consider drain pit discharge hi alarm to start pump and hi hi to alarm to remote operations |
| As well as - concentration / two phase | | | | | | | | | | Oily water minor issue | 15. AECOM Fuel oil discharge to oily water pit detection to be considered in design |
| Other then - impurities / contamination | | | | | | | | | | Pump has strainer on inlet | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------------|--------------------------|------------|-------------|--------------|-------------------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 8 - Fuel Oil - Water injection Dwg A-21043 - Fuel oil system 3 of 5 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Designed accordingly | |
| Pressure Low | BPCS - Flow control | Emissions / run back | Possible | Negligible | Low | | Possible | Negligible | Low | | 16. MHI to confirm at what load level water injection is enabled. Also when water injection is not correct the unit would go to run back load, where water injection is turned off. |
| Pressure Low | BPCS - Flow control | Emissions / run back | Possible | Negligible | Low | | Possible | Negligible | Low | | 17. SHL to confirm action required when water injection is off, i.e. valley will try to restart water injection 3 times and max operating time without water injection is 15 minutes. Automatic shutdown required, tbc and advise to MHI or add into station controls |
| Pressure Low | BPCS - Flow control | Emissions / run back | Possible | Negligible | Low | | Possible | Negligible | Low | | 18. Oily water pit to be covered with rain shelter |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | Low ambient temperature | Emissions / run back | Possible | Negligible | Low | | Possible | Negligible | Low | Existing item for AECOM, is water piping lagging required | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Flow control | Emissions / run back | Possible | Negligible | Low | | Possible | Negligible | Low | | |
| Flow / Level - High | Drain valve out of position | Emissions / run back | Possible | Negligible | Low | | Possible | Negligible | Low | Oily water drain pit design not completed yet | |
| Flow / Level - High | Drain valve out of position | Oily water pit over flow | Possible | Minor | Medium | | Possible | Minor | Medium | Oily water drain pit design not completed yet | 19. AECOM to consider valve failure, excessive flow to oily water pit overflow during runback time. Flow balance required. MHI to advise oily water flow rate and volumes expected during normal operating conditions and if one of the drain valves fails open, MBN13AA735,AA736,AA737 based on SHL RFI document |
| Flow / Level - Low | | | | | | | | | | Same as low pressure | 20. Water injection flow transmitter is a single point of failure which would cause diesel outage, so it is critical for operation. Redundancy for valve control per fuel oil control should be considered. MBU02CP531. |
| Flow / Level - No or not | BPCS - Instrument failure | Loss of production | Possible | Minor | Medium | | Possible | Minor | Medium | Same as low pressure. Run back to preload at 50% production loss and then shutdown after 15 minutes (tbc) | 21. Single point of failure mode analysis should be completed at a suitable time. SHL internal item |
| Flow / Level - No or not | BPCS - Instrument failure | Loss of production | Possible | Minor | Medium | | Possible | Minor | Medium | | 22. Outage, run back, emergency trip restart time cost analysis required for Risk Assessment decision around device fault tolerance, i.e. trip or 1 hours outage = 800k, additional instrument = 10k installed |
| Flow / Level - Reverse | | | | | | | | | | There is no check valve on the HP WI pump outlet. There would be have to be a triple failure before fuel oil could flow back into the demin system | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | Overwatering metal quenching, unlikely event and no history. Would cause run back | |
| Timing / Sequence - Fast / Slow | BPCS - Valve position | Emissions / run back | Possible | Negligible | Low | Combustion pressure monitoring trip | Rare | Negligible | Low | Potential for flame out during commissioning tuning but unlikely after plant commissioned unless valve position control fails | |
| Utility failure - instr. air / oil / power | | | | | | | | | | All valves fail closed. Trouble would cause run back | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 9 - Fuel Oil - Purge credit block valves Dwg A-21046 - Fuel oil purge credit system | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Every thing designed fit for purpose. Purge credit saves 5 minutes start up time. Purge credit based on normal scheduled shutdown and limited to a fixed time. | 23. Purge credit details are not well understood by Operations. There is a manual, Operating Procedure(S4-96597), that describes it in more detail. Type B compliance, intermittent or continuous turning and start and re-purge credit are all good questions. Potentially every 8 days the unit needs repurging, which can lead to more blade wear (wobbling in root) and starter problems. This item to be revisited by Operations with MHI detail input. |
| Pressure Low | Loss of purge medium | 5 minutes additional start time | Possible | Negligible | Low | | Possible | Negligible | Low | | |
| Pressure No or not | BPCS - Instrument failure | Loss of purge credit | Possible | Negligible | Low | | Possible | Negligible | Low | Do we need the N2 vent valve QJA05AA714 ? Standard MHI design based on AS3814 | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Fit for purpose pipeline application | |
| Temperature Low | | | | | | | | | | Ambient limit minus 6 C | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | FO Drain valve out of position will flow to pit | Potential overflow to oily water system | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | | 24. MHI to review if fuel oil from the fuel oil purge credit can go to the tank not the pit as it is clean fuel. Environmental credit |
| | N2 vent valve out of position will flow to atmosphere | Extra N2 consumption | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | | 25. Fuel oil purge credit valves only have a single limit switch, preference for both open and closed indication, all valves (block, drain, N2). AECOM supply these valves |
| Flow / Level - Low | BPSC - Valve out of position | Fail to start - Loss of production | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | | |
| | | Loss of purge credit - Loss of production | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | A small plug of purge credit air and N2 will be entrained in the fuel oil feed but this is not a problem | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | Covered in low flow, negligible impacts | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Valves fail to run strategy. No safety concerns, just loss of purge credit | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--|--|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|---|--|
| NODE No. 10 - Fuel Gas - Supply Dwg A-21061 - Fuel gas system 1 of 7 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | This node was covered by AECOM hazop as they are supplying this system. HAZOP report to be reviewed by this team on Day 3 | |
| NODE No. 11 - Fuel Gas - Supply pressure control Dwg A-21062 - Fuel gas system 2 of 7 | | | | | | | | | | | |
| Pressure High | APA gas yard failure | Potential loss of containment, explosion | Rare | Major | Medium | 2003 High pressure trip and 5 block valves in series | Rare | Major | Medium | Service air supply 5.7 Bar, regulated further downstream. Multiple PRVs also | |
| Pressure Low | APA gas yard failure | Loss of production | Unlikely | Negligible | Low | 2003 Low pressure trip and 5 block valves in series | Unlikely | Negligible | Low | APA gas yard has the WBHs and pressure regs. 4.4 MPA supply | |
| Pressure No or not | | | | | | | | | | Redundant transmitters | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | Heater change over valve failure leading to combustion instability | Loss of production | Unlikely | Negligible | Low | 2003 High temperature trip and 5 block valves in series | Rare | Negligible | Low | AECOM hazop suggest it is possible on part load based on 220 C setpoint. Control valve fail mode to heater | |
| Temperature Low | Heater change over valve failure leading to combustion instability | Loss of efficiency, loss of production, run back | Unlikely | Negligible | Low | Combustion pressure monitoring trip | Unlikely | Negligible | Low | Run back on low temp | |
| Temperature - No or not | 2003 sensor unlikely | | | | | | | | | | |
| Flow / Level - High | Vent valve out of position | Potential gas cloud explosion, environmental release | Unlikely | Moderate | Medium | Vent valve position trip | Rare | Moderate | Low | | 26. MHI to check logic. Gas vent valve out of position during operation should be a trip. Redundant limit switches may be. |
| Flow / Level - Low | | | | | | | | | | The 2 x 100% coalescer has double block and bleed for maintenance but AS3814 needs an isolation valve close to the unit | 27. AECOM should review vent valve position failure actions |
| Flow / Level - No or not | | | | | | | | | | | 28. AECOM to review appliance manual isolation valve per AS3814 requirements within 5m of the appliance. Paul van Dyk to confirm AS3814 clause requirements |
| Flow / Level - Reverse | QEF14AA703 seal failure or incorrect position when gas firing | Excessive gas venting | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Colongra pressure / integrity test valves every 4years. Valley test unit valves annually. Odorised gas, small leak may be able to be detected. Large leak audible | 29. Tapping points for pressure testing / leak testing valves not shown on P&ID. Additional testing points may be required. SHL to review based on length of pipework and valve locations. |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | Vents closed before blocks opened. Purge closed before gas opened. Confirm timings during SAT (No FAT). | 30. MHI to review AS3814 section 2.13 requirement for sufficient test points to verify the integrity of shutoff valve / train. |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Potential for small gas vent time | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Failsafe design. All valves fail to safe position | |
| Volts / Amps High | | | | | | | | | | 24VDC control voltage. DC-ve grounded system | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|--|---|
| NODE No. 12 - Fuel Gas - Flow control Dwg A-21063 - Fuel gas system 3 of 7 | | | | | | | | | | | |
| Pressure High | BPCS - Valve position or DPT flow meter | Excessive start fuel, machine damage, exh temp hi hi, overspeed | Unlikely | Major | Medium | Gas control valve position trip Blade path temperature | Rare | Moderate | Low | Overfueling on start up / light off Overfueling on start up / light off, potential for duct explosion, ignition time 10 seconds. For the purpose of the HAZOP the main question is there a single point of failure and what would be consequence of a critical time pressure excursion / explosion. Multiple burner lines, pilot gas is the smallest but lights off with Main A as well. MHI think over fuelling on start up is not realistic possibility with 1 out of 4 fuel lines and blade path temp trip. The light off is based on a fixed valve position. The DPT sensor is protection for the dual redundant valve position error (tbc). Any position error the unit will trip. | 31. RFI for the purpose of the HAZOP the main question, is there a single point of failure (DPT) and what would be consequence of a critical time pressure excursion explosion. Is DPT control or protection, refer control description fig 2.9.1 |
| Pressure Low | BPCS - Control loop failure | Loss of production | Unlikely | Negligible | Low | Blade path temperature | | | | Fail to start of slow acceleration | |
| Pressure No or not | | | | | | | | | | Fuel control drift from setpoint for Main A Main B or Tophat was discussed and would eventually lead to combustion humming trip | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | 2oo3 High gas temperature trip | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Same as high pressure | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | Unit will trip on hi or low DPT signal | |
| Flow / Level - Reverse | | | | | | | | | | Not possible normally but if gas pilot control valve not shut tight some hot sweep air may enter manifold and potential for condensate. Considered immaterial | |
| Vibration - High Low or not | | | | | | | | | | Pigtail tube connections to burners take up vibration / expansion requirements, refer next node dwg 4 of 7 | |
| As well as - concentration / two phase | | | | | | | | | | MHI have provided fuel spec requirements. On top of APA knockout pot, AECOM also provide additional filter the fuel. | |
| Other then - impurities / contamination | Ambient air condensation possible as units mostly not operating. Stainless steel pipes and heated gas | | | | | | | | | Pigging part of APA scope. MHI also have last chance filter. | |
| Timing / Sequence - Early / Late | | | | | | | | | | Same as high and low pressure | |
| Timing / Sequence - Fast / Slow | | | | | | Overspeed protection | Rare | Major | Medium | Potential for overspeed if slow control or fail to start both have protection | |
| Utility failure - instr. air / oil / power | Fail close valve | Loss of production | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|-----------------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 13 - Fuel Gas - Pilot and Main B burners Dwg A-21064 - Fuel gas system 4 of 7 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Similar to preceding node | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | MBP03CP126 only monitoring manifold pressure. Failure alarm only | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | Shutdown normal operation | | | | | | | | | Designed accordingly, heat dissipates through pigtail connections | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | Possible welding debris, construction materials | Foreign object damage | Unlikely | Major | Medium | | Rare | Major | Medium | Commissioning filter skid temporary installation to collect any construction debris | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|--|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 14 - Fuel Gas - Top Hat and Main A burners Dwg A-21065 - Fuel gas system 5 of 7 | | | | | | | | | | | |
| Pressure High | Combustion problems | | | | | Blade path temperature | | | | Refer preceding nodes. | |
| Pressure Low | Instrument air supply fault | Fail to start - Loss of production | Unlikely | Negligible | Low | Blade path temperature | Rare | Negligible | Low | Igniter extraction fails, spring return | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS - Control loop failure | Potential reduced blade life | Unlikely | Negligible | Low | 2oo3 High temperature trip and 5 block valves in series Blade path temperature Exhaust gas pressure Hi Hi trip | Rare | Negligible | Low | Normally on MW control, blade path and exhaust temp trips | |
| Temperature Low | Flame out | Loss of production | Unlikely | Negligible | Low | Blade path temperature | Rare | Negligible | Low | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Refer flow control nodes | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | BPCS - control loop leading to combustion instability | Potential corn cob of power turbine from stressed combustion components (burners, buckets) | Unlikely | Severe | High | Combustion pressure monitoring trip | Rare | Severe | Medium | Too lean high frequency, too rich low frequency. Blades will be contained within casing | |
| Vibration - High Low or not | Rotor out of balance | Bearing damage | Unlikely | Major | Medium | Rotor vibration hi hi trip | Rare | Moderate | Low | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | Commissioning filter skid temporary installation to collect any construction debris | |
| Timing / Sequence - Early / Late | Fail to ignite | Loss of production | Possible | Negligible | Low | Blade path temperature | Possible | Negligible | Low | Trip prevent more serious consequence | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | Fail to ignite | Loss of production | Possible | Negligible | Low | Blade path temperature | Possible | Negligible | Low | Loss of ignition worst case scenario | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|------------------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 15 - Fuel Gas - Combustor drain valves Dwg A-21066 - Fuel gas system 6 of 7 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | normal flow 0.1 nmch. If both valves failed to open could potentially to flashing off the diesel but normal operation is < 60 Celsius | 32. MHI to confirm temperature rating of pipework after MBA01AA704, burner drain valve. Rating drops from 525 to 60 Celsius |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | Operator error fail to drain water wash liquid from combustor section | Loss of production - fail to ignite and potential for quenching and detergent to oily water pit | Possible | Negligible | Low | Blade path temperature | Possible | Negligible | Low | Operator error could overfill the combustion section? Also has happened with failed heat exchanger tube. If operator fails to open MBA01AA931 detergent could enter oily pit, as the unit fails to start and then automatically opens the drain valves. | 33. Water wash procedure has many manual valves which could potentially lead to false start by flooded combustion chamber and subsequently detergent flow into the oil water pit. SHL to develop a water wash procedure with 2 operators to cross check. Water washing drain header could also have small amounts of diesel residue from liquid fuel false start. |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | same scenario as high flow | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Water wash oily water separator pit contains detergents, diesel and demin water | |
| Other then - impurities / contamination | | | | | | | | | | Demin water with potential for fuel | |
| Timing / Sequence - Early / Late | | | | | | | | | | refer above | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | Drain valve open position is a start permissive | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|-----------------------------|---|------------|-------------|--------------|-------------------------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 16 - Fuel Gas - Burners Dwg A-21066 - Fuel gas system 6 of 7 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | NODE 16 SAME AS OIL BURNER NODE 6 | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS - Control loop failure | Exhaust gas temp Hi Hi - machine damage | Unlikely | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| Temperature Low | Flame out | Flame out, potential reignition explosion | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Control loop failure | Exhaust gas temp Hi Hi - machine damage | Unlikely | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| Flow / Level - Low | Flame out | Flame out, potential reignition explosion | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | No flame detectors only blade path temperature. New improved design | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | Refer purge air, low consequence | |
| Vibration - High Low or not | High frequency combustion | Machine damage - burner tubes | Possible | Major | High | Combustion pressure monitoring trip | Unlikely | Major | Medium | Combustion humming sensors, high frequency combustion will trip the unit. Low frequency is monitored. Is humming more serious for gas fuel? | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other than - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | No purge precombustion as part of the run up. | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|---|--|
| NODE No. 17 - Fuel Gas - GT sweep (purge air) Dwg A-21067 - Fuel gas system 7 of 7 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | CPD recirculated through the burner | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | Check valve may not be gas tight | Potential flash back, combustion problem but only at full load | Rare | Negligible | Low | Fuel transfer limited to part load | Rare | Negligible | Low | Potential for air gas in pipe at close to auto ignition at full load therefore fuel transfer is limited to part load | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | MBH05AA712 vent valve out of position | Combustion problems unlikely, coking potential | Unlikely | Negligible | Low | Blade path temperature | Rare | Negligible | Low | Sweep air venting, potential for nozzle coking Alarm only, does not inhibit liquid firing | |
| Flow / Level - Low | MBH05AA711 or AA713 fail to open, valve out of position | Combustion problems unlikely, coking potential | Unlikely | Negligible | Low | Blade path temperature | Rare | Negligible | Low | Sweep air blocked, potential for nozzle coking Alarm only, does not inhibit liquid firing. Valves fitted with multiple limit switches | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | Check valve may not be gas tight and AA713 not closed | Potential for auto ignition in pipework at full load but this is not considered possible with the vent open to the atmosphere | Unlikely | Major | Medium | Sweep air block valve out of position auto shutdown | Rare | Major | Medium | AA711 or AA713 out of position is a shutdown, 2oo3 limit switches | 30. MHI to review AS3814 section 2.13 requirement for sufficient test points to verify the integrity of shutoff valve / train. |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Refer reverse flow auto ignition scenario | |
| Other then - impurities / contamination | Potential coke from burners or products of combustion condensation, negligible impact | | | | | | | | | Self draining lines | |
| Timing / Sequence - Early / Late | | | | | | | | | | Refer reverse flow auto ignition scenario | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|-----------------------------|---------------------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 18 - Fuel Gas - Flow meter Dwg A-21068 - Fuel gas flow meter | | | | | | | | | | | |
| Pressure High | | | | | | | | | | APA regulated supply | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | MBP01CP101 failure | Loss of flow compensation | UnLikely | Negligible | Low | | UnLikely | Negligible | Low | Just monitoring and alarm | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Flow meter would be removed for construction pipe blow down | 34. Commissioning spool required for flow meter, that will need to be removed for pipe blow down activities. Mark up P&ID |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | Same as pressure, loss of monitoring only | |
| Flow / Level - Reverse | Venting prior to flow meter | No consequence | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------------|---|------------|-------------|--------------|--------------------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 19 - Fuel Gas - Filter and purge credit Dwg A-21069 - Fuel gas filter and purge credit system | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | Blocked filter | Potential low pressure flame out - loss of production | Unlikely | Negligible | Low | Filter dP alarm | Rare | Negligible | Low | | |
| Pressure No or not | BPCS - loop failure | Loss of purge credit | Unlikely | Negligible | Low | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Heater design limited | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Solenoid fail open | Excessive gas venting | Unlikely | Negligible | Low | Vent valve position trip | Rare | Negligible | Low | Annual inspection leak testing would pick up small leaks. Limit switch would pick up full open stuck | |
| Flow / Level - Low | Valve fails to open | Loss of purge credit | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Valve position alarms and start permissives | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | Possible if venting upstream | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other than - impurities / contamination | | | | | | | | | | APA and power island coalescers | |
| Timing / Sequence - Early / Late | | | | | | | | | | venting gas but designed to AS3814 vent close before block open? | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | AECOM HAZOP is considering additional N2 purge tapping point | 35. Add instrument tapping point for Nitrogen entry for valve leak testing, with smaller volume than upstream line |
| Utility failure - instr. air / oil / power | Instrument air supply fault | Loss of purge credit | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Valves fail to run strategy. No safety concerns, just loss of purge credit | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|------------------------|------------------------------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 20 - Fuel Gas - Calorie meter Dwg A-21070 & MYP127-DWG-002 - Fuel gas Calorie meter package | | | | | | | | | | | |
| Pressure High | | | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Multiple regs and relief on gas side but only single reg on cal gas bottles | 36. Calorie meter. 1. Cal gas bottles only have single regulator and no relief valve. Potential single point of failure. Is meter rated for cal gas pressure. 2. If reg fails, is it possible to reverse flow cal gas into the gas line? 3. Why is there a flow meter in the vent line? |
| Pressure Low | Regulator fails closed | Loss of combustion trim monitoring | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Used for combustion trim and combustion pressure fluctuation monitoring. Fails over to values read 30 seconds before to maintain operation on loss of instrument | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | Heated pressure reg in design | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | 1/4" valves only allows low flow rates | |
| Flow / Level - Low | | | | | | | | | | Same as low pressure | |
| Flow / Level - No or not | | | | | | | | | | Same as low pressure | |
| Flow / Level - Reverse | | | | | | | | | | Refer high pressure. | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | We are not considering Hydrogen although this may be incorporated at a later date | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Used for combustion trim and combustion pressure fluctuation monitoring. Fails over to values read 30 seconds before to maintain operation on loss of instrument | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--|--------------------------------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 21 - Air & Flue Gas - Seal air Dwg A-21081 - Air & Flue gas 1 of 5 | | | | | | | | | | | |
| Pressure High | Compressor surge | No experience with damage from surge | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Flow restricted with orifices. Sealing air used to contain oil in bearing and cooling casing | |
| Pressure Low | | | | | | | | | | Cyclonic filter cannot block and air from compressor is very clean | |
| Pressure No or not | BPCS - Instrument failure | | | | | | | | | Alarm only | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | Potential for condensation but no experience with adverse consequences | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Flow restricted with orifice | |
| Flow / Level - Low | | | | | | | | | | same as low pressure | 37. All ball valves to be lockable. Even to confirm who is responsible for providing the pad locking system for all the manual isolation valves and to ensure the valves have lock tabs, refer also action item 4. Also send sample photos to MHI. The requirement is in the tender specification section 2.3 |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | Condensation | | | | | | | | | Water wash into seal air system is knocked out by separator after cyclonic filter | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | BPCS - Instrument failure | | | | | | | | | Monitoring only | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|--------------------|------------|-------------|--------------|--------------------------------|---------------------|----------------------|-----------------------|--|---------|
| NODE No. 22 - Air & Flue Gas - GT LP Bleed valve Dwg A-21081 - Air & Flue gas 1 of 5 | | | | | | | | | | | |
| Pressure High | Valve, MBH01AA701, fails to open on shutdown | Compressor surge | Unlikely | Minor | Low | | Unlikely | Minor | Low | MHI to check with engineering to confirm how many surges a machine is likely to see before consequential damages, i.e.. Oil seals, filter house, blade failure, etc. MHI advise that it is scary for Operator but unlikely to result in damage | |
| Pressure Low | Valve fails to close on start up | Reduced capability | Unlikely | Negligible | Low | Valve out of position shutdown | Unlikely | Negligible | Low | 2oo3 closed limit switches | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Seal air prevent back flow | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Same as pressure. | |
| Flow / Level - Low | | | | | | | | | | Same as pressure. | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | Surge | | | | | | | | Refer pressure | |
| Timing / Sequence - Fast / Slow | | Surge | | | | | | | | Refer pressure | |
| Utility failure - instr. air / oil / power | Power or air failure | | Unlikely | Negligible | Low | Valve out of position shutdown | Unlikely | Negligible | Low | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------|-------------------------------------|------------|-------------|--------------|------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 23 - Air & Flue Gas - GT MP Bleed valve Dwg A-21082 - Air & Flue gas 2 of 5 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Surge same scenarios as LP. The following for cooling air flow control | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - valve position | Potentially reduced mechanical life | Unlikely | Negligible | Low | Start permissive | Rare | Negligible | Low | Valves close at full speed / load. Marginal concern, alarm only. Potentially long term consequences | |
| Flow / Level - Low | BPCS - valve position | Potentially reduced mechanical life | Unlikely | Negligible | Low | Start permissive | Rare | Negligible | Low | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---------------------------------|---|------------|-------------|--------------|--------------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 24 - Air & Flue Gas - GT HP Bleed valve Dwg A-21083 - Air & Flue gas 3 of 5 | | | | | | | | | | | |
| Pressure High | BPCS - valve position | Potentially reduced mechanical life | Unlikely | Negligible | Low | Start permissive | Rare | Negligible | Low | Same as MP surge scenario and heating control scenario | |
| Pressure High | Compressor surge | Potential mechanical damage | Unlikely | Negligible | Low | IGV out of position trip | Rare | Negligible | Low | Single surge events not considered catastrophic, refer node above. Dual redundant IGV position trip | |
| Pressure High | BPCS - IGV position fault | Combustion trouble or compressor surge or efficiency loss or fail to start high torque load on compressor | Unlikely | Negligible | Low | IGV out of position trip | Unlikely | Negligible | Low | IGV has mechanical minimum and maximum stop | |
| Pressure Low | BPCS - IGV position fault | Combustion trouble or compressor surge or efficiency loss or fail to start high torque load on compressor | Unlikely | Negligible | Low | IGV out of position trip | Unlikely | Negligible | Low | Inlet flow has no effect on combustion controls, it is only a long term diagnostic tool. Failure no consequence | |
| Pressure Low | BPCS - Bleed valve open | Loss of start permissive or reduced load | Unlikely | Negligible | Low | Valve out of position shutdown | Unlikely | Negligible | Low | | |
| Pressure No or not | | | | | | | | | | 2003 casing pressure transmitters | |
| Pressure Vacuum | | | | | | | | | | same as surge pressure high | |
| Temperature High | | | | | | | | | | Designed for site ambient conditions | |
| Temperature Low | | | | | | | | | | Designed for site ambient conditions | |
| Temperature - No or not | | | | | | | | | | 2003 inlet temp transmitters | |
| Flow / Level - High | BPCS - Bleed valve open | Loss of start permissive or reduced load | Unlikely | Negligible | Low | Valve out of position shutdown | Unlikely | Negligible | Low | | |
| Flow / Level - Low | BPCS - Bleed closed on shutdown | Surge | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Already shutdown, trip won't work | |
| Flow / Level - No or not | | | | | | | | | | Frozen filter house, refer that node | |
| Flow / Level - Reverse | | | | | | | | | | Refer compressor surge | |
| Vibration - High Low or not | Imbalance or FOB | Blade failure | Unlikely | Major | Medium | Shaft vibration Hi Hi trip | Rare | Major | Medium | | |
| As well as - concentration / two phase | | | | | | | | | | Designed for site ambient conditions. Water wash demin water and detergents | |
| Other then - impurities / contamination | | | | | | | | | | Bush fire covered in filter house node | |
| Timing / Sequence - Early / Late | | | | | | | | | | Refer pressure for IGV and bleed valve position fault | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Refer pressure for IGV and bleed valve position fault | |
| Utility failure - instr. air / oil / power | BPCS - power or oil fault | Surge on shutdown or combustion problems | Unlikely | Negligible | Low | IGV out of position trip | Rare | Negligible | Low | Bleed valves fail safe open. | 38. MHI to confirm failure mode of IGV, i.e. fail last position, fail ramp closed on loss of control oil or power? |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|---|------------|-------------|--------------|-----------------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 25 - Air & Flue Gas - Inlet duct flow Dwg A-21084 - Air & Flue gas 4 of 5 | | | | | | | | | | | |
| Pressure High | Duct back pressure or combustion problems | Bearing No 1 damage due to insufficient seal air pressure | Unlikely | Major | Medium | 2oo3 Exhaust pressure Hi Hi trip | Rare | Major | Medium | | |
| | | Stack damage potential | Rare | Major | Medium | | Rare | Major | Medium | More serious for HRSG application, not for open cycle. Possible silencer but remote for this application. | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | 2oo3 = run, 1oo2 = run alarm, 1oo1 = run alarm | 39. 2oo3 trip voting degradation to be reviewed on a trip by trip basis by SHL, 2oo3, 1oo2 or 2oo2 and 1oo1 = trip or run? |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS - control failure | Blade failure | Unlikely | Major | Medium | Blade path temperature | Rare | Major | Medium | Blade path are dual element thermocouples | 9. Pantac to review blade path flameout voting logic. One or multiple burners, adjacent burners, single or duplex t/c. No optical flame detectors |
| | | NooM Exhaust temp Hi Hi trip | | | | | Rare | Major | Medium | | |
| | | Exhaust gas temp Hi Hi - machine damage | Unlikely | Major | Medium | Blade path temperature | Rare | Major | Medium | | |
| | | Blade failure | Unlikely | Major | Medium | NooM Exhaust temp Hi Hi trip | Rare | Major | Medium | Blowdown line is normally closed. Commissioning pipe clean only | |
| Temperature Low | Flame out | Potential re-ignition and duct explosion | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | Same as fuel oil but probably less likely | |
| Temperature - No or not | | | | | | | | | | Loss of thermocouple signal is a trip. Voting to be confirmed. Dual element | |
| Flow / Level - High | Expansion joint failure | Potential for fire | Rare | Negligible | Low | | Rare | Negligible | Low | | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | Brg 1 vibration sensors are on air intake P&ID. Stack noise emissions are still being worked through by MHI and supplier for the site attenuation requirements | |
| As well as - concentration / two phase | Fail to ignite | Loss of production | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| As well as - concentration / two phase | Stack failure, blowing steel debris (bits of silencer, stack wall, ducts) into the yard. After many years of operation | Potential fatality | Rare | Severe | Medium | | Rare | Severe | Medium | Metal blown from stack has happened at many stations, most of them old except Laverton. > 30 years Hallett, Jeeralang, Somerton. MHI have not experienced any failures for this machine type yet | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | Loss of aviation control power | Compliance | Unlikely | Negligible | Low | DCS general electrical monitoring | Rare | Negligible | Low | Stack aviation lighting may be required. Stack design not finished yet. | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---------------------------------|--|------------|-------------|--------------|----------------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 26 - Air & Flue Gas - Air compressor Dwg A-21084 - Air & Flue gas 4 of 5 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | BPCS - valve control | Loss of production - Potential GT Rotor creep or rub, reduced component life | Unlikely | Minor | Low | Automatic Runback | Rare | Minor | Low | MBH05AA731 fails closed, so air always to rotor. No immediate consequences. Valve position alarm | |
| | | Rotor cooling labyrinth blockage over time | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Loss of dry purge air would potentially increase rotor casing corrosion through condensation. Normally starts 12 hours after shutdown. Carbon steel corrosion potential | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Same as low pressure for GT Rotor. All 3 cooler fans are required but spray water is not likely to be needed | |
| Temperature Low | | | | | | | | | | Not realistic | |
| Temperature - No or not | | | | | | | | | | MBH05CT002 just monitoring MBH05CT012/13 for fan control MBA01CT001/2 GT rotor temp, 1 can fail, 2nd fault = alarm only | |
| Flow / Level - High | | | | | | | | | | Same as high pressure | |
| Flow / Level - Low | | | | | | | | | | Same as low pressure | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | Cooling fan blade fault or loss | Motor bearing damage | Unlikely | Negligible | Low | Shaft vibration Hi Hi trip | Rare | Negligible | Low | Fan blades are enclosed cannot fly off | |
| As well as - concentration / two phase | | | | | | | | | | MBH05AA753 only open on start up and shutdown | |
| Other then - impurities / contamination | | | | | | | | | | Inlet filter house therefore clean air | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | Cooling fan motor fault | Loss of cooling | Unlikely | Minor | Low | Automatic Runback | Rare | Minor | Low | VSD Drive and bypass contactor. Details not apparent for HAZOP | |
| Volts / Amps Low | MCC fault | Loss of cooling | Unlikely | Minor | Low | Automatic Runback | Rare | Minor | Low | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|---|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|--|---|
| NODE No. 27 - Air & Flue Gas - Combustor and Exhaust Dwg A-21084 - Air & Flue gas 4 of 5 | | | | | | | | | | | |
| Pressure High | Duct back pressure or combustion problems | Bearing No 1 damage due to insufficient seal air pressure | Unlikely | Major | Medium | 2oo3 Exhaust pressure Hi Hi trip | Rare | Major | Medium | | |
| | | Stack damage potential | Rare | Major | Medium | | Rare | Major | Medium | More serious for HRSG application, not for open cycle. Possible silencer but remote for this application. | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | 2oo3 = run, 1oo2 = run alarm, 1oo1 = run alarm | 39. 2oo3 trip voting degradation to be reviewed on a trip by trip basis by SHL, 2oo3, 1oo2 or 2oo2 and 1oo1 = trip or run? |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS - control failure | Blade failure | Unlikely | Major | Medium | Blade path temperature NooM Exhaust temp Hi Hi trip | Rare | Major | Medium | Blade path are dual element thermocouples | 9. Pantac to review blade path flameout voting logic. One or multiple burners, adjacent burners, single or duplex t/c. No optical flame detectors |
| Temperature High | BPCS - control failure | Exhaust gas temp Hi Hi - machine damage | Unlikely | Major | Medium | Blade path temperature | Rare | Major | Medium | Blowdown line is normally closed. Commissioning pipe clean only | |
| Temperature Low | Flame out | Potential re-ignition and duct explosion | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | Same as fuel oil but probably less likely | |
| Temperature - No or not | | | | | | | | | | Loss of thermocouple signal is a trip. Voting to be confirmed. Dual element | |
| Flow / Level - High | Expansion joint failure | Potential for fire | Rare | Negligible | Low | | Rare | Negligible | Low | | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | Brg 1 vibration sensors are on air intake P&ID. Stack noise emissions are still being worked through by MHI and supplier for the site attenuation requirements | |
| As well as - concentration / two phase | Fail to ignite | Loss of production | Possible | Severe | High | Blade path temperature | Rare | Severe | Medium | | |
| As well as - concentration / two phase | Stack failure, blowing steel debris (bits of silencer, stack wall, ducts) into the yard. After many years of operation | Potential fatality | Rare | Severe | Medium | | Rare | Severe | Medium | Metal blown from stack has happened at many stations, most of them old except Laverton. > 30 years Hallett, Jeeralang, Somerton. MHI have not experienced any failures for this machine type yet | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | 0 | | |
| Utility failure - instr. air / oil / power | Loss of aviation control power | Compliance | Unlikely | Negligible | Low | DCS general electrical monitoring | Rare | Negligible | 0 | Stack aviation lighting may be required. Stack design not finished yet. | |
| Volts / Amps High | | | | | | | | | 0 | | |
| Volts / Amps Low | | | | | | | | | 0 | | |
| Volts / Amps - No or Not | | | | | | | | | 0 | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---------------------------------|--|------------|-------------|--------------|----------------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 28 - Air & Flue Gas - GT Cooling air supply Dwg A-21085 - Air & Flue gas 5 of 5 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | BPCS - valve control | Loss of production - Potential GT Rotor creep or rub, reduced component life | Unlikely | Minor | Low | Automatic Runback | Rare | Minor | Low | MBH05AA731 fails closed, so air always to rotor. No immediate consequences. Valve position alarm | |
| | | Rotor cooling labyrinth blockage over time | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Loss of dry purge air would potentially increase rotor casing corrosion through condensation. Normally starts 12 hours after shutdown. Carbon steel corrosion potential | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | Same as low pressure for GT Rotor. All 3 cooler fans are required but spray water is not likely to be needed | |
| Temperature - No or not | | | | | | | | | | Not realistic | |
| Flow / Level - High | | | | | | | | | | MBH05CT002 just monitoring MBH05CT012/13 for fan control MBA01CT001/2 GT rotor temp, 1 can fail, 2nd fault = alarm only | |
| Flow / Level - Low | | | | | | | | | | Same as high pressure | |
| Flow / Level - No or not | | | | | | | | | | Same as low pressure | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | Fan blades are enclosed cannot fly off | |
| As well as - concentration / two phase | Cooling fan blade fault or loss | Motor bearing damage | Unlikely | Negligible | Low | Shaft vibration Hi Hi trip | Rare | Negligible | Low | MBH05AA753 only open on start up and shutdown | |
| Other then - impurities / contamination | | | | | | | | | | Inlet filter house therefore clean air | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | Cooling fan motor fault | Loss of cooling | Unlikely | Minor | Low | Automatic Runback | Rare | Minor | Low | VSD Drive and bypass contactor. Details not apparent for HAZOP | |
| Volts / Amps Low | MCC fault | Loss of cooling | Unlikely | Minor | Low | Automatic Runback | Rare | Minor | Low | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 29 - Lube Oil - Tank, pumps, prv Dwg A-21021 - Lube oil system 1 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Centrifugal pumps cannot deadhead. Can run both pumps together. No PRV back to tank only control valve MBV01AA702 | |
| Pressure Low | Loss AC supply and the DC pump fail - Unrealistic | Double jeopardy | Rare | Major | Medium | 2003 Lube oil pressure Lo Lo trip | Rare | Major | Medium | Accumulator for AC pump fail over, shock absorption and DC pump fail over | 40. DC Lube oil pump to be tested prior or after each start to prove functionality. Replacing MBV01CP304 DC lube oil pressure gauge with a transmitter would facilitate fast auto test sequence. Requirements to be confirmed by SHL |
| Pressure No or not | Too many transmitters and switches to be realistic | | | | | | | | | Lube oil pressure selected as MHI consider these work much faster than transmitters | |
| Pressure Vacuum | BPCS - loss of pump | Bearing fire | | | | | | | | Refer to extraction fan node | |
| Temperature High | BPCS - Loss of cooling | Bearing damage | Unlikely | Major | Medium | 2003 Lube oil temperature Hi Hi trip | Rare | Major | Medium | | |
| | BPCS - Tank heater stuck on | | Unlikely | Minor | Low | | Unlikely | Minor | Low | Oil tank heater is too small to create over temp scenario | |
| Temperature Low | Standby operation for a long time, resulting in cold oil tank | Loss of production - pump fail to start | Unlikely | Minor | Low | | Unlikely | Minor | Low | Oil tank heater maintains 15 C on, 20 C off | |
| Temperature – No or not | | | | | | | | | | Oil tank heater is too small to create over temp scenario. Manifold 2003 | |
| Flow / Level – High | Pipe / gland leak | Potential pool fire, low oil pressure | | | | | | | | Oil pressure greater than cooler water supply, wont leak into tank | |
| Flow / Level – Low | Blocked filter and MBV01CP501 not working | Potential bearing damage | Rare | Major | Medium | | Rare | Major | Medium | Normal oil level 1.634mm from bottom of tank. Low level 148mm lower. Low level results in low pressure trip | |
| Flow / Level – No or not | | | | | | | | | | MBV01AA702 stuck closed is protected by the bypass orifice MBV01BP102 which is sized to maintain minimum supply | |
| Flow / Level – Reverse | | | | | | | | | | Check valves on all pumps | |
| Vibration – High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Managed by standard maintenance procedures and oil analysis. Base load station may change over every 5 or so years. Peaking plant may last a very long time. | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | 2003 Lube oil pressure Lo Lo trip | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | 2003 Lube oil pressure Lo Lo trip | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Would need to lose both AC and DC supply and not shutdown. Not realistic | |
| Volts / Amps High | | | | | | | | | | MCC is monitored. No realistic to lose both AC and DC supplies | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|-------------------------|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|--|--|
| NODE No. 30 - Lube Oil - GT bearings Dwg A-21022 - Lube oil system 2 of 4 | | | | | | | | | | | |
| Pressure High | BPCS - loss of AC pumps | Bearing fire | Unlikely | Major | Medium | 1001 MBV10CP101 Loss of vacuum Normal Stop | Rare | Major | Medium | Also Refer to extraction fan node | |
| Pressure Low | | | | | | 2003 Lube oil pressure Lo Lo trip | | | | Refer node above | |
| Pressure No or not | | | | | | | | | | Bearing pressure transmitter fault alarm only. Used for monitoring only. Loss of vacuum transmitter alarm only | |
| Pressure Vacuum | | | | | | | | | | refer pressure high above | |
| Temperature High | Bearing faults, debris or rub | Bearing damage | Unlikely | Major | Medium | | Unlikely | Major | Medium | Bearing > 107 C and lube oil return temp hi alarm > 85 C. Supply oil > 60 alarm, > 65 trip | 41. SHL to review high temperature alarm shutdown requirements for Hunter. Remote operator may not react in time. |
| Temperature Low | | | | | | | | | | Refer node above | |
| Temperature - No or not | | | | | | | | | | Alarm only at this time, subject to action item 41 | |
| Flow / Level - High | | | | | | | | | | Loss of vacuum refer high pressure above | |
| Flow / Level - Low | | | | | | | | | | No experience of lube oil drain or seal lines blocking flow | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | Imbalance, bearing faults, debris or rub | Machine damage - blades | Rare | Major | Medium | Shaft vibration Hi Hi trip | Rare | Major | Medium | Refer dwg 21088 | |
| As well as - concentration / two phase | Hydrogen in Lube Oil, refer generator node | | | | | | | | | Generator bearing seal oil A-13C870 | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | Loss of motor starter but still have air | 42. SHL may request additional oil sampling point downstream of the bearings (generator and turbine). MHI to review installation requirements and advise accordingly |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---------------------------------|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|--|---------|
| NODE No. 31 - Lube Oil - Temp control Dwg A-21023 - Lube oil system 3 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | Blocked exchanger | Potential bearing damage | Rare | Major | Medium | 2003 Lube oil pressure Lo Lo trip | Rare | Major | Medium | Also have alarm and dP across filter, dual exchangers. Change over should be done off line or very very slowly online. Also fill line with bypass valve, MBV01AA103. Standard operating procedure required | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS - Loss of cooling | Bearing damage | Unlikely | Major | Medium | 2003 Lube oil temperature Hi Hi trip | Rare | Major | Medium | | |
| Temperature Low | | | | | | | | | | Heated tank | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | Blocked exchanger or bypass stuck closed, continuous bypass | Bearing damage | Unlikely | Major | Medium | 2003 Lube oil temperature Hi Hi trip | Rare | Major | Medium | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | All manual ball valves to be lockable | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Cooling water to be circulated on cold days | |
| Other then - impurities / contamination | Unit on standby (98% likely) and heater exchanger plate leak (1/50 years) and water recirculating on cold days (1/yr), potential CW ingress to oil system | Slug of oily water to bearings | Rare | Negligible | Low | | Rare | Negligible | Low | Not realistic if continuous barring. Exchanger is 'plate in frame' design which are less likely to leak compared to tube type. | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | Operator switches changeover valve too quickly | Loss of Production - false trip | Certain | Negligible | Low | 2003 Lube oil pressure Lo Lo trip | Certain | Negligible | Low | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--------------------------------|--------------|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 32 - Lube Oil - Mist extraction fans Dwg A-21024 - Lube oil system 4 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | Loss of PT MBV10CP101 is an alarm only, the unit will keep running. Is it a start permissive? No but both extraction fans have MCC monitoring | |
| Pressure Vacuum | Blocked filter or loss of fans | Bearing fire | Unlikely | Major | Medium | 1001 MBV10CP101 Loss of vacuum Normal Stop | Rare | Major | Medium | Duty Standby fans, single PT on oil tank | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | Blocked filter or loss of fans | Bearing fire | Unlikely | Major | Medium | 1001 MBV10CP101 Loss of vacuum Normal Stop | Rare | Major | Medium | | |
| Flow / Level - No or not | | | | | | | | | | same as low flow | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | AECOM will construct solid platform for elevated vent stack, discharge to oily water pit or oil drop receiver | |
| As well as - concentration / two phase | | | | | | | | | | air and oil mist | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Same as low flow | |
| Volts / Amps High | | | | | | | | | | Both fans have overload protection and are monitored in the MCC | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | Both fans have overload protection and are monitored in the MCC | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-------|--------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 33 - Lube Oil - Generator bearing seal oil Dwg A-13C870 - | | | | | | | | | | | |
| Pressure High | | | | | | | | | | This drawing covered by the Generator nodes | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--|--|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|---|---|
| NODE No. 34 - Control Oil - Tank, pumps, temp control Dwg A-21031 - Control oil system 1 of 3 | | | | | | | | | | | |
| Pressure High | Cooler blockage leads to high return line drain pressure | Loss of control oil return and potential valve position error / slow response trip | Rare | Major | Medium | PRV MBX01AA114 | Rare | Major | Medium | Piston pumps have internal pressure relief and the control oil lines have PRVs. Control oil filters are also monitored. The system is not designed to run both pumps at the same time but it is possible to force this event which is protected by the PRV back to the tank | |
| | | | | | | Valve out of position shutdown | | | | Note the trip circuit dumps directly to the tank, therefore high return pressure has no impact on tripping capability | |
| Pressure Low | Loss AC supply | Loss of production trip, potential surge of compressor on rundown if IGV fails last position | Unlikely | Negligible | Low | 2003 Control oil pressure Lo Lo trip | Unlikely | Negligible | Low | Passing PRV covered by standby pump | |
| Pressure No or not | | | | | | | | | | Faulty transmitter will start backup pump | |
| Pressure Vacuum | | | | | | | | | | Not possible tank fitted with breather | |
| Temperature High | BPCS - Tank heater stuck on | | Unlikely | Minor | Low | | | | | Oil tank heater is too small to create over temp scenario | |
| Temperature High | Cooler fault | Loss of oil properties, potential low oil pressure false trip | Unlikely | Negligible | Low | 1001 MBX01CT001 control oil tank temp alarm | Rare | Negligible | Low | Oil tank heater is too small to create over temp scenario. Heater stops at 20 C | |
| Temperature Low | Heater fault and not operating | Potential for pump damage due to high viscosity oil | Unlikely | Negligible | Low | 1001 MBX01CT001 control oil tank temp alarm | Rare | Negligible | Low | Pump cannot be stopped by Operator. Normally just keeps running | |
| Temperature - No or not | | | | | | | | | | Alarm only | |
| Flow / Level - High | Unit shutdown and exchanger leak and cooling water pumps running - Not realistic | | | | | | | | | Not realistic if continuous barring. Exchanger is 'plate in frame' design which are less likely to leak compared to tube type. Oil pressure greater than cooler water supply, wont leak into tank | |
| Flow / Level - Low | Pipe / gland leak | Potential pool fire, low oil pressure trip | Rare | Major | Medium | Fire detection and suppression systems | Rare | Major | Medium | | |
| Flow / Level - Low | | | | | | | | | | MBX01CL201 tank level low is an alarm only. Not a start permissive | 43. There is a wall in the oil tank which may create different tank levels, design to be confirmed by MHI |
| Flow / Level - No or not | Blocked filters | Loss of production - trip | | | | 2003 Control oil pressure Lo Lo trip | | | | Filter hi dP alarm | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Oil piping dead lag leading to oil waxing discussed but MHI have not experienced that. | |
| Other then - impurities / contamination | Metal fragments or varnish from oil | Potential of slow valve response of stuck | Rare | Negligible | Low | | Rare | Negligible | Low | Tank fitted with cleaning system, that runs continuously when oil pumps are running, MBX11SS101. Magnet in tank but is not accessible without draining the tank | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | Loss AC supply | Loss of production trip, potential surge of compressor on rundown if IGV fails last position | Unlikely | Negligible | Low | 2003 Control oil pressure Lo Lo trip | Unlikely | Negligible | Low | | |
| Volts / Amps High | | | | | | | | | | Both pumps have overload protection and are monitored in the MCC | |
| Volts / Amps Low | | | | | | | | | | CO pumps and cooling water systems run continuously and must be manually switched off. | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---------------------|--------------|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 35 - Control Oil - Fuel valve position control Dwg A-21032 - Control oil system 2 of 3 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | Slow valve response | | | | | 2003 Control oil pressure Lo Lo trip | Rare | Negligible | Low | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Valves are close to turbine but in an enclosure (radiant heat shield). No history of problems | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | | | | | | | | | | Low flow valve position error and flame out covered in the burner and fuel system nodes | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | refer previous node. Slow response will lead to valve position error trip covered in the burner fuel system nodes | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | 44. Fuel gas and Fuel Oil control oil dump valves are single point of failure and common cause fraction is high. Is this allowed per the standard. Valves should failsafe and individually actuated?? PVD to review in detail as part of AS3814 compliance |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--------------------------------|--------------|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 36 - Control Oil - Fuel valve trip solenoids & Inlet Guide Vanes Dwg A-21033 - Control oil system 3 of 3 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | refer previous node | |
| Pressure Low | | | | | | 2oo3 Control oil pressure Lo Lo trip | Rare | Negligible | Low | refer previous node | |
| Pressure No or not | | | | | | | | | | refer previous node | |
| Pressure Vacuum | | | | | | | | | | refer previous node | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | Heater fault and not operating | | | | | | | | | refer oil tank nodes. Very cold viscous oil may reduce control valve & solenoid flow response time but discussed at length and not expected to effect time critical trips such as overspeed. | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | Failed solenoid | | | | | | | | | Refer action item 45 below | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | refer filters in previous node | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | Notes on viscosity above | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Fuel control valves, refer P&ID notes. Fail open de-energize to trip. This drawing shows operating state of gas operation, therefore fuel oil is shown tripped. 1oo1 solenoid to trip fuel, common cause factor and hardware fault tolerance for SIL rating to be confirmed. Single point of failure Overspeed trip, Fail open de-energize to trip. Solenoids shown in normal operating state (not de-energized state). 2oo4 to trip | 45. Control oil dump circuits to be reviewed against SIL requirements and AS3814 compliance |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|--|---|
| NODE No. 37 - Package Enclosure Ventilation Dwg A-21088 - Protection system P&ID | | | | | | | | | | | |
| Pressure High | Loss of AC supply - no ventilation | Potential over-temperature in enclosure, potential gas cloud accumulation | Unlikely | Major | Medium | Loss of ventilation trip | Rare | Major | Medium | Fans normally operate continuously | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | Loss of fan flow transmitter starts standby fan. All 3 fans can run at the same time | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | Fire in the enclosure | Major equipment damage | Rare | Major | Medium | Fire detection and suppression systems | Rare | Major | Medium | MHI has not experienced fires with this package yet | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | Fans have discharge check valves | |
| Vibration - High Low or not | | | | | | | | | | Shaft vibration shown in this node but covered in the air compressor node. Overspeed shown in this node but covered in the burners section node | |
| As well as - concentration / two phase | Gas leak, potential oil mist from high pressure control oil leak, CO2 from fire system, H2 and N2 unlikely but from generator package | Fire / explosion | Unlikely | Major | Medium | Combustible gas detection trip | Rare | Major | Medium | Operator must isolate CO2 before entering package. There is a CO2 lockout next to the door. CO2 isolation alarms but does not interlock the door | 46. Note AECOM responsible for Fire protection of the Balance of Plant equipment such as lube oil package, fuel oil pump / valve systems and how that system is interlock or integrated into the plant DCS or MHI GT controls. AECOM is design stage now. Fire safety study is well advanced MHI fire and gas detection limited to GT enclosure and Fuel Gas valve systems. SHL to review final design proposal |
| Other then - impurities / contamination | | | | | | | | | | Clean air from filter hoods used for package ventilation. Louvre dampers at bottom of package close on fire detection, refer comments on P&ID | 47. Door tracking isolating the CO2 if someone enters the GT is to be confirmed by vendor and reviewed by SHL |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | Loss of ventilation trip | | | | | |
| Volts / Amps High | | | | | | | | | | Overload protection and monitoring contactor status | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|--|------------|-------------|--------------|---------------------------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 38 - Air & Flue Gas - Inlet filter Dwg A-21084 - Protection system P&ID | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | Loss of signal alarm only | |
| Pressure Vacuum | Filter blockage | Potential filter media ingress and compressor damage | Rare | Major | Medium | 2003 Inlet filter dP Hi Hi trip | Rare | Major | Medium | Final consequence likelihood limited by SHL risk matrix. Not modified to be conservative | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | Potential filter freezing | Potential filter media ingress and compressor damage | Possible | Major | High | 2003 Inlet filter dP Hi Hi trip | Rare | Major | Medium | Adjust this row after MHI action item 48 resolved | 48. Ambient conditions -5 C to +45 C. Anti-icing system was considered in the tender specification but MHI advised at that time it is not required. MHI to revisit the study and reconfirm anti-icing is not required. |
| Temperature - No or not | | | | | | | | | | Loss of ambient temp sensor will alarm and inhibit evap permissive | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | | | | | | | | | | same as pressure vacuum | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | Compressor surge | | | | | | | | | No history of filter house impact | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | Icy water, snow, dust storm, fly ash bushfire | Potential filter media ingress and compressor damage | Possible | Major | High | 2003 Inlet filter dP Hi Hi trip | Rare | Major | Medium | | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | Filter cleaning pulse system not part of the scope for this site | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | Evap motors have overload protection breaker is monitored and alarmed | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|---|------------|-------------|--------------|----------------------------------|---------------------|----------------------|-----------------------|--|---------|
| NODE No. 39 - Gas Turbine - Casing cooling Dwg A-21090 - GT Casing cooling system | | | | | | | | | | | |
| Pressure High | | | | | | | | | | High pressure coming back to fan, rated at 1 Bar is not realistic with double block fail closed valves | |
| Pressure Low | BPCS - valve failed closed or fan not operating | Loss of production - Loss of start permissive | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Operator can manually start spin turning to even up temperature. Although lack of cooling may result in a rub there is spin cooling back manual operation. Only operates after shutdown and turning/barring speed is reached 3 rpm, to prevent hogging, rub due to unequal casing rotor expansion. Back up is high speed turning 'spin cooling' at 600 rpm If the difference of the two (2) thermocouples located on the upper and the lower half of the same casing section exceeds the reference setting, an alarm will be generated. This alarm does not allow GTC to initiate the normal starting sequence. Rub for any reason would need inspection (borescope) | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | Inlet damper not tight shutoff. Excessive vacuum not possible | |
| Temperature High | | | | | | | | | | Adjacent unit exhaust quite far from this unit, so no ambient temperature rise expected | |
| Temperature Low | | | | | | | | | | | |
| Temperature – No or not | BPCS - Signal fault | Loss of production - Loss of start permissive | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Alarm | |
| Flow / Level – High | | | | | | | | | | | |
| Flow / Level – Low | Blocked filter | Loss of production - Loss of start permissive | Unlikely | Negligible | Low | QEF13CP501 Inlet filler dP alarm | Rare | Negligible | Low | Filter media ingress not considered likely with dP alarm in service | |
| | BPCS - Flow control | Loss of production - Loss of start permissive | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Manual valves to be locked in position | |
| Flow / Level – No or not | | | | | | | | | | | |
| Flow / Level – Reverse | | | | | | | | | | High pressure coming back to fan, rated at 1 Bar is not realistic with double block fail closed valves. Leak test point request to MHI to be considered based on cost and schedule impact | |
| Vibration – High Low or not | | | | | | | | | | Pump has flexible coupling | |
| As well as - concentration / two phase | | | | | | | | | | Self draining lines, condensation not a problem | |
| Other then - impurities / contamination | | | | | | | | | | Inlet filter therefore clean air | |
| Timing / Sequence - Early / Late | BPCS - commissioning error | Potential hot gas reverse flow | Unlikely | Negligible | Low | Operator alarm response | Unlikely | Negligible | Low | Position limit switch alarm and restriction orifice plates at casing to reduce the impact | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Same as low flow | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Same as low flow | |
| Volts / Amps High | | | | | | | | | | MCC is monitored. | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | Same as low flow | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 40 - Gas Turbine - Blade washing device Dwg A-21086 - GTW Washing and drain system 1 of 2 | | | | | | | | | | | |
| Pressure High | Operator error - Overfilling tank | Soapy water on floor, potential burst line Operator exposed to high pressure water jet, fragment debris | Possible | Moderate | Medium | PRV 90SSD01AA904 | Possible | Negligible | Low | Moveable device dwg first | |
| Pressure Low | | | | | | | | | | Process just takes longer to empty the tank | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | Operator error - Overfilling tank | Soapy water on floor, potential burst line Operator exposed to high pressure water jet, fragment debris | Possible | Moderate | Medium | PRV 90SSD01AA904 | Possible | Negligible | Low | | |
| Flow / Level - Low | | | | | | | | | | 150 lpm for 2 minutes. Needle valve adjusted during commissioning, 90SDD01AA108 | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | Demin water and detergent liquid. All clean service. 304 Stainless steel. Service air clean and last catch strainer before tank | |
| Timing / Sequence - Early / Late | Operator error - Select Off-line or On-line valve | No major difference, less optimal cleaning | Possible | Negligible | Low | | Possible | Negligible | Low | | |
| Timing / Sequence - Fast / Slow | | No major difference, less optimal cleaning | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|--|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 41 - Gas Turbine - Blade washing and drain system Dwg A-21087 - GTW Washing and drain system 2 of 2 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | |
| Pressure Low | | | | | | | | | | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature – No or not | | | | | | | | | | | |
| Flow / Level – High | Operator error - leave drain valve open | Potential hot pipework, loss of capacity (less combustion air), air venting at drain pit | Rare | Negligible | Low | | Rare | Negligible | Low | Double hand valves to prevent leakage | 33. Water wash procedure has many manual valves which could potentially lead to false start by flooded combustion chamber and subsequently detergent flow into the oil water pit. SHL to develop a water wash procedure with 2 operators to cross check. Water washing drain header could also have small amounts of diesel residue from liquid fuel false start. |
| Flow / Level – Low | | | | | | | | | | | |
| Flow / Level – No or not | | | | | | | | | | | |
| Flow / Level – Reverse | | | | | | | | | | | |
| Vibration – High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Same as previous node, Clean demin, air and soap. Water rinse does not need to be analysed / visual checked | |
| Other then - impurities / contamination | | | | | | | | | | Carbon drain valves corrosion? | |
| Timing / Sequence - Early / Late | Operator error | Potential for water corrosion if left in machine wheel space for a long time or potential vibration on run up with excessive water in casing | Rare | Negligible | Low | | Rare | Negligible | Low | Potential for water corrosion if left in machine wheel space for a long time or potential vibration on run up with excessive water in casing. MHI to check if opening the offline valve when online creates any hazard | 33. Water wash procedure has many manual valves which could potentially lead to false start by flooded combustion chamber and subsequently detergent flow into the oil water pit. SHL to develop a water wash procedure with 2 operators to cross check. Water washing drain header could also have small amounts of diesel residue from liquid fuel false start. |
| Timing / Sequence - Fast / Slow | Operator error | Water accumulates in inlet filter casing | | | | | | | | Designed for on-line and off-line water wash. Casing drain valve should be open for water wash, MBA01AA915 | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Off-line performed at spin cycle, 600 rpm | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--------------------------------|---|------------|-------------|--------------|-------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 42 - Evaporative Cooler - pump and tank unit Dwg C-50011 - Evaporative cooler system | | | | | | | | | | | |
| Pressure High | BPCS - Valve out of position | Loss of efficiency | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | | |
| Pressure Low | BPCS - power fault | Loss of efficiency | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | MCC is monitored. | |
| | Empty tank or blocked strainer | Loss of efficiency, potential pump damage | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | Pump suction pressure switch is monitored | 49. Valve numbers and instrument numbers and line sizes are not shown on the drawing. Return valve is shown as control valve but is actually a manual lockable isolation valve |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | Same as low pressure | |
| Temperature High | | | | | | | | | | Refer impurities bacteria | |
| Temperature Low | | | | | | | | | | Low ambient temp not a concern as evap is not enable below 15 Celsius | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | BPCS - Level control failure | Water to drain | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Excessive water flow just returns to the tank. There is also a mist eliminator to catch water droplets. Even then unlikely to do anything to the compressor. | 50. Evap tank water is potable water. Should overflow or draining be discharged to Trade Waste or Storm Water. AECOM to review and design accordingly |
| Flow / Level - Low | BPCS - Level control failure | Loss of efficiency | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | | |
| Flow / Level - No or not | | | | | | Operator alarm response | | | | | |
| Flow / Level - Reverse | | | | | | | | | | Not possible tank fitted with breather and overflow | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | Where is the conductivity meter? Not in MHI scope of supply. System continuously blows down to refresh water in tank. Legionella microbe growth in tank? Has happened in Colongra. Snowy to monitor | 51. Evap tank has no sample point. MHI to review option to supply |
| Timing / Sequence - Early / Late | | | | | | | | | | Potential for very heavy media damage discussed but not considered likely by MHI. Has happened at Laverton | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | 8 to 10 minutes to fully saturate the media. 9 minutes to achieve 90% power boost | |
| Utility failure - instr. air / oil / power | | Loss of efficiency | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | | |
| Volts / Amps High | | | | | | | | | | MCC is monitored. | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|---|------------|-------------|--------------|-------------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 43 - Burner nozzle purge air supply and control Dwg A-21100 & A-21042B - Purge air system | | | | | | | | | | | |
| Pressure High | BPCS - Valve out of position | Potential loss of containment, pump damage | Unlikely | Moderate | Medium | PRV QEE02AA903 | Rare | Moderate | Low | | |
| Pressure Low | BPCS - Compressor problem, control loop | Loss of production - fuel oil nozzle carburised | Rare | Negligible | Low | | Rare | Negligible | Low | Duty standby pump and low pressure air when shutdown from LP service air. LP air to be on for 960 minutes after shutdown. Potential nozzle carburising / coking potential failed to reach maximum fuel flow due to restriction. Top off outage to remove fouling. AECOM already have action item on the minimum length of time lower pressure purge air is required. Sizing to be confirmed | |
| Pressure No or not | | | | | | | | | | 2003 Flow Transmitter and 1002 Pressure Transmitter, redundant flow control valves | |
| Pressure Vacuum | Blocked filter | | | | | | | | | Detail design not available at this time | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | Potential auto drain trap freezing but that would be a short term issue, 4 hours. Will not create a process water carry over. The receiver is 13m3, big enough for days of water collection | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | BPCS - Valve out of position | Loss of production - fuel oil nozzle carburised | Unlikely | Minor | Low | Operator alarm response | Rare | Minor | Low | Primary fuel will be gas. It is considered unlikely that one coking event will contribute more than 10% capacity loss. Suggest seek industry operational experience to better quantify this coking scenario. Can annular burners accessible from outside. | |
| Flow / Level - No or not | | | | | | | | | | Not likely 2003 FT | |
| Flow / Level - Reverse | | | | | | | | | | Check valves and fail close double block valves | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Water carry over from receiver was discussed at length and not considered plausible. Water is mixed with air and would vaporise before the burners. Quenching not likely. Faulty drain trap covered by routine operator procedure to check receiver drain function. | |
| Other then - impurities / contamination | | | | | | | | | | Possible scenarios are compressor oil, water humidity and dust but system has adequate filters. There may be construction earth works dust present | |
| Timing / Sequence - Early / Late | | | | | | | | | | Sequencing controlled by speed interlock and when fuel oil firing stops (change over or shutdown). HP purge air on when firing gas and service when 3 rpm turning. MHI will provide sequence timing charts later to explain how the sequencing works | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Potentially increased risk of minor coking. Reverse oil flow not considered a realistic event as there are many block valves and check valves between the receiver and the burner nozzles | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Is possible if the site black outs, loss of low pressure service air. All valves fail closed | |
| Volts / Amps High | | | | | | | | | | MCC is monitored. | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|--|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|---|---|
| NODE No. 44 - Generator cooling water Dwg A13C868 - Cooling water P&ID | | | | | | | | | | | |
| Pressure High | Heat exchanger tube leak, resulting in water entering the Hydrogen system | Generator damage - Imbalance rotor washing, insulation failure, flash over | Unlikely | Major | Medium | dual Hi Hi level Generator water detectors | Rare | Major | Medium | H2 5 Bar Cooling water 6 - 7.5 Bar | 52. MELCO interface details required for AECOM water services. Water pressure recently increased to 7.5 Bar. AECOM to advise MELCO final supply pressure. MELCO cooler to be designed accordingly |
| Pressure Low | Loss of AC or pump or valve would result in low water pressure. Potential exposure to Hydrogen entering water if there was a tube leak | Double jeopardy | Rare | | | | | | | Water cooling system HAZOP required on loss of CW pressure | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | Loss of efficiency, loss of AC, or valve out position | Loss of cooling would have long term effect on stator winding insulation | Unlikely | Major | Medium | Stator winding temp Hi auto stop | Rare | Major | Medium | Design max cooling water delivery is 51 Celsius. Name plate rating 456 MVA with 23 Deg C cooling water. High temperature would raise H2 pressure a little but not catastrophically. There is also a high pressure alarm at 5.35 Bar | 53. MELCO to provide full list of generator protection settings, trips complete with alarms, auto shutdown and run backs |
| Temperature Low | | | | | | | | | | Water running continuously, freezing of water not considered realistic. Fin fan coolers weakest point for freezing but recirculation prevents freezing | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | No flow control | |
| Flow / Level - Low | Operator error - valve out of position | Loss of cooling would have long term effect on stator winding insulation | Unlikely | Major | Medium | Stator winding temp Hi auto stop | Rare | Major | Medium | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | Tube failure covered in pressure | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Potential for ice, refer above temp low | |
| Other then - impurities / contamination | | | | | | | | | | Demin water, clean service. Manual top and sample point for water quality checks | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|---|------------|-------------|--------------|---------------------------------|---------------------|----------------------|-----------------------|--|--|
| NODE No. 45 - Generator CO2 gas supply Dwg AS29623 - Generator H2 & CO2 gas supply diagram for GT | | | | | | | | | | | |
| Pressure High | BPCS Regulator failure | Loss of containment | Unlikely | Major | Medium | PRV RV-2 CO2 release | Rare | Major | Medium | 45A Pressure regulation is not part of this node | |
| Pressure Low | Insufficient purge flow. Need 1.5 volumes for maintenance and 2.0 times for emergency | Potential explosion / flammable mixture under maintenance | | | | | | | | Pressure regulation is not part of this node and there is a gauge on the skid. May need pressure switch monitoring for auto purge system. Currently manual operating procedure. Risk assessed in the regulator node | 55. CO2 site capacity to be assessed against minimum volume required for a successful purge times a safety factor. Potential bottle leak reduces capacity. Is adequate monitoring installed, flow pressure bottle weight |
| Pressure No or not | Operator error - valve out of position | Potential explosion / flammable mixture under maintenance | Unlikely | Major | Medium | Dual operator procedure | Rare | Major | Medium | Multiple gauges. Standard procedure to check vent gas for H2 content | 54. Manual purging requires strict procedure with 2 people to cross check to confirm successful purge |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | Lines freezing considered in AECOM HAZOP. Heat tracing not required | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | CO2 leak from pipework has good ventilation, not an enclosed space | |
| Flow / Level - Low | BPCS - Seal oil system failure | Loss of containment - Potential explosive mixture in or around the generator resulting in fire explosion machine damage, refer Callide incident | Unlikely | Severe | High | Automatic H2 vent and CO2 purge | Rare | Severe | Medium | There is a manually actuated (remote controlled) vent valve but it is not automated in the event of a seal failure. Reasons for emergency auto vent is Seal oil failure, generator enclosure fire, major leak very low pressure requires vessel to be purged? MHI have never automated H2 purge system. Not every seal failure would lead to explosion / fire but there are quite a few sites in Australia with automated vent and purge systems so it is best practice. | 56. Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. MHI incorporate in design, logic to action valve. |
| Flow / Level - No or not | BPCS - CO2 supply failure | Loss of purge - H2 left in generator potential maintenance staff exposure to fire / explosion | Unlikely | Severe | High | Automatic H2 vent and CO2 purge | Rare | Severe | Medium | | 57. Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. AECOM to incorporate automate CO2 supply to the units |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | Vent stack designed for high flow thrust | |
| As well as - concentration / two phase | | | | | | | | | | CO2 and H2 or CO2 and Dry instrument air in later nodes | |
| Other than - impurities / contamination | | | | | | | | | | Clean CO2 | |
| Timing / Sequence - Early / Late | | | | | | | | | | To be reviewed after automated system design is completed | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | To be reviewed after automated system design is completed - suggest fail safe closed | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---------------------------------------|--|------------|-------------|--------------|----------------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 46 - Generator H2 gas supply Dwg AS29623 - Generator H2 & CO2 gas supply diagram for GT | | | | | | | | | | | |
| Pressure High | BPCS - regulator fails open | Loss of Production - Continuous venting of H2 until supply exhausted | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | Node 45B AECOM have H2 manifold pressure monitoring with Hi and Lo alarms | 58. Unit H2 flow meter can be used for make up flow monitoring, leak and PRV lifting detection. SHL to review |
| Pressure Low | BPCS - regulator fails closed or leak | Loss of cooling would have long term effect on stator winding insulation | Unlikely | Major | Medium | Stator winding temp Hi auto stop | Rare | Major | Medium | | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | 90% above ground next to gas line. Ambient temperature only. 17 m3/day make up | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Same as pressure high | |
| Flow / Level - Low | | Blocked filter | Unlikely | Negligible | Low | Operator alarm response | Rare | Negligible | Low | Same as pressure low | |
| Flow / Level - No or not | | | | | | | | | | Same as pressure low | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | 100% H2 | |
| Other then - impurities / contamination | | | | | | | | | | Due consideration is given to piping materials. Mostly carbon steel suitable for low pressure H2 applications but MELCO supply all 304 stainless steel (SUS) | 59. AECOM to review H2 pipework for dissimilar metals. MELCO supply all 304 stainless. Potential corrosion and Haz area issue |
| Timing / Sequence - Early / Late | | | | | | | | | | To be reviewed after automated system design is completed - suggest fail safe closed | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | H2 is contained with seal oil even when the unit is completely shutdown and not rotating | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|---|------------|-------------|--------------|-------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 47 - Generator CO2 Dwg A13C869 - H2 and CO2 for P&ID for GT | | | | | | | | | | | |
| Pressure High | | | | | | | | | | CO2 Pressure regulation previous node. Automation to be considered | |
| Pressure Low | | | | | | | | | | Refer previous node | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | Operator - sets valve open | Lift prv, environment but small issue if attended | Possible | Negligible | Low | | Possible | Negligible | Low | Needle valve on CO2 sets the supply flow rate. Operator looks at PI3 to set flow rate. Would need regulator for automated system | |
| Flow / Level - Low | Operator error - valve out of position | Potential explosion / flammable mixture under maintenance | Unlikely | Major | Medium | Dual operator procedure | Rare | Major | Medium | Multiple gauges. Standard procedure to check vent gas for H2 content | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | CO2 and H2 or CO2 and Dry instrument air in later nodes | |
| Other then - impurities / contamination | | | | | | | | | | Clean CO2. no filter on drawings. H2 has 2 filters. CO2 pipework rarely used could cause fouling issue | 60. CO2 line has no filter or strainer. It is rarely used which could create fouling issues. MELCO to consider and quote option |
| Timing / Sequence - Early / Late | | | | | | | | | | Review after automated vent and purge design is completed | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|---|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|--|---|
| NODE No. 48 - Generator H2 Dwg A13C869 - H2 and CO2 for P&ID for GT | | | | | | | | | | | |
| Pressure High | BPCS Regulator failure | No real concern | | | | PRV RV-1 H2 release | | | | CV-1 failure would raise pressure to 7 bar RV-1 set to 7 bar | |
| Pressure Low | BPCS Regulator failure | Loss of cooling would have long term effect on stator winding insulation | Unlikely | Major | Medium | Stator winding temp Hi auto stop | Rare | Major | Medium | H2 make up valve is manual at this time. | 61. MELCO to review automating the Hydrogen make up valve as the site is normally not manned. |
| Pressure No or not | | | | | | | | | | PT1 - H2 pressure in generator. Single sensor to interlock for HiHi and LoLo pressure | 62. Hydrogen pressure transmitter PT1 is potentially a single point of failure for an unmanned site. MHI to confirm signal failure response |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS Regulator failure | Loss of cooling would have long term effect on stator winding insulation | Unlikely | Major | Medium | Stator winding temp Hi auto stop | Rare | Major | Medium | Stainless steel piping. Mounting suitable for expansion. Carbon steel within generator designed to maximum Hydrogen temperature on loss of cooling | |
| Temperature Low | Ambient temperature | Loss of production and instrument failure | Certain | Negligible | Low | | Certain | Negligible | Low | -5 Celsius, analyser doesn't have a heater but is suitably rated. Located under the generator near the pedestal on an open gear plate | 66. Site wide review of field mounted instrumentation junction boxes and field panels required. These are normally fitted with heaters to prevent condensation 67. MHI to supply instrumentation datasheets for action item 66. To confirm field instrumentation ratings, i.e. +5 - +45 non-condensing?? |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | Leak | Potential explosive atmosphere | Unlikely | Minor | Low | | Unlikely | Minor | Low | Open access area classified as Hazardous Area well ventilated area, fatality unlikely | 68. AECOM to study hydrogen detection requirements for this open area plant area and that location is under exciter which probably has cooling fans that could draw H2 into enclosure |
| | Heat exchanger tube leak, resulting in water entering the Hydrogen system | Generator damage - Imbalance rotor washing, insulation failure, flash over | Unlikely | Major | Medium | dual Hi Hi level Generator water detectors | Rare | Major | Medium | H2 5 Bar Cooling water 6 - 7.5 Bar | |
| Flow / Level - Low | | | | | | | | | | | 64. Melco to confirm what happens to the purity meter if CV-1 fails and flow is too low or no flow or needle valve set incorrectly. Hydrogen purity is important for purging requirements |
| Flow / Level - No or not | | | | | | | | | | No flow transmitters only indicators | |
| Flow / Level - Reverse | CO2 manual isolation valve out of position or passing | H2 leaking back into CO2 supply system up the check valve | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | | 69. MELCO to add check valve before CO2 manual isolation valve |
| Vibration - High Low or not | | | | | | | | | | Fit for purpose mounting and fixing. Can be rechecked on site. | |
| As well as - concentration / two phase | Dew point from tube leak, refer cooling water node | | | | | | | | | Loss of purity analyser signal will alarm. It is possible to determine purity (density) from DPI1 but only at rated speed. Danger for purity is < 35%. As long as seal oil system is operating, it is not possible to accumulate moisture but there is a hydrogen dryer. Cooling exchanger water leak is most likely | 63. Dew point monitoring is currently not part of the scope. SHL to request a quotation from MDI to add dew point monitoring |
| Other then - impurities / contamination | | | | | | | | | | Loss of purity analyser signal will alarm | |
| Timing / Sequence - Early / Late | All manual valves | Low hydrogen pressure, loss of cooling, stator winding damage | Unlikely | Major | Medium | Stator winding temp Hi auto stop | Rare | Major | Medium | Manual H2 topping has time to respond, say 2 days from the time of alarm under normal circumstances | |
| Timing / Sequence - Fast / Slow | All manual valve operation. Insufficient purge flow. Need 1.5 volumes for maintenance and 2.0 times for emergency | Loss of purge - H2 left in generator potential maintenance staff exposure to fire / explosion | Unlikely | Severe | High | Dual operator procedure | Rare | Severe | Medium | Purge complete based on flow timing and analyser | 65. SHL to develop written procedure for sampling purity with portable analyser to confirm main analyser reading is correct. Drain sampling and valve switching is manual to select top or bottom of the generator sampling. Note sampling drain point is within hazardous area |
| Utility failure - instr. air / oil / power | | | | | | | | | | All valves fail closed | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | Loss of analyser. | Purge delays | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|---|------------|-------------|--------------|-------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 49 - Generator H2 drying system Dwg A13C869 - H2 and CO2 for P&ID for GT | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Very low pressure blower | |
| Pressure Low | Leak or enclosure seals passing | Hydrogen leak, potential for fire / explosion | Rare | Minor | Low | | Rare | Minor | Low | Manufactured to Australian pressure vessel standards | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Auto ignition temperature of H2 is 585 C well above 1.6 KW heater design 200 (170 + ambient). Temp switch cut out is 50 C above expected normal operating temp. Not a control circuit only protection. Vessel is lagged to protect Operator hot contact | |
| Temperature Low | BPCS - Heater failure | Potential long term humidity winding damage | Unlikely | Moderate | Medium | Dew point monitoring | Rare | Moderate | Low | Dew point alarms excess moisture | 71. MELCO to quote additional double block and vent isolation valves for on-line maintenance of heater system, to eliminate H2 purge of complete system. Snowy standard maintenance requirement |
| Temperature - No or not | Loss of heater over-temperature circuit | | | | | | | | | Heater sized to prevent excessively high auto ignition temperature and only operates during regeneration | |
| Flow / Level - High | Operator error valve out of position | Vent H2, potential flammable explosive cloud at fan intake | | | | | | | | Refer action item 70 below | |
| Flow / Level - Low | Operator error valve out of position | Desiccator out of service, humidity build up, long term insulation damage | Unlikely | Minor | Low | Dew point monitoring | Rare | Minor | Low | | |
| Flow / Level - No or not | | | | | | | | | | Flow is not measured | |
| Flow / Level - Reverse | Operator error valve out of position | Vent H2, potential flammable explosive cloud at fan intake | Unlikely | Severe | High | Dual operator procedure | Rare | Severe | Medium | | 70. Hydrogen dryer blower intake is open to atmosphere and in close proximity to the Operator swinging the 3-ways valves. Incorrect procedure (monthly) or Operator error would vent Hydrogen out of air intake. Operator exposure to fire / explosion (static). Design review required. Air intake pipe to safe area to seal system or automated double block and bleed per combustion standard |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Regen is required to eliminate moisture which long term can degrade winding insulation | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | Operator error same as above Reverse flow | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Loss of regeneration, monthly process | 71. MELCO to quote additional double block and vent isolation valves for on-line maintenance of heater system, to eliminate H2 purge of complete system. Snowy standard maintenance requirement |
| Volts / Amps High | | | | | | | | | | MCC is monitored. | |
| Volts / Amps Low | | | | | | | | | | MCC is monitored | |
| Volts / Amps - No or Not | | | | | | | | | | If generator in service, monthly regeneration. With generator in standby with seal oil system in service may not require as frequent regen. | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|---|------------|-------------|--------------|-----------------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 50 - Generator - Lube oil system Dwg A13C870 - Generator seal oil diagram for GT | | | | | | | | | | | |
| Pressure High | | | | | | | | | | | 73. MELCO design is heavily reliant on Operator alarm response and on site Operator rounds. This is not how Snowy normally operate. Additional instrumentation would be likely be installed on future upgrades. MELCO design to be reviewed for potential instrumentation upgrades |
| Pressure Low | Loss AC and DC power or blockage or major pipe failure | Bearing damage | Rare | Severe | Medium | 2003 Lube oil pressure Lo Lo trip | Rare | Severe | Medium | | |
| Pressure No or not | | | | | | | | | | No pressure measurements in this section | |
| Pressure Vacuum | Loss of fan power or damper out of position | No real concern | | | | | | | | Loss of vacuum fan / H2 eliminator (not for oil mist) is not a concern for oil flow oil temp and has spring loaded non return valve as back up. Loss of oil vacuum has no impact on the seal oil vacuum and vice versa | |
| Temperature High | Bearing faults, debris or rub | Bearing damage | Unlikely | Major | Medium | Operator alarm response | Rare | Major | Medium | Bearing > 107 C and lube oil return temp hi alarm > 85 C. Supply oil > 60 alarm, > 65 trip | 41. SHL to review high temperature alarm shutdown requirements for Hunter. Remote operator may not react in time. |
| Temperature Low | Standby operation for a long time, resulting in cold oil tank | Loss of production - pump fail to start | Unlikely | Minor | Low | | Unlikely | Minor | Low | Oil tank heater maintains 15 C on, 20 C off | |
| Temperature – No or not | BPCS Sensor fault | | | | | | | | | TC 1,2,3 alarm only, so loss of signal is alarm. There will be an alarm priority / call out response strategy implemented for the site | |
| Flow / Level – High | LOOP tank | | | | | | | | | Very large size pipework, unrealistic to block up. Leaving commissioning strainer in or spade would be detected by seal oil level high alarms on LS3 and LS1,2. Potential to pump oil out of vent discussed but not realistic scenario | |
| Flow / Level – Low | | | | | | | | | | Normally the seal oil system flows into the LOOP tank to maintain tank level. Loss of oil level is really only possible during commissioning by leaving spade or block strainers. Discussed at length but would be detected by GTC system somehow | 72. There is a discrepancy between MELCO pipe sizes and MHI drawing A-21022 page 2of 4. MHI to review and correct |
| Flow / Level – No or not | | | | | | | | | | Level is not measured | |
| Flow / Level – Reverse | | | | | | | | | | Possible when the DC pump runs. Designed accordingly. Also possible if seal oil vacuum pump is not running but not an issue | |
| Vibration – High Low or not | Bearing faults, debris or rub | Potential bearing damage | Rare | Major | Medium | Shaft vibration Hi Hi trip | Rare | Major | Medium | | |
| As well as - concentration / two phase | | | | | | | | | | Designed for hydrogen and lube oil | |
| Other then - impurities / contamination | | | | | | | | | | Oil system is filtered and dP monitored | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | mcc is monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|---|---|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|---|--|
| NODE No. 51 - Generator - Seal oil vacuum pump and tank Dwg A13C870 - Generator seal oil diagram for GT | | | | | | | | | | | |
| Pressure High | Loss of vacuum pump | Slow loss of Hydrogen purity | Rare | Negligible | Low | Operator alarm response | Rare | Negligible | Low | Node 47B start - Seal oil vacuum pump | |
| Pressure Low | Solenoid failure | Vacuum pump failure | Rare | Negligible | Low | | Rare | Negligible | Low | MCC is monitored but the seals would already be damaged. There is no instrumentation on the pump, local pressure gauge | |
| Pressure No or not | | | | | | | | | | No instrumentation on the vacuum system, refer action item 73 | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | Oil leak | Environmental - Oil / water to ground | Possible | Negligible | Low | | Possible | Negligible | Low | Sight glass to be checked every day. Oily water drain to keep vent line clear | 75. Seal oil system drip tray or banded area should be remotely monitored for large leaks and potentially auto draining function of sight glass. Similar to fuel oil / lube oil bunds |
| Flow / Level - High | BPCS - Seal oil vacuum tank fill valve stuck open | Environmental - Oil pumped up to vent stack | Rare | Moderate | Low | | Rare | Moderate | Low | Tank fill float valve likely to fail every 50 years? Remote operator / unmanned site, no time to respond. LS-5 stops vacuum pump but that doesn't stop the lube oil filling | 76. Seal oil vacuum tank fill valve is a single point of failure which can lead to lube oil overfilling the tank and lube oil discharging via the vent stack, potential large quantities due to unmanned site. Alarm response cannot prevent this consequence and would happen quite quickly. Design review required |
| Flow / Level - Low | BPCS - Seal oil vacuum tank fill valve stuck closed | Potential loss of H2 seal | Rare | Negligible | Low | PS-1 seal oil pressure c/w DC back up pump | Rare | Negligible | Low | No credit for LS-6 low tank level alarm, remote Operator response too slow. Battery charger would keep DC system running plus 3 hours battery time | |
| Flow / Level - Low | BPCS - Seal oil vacuum tank fill valve stuck closed | Potential loss of H2 seal | Rare | Negligible | Low | DPS-1 seal oil diff pressure c/w DC back up pump | Rare | Negligible | Low | No credit for LS-6 low tank level alarm, remote Operator response too slow | |
| Flow / Level - No or not | | | | | | | | | | Flow is not measured | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Clean lube oil system with some moisture in H2 | |
| Other then - impurities / contamination | | | | | | | | | | clean filtered system | |
| Timing / Sequence - Early / Late | | | | | | | | | | Solenoid and fill valve covered above | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | mcc is monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|---|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|---|--|
| NODE No. 52 - Generator - AC seal oil system Dwg A13C870 - Generator seal oil diagram for GT | | | | | | | | | | | |
| Pressure High | Differential pressure regulator valve not controlling well | Oil flows into generator level detection circuit. Diagnostic alarm for seal or pressure system | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Confirm strainer on AC pump inlet is not required - Karl | |
| Pressure Low | Differential pressure regulator valve not controlling well | Loss of cooling - Hydrogen would flow into lube oil collection area and vent via the LOOP tank system | Unlikely | Negligible | Low | DPS-1 seal oil diff pressure c/w DC back up pump | Rare | Negligible | Low | Monthly function test of DC pump recommended by Melco | |
| Pressure No or not | | | | | | | | | | PS1 stuck fails over to DC pump and also via DPS-1 | |
| Pressure Vacuum | Manual valve closed or blocked filter | Pump damage | Rare | Negligible | Low | PS-1 seal oil pressure c/w DC back up pump | Rare | Negligible | Low | All manual ball valves to be lockable | |
| Temperature High | Loss of cooling | Low discharge pressure | Rare | Negligible | Low | | Rare | Negligible | Low | Oil temperature controlled by main lube oil system. Not realistic for this node but would result in low discharge pressure | |
| Temperature Low | | | | | | | | | | Oil tank heaters | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | Blocked filter or loss of AC or valve position | | | | | Operator alarm response | | | | refer above low pressure. Redundant filter set with on-line change over capability | |
| Flow / Level - No or not | | | | | | | | | | Flow is not measured | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | Flexible coupling on AC pump inlet more for thermal expansion compensation | |
| As well as - concentration / two phase | | | | | | | | | | Clean oil H2 service | |
| Other then - impurities / contamination | Metal fragments or varnish from oil | Blocked filter | | | | Operator alarm response | | | | refer above low pressure. Redundant filter set with on-line change over capability | |
| Timing / Sequence - Early / Late | | | | | | | | | | AC DC pump failover timing, 0.2 sec on change over and no delay on low pressure PS1. No accumulators in the system. H2 escape time on complete loss of oil pressure a few seconds only. | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | Loss of AC supply | Low discharge pressure, potential loss of containment | Rare | Negligible | Low | PS-1 seal oil pressure c/w DC back up pump | Rare | Negligible | Low | MCC contactor also monitored refer timing above. Potential scenarios include loss of control power per Callide incident | 77. MELCO to review design to define the potential consequences of an unmanaged seal oil system failure and loss of hydrogen containment. Snowy will use this information to risk assess the installation per HAZOP guidelines |
| Volts / Amps High | | | | | | | | | | mcc is monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---|--|------------|-------------|--------------|--|---------------------|----------------------|-----------------------|---|---|
| NODE No. 53 - Generator - DC seal oil system Dwg A13C870 - Generator seal oil diagram for GT | | | | | | | | | | | |
| Pressure High | Differential pressure regulator valve not controlling well | Oil flows into generator level detection circuit. Diagnostic alarm for seal or pressure system | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Generator casing vacuum test normally used for water cooled generators not required for H2 cooled systems. MELCO do positive pressure decay test on the casing | |
| Pressure Low | Differential pressure regulator valve not controlling well | Loss of cooling - Hydrogen would flow into lube oil collection area and vent via the LOOP tank system | Unlikely | Negligible | Low | DPS-1 seal oil diff pressure c/w DC back up pump | Rare | Negligible | Low | | |
| Pressure Low | DC Pump fault | Loss of H2 containment | Unlikely | Severe | High | | Unlikely | Severe | High | There is no safeguard for DC pump failure. No DC pump discharge pressure sensor. Pump is tested monthly. Proof test procedure with pressure limits and response time to be confirmed on site. No method for automatic H2 venting system. | 78. Change DC pressure PI-5 to pressure transmitter for DC pump test run and linking to H2 automatic venting system. MELCO team suggest change is technically possible but may cause delays. Snowy to review schedule impact and instruct MELCO accordingly |
| Pressure Low | Oversized DC pressure relief valve RV-2 passing | Loss of H2 containment | Unlikely | Severe | High | | Unlikely | Severe | High | Note monthly testing regime | 79. MELCO team to confirm DC pump recirc line size. The large size valve passing may result in very low DC seal oil pressure |
| Pressure No or not | | | | | | | | | | Currently no sensor but we plan to install one. Failure would be alarm only. | 81. DC pump inlet (suction side) check valve stuck closed resulting in no oil pressure in a demand scenario. Why do we need this valve and is it normally open or closed. Confirm also design of this valve, i.e. spring, lockable, power cylinder?? |
| Pressure Vacuum | DC pump inlet (suction side) check valve stuck closed resulting in no oil pressure in a demand scenario | Loss of H2 containment | Rare | Severe | Medium | | Rare | Severe | Medium | Powered (spring or cylinder or lockable) check valve design to be confirmed | 80. AC and DC suction pressure indicators not shown on drawing but will be provided. MELCO to update drawing |
| Temperature High | Loss of oil cooling | Low discharge pressure AND AC system is not running AND temperature so high that oil pressure is completely lost = not realistic | | | | | | | | Oil temperature controlled by main lube oil system. Not realistic for this node but would result in low discharge pressure. DC pump pressure greater than AC pump, so continuous recirc not possible. | |
| Temperature High | DC pump running for long time or gland seal problem leading to high temp resulting in low oil pressure | Loss of H2 containment potential explosion equipment damage, fatality | Rare | Severe | Medium | | Rare | Severe | Medium | Operator opens valve (1) to blend lube oil with seal oil to reduce the temperature when the DC pump is running or seal gland problems? MELCO thinks this will never be required, as normally batteries would run out and Operator would manually vent H2. Standard procedure is to vent hydrogen as soon as the DC pump starts running. The check valve (2) prevents lube oil overfilling LOOP tank | 56. Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. MHI incorporate in design, logic to action valve. |
| Temperature Low | | | | | | | | | | Oil tank heaters. DC circuit is normally not running but the valves are suitably rated | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Both AC and DC pumps running but has no consequence | |
| Flow / Level - Low | Blocked filter or loss of DC or valve position | | | | | Operator alarm response | | | | refer above low pressure. Redundant filter set with on-line change over capability | |
| Flow / Level - No or not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|--|------------------------------------|------------|-------------|--------------|-------------------------|---------------------|----------------------|-----------------------|---|--|
| Flow / Level – Reverse | | | | | | | | | | Operator opens valve (1) to blend lube oil with seal oil to reduce the temperature when the DC pump is running or seal gland problems? MELCO thinks this will never be required, as normally batteries would run out and Operator would manually vent H2. Standard procedure is to vent hydrogen as soon as the DC pump starts running. The check valve (2) prevents lube oil overfilling LOOP tank | |
| Vibration – High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Clean oil H2 service | |
| Other then - impurities / contamination | Metal fragments or varnish from oil | Blocked filter | | | | Operator alarm response | | | | refer above low pressure. Redundant filter set with on-line change over capability | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | DC pump starter takes a few seconds to build pressure subject to oil temperature | Momentary dip in seal oil pressure | | | | | | | | No problem for MELCO design. Accumulator not required to maintain pressure | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Redundant DC battery banks. Pump supply fails over (Locky to confirm) | |
| Volts / Amps High | | | | | | | | | | MCC is monitored. Single AC pump. Why is the design not as robust as the lube oil system 2 x AC + 1 x DC? MELCO delivery per tender specification. Snowy correspondence notes based on auto hydrogen dump on loss of AC pump | 82. Snowy to review redundant AC seal oil pump configuration requirement and work with MELCO on solution |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--|---|------------|-------------|--------------|----------------------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 54 - Generator - Gland seal oil system Dwg A13C870 - Generator seal oil diagram for GT | | | | | | | | | | | |
| Pressure High | Blocked filter | Used to match up the oil and hydrogen pressure. No real consequence, potentially high vibration on start up if rings are well positioned around the shaft | Unlikely | Moderate | Medium | Rotor vibration hi hi trip | Rare | Moderate | Low | Gland seal is needed to centre the seal rings around the shaft. Shaft moves within the bearing casing (low position at no speed and moves progressively up and to the right with speed). If the seal rings are touching the shaft it will lead to high vibration. If gland seal is left on too long it can lead to ring destabilising and that again leads to high vibration. Ring shaft clearances vary from site to site and it is not clear if gland seal is needed every start up but in any case it is currently a manual Operator procedure for a remote operated site. It is best practice to enable the gland seal on hydrogen fill and at full speed for a short time on high vibration. | 83. Gland seal system if currently a manually operated procedure that is required during hydrogen fill and 'potentially' at full speed to centre the seal rings to reduce shaft vibration. Remotely operated solenoid would be the ideal solution. MELCO to confirm the design requirements and schedule impact to be confirmed |
| Pressure Low | Blocked filter | Poor seal hydrogen consumption through seal into LOOP seal oil tank | Unlikely | Negligible | Low | Operator alarm response | Unlikely | Negligible | Low | | |
| Pressure No or not | | | | | | | | | | Indicator gauges only. Loss of filter dP alarm | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | | | | | | | | | | Only used on start up with AC pump | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | Sensor failure | Alarm only | | | | | | | | | |
| Flow / Level - High | Needle valve not set correctly | Used to match up the oil and hydrogen pressure. No real consequence, potentially high vibration on start up if rings are well positioned around the shaft | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Operator procedure with pressure indicator PI-9 | |
| Flow / Level - High | Check valve left open after initial start up | Hydrogen seal ring damage after a long time | Rare | Negligible | Low | | Rare | Negligible | Low | Dual Operator procedure with lockable valve | |
| Flow / Level - Low | Needle valve not set correctly | Poor seal hydrogen consumption through seal into LOOP seal oil tank | Unlikely | Negligible | Low | Operator alarm response | Unlikely | Negligible | Low | | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | Only possible if DC pump running and NC check valve is open on start up. | Poor seal hydrogen consumption through seal into LOOP seal oil tank | Rare | Negligible | Low | | Rare | Negligible | Low | Start up and hydrogen fill would be aborted if DC pump started | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | | | | | | | | | | Clean oil H2 service | |
| Other then - impurities / contamination | Metal fragments or varnish from oil | Blocked filter | | | | Operator alarm response | | | | refer above low pressure. Redundant filter set with on-line change over capability | |
| Timing / Sequence - Early / Late | Operator error | Used to match up the oil and hydrogen pressure. No real consequence, potentially high vibration on start up if rings are well positioned around the shaft | Unlikely | Moderate | Medium | Rotor vibration hi hi trip | Rare | Moderate | Low | Dual Operator procedure with lockable valve. If Operator forgets to turn on gland seal oil before hydrogen fill then worst case poor hydrogen seal would flow hydrogen to LOOP seal oil tank and then to vent, potential loss of containment is considered NOT possible because seal oil system is running | |
| Timing / Sequence - Fast / Slow | Operator error - early | Poor seal hydrogen consumption through seal into LOOP seal oil tank | Unlikely | Negligible | Low | Operator alarm response | Unlikely | Negligible | Low | Dual Operator procedure with lockable valve | |
| Timing / Sequence - Fast / Slow | Operator error - late | Used to match up the oil and hydrogen pressure. No real consequence, potentially high vibration on start up if rings are well positioned around the shaft | Unlikely | Moderate | Medium | Rotor vibration hi hi trip | Rare | Moderate | Low | Dual Operator procedure with lockable valve | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-------|--------------|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|----------|---------|
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |

| | | | |
|------------------|---|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 9 of 13 |

Appendix 3: SnowyHydro Risk Matrix

When business risk is considered in the risk assessment, instrumented functions that are classified as machine interlocks may be re-classified as Safety Instrumented Functions (SIF) and will then require a Safety Integrity Level (SIL) assignment and SIF architecture verification study.

Likelihood frequencies were taken from the SnowyHydro corporate risk matrix, where

| | |
|----------|--|
| Certain | > 1 event / year |
| Likely | 1 to 2 years / event |
| Possible | 2 to 10 years / event (basic process control failure (machine life)) |
| Unlikely | 10 to 50 years / event (machine life, has happened in industry) |
| Rare | > 50 years /event (remote but theoretically possible event) |

Note that a basic process control system (BPCS) failure rate is typically 1 event per 10 years and therefore study records tend to be limited to Unlikely or Rare. A BPCS failure includes the sensors, the logic solver, the final elements (valves, contactors, etc) and where applicable the wiring and power supplies

| | | | | | | | | | |
|------------|------------|-------|----------|--------|---------|--------------|-------------------|------------|---------------------|
| Likelihood | Certain | Low | Medium | High | Extreme | Extreme | Extreme | > 0.9 | 1 yr /event |
| | Likely | Low | Medium | High | High | Extreme | Extreme | 0.5 - 1 | 1 - 2 yrs / event |
| | Possible | Low | Medium | Medium | High | High | Extreme | 0.1 - 0.5 | 2 - 10 yrs /event |
| | UnLikely | Low | Low | Medium | Medium | High | High | 0.02 - 0.1 | 10 - 50 yrs / event |
| | Rare | Low | Low | Low | Medium | Medium | High | < 0.02 | > 50 yrs /event |
| | Negligible | Minor | Moderate | Major | Severe | Catastrophic | Consequence Level | | |

| | | | | | | | |
|------------|----------|------------|-------|----------|-------|--------|--------------|
| Likelihood | Certain | 1 | 2 | 3 | 4 | 4 | 4 |
| | Likely | 1 | 2 | 3 | 3 | 4 | 4 |
| | Possible | 1 | 2 | 2 | 3 | 3 | 4 |
| | UnLikely | 1 | 1 | 2 | 2 | 3 | 3 |
| | Rare | 1 | 1 | 1 | 2 | 2 | 3 |
| | | Negligible | Minor | Moderate | Major | Severe | Catastrophic |

| RISK RATING MATRIX | | LIKELIHOOD | | | | |
|--------------------|--------------|------------|----------|----------|---------|----------------|
| | | Rare | Unlikely | Possible | Likely | Almost Certain |
| CONSEQUENCE | Catastrophic | High | High | Extreme | Extreme | Extreme |
| | Severe | Med | High | High | Extreme | Extreme |
| | Major | Med | Med | High | High | Extreme |
| | Moderate | Low | Med | Med | High | High |
| | Minor | Low | Low | Med | Med | Med |
| | Negligible | Low | Low | Low | Low | Low |

Risk Rating Matrix

Likelihood Criteria

| RATING | LIKELIHOOD | PROBABILITY |
|----------------|-------------------------------------|-------------|
| Almost Certain | The event is very likely to occur | >90% |
| Likely | The event will probably occur | 50% to 90% |
| Possible | The event might occur | 10% to 50% |
| Unlikely | The event probably won't occur | 2% to 10% |
| Rare | The event is very unlikely to occur | <2% |

In determining the appropriate likelihood rating for your risk, consider the timeframe within which you are delivering your objective and select a rating that indicates the likelihood of the risk event occurring over that period. The timeframe could be, for example, the life of an asset (years) or an individual payroll run (hours).

* For example, a risk with a likelihood of "Possible" and a consequence

| Consequence Criteria | RATING | FINANCIAL | SAFETY | ENVIRONMENT | COMPLIANCE | AVAILABILITY | REPUTATION | |
|----------------------|--------------|---|---|--|---|--|--|---|
| | Catastrophic | Cost variation or financial loss greater than \$300M. | Multiple fatalities involving employees, contractors or members of the public. | Permanent impact on populations of significant (eg threatened) flora or fauna. Permanent unconfined impact on previously undisturbed ecosystem. | Permanent impact on populations of significant (eg threatened) flora or fauna. Long term impacts on soil, air or water quality. Or Potential for long term off-site impacts. Loss of numerous significant heritage items. | Snowy Hydro loses a licence to operate (eg AFSL, Snowy Park Lease, Retail licence). | Approximately 1500MW of generating plant unavailable to the market for more than 6 months. | Court, regulator or Government inquiry concludes improper, corrupt or grossly negligent conduct by Snowy Hydro. |
| | Severe | Cost variation or financial loss between \$20M and \$300M. (The current consequence criteria simply has a threshold of \$20 million). | Single fatality or permanent significant disability, long term impairment or illness significantly affecting the quality of life for an employee, contractor or member of the public. | Long term (>10 year) impact on populations of significant (eg threatened) flora or fauna. Long term impacts on soil, air or water quality. Or Potential for long term off-site impacts. Loss of numerous significant heritage items. | Claim or action (other than by a Regulator) involving an amount greater than \$20M (including court/defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty greater than \$5M; and/or 2. Imposition of requirements that would cost more than \$20M (including court/defence/compliance costs and loss of revenue) | Approximately 1500MW between generating plant unavailable to the market for between 1 week and 6 months. | Incident or issue causes prolonged, negative national media coverage. Court, regulator or Government inquiry alleges improper, corrupt or grossly negligent conduct by Snowy Hydro. Other action by Snowy Hydro results in shareholders dismissing one or more directors. | |
| | Major | Cost variation or financial loss between \$5M and \$20M. | Long term or permanent disability, impairment or illness not significantly affecting the quality of life for an employee, contractor or member of the public. | Medium term (3-10 year) impact on populations of native flora or fauna. Medium term impacts on soil, air, water quality or habitat. Potential for medium term off-site impacts. | Claim or action (other than by a Regulator) involving an amount between \$5M and \$20M (including court/defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty between \$1M and \$5M; and/or 2. Imposition of requirements that would cost between \$5M and \$20M (including court/defence/compliance costs and loss of revenue) | Approximately 1500MW of generating plant unavailable to the market for between 1 day and 1 week; or 600MW of plant unavailable for at least 1 week; or 300MW of generating plant unavailable for a month or more. | Incident or issue causes negative state wide media attention and regulatory intervention. Government inquiry into Snowy Hydro's actions or operations in regard to conduct, pricing etc. Action by Snowy Hydro results in one or more Executives or senior managers being terminated. | |
| | Moderate | Cost variation or financial loss between \$1M and \$5M. | Hospitalisation with medical intervention of an employee, contractor or member of the public. | Short term (1-3 year) impact on flora or fauna. Short term impact on soil, air, water quality or habitat. Impact mostly confined to work area but potential short term off-site impacts. Loss of a significant (eg Category A and B) heritage item. Visual, noise or airborne dust impacts with potential for regulator response. | Claim or action (other than by a Regulator) involving an amount between \$1M and \$5M (including court/defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty between \$100K and \$1M; and/or 2. Imposition of requirements that would cost between \$1M and \$5M (including court defence/compliance costs and loss of revenue) | Approximately 1500MW of generating plant unavailable to the market for between 1 hour and 1 day; or 600MW generating plant unavailable for between 1 day and 1 week; or 150MW of generating plant unavailable for a month or more. | Incident or issue causes local outrage with potential for escalation to state media and/or to generate regulator interest. State or Federal regulator conducts formal inquiry into broader industry issues which encompass Snowy Hydro's operations. Major changes to Snowy Hydro operations have significant local community impacts. | |
| | Minor | Cost variation or financial loss between \$100K and \$1M. | Injury or illness requiring medical treatment of an employee, contractor or member of the public. | Adverse impact to significant (eg Category A and B) heritage item. Visual, noise or airborne dust impacts with potential for credible stakeholder/public complaint. | Claim or action (other than by a Regulator) involving an amount between \$100K and 1M (including court/ defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty between \$10K and \$100K; and/or 2. Imposition of requirements that would cost between \$100K and \$1M (including court defence/compliance costs and loss of revenue) | Approximately 600MW of generating plant unavailable to the market for up to 1 day; or up to 300MW of generating plant unavailable for up to 1 week; or up to 100MW of generating plant unavailable for a month or more. | Incident or issue causes local outrage with no potential for escalation. Short term negative regional media attention around a minor, localised issue. Minor damage to reputation with a regulator. | |
| | Negligible | Cost variation or financial loss less than \$100K. | Nil to first aid injury, low level short term inconvenience or symptoms for an employee, contractor or member of the public. | Promptly reversible/trivial impact on air, water, soil, flora, fauna, habitat or heritage.. | Claim or action (other than by a Regulator) involving an amount up to \$100K (including court/defence/ compliance costs and loss of revenue); or Notification to a Regulator is required (but with no other consequence); or Regulator action that results in: 1. A warning notice; 2. A penalty up to \$10K; and/or 3. Imposition of requirements that would cost up to \$100K (including court/defence/compliance costs and loss of revenue) | Loss of a single generating unit for up to a day. | Incident or issue causes local inconvenience. Negative comment about Snowy Hydro at regional level. Formal complaint made to Snowy Hydro by the public. | |

330 mw Capacity loss
300 \$/mw Unit loss
24 hrs out Outage time
\$ 2,376,000 Event impact

| | | | |
|------------------|---|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 10 of 13 |

Appendix 4: HAZOP action items

Note that this section collates all the workshop action items into one list for quick reference. The reader will need to refer to the Study Records in Appendix 2 for the background and references (node, dwg, descriptions, etc) of each action.

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|--|--------------------------------|---------------------------|------------|----------------------------------|---|--------|
| 1 | 1. Confirm forwarding pump deadhead pressure and prv | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | SHL to coordinate | | Open |
| 2 | 2. Review bunding requirements around FO pumps | sara.roder@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | SHL AECOM to coordinate | | Open |
| 3 | 3. Confirm \$ cost per unit trip / 1 hr outage | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | | | Open |
| 4 | 4. All ball valves to be lockable | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | SHL AECOM to coordinate | | Open |
| 5 | 5. SHL to review who supplies instrumentation at MHI interfaces | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | | | Open |
| 6 | 6. AECOM to consider heat tracing for FO dwg 2of 5. Start up temperature should be 11 deg C. Alternative may be an enclosure for the pump and piping | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 7 | 7. The screw pump has no min flow bypass return line. The HP pump only starts when burners are to be lit. When no burner flow the manifold pressure control valve acts as the min flow control. MHI to confirm forwarding pump flow rate through HP screw pump when shutdown | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 8 | 8. MHI manual ball valves should all be lockable type, i.e. flow divider drain valves. SHL to discuss requirements with MHI | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 9 | 9. Pantac to review blade path flameout voting logic. One or multiple burners, adjacent burners, single or duplex t/c. No optical flame detectors | paul.vandyk@pantac.com.au | 2. Prior to Commissioning | 25.2.2022 | in time for coordination meeting | | Open |
| 10 | 10. MHI to advise combustion frequency sensor criticality. Commissioning tool or protection | MHI | 2. Prior to Commissioning | 25.2.2022 | in time for coordination meeting | Extended operation can lead to catastrophic failure. Combustion components and blades | Closed |
| 11 | 11. SHL investigating additional diesel fuel quality reports | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 25.2.2022 | in time for coordination meeting | | Open |
| 12 | 12. MHI to confirm if there is a drain tank Hi level start permissive. Unit wont start with high level | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 13 | 13. SHL to confirm with operations to see if small lines have been problematic with non-return valves failing / passing | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 14 | 14. AECOM to consider drain pit discharge hi alarm to start pump and hi hi to alarm to remote operations | jason.lawer@aecom.com | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 15 | 15. AECOM Fuel oil discharge to oily water pit detection to be considered in design | jason.lawer@aecom.com | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 16 | 16. MHI to confirm at what load level water injection is enabled. Also when water injection is not correct the unit would go to run back load, where water injection is turned off. | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | WI on at 50% load, Pilot water injection on during start up | Closed |
| 17 | 17. SHL to confirm action required when water injection is off, i.e. valley will try to restart water injection 3 times and max operating time without water injection is 15 minutes. Automatic shutdown required, tbc and advise to MHI or add into station controls | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 25.2.2022 | in time for coordination meeting | | Open |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|--|--|---|------------|----------------------------------|---|--------|
| 18 | 18. Oily water pit to be covered with rain shelter | jason.lawer@aecom.com | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 19 | 19. AECOM to consider valve failure, excessive flow to oily water pit overflow during runback time. Flow balance required. MHI to advise oily water flow rate and volumes expected during normal operating conditions and if one of the drain valves fails open, MBN13AA735,AA736,AA737 based on SHL RFI document | 1. SHL then 2. MHI then 3. AECOM to design accordingly | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 20 | 20. Water injection flow transmitter is a single point of failure which would cause diesel outage, so it is critical for operation. Redundancy for valve control per fuel oil control should be considered. MBU02CP531. | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | | | Open |
| 21 | 21. Single point of failure mode analysis should be completed at a suitable time. SHL internal item | evan.bayliss@snowyhydro.com.au | 3. Prior to Handover for Beneficial Operation | 25.2.2022 | | | Open |
| 22 | 22. Outage, run back, emergency trip restart time cost analysis required for Risk Assessment decision around device fault tolerance, i.e. trip or 1 hours outage = 800k (330MW x 2500MW/Hr x 1 hr), additional instrument = 20k installed | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | | | Open |
| 23 | 23. Purge credit details are not well understood by Operations. There is a manual, Operating Procedure(S4-96597), that describes it in more detail. Type B compliance, intermittent or continuous turning and start and re-purge credit are all good questions. Potentially every 8 days the unit needs repurging, which can lead to more blade wear (wobbling in root) and starter problems. This item to be revisited by Operations with MHI detail input. | evan.bayliss@snowyhydro.com.au | 3. Prior to Handover for Beneficial Operation | 25.2.2022 | in time for coordination meeting | | Open |
| 24 | 24. MHI to review if fuel oil from the fuel oil purge credit can go to the tank not the pit as it is clean fuel. Environmental credit | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 25 | 25. Fuel oil purge credit valves only have a single limit switch, preference for both open and closed indication, all valves (block, drain, N2). AECOM supply these valves | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 26 | 26. MHI to check logic. Gas vent valve out of position during operation should be a trip. Redundant limit switches may be. | | 2. Prior to Commissioning | 25.2.2022 | in time for coordination meeting | | Open |
| 27 | 27. AECOM should review vent valve position failure actions | jason.lawer@aecom.com | 2. Prior to Commissioning | 25.2.2022 | | | Open |
| 28 | 28. AECOM to review appliance manual isolation valve per AS3814 requirements within 5m of the appliance. Paul van Dyk to confirm AS3814 clause requirements | paul.vandyk@pantac.com.au | 1. Prior to Construction | 25.2.2022 | | 5m is considered remote for individual burners but one lockable hand valve for the unit pre-coalescer meets the requirements. AECOM model location is similar to Laverton | Closed |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|---|--------------------------------|---|------------|----------------------------------|--------|--------|
| 29 | 29. Tapping points for pressure testing / leak testing valves not shown on P&ID. Additional testing points may be required. SHL to review based on length of pipework and valve locations. | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 30 | 30. MHI to review AS3814 section 2.13 requirement for sufficient test points to verify the integrity of shutoff valve / train. | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 31 | 31. RFI for the purpose of the HAZOP the main question, is there a single point of failure (DPT) and what would be consequence of a critical time pressure excursion explosion. Is DPT control or protection, refer control description fig 2.9.1 | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 32 | 32. MHI to confirm temperature rating of pipework after MBA01AA704, burner drain valve. Rating drops from 525 to 60 Celsius | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 33 | 33. Water wash procedure has many manual valves which could potentially lead to false start by flooded combustion chamber and subsequently detergent flow into the oil water pit. SHL to develop a water wash procedure with 2 operators to cross check. Water washing drain header could also have small amounts of diesel residue from liquid fuel false start. | evan.bayliss@snowyhydro.com.au | 3. Prior to Handover for Beneficial Operation | | | | Open |
| 34 | 34. Commissioning spool required for flow meter, that will need to be removed for pipe blow down activities. Mark up P&ID | jason.lawer@aecom.com | 2. Prior to Commissioning | 25.2.2022 | | | Open |
| 35 | 35. Add instrument tapping point for Nitrogen entry for valve leak testing, with smaller volume than upstream line | jason.lawer@aecom.com | 1. Prior to Construction | 25.2.2022 | | | Open |
| 36 | 36. Calorie meter. 1. Cal gas bottles only have single regulator and no relief valve. Potential single point of failure. Is meter rated for cal gas pressure. 2. If reg fails, is it possible to reverse flow cal gas into the gas line? 3. Why is there a flow meter in the vent line? | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 37 | 37. All ball valves to be lockable. Evan to confirm who is responsible for providing the pad locking system for all the manual isolation valves and to ensure the valves have lock tabs, refer also action item 4. Also send sample photos to MHI. The requirement is in the tender specification section 2.3 | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | SHL AECOM to coordinate | | Open |
| 38 | 38. MHI to confirm failure mode of IGV, i.e. fail last position, fail ramp closed on loss of control oil or power? | MHI | 2. Prior to Commissioning | 25.2.2022 | in time for coordination meeting | | Open |
| 39 | 39. 2oo3 trip voting degradation to be reviewed on a trip by trip basis by SHL, 2oo3, 1oo2 or 2oo2 and 1oo1 = trip or run? | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 25.2.2022 | | | Open |
| 40 | 40. DC Lube oil pump to be tested prior or after each start to prove functionality. Replacing MBV01CP304 DC lube oil pressure gauge with a transmitter would facilitate fast auto test sequence. Requirements to be confirmed by SHL | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 25.2.2022 | | | Open |
| 41 | 41. SHL to review high temperature alarm shutdown requirements for Hunter. Remote operator may not react in time. | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 25.2.2022 | | | Open |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|---|--|---|------------|----------------------------------|--------|--------|
| 42 | 42. SHL may request additional oil sampling point downstream of the bearings (generator and turbine). MHI to review installation requirements and advise accordingly | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 43 | 43. There is a wall in the oil tank which may create different tank levels, design to be confirmed by MHI | MHI | 1. Prior to Construction | 25.2.2022 | in time for coordination meeting | | Open |
| 44 | 44. Fuel gas and Fuel Oil control oil dump valves are single point of failure and common cause fraction is high. Is this allowed per the standard. Valves should failsafe and individually actuated?? PVD to review in detail as part of AS3814 compliance | paul.vandyk@pantac.com.au | 1. Prior to Construction | 1.4.2022 | | | Open |
| 45 | 45. Control oil dump circuits to be reviewed against SIL requirements and AS3814 compliance | paul.vandyk@pantac.com.au | 1. Prior to Construction | 1.4.2022 | | | Open |
| 46 | 46. Note AECOM responsible for Fire protection of the Balance of Plant equipment such as lube oil package, fuel oil pump / valve systems and how that system is interlock or integrated into the plant DCS or MHI GT controls. AECOM is design stage now. Fire safety study is well advanced MHI fire and gas detection limited to GT enclosure and Fuel Gas valve systems. SHL to review final design proposal | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 15.03.2022 | | | Open |
| 47 | 47. Door tracking isolating the CO2 if someone enters the GT is to be confirmed by vendor and reviewed by SHL | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 15.03.2022 | | | Open |
| 48 | 48. Ambient conditions -5 C to +45 C. Anti-icing system was considered in the tender specification but MHI advised at that time it is not required. MHI to revisit the study and reconfirm anti-icing is not required. | MHI | 1. Prior to Construction | 1.04.2022 | in time for coordination meeting | | Open |
| 49 | 49. Valve numbers and instrument numbers and line sizes are not shown on the drawing. Return valve is shown as control valve but is actually a manual lockable isolation valve | MHI | 3. Prior to Handover for Beneficial Operation | 15.3.2022 | in time for coordination meeting | | Open |
| 50 | 50. Evap tank water is potable water. Should overflow or draining be discharged to Trade Waste or Storm Water. AECOM to review and design accordingly | AECOM | 1. Prior to Construction | 1.06.2022 | | | Open |
| 51 | 51. Evap tank has no sample point. MHI to review option to supply | MHI | 1. Prior to Construction | 1.04.2022 | in time for coordination meeting | | Open |
| 52 | 52. MELCO interface details required for AECOM water services. Water pressure recently increased to 7.5 Bar. AECOM to advise MELCO final supply pressure. MELCO cooler to be designed accordingly | blair murray AECOM | 1. Prior to Construction | 1.04.2022 | in time for coordination meeting | | Open |
| 53 | 53. MELCO to provide full list of generator protection settings, trips complete with alarms, auto shutdown and run backs | Melco - Kohei Miura - H2 seal oil system | 2. Prior to Commissioning | 1.04.2022 | in time for coordination meeting | | Open |
| 54 | 54. Manual purging requires strict procedure with 2 people to cross check to confirm successful purge | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 15.03.2022 | | | Open |
| 55 | 55. CO2 site capacity to be assessed against minimum volume required for a successful purge times a safety factor. Potential bottle leak reduces capacity. Is adequate monitoring installed, flow pressure bottle weight | AECOM | 1. Prior to Construction | 1.06.2022 | | | Open |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|---|--|---------------------------|------------|----------------------------------|--------|--------|
| 56 | 56. Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. MHI incorporate in design, logic to action valve. | MHI | 1. Prior to Construction | 1.04.2022 | in time for coordination meeting | | Open |
| 57 | 57. Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. AECOM to incorporate automate CO2 supply to the units | AECOM | 1. Prior to Construction | 1.06.2022 | | | Open |
| 58 | 58. Unit H2 flow meter can be used for make up flow monitoring, leak and PRV lifting detection. SHL to review | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 1.04.2022 | | | Open |
| 59 | 59. AECOM to review H2 pipework for dissimilar metals. MELCO supply all 304 stainless. Potential corrosion and Haz area issue | AECOM | 1. Prior to Construction | 1.04.2022 | | | Open |
| 60 | 60. CO2 line has no filter or strainer. It is rarely used which could create fouling issues. MELCO to consider and quote option | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | | Open |
| 61 | 61. MELCO to review automating the Hydrogen make up valve as the site is normally not manned. | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | | Open |
| 62 | 62. Hydrogen pressure transmitter PT1 is potentially a single point of failure for an unmanned site. MHI to confirm signal failure response | MHI | 2. Prior to Commissioning | 1.04.2022 | in time for coordination meeting | | Open |
| 63 | 63. Dew point monitoring is currently not part of the scope. SHL to request a quotation from MDI to add dew point monitoring | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 64 | 64. Melco to confirm what happens to the purity meter if CV-1 fails and flow is too low or no flow or needle valve set incorrectly. Hydrogen purity is important for purging requirements | MHI | 2. Prior to Commissioning | 1.04.2022 | in time for coordination meeting | | Open |
| 65 | 65. SHL to develop written procedure for sampling purity with portable analyser to confirm main analyser reading is correct. Drain sampling and valve switching is manual to select top or bottom of the generator sampling. Note sampling drain point is within hazardous area | evan.bayliss@snowyhydro.com.au | 2. Prior to Commissioning | 1.09.2022 | | | Open |
| 66 | 66. Site wide review of field mounted instrumentation junction boxes and field panels required. These are normally fitted with heaters to prevent condensation | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 67 | 67. MHI to supply instrumentation datasheets for action item 66. To confirm field instrumentation ratings, i.e. +5 - +45 non-condensing?? | MHI | 1. Prior to Construction | 1.04.2022 | in time for coordination meeting | | Open |
| 68 | 68. AECOM to study hydrogen detection requirements for this open area plant area and that location is under exciter which probably has cooling fans that could draw H2 into enclosure | AECOM | 1. Prior to Construction | 1.04.2022 | | | Open |
| 69 | 69. MELCO to add check valve before CO2 manual isolation valve | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | | Open |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|--|--|---------------------------|------------|----------------------------------|---------------------|--------|
| 70 | 70. Hydrogen dryer blower intake is open to atmosphere and in close proximity to the Operator swinging the 3-ways valves. Incorrect procedure (monthly) or Operator error would vent Hydrogen out of air intake. Operator exposure to fire / explosion (static). Design review required. Air intake pipe to safe area to seal system or automated double block and bleed per combustion standard | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 71 | 71. MELCO to quote additional double block and vent isolation valves for on-line maintenance of heater system, to eliminate H2 purge of complete system. Snowy standard maintenance requirement | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | | Open |
| 72 | 72. There is a discrepancy between MELCO pipe sizes and MHI drawing A-21022 page 2of 4. MHI to review and correct | MHI | 1. Prior to Construction | 1.04.2022 | in time for coordination meeting | | Open |
| 73 | 73. MELCO design is heavily reliant on Operator alarm response and on site Operator rounds. This is not how Snowy normally operate. Additional instrumentation would be likely be installed on future upgrades. MELCO design to be reviewed for potential instrumentation upgrades | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 74 | 74. AECOM to incorporate seal oil system drip / leak tray overflow to oily water system in their design | AECOM | 2. Prior to Commissioning | 1.04.2022 | | | Open |
| 75 | 75. Seal oil system drip tray or banded area should be remotely monitored for large leaks and potentially auto draining function of sight glass. Similar to fuel oil / lube oil bunds | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 76 | 76. Seal oil vacuum tank fill valve is a single point of failure which can lead to lube oil overflowing the tank and lube oil discharging via the vent stack, potential large quantities due to unmanned site. Alarm response cannot prevent this consequence and would happen quite quickly. Design review required | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 77 | 77. MELCO to review design to define the potential consequences of an unmanaged seal oil system failure and loss of hydrogen containment. Snowy will use this information to risk assess the installation per HAZOP guidelines | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | Potential explosion | Closed |
| 78 | 78. Change DC pressure PI-5 to pressure transmitter for DC pump test run and linking to H2 automatic venting system. MELCO team suggest change is technically possible but may cause delays. Snowy to review schedule impact and instruct MELCO accordingly | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 79 | 79. MELCO team to confirm DC pump recirc line size. The large size valve passing may result in very low DC seal oil pressure | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | | Open |
| 80 | 80. AC and DC suction pressure indicators not shown on drawing but will be provided. MELCO to update drawing | Melco - Kohei Miura - H2 seal oil system | 2. Prior to Commissioning | 1.04.2022 | | | Open |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|---|--|--------------------------|------------|---------------------|--------|--------|
| 81 | 81. DC pump inlet (suction side) check valve stuck closed resulting in no oil pressure in a demand scenario. Why do we need this valve and is it normally open or closed. Confirm also design of this valve, i.e. spring, lockable, power cylinder?? | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | Normally open valve | | Open |
| 82 | 82. Snowy to review redundant AC seal oil pump configuration requirement and work with MELCO on solution | evan.bayliss@snowyhydro.com.au | 1. Prior to Construction | 1.04.2022 | | | Open |
| 83 | 83. Gland seal system if currently a manually operated procedure that is required during hydrogen fill and 'potentially' at full speed to centre the seal rings to reduce shaft vibration. Remotely operated solenoid would be the ideal solution. MELCO to confirm the design requirements and schedule impact to be confirmed | Melco - Kohei Miura - H2 seal oil system | 1. Prior to Construction | 1.04.2022 | | | Open |

| | | | |
|------------------|---|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 11 of 13 |

Appendix 5: Safeguards

| No | Safeguards - Description | Instances | Notes |
|----|---|-----------|--|
| 1 | PRV MBN12AA126 | 0 | 0 instance means it is not referenced in the study records |
| 2 | PS MBN12CP211 | 2 | |
| 3 | PT MBN12CP118, MBN12CP119 | 2 | |
| 4 | PDIT MBN12CP521 MBN12CP522 | 2 | |
| 5 | Blade path temperature | 30 | High instance count for flame out and combustion trouble detection |
| 6 | Limit switch alarm | 2 | |
| 7 | Overspeed protection | 3 | |
| 8 | Combustion pressure monitoring trip | 5 | |
| 9 | 2oo3 High pressure trip and 5 block valves in series | 1 | |
| 10 | 2oo3 Low pressure trip and 5 block valves in series | 1 | |
| 11 | 2oo3 High temperature trip and 5 block valves in series | 2 | |
| 12 | Vent valve position trip | 2 | |
| 13 | Gas control valve position trip | 1 | |
| 14 | 2oo3 High gas temperature trip | 1 | |
| 15 | Exhaust gas pressure Hi Hi trip | 1 | |
| 16 | Rotor vibration hi hi trip | 4 | Generator rotor vibration |
| 17 | Fuel transfer limited to part load | 1 | |
| 18 | Sweep air block valve out of position auto shutdown | 1 | |
| 19 | Filter dP alarm | 1 | |
| 20 | Valve out of position shutdown | 5 | |
| 21 | Start permissive | 3 | |
| 22 | IGV out of position trip | 4 | |
| 23 | Shaft vibration Hi Hi trip | 5 | Turbine shaft vibration |
| 24 | 2oo3 Exhaust pressure Hi Hi trip | 2 | |
| 25 | NooM Exhaust temp Hi Hi trip | 3 | |
| 26 | DCS general electrical monitoring | 2 | |
| 27 | Automatic Runback | 6 | |
| 28 | 2oo3 Lube oil pressure Lo Lo trip | 7 | |
| 29 | 2oo3 Lube oil temperature Hi Hi trip | 3 | |
| 30 | Bearing temp Hi Hi trip - does not exist | 0 | 0 instance means it is not referenced in the study records |
| 31 | 1oo1 MBV10CP101 Loss of vacuum Normal Stop | 3 | |
| 32 | PRV MBX01AA114 | 1 | |

| | | | |
|----|--|----|---|
| 33 | 2oo3 Control oil pressure Lo Lo trip | 5 | |
| 34 | 1oo1 MBX01CT001 control oil tank temp alarm | 2 | |
| 35 | Fire detection and suppression systems | 2 | |
| 36 | Loss of ventilation trip | 2 | |
| 37 | Combustible gas detection trip | 1 | |
| 38 | 2oo3 Inlet filter dp Hi Hi trip | 3 | |
| 39 | QEF13CP501 Inlet filler dp alarm | 1 | |
| 40 | Operator alarm response | 20 | High instance count but an administrative control is not actually a reliable Protection Layer |
| 41 | PRV 90SSD01AA904 | 2 | |
| 42 | PRV QEE02AA903 | 1 | |
| 43 | dual Hi Hi level Generator water detectors | 2 | |
| 44 | Stator winding temp Hi auto stop | 6 | |
| 45 | PRV RV-2 CO2 release | 1 | |
| 46 | Dual operator procedure | 4 | |
| 47 | Automatic H2 vent and CO2 purge | 2 | |
| 48 | PRV RV-1 H2 release | 1 | |
| 49 | Dew point monitoring | 2 | |
| 50 | LS-5 seal oil vacuum tank level hi | 0 | Does not prevent consequence |
| 51 | PS-1 seal oil pressure c/w DC back up pump | 3 | |
| 52 | DPS-1 seal oil diff pressure c/w DC back up pump | 3 | |

| | | | |
|------------------|---|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 12 of 13 |

Appendix 6: Participants

| No | Email | Attendance | | | | | | | | | | | Discipline |
|----|--|----------------|-----------------|-----------------|-----------------|-----------------|-----------------|----------------|-----------------|-----------------|------------------|------------------|--|
| | | day 1 7 Feb | day 2 10 Feb | day 3 14 Feb | day 4 16 Feb | day 5 21 Feb | day 6 24 Feb | day 7 9 Mar | day 8 10 Mar | day 9 16 Mar | day 10 18 Mar | day 11 25 Mar | |
| 1 | ben.teh@snowyhydro.com.au | am | n | y | n | n | n | n | n | n | n | n | Project engineer |
| 2 | Blair.Murray@aecom.com | n | y | y | y | y | y | y | y | y | y | y | Project Engineer - Mechanical |
| 3 | damian.cooper@snowyhydro.com.au | y | n | y | n | y | n | y | n | y | y | y | Operations |
| 4 | david.bedding@snowyhydro.com.au | x | n | n | n | n | y | n | n | n | n | n | Operations |
| 5 | desk@pooetranslation.com.au | y | y | y | y | y | y | y | y | y | y | y | Translation services |
| 6 | Donny Richmond - Jacobs | y | y | n | n | n | n | n | n | n | n | n | Combustion engineer |
| 7 | emily.9CPT@pooetranslation.com.au | n | y | n | n | y | y | n | n | n | n | n | Translation QC |
| 8 | Errol.Lannin@snowyhydro.com.au | am | n | n | n | n | n | n | n | n | n | n | Operations - Plant manager LPS |
| 9 | evan.bayliss@snowyhydro.com.au | am | y | n | n | n | n | n | n | n | n | n | Design and Quality lead engineer |
| 10 | frank.safi@wsp.com | y | y | y | y | n | n | n | n | n | y | y | Gas turbine combustion specialist |
| 11 | jason.lawer@aecom.com | y | n | n | n | n | n | n | n | n | n | n | Project technical director |
| 12 | Karl.Ivanusic@jacobs.com | y | y | y | y | y | y | y | y | y | y | y | Project Engineer - Mechanical |
| 13 | Kerri Wells AECOM | n | n | 1 hr | n | n | n | n | n | n | n | n | Project Engineer - Mechanical |
| 14 | lachlan.smith@snowyhydro.com.au | y | y | y | y | y | y | n | y | y | y | y | Project Egnieer - Mechatronics |
| 15 | maria.iseya@ | n | y | n | n | y | y | n | n | n | n | n | Translation services |
| 16 | MHI - hirofumi.moriguchi.3h@mhi.com | n | y | y | y | y | y | y | y | y | y | y | Project manager |
| 17 | MHI - eiki.anzawa.c7@mhi.com | y | y | y | n | y | y | y | y | n | n | n | Control system engineer |
| 18 | MHI - daisuke.shibita.37@mhi.com | y | y | y | y | y | y | y | y | n | n | n | Control system engineer |
| 19 | MHI - yoji.oshino.mr@mhi.com | n | y | y | y | y | y | y | y | n | n | n | Plant Engineer |
| 20 | MHI - masaaki.yamasaki.4e@mhi.com | n | n | n | n | n | y | y | y | n | n | n | Plant Engineer |
| 21 | MHI action item | | | | | | | | | | | | |
| 22 | olivia.panjkov@snowyhydro.com.au | n | am | n | n | n | n | n | n | n | n | n | |
| 23 | Patrick.Scholtes@snowyhydro.com.au | n | n | y | n | y | y | n | n | n | n | y | Mechanical gas assets |
| 24 | paul.hill@snowyhydro.com.au | n | y | n | n | n | n | n | n | n | n | n | Operations |
| 25 | paul.vandyk@pantac.com.au | y | y | y | y | y | y | y | y | y | y | y | Facilitator - Functional Safety Engineer |
| 26 | rebecca.johnson@snowyhydro.com.au | y | n | n | n | n | n | n | n | n | n | n | Mech eng 1st year |
| 27 | sara.roder@snowyhydro.com.au | y | y | y | y | y | y | y | y | y | y | y | Mech eng 1st year |
| 28 | francois.vallette@snowyhydro.com.au | n | n | n | n | y | y | y | y | y | n | n | Mechanical |
| 29 | Melco - Kohei Miura - H2 seal oil system | n | n | n | n | n | y | n | y | y | y | y | Project Engineer - Mechanical |
| 30 | Melco - Eura - H2 seal oil system | n | n | n | n | n | n | n | n | n | y | y | Project Engineer - Mechanical |
| 31 | Tony Slinko - Jacob | n | n | n | n | n | n | n | n | n | y | n | Electrical Engineer |

| | | | |
|------------------|---|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 001-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | PO No. | |
| Area/Unit/System | HPS/GT1 and 2/Gas Turbine Generator process systems | Page | Page 13 of 13 |

Appendix 7: Acronyms

ACRONYMS

The following acronyms may be used throughout this course and reference documents:

| | |
|---------------------------|---|
| AIChE | American Institute of Chemical Engineers |
| AC/DC | Alternating current/direct current |
| ALARP | As low as reasonably practicable |
| ANSI | American National Standards Institute |
| ANSI/ISA | American National Standards Institute/ Instrumentation, Systems and Automation |
| API | American Petroleum Institute |
| ANSI / API 611 | American Petroleum Institute: General purpose steam turbines |
| ANSI / API 612 | Australian Standard: Special purpose steam turbines |
| ANSI/ISA-84.01 | Application of Safety Instrumented Systems for the Process Industries. |
| AS | Australian Standard |
| ASME | American Society of Mechanical Engineers |
| AS 1375 | Australian Standard: Industrial fuel fired appliances |
| AS 3814 | Australian Standard: Industrial and commercial gas-fired app. |
| AS 4629 | Australian Standard: Automatic shut off and vent valves. |
| AS / IEC 61508 | Australian Standard: Functional safety of electrical /electronic/programmable electronic safety-related systems - Set |
| AS / IEC 61511 process | Australian Standard: Functional safety - Safety instrumented systems for the industry sector |
| BI | Business Interruption |
| BLEVE | Boiling Liquid Expanding Vapor Explosion |
| B.P. | Boiling Point |
| BPCS | Basic Process Control System |
| C | Consequence factor, related to magnitude of severity |
| CCF | Common Cause Failure |
| CCF | Common Cause Factor |
| CCPS | Center for Chemical Process Safety, American Institute of Chemical Engineers |
| CEI | Dow Chemical Exposure Index |
| HAZOP | Controls Hazard & Operability Study |
| CMS | Consequence Mitigation System |
| CPQRA | Chemical Process Quantitative Risk Assessment |
| CW | Cooling Water |
| DC | Diagnostic coverage |
| <i>D</i> | Number of times a component or system is challenged (hr ⁻¹ or year ⁻¹) |
| DCS | Distributed Control System |
| DIERS | Design Institute for Emergency Relief Systems, American Institute of Chemical Eng. |
| DOT | Department of Transportation |
| EBV | Emergency Block Valve |
| E/E/PE | Electrical/electronic/programmable electronic |
| E/E/PES | Electrical/electronic/programmable electronic system |
| EMC | Electro-magnetic compatibility |
| ERPG | Emergency Response Planning Guideline |
| EuReData | European Reliability Data (series of conferences)FAT Factory acceptance testing |
| <i>F</i> | Failure Rate (hr ⁻¹ or year ⁻¹) |
| <i>f</i> | Frequency (hr ⁻¹ or year ⁻¹) |
| F&EI | Dow Fire and Explosion Index |
| F/N | Fatality Frequency versus Cumulative Number |
| FCE | Final Control Element |

| | |
|-------------------------|--|
| FMEA | Failure Modes and Effect Analysis |
| FMECA | Failure Mode Effect and Criticality Analysis |
| FPL | Fixed program language |
| FTA | Fault Tree Analysis |
| FVL | Full variability language |
| HAZOP | Hazard and Operability Study |
| HE | Hazard Evaluation |
| HFT | Hardware fault tolerance |
| HMI | Human machine interface |
| HRA | Human Reliability Analysis H&RA Hazard and risk assessment |
| H/W | Hardware |
| IEC | International Electro technical Committee |
| IEEE | Institute of Electrical and Electronic Engineers |
| IEV | International Electrotechnical Vocabulary |
| I/O | Input or Output |
| IPL | Independent Protection Layer |
| ISA | The Instrumentation, Systems, and Automation Society |
| ISO | International Organization for Standardization |
| ISO 10437 | Special purpose steam turbines |
| LAH | Level Alarm—High |
| LI | Level Indicator |
| LIC | Level Indicator—Control |
| LFL | Lower Flammability Limit |
| LNG | Liquefied Natural Gas |
| LOP | Layer of Protection |
| LOPA | Layer of Protection Analysis |
| LOTO | Lock-Out Tag-Out |
| LT | Level Transmitter |
| LVL | Limited variability language |
| MAWP | Maximum Allowable Working Pressure |
| MOC | Management of Change |
| MOC | Management of Change |
| Moon | “M” out of “N” |
| MTBF | Mean Time Between Failures |
| MTTF | Mean Time To Failure |
| NFPA | National Fire Protection Authority |
| NFPA 85 | NFPA Standard: Boiler and Combustion Systems Hazards Code |
| NFPA 86 | NFPA Standard: Ovens and Furnaces |
| NP | Non-programmable |
| N ₂ | Nitrogen |
| OSBL | Outside Battery Limits |
| OREDA | The Offshore Reliability Data project |
| OSHA | Occupational Safety and Health Administration (U.S.) |
| <i>P</i> fatality | Probability of Fatality |
| <i>P</i> ignition | Probability of Ignition |
| <i>P</i> person present | Probability of Person Present |
| <i>P</i> | Probability |
| PCS | Premier Consulting Service |
| PE | Programmable electronics |
| PES | Programmable electronic system |
| PFD | Probability of Failure on Demand |

| | |
|-----------|--|
| PFDavg | Average probability of failure on demand |
| PHA | Process Hazard Analysis |
| PI | Pressure Indicator |
| PL | Protection Layer |
| PLC | Programmable logic controller |
| P&ID | Piping and Instrumentation Diagram |
| PLC | Programmable Logic Controller |
| PM | Preventive Maintenance |
| PSM | Process Safety Management |
| PSV | Pressure Safety Valve (Relief Valve) |
| PSAT | Pre-Startup Acceptance Test |
| QRA | Quantitative Risk Assessment |
| R | Risk |
| RV | Relief Valve |
| RTD | Resistance Temperature Detector |
| SAT | Site acceptance test |
| SCE | Safety Critical Equipment |
| SFF | Safe failure fraction |
| SIF | Safety Instrumented Function |
| SIL | Safety Integrity Level |
| SIS | Safety Instrumented System |
| SOP | Standard Operating Procedures |
| SOV | Solenoid Valve |
| SRS | Safety Requirement Specification |
| S/W | Software |
| T | Test Interval for the Component or System (hours or years) |
| T/C or TE | Thermocouple |
| TMR | Triple Modular Redundant |
| UPS | Uninterruptible Power Supply |
| VCE | Vapor Cloud Explosion |
| VLE | Vapor Liquid Equilibrium |
| WDT | Watch Dog Timer |
| XV | Remote Activated/Controlled Valve |
| 1oo1 | One-out-of-One Voting |
| 2oo2 | Two-out-of-Two Voting |
| 3oo3 | Three-out-of-Three Voting |

Appendix C

Power Island Closed Cooling Water System HAZOP Study Report



0.

HAZOP STUDY

SnowyHydro – Hunter Power Station
Mitsubishi Heavy Industries
M701G Gas turbine generators
SHL Work Order No. 314502



ABSTRACT

Hazard and Operability (HAZOP) Study of the Hunter Power Station closed cooling water system process design

Pantac System Control

Risk Assessment Doc No 21081700-002-R0

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 1 of 13 |

Contents

| | |
|---|----|
| Revision History..... | 2 |
| 1. Executive Summary | 3 |
| 2. Background | 4 |
| 3. Process description..... | 4 |
| 4. Scope..... | 4 |
| 5. Objectives..... | 4 |
| 6. Methodology..... | 5 |
| 6.1 Guide words and Deviations | 5 |
| 7. Participants | 6 |
| Appendix 1: HAZOP Nodes and drawings..... | 7 |
| Appendix 2: Study records..... | 8 |
| Appendix 3: SnowyHydro Risk Matrix | 9 |
| Appendix 4: HAZOP action items | 10 |
| Appendix 5: Safeguards | 11 |
| Appendix 6: Participants..... | 12 |
| Appendix 7: Acronyms..... | 13 |

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 2 of 13 |

Revision History

| Date | Rev | Description |
|------------|-----|-----------------------------|
| 5 May 2022 | 0 | Draft – Issued for comments |

| Revision | Prepared By | Reviewed by | Approved By |
|----------|--------------|-----------------|--------------|
| 0 | Paul van Dyk | Reinier van Dyk | Paul van Dyk |

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 3 of 13 |

1. Executive Summary

This report covers the findings of the HAZOP study workshop for the SnowyHydro Hunter Power Station closed cooling water system process design. Due to COVID travel restrictions, the workshop was performed remotely via google meet with client, vendor, translation services and specialist representation. The scope and focus of the study are limited to the closed cooling water system Process and Instrumentation Design (P&IDs) systems.

The workshop was performed according to the agreed scope as outlined in Section 4, using the methodology described in Section 6. It is considered that the stated objectives listed in Section 5 were satisfactorily met, subject to implementation of the recommendations generated.

The workshop generated:

28 recommendations tabled in appendix 4 and identified

11 Safeguards tabled in appendix 5

It is worth noting the following:

- The system design relies on a cooling water system discharge pressure that is greater than the generator hydrogen pressure to prevent any hydrogen accumulation in the water system in the event of an exchanger leak.

The system design is not 100% complete and action item 23 relates specifically to the cooling water system discharge pressure control.

- The high-pressure air compressors interlocks and protection is not well understood at this time and action items 20 and 21 are with MHI to confirm with their 3rd party vendor.

This section of the plant will need to be reviewed again on completion of design and suitable interlock and protection information becomes available

- The P&IDs in appendix 1 Nodes and Drawings, includes commented additions as advised before the HAZOP (known omissions) and as mark ups (design modifications and details appended during the workshop i.e., not all drawing comments are re-designs.

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 4 of 13 |

2. Background

This new gas turbine peaking plant will be commissioned on liquid fuel in 2023 to provide power to the New South Wales electricity spot market. Natural gas firing will follow 6 to 12 months after that.

The plant will be owned and operated by SnowyHydro Ltd.

Hydrogen blending with natural gas for combustion is not included at the time of this study.

3. Process description

Hunter Power Station will be a dual fuel (high speed diesel and natural gas fired), Open Cycle Gas Turbine Power Station with a rated output of approximately 2 x 330 MW. The plant consists of two dual fuel, MHI M701G series gas turbines with water injection for fuel oil low NOx control, two hydrogen cooled generators, associated lube and seal oil and gas systems, electrical equipment and I&C, emergency diesel generator, power/distribution transformers, closed circuit cooling system, firefighting and detection systems and HVAC. The GT intakes are equipped with an evaporative cooling system to increase output performance.

The station is designed for peak load operation with fast start-up and loading (approximately 5 minutes to synchronising and 15 MW/min normal load rate {TBC}) but has a predicted operating regime of only 48 fired hours per year {TBC} with 25 starts {TBC}.

The plant may be dispatched and operated remotely for much of the time. Site staffing will be minimal.

4. Scope

The scope of the HAZOP workshop was limited to the closed cooling water system Process and Instrumentation Design systems and any associated control requirements to maintain system protection and minimise environmental excursions in accordance with the targets defined in the SnowyHydro corporate Risk Matrix, refer appendix 3.

5. Objectives

The objective of the HAZOP workshop is to

- Review the proposed design
- Generate action items for any areas of concern brought to the meeting
- Identify potential hazards and operability problems, to examine safeguards and to make recommendations to address identified problems

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 5 of 13 |

- Ensure that all applicable recommendations related to the hierarchical controls are recorded

6. Methodology

The HAZOP examination procedure systematically questions every part of a process or operation to discover qualitatively how deviations from normal operation can occur and whether further protective measures, altered operating procedures or design changes are required.

The examination procedure uses a full description of the process which will, almost invariably, include a P&ID or equivalent, and systematically questions every part of it to discover how deviations from the intention of the design can occur and determine whether these deviations can give rise to hazards.

The questioning is sequentially focused on guide words which are derived from method study techniques. The guide words ensure that the questions posed to test the integrity of each part of the design will explore ways in which operation could deviate from the design intention.

Some of the causes may be so unlikely or trivial, that they need not be considered further, however there may be some deviations with causes that are conceivable and consequences that are potentially serious. The potential problems are then noted for remedial action.

The immediate solution to a problem may not be obvious and could need further consideration either by a team member or perhaps a specialist. All decisions taken are recorded.

The main advantage of this technique is its systematic thoroughness in failure case identification. The method may be used at the design stage, when plant alterations or extensions are to be made, or applied to an existing facility.

6.1 Guide words and Deviations

The following deviations were applied to each study node

| No | Deviation | Notes |
|----|-------------------------|--------------|
| 1 | Pressure High | |
| 2 | Pressure Low | |
| 3 | Pressure No or not | |
| 4 | Pressure Vacuum | |
| 5 | Temperature High | Include Fire |
| 6 | Temperature Low | |
| 7 | Temperature – No or not | |
| 8 | Flow / Level – High | |
| 9 | Flow / Level – Low | |

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 6 of 13 |

| | | |
|----|--|--|
| 10 | Flow / Level – No or not | |
| 11 | Flow / Level – Reverse | |
| 12 | Vibration – High Low or not | |
| 13 | As well as - concentration / two phase | |
| 14 | Other then - impurities / contamination | |
| 15 | Timing / Sequence - Early / Late | Start up, shutdown, Auto / manual valves |
| 16 | Timing / Sequence - Fast / Slow | |
| 17 | Utility failure - instr. air / oil / power | Fail safe? |
| 18 | Volts / Amps High | |
| 19 | Volts / Amps Low | |
| 20 | Volts / Amps - No or Not | |
| 21 | Maintenance | Access, discharge points and storm water |

7. Participants

Study attendance is normally recorded and listed here in the body of the document but to be consistent with the gas turbine controls HAZOP report, the participants are listed in Appendix 6

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 7 of 13 |

Appendix 1: HAZOP Nodes and drawings

The nodes and drawings should be read in conjunction with the system descriptions listed below


20220426_Cooling Water Loop - Basis of Design excerpt.docx

20220426_Cooling Water Loop - Control Philosophy excerpt.docx


| | Node | Dwg | Dwg Title | Day |
|---|--------------------------------|-------------------------------|---|-----|
| 1 | Fin fans | HPP-AEC-MEC-SW-GEN-DRG-1160-A | HPS P&ID Power island closed cooling water system, Sht 1 of 4 | 1 |
| 2 | Helper cooler and booster pump | HPP-AEC-MEC-SW-GEN-DRG-1160-A | HPS P&ID Power island closed cooling water system, Sht 1 of 4 | 1 |
| 3 | Expansion tank | HPP-AEC-MEC-SW-GEN-DRG-1161-A | HPS P&ID Power island closed cooling water system, Sht 2 of 4 | 2 |
| 4 | Cooling water pumps | HPP-AEC-MEC-SW-GEN-DRG-1161-A | HPS P&ID Power island closed cooling water system, Sht 2 of 4 | 2 |
| 5 | GT HP Purge air coolers | HPP-AEC-MEC-SW-GEN-DRG-1162-A | HPS P&ID Power island closed cooling water system, Sht 3 of 4 | 1 |
| 6 | GTG H2 air coolers | HPP-AEC-MEC-SW-GEN-DRG-1162-A | HPS P&ID Power island closed cooling water system, Sht 3 of 4 | 1 |
| 7 | GT Control oil coolers | HPP-AEC-MEC-SW-GEN-DRG-1163-A | HPS P&ID Power island closed cooling water system, Sht 4 of 4 | 1 |
| 8 | GT Lube oil coolers | HPP-AEC-MEC-SW-GEN-DRG-1163-A | HPS P&ID Power island closed cooling water system, Sht 4 of 4 | 1 |

NODE 1

01GHC10AP001
BOOSTER PUMP
CAPACITY: 0.5m³/h @ 300m HEAD



NODE 2



HOLDS:

- 1. THE KKS NUMBERING SYSTEM SHOWN IS INDICATIVE ONLY AND SUBJECT TO CHANGE.

NOTES:

- 1. THIS P&ID GIVES COOLING WATER SYSTEM FOR ONE SET OF GT. THE TWO SETS ARE IDENTICAL.
- 2. FIN FAN COOLER MOTOR IS SUITABLE FOR VSD OPERATION.
- 3. BLADDER TYPE EXPANSION TANK FOR CLOSE COOLING WATER SYSTEM.
- 4. GOULDS PUMP IS CONSIDERED FOR HOT WATER.
- 5. SMALL CIRCULATING PUMP FOR WINTERIZATION OPERATION.
- 6. CHEMICAL DOSING FOR IMPROVING WATER QUALITY.
- 7. REFER TO MITSUBISHI DRAWINGS FOR DETAILS OF COOLERS FOR LUBE OIL, CONTROL OIL, GENERATOR HYDROGEN AND PURGE AIR COMPRESSOR.
- 8. REFER TO VENDOR DRAWING FOR DETAIL OF FIN FAN & HELPER COOLERS.

PRELIMINARY


| | | | | | |
|---|--|--|------------------------------------|---|------------------------------|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-SW-GEN-DRG-1160 | | | DRAWN EDP 21.02.2022 | DRAWING CHECKED BW 21.02.2022 | snowyhydro LIMITED |
| DESIGNED NS 21.02.2022 | | | DESIGN CHECKED KW 21.02.2022 | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM POWER ISLAND CLOSED COOLING WATER SYSTEM | |
| REV: A | | | SCALE WORK ORDER No | APPROVED CDT 21.02.2022 | |
| REV NAME DATE DESCRIPTION | | | SECTION No/KKS PGG | A1 SHEET SIZE | A 1 SH 1 OF 4 |

01GHC10BB001
EXPANSION TANK
VOLUME: 2.5m³

01PGG01AP001
01PGG02AP001
COOLING WATER PUMP
CAPACITY: 720m³/h @ 86m HEAD
ARRANGEMENT: DUTY/STANDBY

NODE 4

NODE 3



HOLDS:

- 1. THE KKS NUMBERING SYSTEM SHOWN IS INDICATIVE ONLY AND SUBJECT TO CHANGE.

NOTES:

- 1. THIS P&ID GIVES COOLING WATER SYSTEM FOR ONE SET OF GT. THE TWO SETS ARE IDENTICAL.
- 2. FIN FAN COOLER MOTOR IS SUITABLE FOR VSD OPERATION.
- 3. BLADDER TYPE EXPANSION TANK FOR CLOSE COOLING WATER SYSTEM.
- 4. GOULDS PUMP IS CONSIDERED FOR HOT WATER.
- 5. SMALL CIRCULATING PUMP FOR WINTERIZATION OPERATION.
- 6. CHEMICAL DOSING FOR IMPROVING WATER QUALITY.
- 7. REFER TO MITSUBISHI DRAWINGS FOR DETAILS OF COOLERS FOR LUBE OIL, CONTROL OIL, GENERATOR HYDROGEN AND PURGE AIR COMPRESSOR.
- 8. REFER TO VENDOR DRAWING FOR DETAIL OF FIN FAN & HELPER COOLERS.


PRELIMINARY

| | | | | | | | |
|-----|------|------|---|--|---|--|---|
| | | | THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-SW-GEN-DRG-1161 | | DRAWN EDP 21.02.2022 DESIGNED NS 21.02.2022 SCALE WORK ORDER No SECTION No/KKS PGG | DRAWING CHECKED BW 21.02.2022 DESIGN CHECKED KW 21.02.2022 APPROVED CDT 21.02.2022 A1 SHEET SIZE | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM POWER ISLAND CLOSED COOLING WATER SYSTEM |
| REV | NAME | DATE | DESCRIPTION | | REV: A | A SH 2 OF 4 | |

08 | MEC-SW-GEN-1160
TO HELPER COOLER
SPARY WATER HEADER

01QEE02 AN101
01QEE02 AN102
PURGE AIR COMPRESSOR COOLER
(SUPPLIED BY MHI)
HEAT LOAD: 63 kW
ARRANGEMENT: DUTY/STANDBY

01PGG01AC004/01PGG02AC004
01PGG03AC004/01PGG04AC004
GTG H2 GAS COOLER
(SUPPLIED BY MHI)
HEAT LOAD: 3801 kW
ARRANGEMENT:
DUTY/DUTY/DUTY/DUTY



NODE 5

NODE 6

HOLDS:


1. THE KKS NUMBERING SYSTEM SHOWN IS INDICATIVE ONLY AND SUBJECT TO CHANGE.

NOTES:

1. SAMPLE POINT.

PRELIMINARY

| | | | | | | | | |
|---|--|--|--|----------------|--|----------------------------------|--|--|
| THIS DRG SUPPLIED BY | | | | DRAWN | | DRAWING CHECKED | | |
| AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-SW-GEN-DRG-1162 | | | | 21.02.2022 | | 21.02.2022 | | |
| DESIGNED | | | | DESIGN CHECKED | | HUNTER POWER STATION | | |
| NS | | | | KW | | PIPING & INSTRUMENTATION DIAGRAM | | |
| SCALE | | | | APPROVED | | POWER ISLAND CLOSED COOLING | | |
| WORK ORDER No | | | | CDT | | WATER SYSTEM | | |
| REV: A | | | | SECTION No/KKS | | A1 | | |
| REV | | | | NAME | | DATE | | |
| DESCRIPTION | | | | P | | SH 3 OF 4 | | |



04 MEC-SW-GEN-1162
COOLING WATER SUPPLY
CONTINUED

NODE 7

NODE 8

01MBX01 AC101 (A)
01MBX01 AC102 (B)
GT CONTROL OIL COOLER
(SUPPLIED BY MHI)
HEAT LOAD: 24 kW
ARRANGEMENT: DUTY/STANDBY

01MBV01 AC101 (A)
01MBV01 AC102 (B)
GT LUBE OIL COOLER
(SUPPLIED BY MHI)
HEAT LOAD: 2023 kW
ARRANGEMENT: DUTY/STANDBY

HOLDS:


- THE KKS NUMBERING SYSTEM SHOWN IS INDICATIVE ONLY AND SUBJECT TO CHANGE.

NOTES:

- SAMPLE POINT.

PRELIMINARY

| | | | | | | |
|---|------|------|-------------|-----------------------|------------------|------------------|
| THIS DRG SUPPLIED BY | | | | DRAWN | DRAWING CHECKED | |
| AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-SW-GEN-DRG-1163 | | | | EDP 21.02.2022 | BW 21.02.2022 | |
| | | | | DESIGNED | | |
| NS 21.02.2022 | | | | KW 21.02.2022 | APPROVED | |
| SCALE | | | | WORK ORDER No | CDT | A1 SHEET SIZE |
| REV: A | | | | SECTION No/KKS PGG | 21.02.2022 | |
| REV | NAME | DATE | DESCRIPTION | A SH 4 OF 4 | | |



| FLOW STREAM | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 |
|------------------------------|------|------|-------|--------|--------|--------|------|--------|--------|-------|--------|-------|--------|-------|-------|-------|-----|-----|-----|-----|------|
| PIPE SIZE (DN) | 350 | 350 | 80 | 350 | 250 | 250 | 250 | 50 | 50 | 250 | 250 | 250 | 350 | 80 | 80 | 350 | 50 | 25 | 25 | 25 | 25 |
| PIPE SCHEDULE | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD | STD |
| FLOWRATE (M ³ /H) | 720 | 720 | 13.20 | 706.80 | 319.00 | 387.80 | 5.50 | 382.30 | 382.30 | 5.50 | 387.80 | 319 | 706.80 | 13.20 | 13.20 | 720 | - | - | - | 0.5 | 0.5 |
| VELOCITY (M/S) | 2.25 | 2.25 | 0.77 | 2.21 | 1.74 | 2.12 | 0.71 | 2.04 | 2.04 | 0.71 | 2.12 | 1.74 | 2.21 | 0.77 | 0.77 | 2.25 | 3 | 3 | 8 | 1.5 | 1.5 |
| PRESSURE (KPA) | 289 | 607 | 579 | 564 | 564 | 556 | 556 | 556 | 436 | 436 | 430 | 430 | 417 | 569 | 417 | 404 | 750 | 650 | - | 750 | 3000 |
| TEMPERATURE (°C) | 51 | 51 | 51 | 51 | 51 | 51 | 51 | 51 | 55.70 | 54.70 | 55.70 | 61.20 | 58.20 | 40 | 44.10 | 58.20 | 30 | 30 | 30 | 30 | 30 |

NOTES:

- SEPARATE IDENTICAL CLOSED COOLING WATER SYSTEM IS REQUIRED FOR EACH OF THE GAS TURBINES GENERATOR (TWO IN TOTAL)
- FIN FAN COOLERS AND HELPER COOLERS ARE SUPPLIED BY OTHERS AS A COMPLETE PACKAGE.
- POWER ISLAND COOLERS ARE SUPPLIED BY MITSUBISHI AND CONNECTED AT FLANGES.
- THE MAXIMUM DESIGN TEMPERATURES 51°C AND 40°C ON THE SUPPLY LINES DOWNSTREAM OF THE FIN FAN COOLERS, AND THE MAXIMUM AMBIENT AIR TEMPERATURE 46°C ARE BASED ON MHI UTILITY LIST S4-96585, REV.1

ISSUED FOR INFORMATION ONLY

| | | | | | |
|-----|------|---|------------------------------|--------------------------------------|---|
| | | THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-CL-GEN-DRG-1007 REV: B | DRAWN CAR 30.11.2021 | DRAWING CHECKED BVA 30.11.2021 | HUNTER POWER STATION PROCESS FLOW DIAGRAM UNIT XX – FIN FAN COOLER |
| | | | DESIGNED NS 30.11.2021 | DESIGN CHECKED DBM 30.11.2021 | |
| | | | SCALE WORK ORDER No | APPROVED CDT 30.11.2021 | |
| REV | NAME | DATE | DESCRIPTION | SECTION No/KKS | A1 SHEET SIZE |
| | | | | | B SH 1 OF 1 |

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 8 of 13 |

Appendix 2: Study records

Notes on study records

Column 4 'Likelihood' and column 5 'Severity' represent the possibility and consequence of a hazard without taken credit for the safety protection layer (SPL).

Column 8 'Likelihood with SPL' and column 9 'Severity with SPL' represent the possibility and consequence of a hazard taken credit for the correct operation of the SPL. The consequence remains the same, only the frequency is modified.

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|-----------------------------|---|------------|-------------|--------------|----------------------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 1 - Fin fans Dwg HPP-AEC-MEC-SW-GEN-DRG-1160-A - HPS P&ID Power island closed cooling water system, Sht 1 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Designed for 2 pumps running | 1. Add drain points and vibration sensors to P&ID Sht 1 of 4 |
| Pressure Low | | | | | | | | | | Its possible but should be set up correctly during commissioning. Many process alarms would show insufficient cooling | 2. Piping ratings on drawings need to be corrected |
| Pressure No or not | | | | | | | | | | Alarm monitoring only | 3. Pumps have not been specified yet. System pressure with 2 pumps running to be checked against MHI supplied heat exchangers and the fin fan cooler design pressure |
| Pressure Vacuum | | | | | | | | | | | 4. Delete upstream individual header pressure indicators and change the downstream individual header pressure indicators to temperature sensors to assist with flow balancing |
| Temperature High | | | | | | | | | | Ambient temp change and both isolation valves without draining the system could lead to deadhead but this is a maintenance task. High process temperature managed by downstream nodes | 5. Add fin fan overall dP sensor |
| Temperature Low | Ambient temperature | | | | | | | | | Freezing mitigated by running system at temperatures below 5 Celsius. System would normally be operating all the time | 6. Add helper cooler discharge pressure and temperature transmitter to P&ID |
| Temperature – No or not | BPCS failure - sensor fault | Loss of production - Potential process problems | Unlikely | Negligible | Low | Redundant sensor fail over | Rare | Negligible | Low | Fail over to the header temperature sensor, sht 1162. Loss of both sensors starts all fans. Operator can also manually stop start fin fans | 7. Review system design for thermal expansion to assess if a flexible connection is required |
| Flow / Level – High | | | | | | | | | | | 8. Review which sensor is better to control the fin fans, CT102 or CT103 |
| Flow / Level – Low | | | | | | | | | | | 9. Review sensor failure on loss of signal for fin fans, CT102 and CT103 |
| Flow / Level – No or not | | | | | | | | | | | 10. Temperature sensors should be dual elements, even if only 1 is used. Consistent with MHI design |
| Flow / Level – Reverse | | | | | | | | | | | 11. Flow balancing valves should be set and forget. Not move with water vibration. Valve selection to consider locking or rigid stem packing to hold commissioned position |
| Vibration – High Low or not | Fin fan imbalance | Loss of production - Throw a blade | Unlikely | Negligible | Low | Fin fan vibration Hi Hi | Rare | Negligible | Low | Blades are guarded | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | Carbon steel and corrosion covered by routine maintenance | |
| Timing / Sequence - Early / Late | | | | | | | | | | | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | MCC are monitored. Individual motor = loss of performance. Total AC outage would mean unit out | |
| Volts / Amps High | | | | | | | | | | MCC are monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | Motors are underslung but would need scaffold. Grease points also accessible underneath. Access typically 3 to 6 mth intervals. Need scissor lift. SHL to cover this in Operability study | 12. Grease points access needs a lift. SHL to review site requirements hire or buy a scissor lift |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|------------------------------------|------------------------------------|------------|-------------|--------------|------------------------------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 2 - Helper cooler and booster pump Dwg HPP-AEC-MEC-SW-GEN-DRG-1160-A - HPS P&ID Power island closed cooling water system, Sht 1 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Designed for 2 pumps running. Manual valves locked open | 13. Add duty standby pumps to drawing |
| Pressure Low | | | | | | | | | | | 14. Confirm piping pressure rated for two pumps running |
| Pressure No or not | BPCS failure - sensor fault | | | | | | | | | Alarm only. Used to monitor pump | |
| Pressure Vacuum | Demin forwarding pumps not running | Potential cavitation - pump damage | Possible | Negligible | Low | Forwarding pumps running interlock | Rare | Negligible | Low | Small but high pressure pumps | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | Ambient temperature | | | | | | | | | Low ambient temp does not need helper pump running. -5 C for only a few hours. Freezing low risk and low impact | 15. Review instrument impulse lines for low ambient temp. Threaded socket direct to pipe is probably the best approach. |
| Temperature - No or not | | | | | | | | | | TT used for pump control. Alarm only. Only required on very high ambient temp days 46 C | 7. Review system design for thermal expansion to assess if a flexible connection is required |
| Flow / Level - High | | | | | | | | | | | |
| Flow / Level - Low | | | | | | | | | | Isolation valves locked open | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | Fin fan imbalance | Loss of production - Throw a blade | Unlikely | Negligible | Low | Fin fan vibration Hi Hi | Rare | Negligible | Low | Blades are guarded | |
| As well as - concentration / two phase | | | | | | | | | | | |
| Other then - impurities / contamination | | | | | | | | | | Nozzle blocking over time would be alarmed in process temp | |
| Timing / Sequence - Early / Late | | | | | | | | | | | 16. Potential forwarding pressure is sufficient to continuously leak out of helper spray nozzles. Review booster pump or spray bar isolation requirements |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Pumps are fixed speed | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Potential loss of performance. Negligible | |
| Volts / Amps High | | | | | | | | | | MCC are monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | Same as above. Rain water flows to trade waste | 17. Helper Cooler spray water is demin that needs to flow (if any) to Trade waste. System is not covered so rain water catchment would also flow to trade waste. To be considered in the design. |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|--------------------------------------|---|------------|-------------|--------------|---|---------------------|----------------------|-----------------------|---|---|
| NODE No. 3 - Expansion tank Dwg HPP-AEC-MEC-SW-GEN-DRG-1161-A - HPS P&ID Power island closed cooling water system, Sht 2 of 4 | | | | | | | | | | | |
| Pressure High | Regulator failure | Loss of production - Heat exchanger damage | Unlikely | Major | Medium | PRV | Rare | Major | Medium | 1. High suction would result in high discharge from pumps potentially greater than system design causing equipment failure. Long lead time no spare. Water system is common to both exchangers. 2. System designed for both pumps running but normal operation is 1 pump duty / standby configuration | 19. Add PRVs to instrument air and forwarding demin supplies to prevent overpressure, Press Reg, Sight glass, manifold suction pressure transmitter and level switch to P&ID and suitably rated |
| Pressure Low | Leak or normal operation consumption | Loss of production - Generator load limited | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | This row discharge pressure low Refer notes in H2 coolers, Node 6 | |
| Pressure Low | Leak or normal operation consumption | Loss of production - Generator load limited | Unlikely | Negligible | Low | Expansion tank level Lo Lo Inlet manifold pressure Lo Lo | Rare | Negligible | Low | This row suction pressure low | |
| Pressure No or not | | | | | | | | | | Alarm only | |
| Pressure Vacuum | | | | | | | | | | Manual isolation valves will be lockable type | |
| Temperature High | | | | | | | | | | Designed for max water temp of 60 C and ambient 46 C | |
| Temperature Low | | | | | | | | | | Ambient to -5 C for a couple of hours | |
| Temperature - No or not | | | | | | | | | | No instrument here for temp | |
| Flow / Level - High | Air leak | Loss of production - Generator load limited | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | System pressure would become low | |
| Flow / Level - Low | Leak or normal operation consumption | Loss of production - Generator load limited | Unlikely | Negligible | Low | Expansion tank level Lo Lo | Rare | Negligible | Low | | 18. Water consumption of pump gland seals and leakage to be estimated to evaluate automating tank filling and pump discharge pressure stability. More than 1 x per mth suggest automation required. |
| Flow / Level - No or not | | | | | | | | | | Alarm only | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | Bladder leak | Aerated water, potential pump cavitation | Unlikely | Negligible | Low | Discharge manifold pressure Lo | Rare | Negligible | Low | | 26. Expansion tank bladder inspection and repair access and maintenance requirements to be specified |
| Other then - impurities / contamination | | | | | | | | | | Clean demin system | |
| Timing / Sequence - Early / Late | | | | | | | | | | Add water first then air to balance tank level | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | | 26. Expansion tank bladder inspection and repair access and maintenance requirements to be specified |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|---------------------|---|------------|-------------|--------------|---------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 4 - Cooling water pumps Dwg HPP-AEC-MEC-SW-GEN-DRG-1161-A - HPS P&ID Power island closed cooling water system, Sht 2 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | System designed for both pumps running but normal operation is 1 pump duty / standby configuration. High pressure refer expansion tank node 3 | 27. Pump discharge manifold PRV to discharge to trade waste system. All (all nodes) CW system drain points need to go to trade waste |
| Pressure Low | Motor starter fault | Loss of production - Potential process problems | Unlikely | Negligible | Low | Pump discharge flow Lo Lo | Rare | Negligible | Low | Refer expansion tank node 3. Pump flow switch start check incorporated in design | |
| Pressure No or not | | | | | | | | | | Alarm only. Constant speed pumps | |
| Pressure Vacuum | | | | | | | | | | Manual isolation valves will be lockable type. Blocked strainer on clean demin system unlikely and slow to build so would be detected by low discharge pressure. Potential pump damage cost is < 100K negligible | |
| Temperature High | | | | | | | | | | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | No instrument here for temp | |
| Flow / Level - High | | | | | | | | | | Refer high pressure above | |
| Flow / Level - Low | | | | | | | | | | Refer expansion tank and strainer comments above | |
| Flow / Level - No or not | | | | | | | | | | Option to auto transfer to standby pump | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | Manual spot checking suggested | |
| As well as - concentration / two phase | | | | | | | | | | Air same as above, corrosion inhibitor manual dosing. Water leaks into the oil systems | |
| Other then - impurities / contamination | | | | | | | | | | After commissioning it is clean demin system with dosing only. | |
| Timing / Sequence - Early / Late | | | | | | | | | | Late picked up by process. Early no problem | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Constant speed pumps | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Black stop capability? MCC are monitored | 28. On loss of AC supply, does the closed cooling water system (fans and / or pumps) need to be operational for any specified period time after a black stop. MHI to confirm any run down time requirements |
| Volts / Amps High | | | | | | | | | | MCC are monitored | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | Pumps are accessible and isolatable | 27. Pump discharge manifold PRV to discharge to trade waste system. All (all nodes) CW system drain points need to go to trade waste |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|-----------------------------|--|------------|-------------|--------------|-------------|---------------------|----------------------|-----------------------|---|--|
| NODE No. 5 - GT HP Purge air coolers Dwg HPP-AEC-MEC-SW-GEN-DRG-1162-A - HPS P&ID Power island closed cooling water system, Sht 3 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | Refer flow AA020 back pressure | |
| Pressure Low | | | | | | | | | | Manual isolation valves will be lockable type | |
| Pressure No or not | | | | | | | | | | | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS failure - sensor fault | Loss of production - Compressor damage | Unlikely | Minor | Low | | Unlikely | Minor | Low | CW spec is 40 C max. Only used when running on diesel | 20. MHI to review HP compressor protection requirements. What are the consequences if the closed cooling water temperature increases above 40 C. Do we need to shutdown the compressors to protect them from damage? |
| Temperature Low | | | | | | | | | | CW temp range 23 to 40 C in design spec. There is no flow temperature control on the exchanger flow. Too warm managed by helper coil but too cold? HP compressor is within an enclosure and would generate heat when running. MHI don't think low temp is a major concern based on 20 C cooling water temp. HP compressors only used at barring so turbine would also generate heat low | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Set during commissioning. Loss of performance consequence if set incorrectly. | |
| Flow / Level - Low | | | | | | | | | | Same as high flow | |
| Flow / Level - No or not | | | | | | | | | | | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | | |
| As well as - concentration / two phase | Exchanger leak | Loss of production - Compressor bearing damage | Unlikely | Minor | Low | | Unlikely | Minor | Low | CW 5.5 Bar, Oil tbc Bar | 21. MHI to confirm HP compressor oil pressure and if there is an exchanger leak, will the water flow into the compressor and cause damage? How is this detected? |
| Other then - impurities / contamination | | | | | | | | | | Clean demin system | |
| Timing / Sequence - Early / Late | | | | | | | | | | All manual valves | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|------------------------------------|---|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|--|---|
| NODE No. 6 - GTG H2 air coolers Dwg HPP-AEC-MEC-SW-GEN-DRG-1162-A - HPS P&ID Power island closed cooling water system, Sht 3 of 4 | | | | | | | | | | | |
| Pressure High | | | | | | | | | | H2 press 5 Bar and CW press 5.5 Bar | 22. P&ID line 100mm to be updated to 125mm |
| Pressure Low | BPCS failure - pressure regulation | Potential H2 accumulation in water | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | CW pressure low and tube leak could potentially leak H2 into water system, which would accumulate at the fin fan vent pipe. Automation for double jeopardy discussed and will be further reviewed by AECOM | 23. Pressure regulation wont work as shown. AECOM to review water pressure balancing system. It is important to maintain 5.5 Bar cooling water at exchangers to inhibit H2 leak |
| Pressure No or not | | | | | | | | | | PI only used for commissioning to set balance | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS failure - pressure regulation | Loss of production - Generator load limited | Unlikely | Negligible | Low | Procedural - Operator alarm response | Unlikely | Negligible | Low | | |
| Temperature Low | | | | | | | | | | | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Flows set during commissioning. Worst case loss of production, retuning | |
| Flow / Level - Low | | | | | | | | | | | |
| Flow / Level - No or not | | | | | | | | | | Loss of performance monitoring | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | All AECOM pipework is stress analysed for thermal expansion | |
| As well as - concentration / two phase | Exchanger leak | Potential water accumulation in generator | Unlikely | Major | Medium | Generator level switches | Rare | Major | Medium | Refer to GTG HAZOP | |
| Other then - impurities / contamination | | | | | | | | | | | |
| Timing / Sequence - Early / Late | | | | | | | | | | All valves are manual and locked open / closed | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | | 24. AECOM to review and confirm with MHI if any closed cooling water commissioning strainer / removal spool requirements |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|---|------------------------------------|--|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|---|---|
| NODE No. 7 - GT Control oil coolers Dwg HPP-AEC-MEC-SW-GEN-DRG-1163-A - HPS P&ID Power island closed cooling water system, Sht 4 of 4 | | | | | | | | | | | |
| Pressure High | Exchanger leak | Potential oil accumulation in control oil tank | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | CO press 80 Bar supply but return 5 Bar return and CW press 5.5 Bar | |
| Pressure Low | Exchanger leak | Potential oil accumulation in cooling water system | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | Tube leak and low pressure (double jeopardy) would leak oil into water but before it became an issue for cooling water it would trigger low control oil level | |
| Pressure No or not | | | | | | | | | | PI only used for commissioning to set balance | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS failure - pressure regulation | | | | | | | | | CW temp max 51 C. MHI advise no real concern. | |
| Temperature Low | BPCS failure - pressure regulation | Loss of production - Potential process problems | Unlikely | Negligible | Low | | Unlikely | Negligible | Low | Valve sticking or poor control if oil too cold. CO temp is monitored in the tank for heater control. | |
| Temperature - No or not | | | | | | | | | | Alarm, loss of heater control but not in this node | |
| Flow / Level - High | | | | | | | | | | Potential loss of performance. Negligible | |
| Flow / Level - Low | | | | | | | | | | Potential loss of performance. Negligible | |
| Flow / Level - No or not | | | | | | | | | | Loss of performance monitoring | |
| Flow / Level - Reverse | | | | | | | | | | | 25. AECOM to review check valve quantity and location. Control oil only has 1 common NRV but other exchangers are individually controlled. Do we need them? |
| Vibration - High Low or not | | | | | | | | | | All AECOM pipework is stress analysed for thermal expansion | |
| As well as - concentration / two phase | | | | | | | | | | Refer pressure hi and low above | |
| Other then - impurities / contamination | | | | | | | | | | Same above | |
| Timing / Sequence - Early / Late | | | | | | | | | | Same above | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Same above | |
| Utility failure - instr. air / oil / power | | | | | | | | | | Same above | |
| Volts / Amps High | | | | | | | | | | Same above | |
| Volts / Amps Low | | | | | | | | | | Same above | |
| Volts / Amps - No or Not | | | | | | | | | | Same above | |
| Maintenance | | | | | | | | | | | |

| Deviation | Cause | Consequences | Likelihood | Consequence | Cost Ranking | Safe Guards | Likelihood with SPL | Consequence with SPL | Risk Ranking with SPL | Comments | Actions |
|--|------------------------------------|---|------------|-------------|--------------|--------------------------------------|---------------------|----------------------|-----------------------|---|---------|
| NODE No. 8 - GT Lube oil coolers Dwg HPP-AEC-MEC-SW-GEN-DRG-1163-A - HPS P&ID Power island closed cooling water system, Sht 4 of 4 | | | | | | | | | | | |
| Pressure High | Exchanger leak | Potential oil accumulation in lube oil tank | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | LO press 5 Bar supply and CW press 5.5 Bar | |
| Pressure Low | Exchanger leak | Potential oil accumulation in lube oil tank | Unlikely | Negligible | Low | Procedural - Operator alarm response | Rare | Negligible | Low | Tube leak and low pressure (double jeopardy) would leak oil into water but system volume is big enough to raise CW suction pressure and discharge pressure until system is balanced and water would flow into the lube oil tank | |
| Pressure No or not | | | | | | | | | | PI only used for commissioning to set balance | |
| Pressure Vacuum | | | | | | | | | | | |
| Temperature High | BPCS failure - pressure regulation | Potential bearing damage | Unlikely | Moderate | Medium | Lube oil temperature Hi Hi | Rare | Moderate | Low | CW temp max 51 C. | |
| Temperature Low | | | | | | | | | | Turbine running will heat oil and also tank has an oil heater and the exchangers have a bypass control. Less than 15 C could be a problem | |
| Temperature - No or not | | | | | | | | | | | |
| Flow / Level - High | | | | | | | | | | Potential loss of performance. Negligible | |
| Flow / Level - Low | | | | | | | | | | Potential loss of performance. Negligible | |
| Flow / Level - No or not | | | | | | | | | | Loss of performance monitoring | |
| Flow / Level - Reverse | | | | | | | | | | | |
| Vibration - High Low or not | | | | | | | | | | All AECOM pipework is stress analysed for thermal expansion | |
| As well as - concentration / two phase | | | | | | | | | | Refer pressure hi and low above | |
| Other then - impurities / contamination | | | | | | | | | | Same above | |
| Timing / Sequence - Early / Late | | | | | | | | | | Same above | |
| Timing / Sequence - Fast / Slow | | | | | | | | | | Same above | |
| Utility failure - instr. air / oil / power | | | | | | | | | | | |
| Volts / Amps High | | | | | | | | | | | |
| Volts / Amps Low | | | | | | | | | | | |
| Volts / Amps - No or Not | | | | | | | | | | | |
| Maintenance | | | | | | | | | | | |

| | | | |
|------------------|--|-------------|--------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 9 of 13 |

Appendix 3: SnowyHydro Risk Matrix

When business risk is considered in the risk assessment, instrumented functions that are classified as machine interlocks may be re-classified as Safety Instrumented Functions (SIF) and will then require a Safety Integrity Level (SIL) assignment and SIF architecture verification study.

Likelihood frequencies were taken from the SnowyHydro corporate risk matrix, where

| | |
|----------|--|
| Certain | > 1 event / year |
| Likely | 1 to 2 years / event |
| Possible | 2 to 10 years / event (basic process control failure (machine life)) |
| Unlikely | 10 to 50 years / event (machine life, has happened in industry) |
| Rare | > 50 years /event (remote but theoretically possible event) |

Note that a basic process control system (BPCS) failure rate is typically 1 event per 10 years and therefore study records tend to be limited to Unlikely or Rare. A BPCS failure includes the sensors, the logic solver, the final elements (valves, contactors, etc) and where applicable the wiring and power supplies

| | | | | | | | | | |
|------------|------------|-------|----------|--------|---------|--------------|-------------------|------------|---------------------|
| Likelihood | Certain | Low | Medium | High | Extreme | Extreme | Extreme | > 0.9 | 1 yr /event |
| | Likely | Low | Medium | High | High | Extreme | Extreme | 0.5 - 1 | 1 - 2 yrs / event |
| | Possible | Low | Medium | Medium | High | High | Extreme | 0.1 - 0.5 | 2 - 10 yrs /event |
| | UnLikely | Low | Low | Medium | Medium | High | High | 0.02 - 0.1 | 10 - 50 yrs / event |
| | Rare | Low | Low | Low | Medium | Medium | High | < 0.02 | > 50 yrs /event |
| | Negligible | Minor | Moderate | Major | Severe | Catastrophic | Consequence Level | | |

| | | | | | | | |
|------------|----------|------------|-------|----------|-------|--------|--------------|
| Likelihood | Certain | 1 | 2 | 3 | 4 | 4 | 4 |
| | Likely | 1 | 2 | 3 | 3 | 4 | 4 |
| | Possible | 1 | 2 | 2 | 3 | 3 | 4 |
| | UnLikely | 1 | 1 | 2 | 2 | 3 | 3 |
| | Rare | 1 | 1 | 1 | 2 | 2 | 3 |
| | | Negligible | Minor | Moderate | Major | Severe | Catastrophic |

| RISK RATING MATRIX | | LIKELIHOOD | | | | |
|--------------------|--------------|------------|----------|----------|---------|----------------|
| | | Rare | Unlikely | Possible | Likely | Almost Certain |
| CONSEQUENCE | Catastrophic | High | High | Extreme | Extreme | Extreme |
| | Severe | Med | High | High | Extreme | Extreme |
| | Major | Med | Med | High | High | Extreme |
| | Moderate | Low | Med | Med | High | High |
| | Minor | Low | Low | Med | Med | Med |
| | Negligible | Low | Low | Low | Low | Low |

Risk Rating Matrix

Likelihood Criteria

| RATING | LIKELIHOOD | PROBABILITY |
|----------------|-------------------------------------|-------------|
| Almost Certain | The event is very likely to occur | >90% |
| Likely | The event will probably occur | 50% to 90% |
| Possible | The event might occur | 10% to 50% |
| Unlikely | The event probably won't occur | 2% to 10% |
| Rare | The event is very unlikely to occur | <2% |

In determining the appropriate likelihood rating for your risk, consider the timeframe within which you are delivering your objective and select a rating that indicates the likelihood of the risk event occurring over that period. The timeframe could be, for example, the life of an asset (years) or an individual payroll run (hours).

* For example, a risk with a likelihood of "Possible" and a consequence

| Consequence Criteria | RATING | FINANCIAL | SAFETY | ENVIRONMENT | COMPLIANCE | AVAILABILITY | REPUTATION |
|----------------------|--------------|---|---|--|---|--|--|
| | Catastrophic | Cost variation or financial loss greater than \$300M. | Multiple fatalities involving employees, contractors or members of the public. | Permanent impact on populations of significant (eg threatened) flora or fauna. Permanent unconfined impact on previously undisturbed ecosystem. | Snowy Hydro loses a licence to operate (eg AFSL, Snowy Park Lease, Retail licence). | Approximately 1500MW of generating plant unavailable to the market for more than 6 months. | Court, regulator or Government inquiry concludes improper, corrupt or grossly negligent conduct by Snowy Hydro. |
| | Severe | Cost variation or financial loss between \$20M and \$300M. (The current consequence criteria simply has a threshold of \$20 million). | Single fatality or permanent significant disability, long term impairment or illness significantly affecting the quality of life for an employee, contractor or member of the public. | Long term (>10 year) impact on populations of significant (eg threatened) flora or fauna. Long term impacts on soil, air or water quality. Or Potential for long term off-site impacts. Loss of numerous significant heritage items. | Claim or action (other than by a Regulator) involving an amount greater than \$20M (including court/defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty greater than \$5M; and/or 2. Imposition of requirements that would cost more than \$20M (including court/defence/compliance costs and loss of revenue) | Approximately 1500MW between generating plant unavailable to the market for between 1 week and 6 months. | Incident or issue causes prolonged, negative national media coverage. Court, regulator or Government inquiry alleges improper, corrupt or grossly negligent conduct by Snowy Hydro. Other action by Snowy Hydro results in shareholders dismissing one or more directors. |
| | Major | Cost variation or financial loss between \$5M and \$20M. | Long term or permanent disability, impairment or illness not significantly affecting the quality of life for an employee, contractor or member of the public. | Medium term (3-10 year) impact on populations of native flora or fauna. Medium term impacts on soil, air, water quality or habitat. Potential for medium term off-site impacts. | Claim or action (other than by a Regulator) involving an amount between \$5M and \$20M (including court/defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty between \$1M and \$5M; and/or 2. Imposition of requirements that would cost between \$5M and \$20M (including court/defence/compliance costs and loss of revenue) | Approximately 1500MW of generating plant unavailable to the market for between 1 day and 1 week; or 600MW of plant unavailable for at least 1 week; or 300MW of generating plant unavailable for a month or more. | Incident or issue causes negative state wide media attention and regulatory intervention. Government inquiry into Snowy Hydro's actions or operations in regard to conduct, pricing etc. Action by Snowy Hydro results in one or more Executives or senior managers being terminated. |
| | Moderate | Cost variation or financial loss between \$1M and \$5M. | Hospitalisation with medical intervention of an employee, contractor or member of the public. | Short term (1-3 year) impact on flora or fauna. Short term impact on soil, air, water quality or habitat. Impact mostly confined to work area but potential short term off-site impacts. Loss of a significant (eg Category A and B) heritage item. Visual, noise or airborne dust impacts with potential for regulator response. | Claim or action (other than by a Regulator) involving an amount between \$1M and \$5M (including court/defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty between \$100K and \$1M; and/or 2. Imposition of requirements that would cost between \$1M and \$5M (including court defence/compliance costs and loss of revenue) | Approximately 1500MW of generating plant unavailable to the market for between 1 hour and 1 day; or 600MW generating plant unavailable for between 1 day and 1 week; or 150MW of generating plant unavailable for a month or more. | Incident or issue causes local outrage with potential for escalation to state media and/or to generate regulator interest. State or Federal regulator conducts formal inquiry into broader industry issues which encompass Snowy Hydro's operations. Major changes to Snowy Hydro operations have significant local community impacts. |
| | Minor | Cost variation or financial loss between \$100K and \$1M. | Injury or illness requiring medical treatment of an employee, contractor or member of the public. | Adverse impact to significant (eg Category A and B) heritage item. Visual, noise or airborne dust impacts with potential for credible stakeholder/public complaint. | Claim or action (other than by a Regulator) involving an amount between \$100K and 1M (including court/ defence/compliance costs and loss of revenue); or Regulator action that results in: 1. A penalty between \$10K and \$100K; and/or 2. Imposition of requirements that would cost between \$100K and \$1M (including court defence/compliance costs and loss of revenue) | Approximately 600MW of generating plant unavailable to the market for up to 1 day; or up to 300MW of generating plant unavailable for up to 1 week; or up to 100MW of generating plant unavailable for a month or more. | Incident or issue causes local outrage with no potential for escalation. Short term negative regional media attention around a minor, localised issue. Minor damage to reputation with a regulator. |
| | Negligible | Cost variation or financial loss less than \$100K. | Nil to first aid injury, low level short term inconvenience or symptoms for an employee, contractor or member of the public. | Promptly reversible/trivial impact on air, water, soil, flora, fauna, habitat or heritage.. | Claim or action (other than by a Regulator) involving an amount up to \$100K (including court/defence/ compliance costs and loss of revenue); or Notification to a Regulator is required (but with no other consequence); or Regulator action that results in: 1. A warning notice; 2. A penalty up to \$10K; and/or 3. Imposition of requirements that would cost up to \$100K (including court/defence/compliance costs and loss of revenue) | Loss of a single generating unit for up to a day. | Incident or issue causes local inconvenience. Negative comment about Snowy Hydro at regional level. Formal complaint made to Snowy Hydro by the public. |

330 mw Capacity loss
300 \$/mw Unit loss
24 hrs out Outage time
\$ 2,376,000 Event impact

| | | | |
|------------------|--|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 10 of 13 |

Appendix 4: HAZOP action items

This section collates all the workshop action items into one list for quick reference. The reader will need to refer to the Study Records in Appendix 2 for the background and references (node, dwg, descriptions, etc) of each action.

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|--|------------------------------|---|------------|-------|--------|--------|
| 1 | 1. Add drain points and vibration sensors to P&ID Sht 1 of 4 | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 2 | 2. Piping ratings on drawings need to be corrected | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 3 | 3. Pumps have not been specified yet. System pressure with 2 pumps running to be checked against MHI supplied heat exchangers and the fin fan cooler design pressure | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 4 | 4. Delete upstream individual header pressure indicators and change the downstream individual header pressure indicators to temperature sensors to assist with flow balancing | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 5 | 5. Add fin fan overall dP sensor | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 6 | 6. Add helper cooler discharge pressure and temperature transmitter to P&ID | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 7 | 7. Review system design for thermal expansion to assess if a flexible connection is required | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 8 | 8. Review which sensor is better to control the fin fans, CT102 or CT103 | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 9 | 9. Review sensor failure on loss of signal for fin fans, CT102 and CT103 | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 10 | 10. Temperature sensors should be dual elements, even if only 1 is used. Consistent with MHI design | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 11 | 11. Flow balancing valves should be set and forget. Not move with water vibration. Valve selection to consider locking or rigid stem packing to hold commissioned position | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 12 | 12. Grease points access needs a lift. SHL to review site requirements hire or buy a scissor lift | sara.roder@snowyhydro.com.au | 3. Prior to Handover for Beneficial Operation | 1.6.23 | | | Open |
| 13 | 13. Add duty standby pumps to drawing | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 14 | 14. Confirm piping pressure rated for two pumps running | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 15 | 15. Review instrument impulse lines for low ambient temp. Threaded socket direct to pipe is probably the best approach. | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 16 | 16. Potential forwarding pressure is sufficient to continuously leak out of helper spray nozzles. Review booster pump or spray bar isolation requirements | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 17 | 17. Helper Cooler spray water is demin that needs to flow (if any) to Trade waste. System is not covered so rain water catchment would also flow to trade waste. To be considered in the design. | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |

| No | Action items | By | Due - Completion Phase | Due - Date | Notes | Answer | Status |
|----|--|-------------------------------------|---------------------------|------------|-------|--------|--------|
| 18 | 18. Water consumption of pump gland seals and leakage to be estimated to evaluate automating tank filling and pump discharge pressure stability. More than 1 x per mth suggest automation required. | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 19 | 19. Add PRVs to instrument air and forwarding demin supplies to prevent overpressure, Press Reg, Sight glass, manifold suction pressure transmitter and level switch to P&ID and suitably rated | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 20 | 20. MHI to review HP compressor protection requirements. What are the consequences if the closed cooling water temperature increases above 40 C. Do we need to shutdown the compressors to protect them from damage? | MHI - hirofumi.moriguchi.3h@mhi.com | 2. Prior to Commissioning | 1.6.22 | | | Open |
| 21 | 21. MHI to confirm HP compressor oil pressure and if there is an exchanger leak, will the water flow into the compressor and cause damage? How is this detected? | MHI - hirofumi.moriguchi.3h@mhi.com | 2. Prior to Commissioning | 1.6.22 | | | Open |
| 22 | 22. P&ID line 100mm to be updated to 125mm | Blair.Murray@aecom.com | 2. Prior to Commissioning | 1.6.22 | | | Open |
| 23 | 23. Pressure regulation wont work as shown. AECOM to review water pressure balancing system. It is important to maintain 5.5 Bar cooling water at exchangers to inhibit H2 leak | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 24 | 24. AECOM to review and confirm with MHI if any closed cooling water commissioning strainer / removal spool requirements | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 25 | 25. AECOM to review check valve quantity and location. Control oil only has 1 common NRV but other exchangers are individually controlled. Do we need them? | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 26 | 26. Expansion tank bladder inspection and repair access and maintenance requirements to be specified | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 27 | 27. Pump discharge manifold PRV to discharge to trade waste system. All (all nodes) CW system drain points need to go to trade waste | Blair.Murray@aecom.com | 1. Prior to Construction | 1.6.22 | | | Open |
| 28 | 28. On loss of AC supply, does the closed cooling water system (fans and / or pumps) need to be operational for any specified period time after a black stop. MHI to confirm any run down time requirements | MHI - hirofumi.moriguchi.3h@mhi.com | 1. Prior to Construction | 1.6.22 | | | Open |

| | | | |
|------------------|--|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 11 of 13 |

Appendix 5: Safeguards

| No | Safeguards - Description | Instances |
|----|--------------------------------------|-----------|
| 1 | Redundant sensor fail over | 1 |
| 2 | Fin fan vibration Hi Hi | 2 |
| 3 | Forwarding pumps running interlock | 1 |
| 4 | PRV | 1 |
| 5 | Procedural - Operator alarm response | 8 |
| 6 | Generator level switches | 1 |
| 7 | Lube oil temperature Hi Hi | 1 |
| 8 | Expansion tank level Lo Lo | 2 |
| 9 | Inlet manifold pressure Lo Lo | 1 |
| 10 | Discharge manifold pressure Lo | 1 |
| 11 | Pump discharge flow Lo Lo | 1 |

| | | | |
|------------------|--|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 12 of 13 |

Appendix 6: Participants

| No | Email | Attendance | | Discipline |
|----|--|-------------------|----------------|-------------------------------------|
| | | day 1 28 April | day 2 5 May | |
| 1 | Bridget McArthur@aecom.com | y | n | Process engineer |
| 2 | Blair.Murray@aecom.com | y | y | Project Engineer - Mechanical |
| 3 | Brooke Mackley1@consultant.aecom.com | y | y | Process mechanical engineer |
| 4 | francois.valette@snowyhydro.com.au | y | y | Mechanical Engineer |
| 5 | Neil Shen@aecom.com | y | y | Mechanical Engineer |
| 6 | desk@poolettranslation.com.au | y | n | Translation services |
| 7 | Karl.Ivanusic@jacobs.com | y | y | Project Engineer - Mechanical |
| 8 | lachlan.smith@snowyhydro.com.au | y | y | Project Engineer - Mechatronics |
| 9 | MHI - hirofumi.moriguchi.3h@mhi.com | y | n | Project manager |
| 10 | MHI - yoji.oshino.mr@mhi.com | y | n | Plant Engineer |
| 11 | Mitchell Stokes@aecom.com | y | y | Electrical Instrumentation engineer |
| 12 | sara.roder@snowyhydro.com.au | y | y | Mechanical Engineer |
| 13 | Melco - Kohei Miura - H2 seal oil system | y | n | Project Engineer - Mechanical |
| 14 | Patrick Scholtes | n | y | Mechanical - Gas Assets |

| | | | |
|------------------|--|-------------|---------------|
| Project Name | SnowyHydro Hunter Power Station | Doc. No. | 002-R0 |
| Project Location | Hunter Kurri Kurri, New South Wales | Project No. | 21081700 |
| Doc. Description | HAZOP report | WO No. | 314502 |
| Area/Unit/System | HPS/GT1 and 2/Closed cooling water systems | Page | Page 13 of 13 |

Appendix 7: Acronyms

ACRONYMS

The following acronyms may be used throughout this course and reference documents:

| | |
|---------------------------|---|
| AIChE | American Institute of Chemical Engineers |
| AC/DC | Alternating current/direct current |
| ALARP | As low as reasonably practicable |
| ANSI | American National Standards Institute |
| ANSI/ISA | American National Standards Institute/ Instrumentation, Systems and Automation |
| API | American Petroleum Institute |
| ANSI / API 611 | American Petroleum Institute: General purpose steam turbines |
| ANSI / API 612 | Australian Standard: Special purpose steam turbines |
| ANSI/ISA-84.01 | Application of Safety Instrumented Systems for the Process Industries. |
| AS | Australian Standard |
| ASME | American Society of Mechanical Engineers |
| AS 1375 | Australian Standard: Industrial fuel fired appliances |
| AS 3814 | Australian Standard: Industrial and commercial gas-fired app. |
| AS 4629 | Australian Standard: Automatic shut off and vent valves. |
| AS / IEC 61508 | Australian Standard: Functional safety of electrical /electronic/programmable electronic safety-related systems - Set |
| AS / IEC 61511 process | Australian Standard: Functional safety - Safety instrumented systems for the industry sector |
| BI | Business Interruption |
| BLEVE | Boiling Liquid Expanding Vapor Explosion |
| B.P. | Boiling Point |
| BPCS | Basic Process Control System |
| C | Consequence factor, related to magnitude of severity |
| CCF | Common Cause Failure |
| CCF | Common Cause Factor |
| CCPS | Center for Chemical Process Safety, American Institute of Chemical Engineers |
| CEI | Dow Chemical Exposure Index |
| HAZOP | Controls Hazard & Operability Study |
| CMS | Consequence Mitigation System |
| CPQRA | Chemical Process Quantitative Risk Assessment |
| CW | Cooling Water |
| DC | Diagnostic coverage |
| <i>D</i> | Number of times a component or system is challenged (hr ⁻¹ or year ⁻¹) |
| DCS | Distributed Control System |
| DIERS | Design Institute for Emergency Relief Systems, American Institute of Chemical Eng. |
| DOT | Department of Transportation |
| EBV | Emergency Block Valve |
| E/E/PE | Electrical/electronic/programmable electronic |
| E/E/PES | Electrical/electronic/programmable electronic system |
| EMC | Electro-magnetic compatibility |
| ERPG | Emergency Response Planning Guideline |
| EuReData | European Reliability Data (series of conferences)FAT Factory acceptance testing |
| <i>F</i> | Failure Rate (hr ⁻¹ or year ⁻¹) |
| <i>f</i> | Frequency (hr ⁻¹ or year ⁻¹) |
| F&EI | Dow Fire and Explosion Index |
| F/N | Fatality Frequency versus Cumulative Number |
| FCE | Final Control Element |

| | |
|-------------------------|--|
| FMEA | Failure Modes and Effect Analysis |
| FMECA | Failure Mode Effect and Criticality Analysis |
| FPL | Fixed program language |
| FTA | Fault Tree Analysis |
| FVL | Full variability language |
| HAZOP | Hazard and Operability Study |
| HE | Hazard Evaluation |
| HFT | Hardware fault tolerance |
| HMI | Human machine interface |
| HRA | Human Reliability Analysis H&RA Hazard and risk assessment |
| H/W | Hardware |
| IEC | International Electro technical Committee |
| IEEE | Institute of Electrical and Electronic Engineers |
| IEV | International Electrotechnical Vocabulary |
| I/O | Input or Output |
| IPL | Independent Protection Layer |
| ISA | The Instrumentation, Systems, and Automation Society |
| ISO | International Organization for Standardization |
| ISO 10437 | Special purpose steam turbines |
| LAH | Level Alarm—High |
| LI | Level Indicator |
| LIC | Level Indicator—Control |
| LFL | Lower Flammability Limit |
| LNG | Liquefied Natural Gas |
| LOP | Layer of Protection |
| LOPA | Layer of Protection Analysis |
| LOTO | Lock-Out Tag-Out |
| LT | Level Transmitter |
| LVL | Limited variability language |
| MAWP | Maximum Allowable Working Pressure |
| MOC | Management of Change |
| MOC | Management of Change |
| Moon | “M” out of “N” |
| MTBF | Mean Time Between Failures |
| MTTF | Mean Time To Failure |
| NFPA | National Fire Protection Authority |
| NFPA 85 | NFPA Standard: Boiler and Combustion Systems Hazards Code |
| NFPA 86 | NFPA Standard: Ovens and Furnaces |
| NP | Non-programmable |
| N ₂ | Nitrogen |
| OSBL | Outside Battery Limits |
| OREDA | The Offshore Reliability Data project |
| OSHA | Occupational Safety and Health Administration (U.S.) |
| <i>P</i> fatality | Probability of Fatality |
| <i>P</i> ignition | Probability of Ignition |
| <i>P</i> person present | Probability of Person Present |
| <i>P</i> | Probability |
| PCS | Premier Consulting Service |
| PE | Programmable electronics |
| PES | Programmable electronic system |
| PFD | Probability of Failure on Demand |

| | |
|-----------|--|
| PFDavg | Average probability of failure on demand |
| PHA | Process Hazard Analysis |
| PI | Pressure Indicator |
| PL | Protection Layer |
| PLC | Programmable logic controller |
| P&ID | Piping and Instrumentation Diagram |
| PLC | Programmable Logic Controller |
| PM | Preventive Maintenance |
| PSM | Process Safety Management |
| PSV | Pressure Safety Valve (Relief Valve) |
| PSAT | Pre-Startup Acceptance Test |
| QRA | Quantitative Risk Assessment |
| R | Risk |
| RV | Relief Valve |
| RTD | Resistance Temperature Detector |
| SAT | Site acceptance test |
| SCE | Safety Critical Equipment |
| SFF | Safe failure fraction |
| SIF | Safety Instrumented Function |
| SIL | Safety Integrity Level |
| SIS | Safety Instrumented System |
| SOP | Standard Operating Procedures |
| SOV | Solenoid Valve |
| SRS | Safety Requirement Specification |
| S/W | Software |
| T | Test Interval for the Component or System (hours or years) |
| T/C or TE | Thermocouple |
| TMR | Triple Modular Redundant |
| UPS | Uninterruptible Power Supply |
| VCE | Vapor Cloud Explosion |
| VLE | Vapor Liquid Equilibrium |
| WDT | Watch Dog Timer |
| XV | Remote Activated/Controlled Valve |
| 1oo1 | One-out-of-One Voting |
| 2oo2 | Two-out-of-Two Voting |
| 3oo3 | Three-out-of-Three Voting |

Appendix D

Balance of Plant HAZOP Study Report

HAZOP Study Report

Balance of Plant Scope

15-Jul-2022
Hunter Valley Power Station
Doc No. HPP-AEC-SYS-PT-GEN-REP-0001

HAZOP Study Report

Balance of Plant Scope

Client: Snowy Hydro Limited

ABN: 17 090 574 431

Prepared by

AECOM Australia Pty Ltd

Level 8, 540 Wickham Street, PO Box 1307, Fortitude Valley QLD 4006, Australia

T +61 7 3056 4800 www.aecom.com

ABN 20 093 846 925

15-Jul-2022

Job No.: 60666845

AECOM in Australia and New Zealand is certified to ISO9001, ISO14001 and ISO45001.

© AECOM Australia Pty Ltd (AECOM). All rights reserved.

AECOM has prepared this document for the sole use of the Client and for a specific purpose, each as expressly stated in the document. No other party should rely on this document without the prior written consent of AECOM. AECOM undertakes no duty, nor accepts any responsibility, to any third party who may rely upon or use this document. This document has been prepared based on the Client's description of its requirements and AECOM's experience, having regard to assumptions that AECOM can reasonably be expected to make in accordance with sound professional principles. AECOM may also have relied upon information provided by the Client and other third parties to prepare this document, some of which may not have been verified. Subject to the above conditions, this document may be transmitted, reproduced or disseminated only in its entirety.

Quality Information

Document HAZOP Study Report

Ref 60666845

Date 15-Jul-2022

Prepared by Steven Sylvester

Reviewed by David Lockley/ Kerrie Wells

Revision History


| Rev | Revision Date | Details | Authorised | |
|-----|---------------|--|--------------------------------|---|
| | | | Name/Position | Signature |
| A | 28-Apr-2022 | For Internal Review | Jason Lawer Project Manager | |
| 0 | 14-Jun-2022 | For Information | Jason Lawer Project Manager | |
| 1 | 15-Jul-2022 | Required Action Completion Phase added to Detail Records | Jason Lawer Project Manager |  |
| | | | | |

Table of Contents

| | |
|--|----|
| Executive Summary | i |
| 1.0 Introduction | 2 |
| 1.1 Background | 2 |
| 1.2 Objectives | 2 |
| 1.3 Scope of the HAZOP | 2 |
| 1.4 Qualifications of the Facilitator | 3 |
| 2.0 Methodology | 4 |
| 2.1 HAZOP Study Background | 4 |
| 2.2 HAZOP Study Approach | 4 |
| 2.3 HAZOP Location, Timing and Study Participants | 6 |
| 2.4 Drawings Used and Nodes Selected for the HAZOP | 11 |
| 3.0 Brief Description of the Services Systems | 14 |
| 3.1 Hunter Power Project Regional Location | 14 |
| 3.2 Brief Description of the Services Systems – Hunter Power Project | 14 |
| 3.3 Natural Gas Supply System | 15 |
| 3.4 Diesel Fuel System | 16 |
| 3.5 Process Gas and Air Systems | 17 |
| 3.6 Potable Water and Service Water Systems | 18 |
| 3.7 Trade Waste System | 19 |
| 3.8 Storm Water System | 19 |
| 4.0 HAZOP Study Results | 20 |
| 4.1 Introduction | 20 |
| 4.2 Summary of HAZOP Study Results | 20 |
| 5.0 References | 21 |
| Appendix A | |
| HAZOP Workshop Minutes Including Action Record & Date Completed | A |
| Appendix B | |
| Diesel System P&IDs Showing Nodes Applied in the HAZOP | B |
| Appendix C | |
| Natural Gas P&IDs Showing Nodes Applied in the HAZOP | C |
| Appendix D | |
| Instrument Air System P&IDs Showing Nodes Applied in the HAZOP | D |
| Appendix E | |
| Service Air System P&IDs Showing Nodes Applied in the HAZOP | E |
| Appendix F | |
| H2, CO2 & N2 Systems P&IDs Showing Nodes Applied in the HAZOP | F |
| Appendix G | |
| Demin. Water System P&IDs Showing Nodes Applied in the HAZOP | G |
| Appendix H | |
| Water System P&IDs Showing Nodes Applied in the HAZOP | H |
| Appendix I | |
| Fire Water System P&IDs Showing Nodes Applied in the HAZOP | I |
| Appendix J | |
| Effluent Treatment System P&IDs Showing Nodes Applied in the HAZOP | J |

Executive Summary

Introduction, Objectives and Scope

Snowy Hydro Limited (Snowy Hydro) proposes to construct and operate a Gas Turbine Peaking Power Station in the Hunter Valley, NSW. AECOM has been commissioned to design the services systems for the power station and as part of the power station design, Hazard and Operability studies (HAZOP) were performed to identify any potential hazards and operational issues prior to the plant construction/operation. Snowy Hydro and AECOM commissioned RiskCon Engineering Pty Ltd (RiskCon) to provide an independent HAZOP facilitator for the proposed studies conducted for the power station service systems project.

The objectives of the HAZOP were to identify hazard and operability issues associated with the design and operation of the proposed services areas, identify hazard management & control measures and report on the study findings including HAZOP minutes incorporating action recording functions.

The scope of work for the HAZOP was for the services systems (Balance of Plant) only and does not include the gas turbines and associated power components.

Methodology

The HAZOP study was conducted using a workshop format following the principles of Hazardous Industry Planning Advisory Paper No. 8 (Ref.2), Kletz (Ref.1) and AS/IEC 61882 (Ref.3). To ensure the most effective recording of results was achieved, for the Hunter Power Services Systems, or Balance of Plant, HAZOP study, the following recording format was adopted:

1. For the issues identified in the assessment, where a discussion issue was clearly identified to result in no hazard or operability issue, no entry was made in the HAZOP minutes sheet. This entry approach was followed to minimise the recording requirements of the study.
2. Where a hazard and operability issue may have a potential to occur as a result of the process design or operation, the deviation from normal operations was reviewed and where the safeguards were considered adequate to control the identified hazard/operability issue, a part record was made with "no action required" recorded.
3. Where a discussion point was identified to result in a potential hazard/operations issue, and safeguards were identified to be insufficient to control the hazard/operability issue, a full minute point was recorded, identifying deviation cause, consequence, proposed safeguards and action required to prevent, detect, protect and/or mitigate the operations consequences.

The summary of HAZOP Minutes recorded during the workshop sessions are presented in Appendix A.

HAZOP Study Results

The meeting was able to review the proposed design in a satisfactory manner, including the impact of disturbances from the Kurri Kurri Gas Lateral on the Hunter Power site (design representatives from the Kurri Kurri Gas Lateral Project Team, APA, participated in the relevant session). Adequate information was available, and the HAZOP participants had a sound range of relevant design and production experience.

The HAZOP study did not reveal any significant hazards that would compromise the safety or integrity of the project and that could not be managed. The project can proceed, subject to satisfactory resolution of the HAZOP recommendations.

There were 316-minute points discussed during the HAZOP study, with a number of these requiring no action or follow up item. However, there were a number of issues raised due to the specific requirements of the systems and the proposed operation.

A total of 213-minute points were recorded requiring action, which are listed in the HAZOP minutes at Appendix A.

Many of these were related to the requirement for update of P&IDs, procedures, detailed operation of the isolation function, access requirements, relocation or addition of valves when in use or when isolated and fail-safe valve failure position, etc. The drawings used in the HAZOP are included at Appendix B, showing the nodes applied during the workshop study.

To ensure appropriate follow-up is recorded for each of the minute points requiring action, HAZOP action columns have been included in the HAZOP minutes at Appendix A. These columns can be used by the project management team to input the action taken and date completed as a record of the minute point follow up. Prior to commencement of operations at the plant, all action points relating to design, operating procedures and commissioning should be completed and the action taken recorded to ensure appropriate hazard reduction or increase in operability has been implemented. Where the HAZOP actions are associated with maintenance activities these may not be fully closed out until the relevant experience has been gained when performing maintenance.

Abbreviations

| | |
|-------------------------|--|
| AS | Australian Standard |
| BOP | Balance of Plant |
| CO₂ | Carbon Dioxide |
| CPEng. | Chartered Professional Engineer |
| Demin. | Demineralised Water |
| EEHA | Electrical Engineering Hazardous Areas |
| FIE Aust. | Fellow of Engineers Australia |
| FT | Full Time |
| GT | Gas Turbine |
| GTG | Gas Turbine Generator |
| H₂ | Hydrogen |
| HAZOP | Hazard & Operability Study |
| ICI | Imperial Chemical Industries |
| IEC | International Electrotechnical Commission |
| kg/h | kilograms per hour |
| km | Kilometres |
| kPag | kilo Pascals (gauge) |
| kV | kilo Volts |
| L/s | Litres per second |
| m³ | Cubic Metres |
| m³/h | Cubic metres per hour |
| MHI | Mitsubishi Heavy Industries |
| MPa | Mega Pascals |
| MW | Mega Watts |
| N₂ | Nitrogen |
| NER | National Engineering Register |
| NG | Natural Gas |
| Nm³/h | Normal cubic metres per hour |
| OCGT | Open Cycle Gas Turbine |
| P&IDs | Piping and Instrumentation Diagrams |
| P/T | Part time |
| pH | Measure of acidity/Alkalinity |
| RPRQ | Registered Professional Engineer in Queensland |
| SCADA | Supervisory Control and Data Acquisition |
| SCADA | Supervisory Control and Data Acquisition |
| SFAIRP | So Far As Is Reasonably Practicable |
| SMS | Safety Management System |

1.0 Introduction

1.1 Background

Snowy Hydro Limited (Snowy Hydro) proposes to construct and operate a Gas Turbine Peaking Power Station in the Hunter Valley, NSW. AECOM has been commissioned to design the services systems for the power station and as part of the power station design, Hazard and Operability studies (HAZOP) were performed to identify any potential hazards and operational issues prior to the plant construction/operation.

Snowy Hydro and AECOM commissioned RiskCon Engineering Pty Ltd (RiskCon) to provide an independent HAZOP facilitator for the proposed studies conducted for the power station service systems project.

This document provides the HAZOP study minutes, action sheets and report for the services systems for the proposed Hunter Power Station, NSW.

1.2 Objectives

The objectives of the HAZOP study of the Hunter Power Project services systems were to:

- identify hazard and operability issues associated with design and operation of the proposed services areas associated with the Hunter Power Project
- identify hazard management & control measures that can be applied to minimize the potential for hazard and operability impacts
- develop HAZOP action sheets to assist AECOM & Snowy Hydro in implementing the HAZOP actions
- report on the findings of the study, including draft and final HAZOP reports.

1.3 Scope of the HAZOP

The scope of the HAZOP was for the services systems associated with the Hunter Power project only. The HAZOP does not include the Gas Turbine (GT) systems or enclosures, the HAZOP for these systems will be prepared under a separate HAZOP assessment.

The following systems were included in the scope of the HAZOP:

- Natural Gas Supply – from the main gas supply provider at the power station boundary to the GT enclosure, including metering systems, knock out drums, filter/coalescers, cartridge filters, condensate tank and associated pipework
- Diesel Fuel Supply – including diesel fuel unloading, diesel storage tanks, forwarding pumps and associated delivery pipework from the tanks to the GT enclosure
- Process Gas – Hydrogen gas systems including gas cylinders (trailers) and delivery pipework to the generator for each GT
- Process Gas – Carbon Dioxide (CO₂) gas systems including cylinders and delivery pipework to the generator for each GT
- Process gas - Nitrogen gas systems including cylinders and delivery pipework to the natural gas supply line to the GT
- Compressed Air and Instrument air systems supplying air services to the site and to the GT equipment
- Water Supply – potable water supply to the service water tank and site users, including service water tank, service water pumps and associated pipework to users
- Water Supply – service water systems including pumps to Reverse Osmosis (RO) plant, RO plant, demineralised (demin.) water tanks, pumps, filters and chemical dosing systems

- Water Supply – fire water and fire services systems, including fire water tanks, pumps and pipework
- Waste-Water Systems – Oily water collection and treatment systems, Demin plant and blade washing waste water systems, chemical dosing systems for the trade waste system and sewer systems.

1.4 Qualifications of the Facilitator

The HAZOP study was facilitated by Steve Sylvester, Technical Director at RiskCon Engineering. Steve is a mechanical engineer (BEng., Mech.Hons) with over 50 years engineering experience, including 20 years in marine and chemical plant operations and over 30 years in engineering consultancy. Steve spent several years with ICI (inventors of HAZOP) in the early 1990's where he was trained as a HAZOP leader. Since this time he has conducted over 100 HAZOP studies, including major projects such as Goro and Koniambo Nickel plants (New Caledonia), Ichthys Project in Darwin and numerous smaller mining, mineral processing and Oil/Gas project HAZOPs. He is an internationally accredited Functional Safety Engineer (FSE TÜV 2203/10), a founding member and Fellow of the Australasian Institute of Dangerous Goods Consultants (www.aidgc.org.au) and has completed the competency training for Electrical Engineering Hazardous Areas (EEHA). He is a Fellow and Chartered Professional Engineer (FIEAust/CPEng.), is listed on the National Engineering Register (NER) and is a Registered of Professional Engineers in Queensland (RPEQ). A full resume can be provided on request.

2.0 Methodology

2.1 HAZOP Study Background

The hazard and operability study (HAZOP) is a workshop-based approach structured particularly for process operations. However, HAZOP studies have been successfully applied to mechanical electrical and computer systems alike.

The HAZOP study methodology was developed in the mid 1970's by Professor Trevor Kletz* for Imperial Chemical Industries (ICI) and has developed into a useful design tool for project managers to take stock of the status of the design and to assess the hazards associated with a project and how the proposed design caters for the safe management of those hazards.

Whilst HAZOP was originally designed to assess new projects, it has (over time) become a useful tool for assessing existing plant and facilities to determine hazard and operability issues that may have been overlooked in original designs that may not have been subject to the HAZOP process. It is also a useful tool for conducting due diligence assessments to determine whether a proposed purchase is a viable option.

* Trevor Kletz – former Professor Emeritus, Loughborough University, UK (Deceased).

2.2 HAZOP Study Approach

The basic approach used for the Hunter Power Project Services HAZOP was that published by the Department of Planning, Industry and Environment (DPIE, Ref.2), Kletz (Ref.1) and Australian Standard AS/IEC 61882 (Ref.3). The process is as follows:

Preliminary work included the identification of nodes used in the HAZOP assessment and determine the guidewords proposed for use in the study. Preliminary work was discussed with Snowy Hydro and AECOM to confirm the appropriate nodes and guideword selection reflected the proposed design and operations.

Prior to the study commencement, piping and instrumentation diagrams (P&IDs) were provided to the study participants to assist in the detailed assessment of the proposed Hunter Power Project Services systems. P&IDs were provided in electronic format for review and comment by the participants.

Owing to the current health orders and individual company meeting restrictions (i.e. Covid meeting restriction numbers) the HAZOP study sessions were conducted on-line using Microsoft Teams. All participants logged into the teams meeting and each participant was requested, by the facilitator, to introduce their role in the HAZOP so that the facilitator was aware of the team's experience and therefore specific questions could be directed to the person responsible for the point under discussion.

Once the team was introduced, an overview of the proposed Hunter Power Station Project was provided by the Snowy Hydro project manager. Once the team were familiar with the overall project proposed design, the services design engineer from AECOM provided a brief overview description of the services systems. During the system description, participants were encouraged to ask questions and clarify any points to ensure they were familiar with the proposed designs. The overall aim of this "step", in the HAZOP process, is to ensure all team members were commencing the HAZOP on a reasonable knowledgeable basis.

Once the project descriptions were completed, the facilitator selected a service system and P&ID and displayed the P&ID on screen so that all participants were able to see the system and nodes selected for the HAZOP assessment. A "Node" was selected and a team member explained the "Node" design and operation in detail and questions were asked at this point for clarification.

Once "Node" design and operation clarifications were completed, the facilitator confirmed the section on the master drawings to ensure all participants were aware of the "Node" under consideration.

The facilitator then selected a guideword (e.g. pressure, flow, level, temperature, etc., for process systems). The team then reviewed the potential for a deviation from normal operating conditions associated with the guideword. Table 2 shows the list of guidewords used in the study.

Where a deviation from normal operating conditions was identified (e.g. high level), a HAZOP minute was recorded, noting the minute number, guideword used, cause of the deviation, consequence of the deviation, proposed safeguards and required action to control the identified deviation. To ensure the minute action is completed and followed up, the minute action was allocated to a member of the team.

The minutes for the project HAZOP study were recorded on a laptop computer by a dedicated minute taker. The deviation assessment process was continued until all guidewords were reviewed for the specific "Node". On completion of the "Node", the HAZOP minutes were displayed on screen and all participants were able to review the minutes and make comments regarding any recording errors. This minimised lengthy review of the minutes on completion of the HAZOP as all team members were able to see the recorded minute on the shared screen prior to issue of the minutes. An example minute sheet is shown at Table 1.

Table 1 HAZOP Study Team

| HAZOP STUDY MINUTES | | | | | | |
|---------------------|-----------|---------------|-------------|-----------|--------------|-------------|
| Plant: | | Section/Line: | | | Drawing No.: | Date: |
| No. | Guideword | Cause | Consequence | Safeguard | Action | Responsible |
| | | | | | | |

On completion of the study a draft set of study minutes were developed and passed to the HAZOP team for review & comment. Updates to the minutes for points of fact were made and a draft report issued for review and comment by the HAZOP team. A final report was then issued incorporating comments on the draft report for points of fact.

Table 2 Guidewords Used in the Hunter Power Project Services HAZOP

| Process Systems Guidewords (e.g. Pipework Pumps, Tanks, etc.) | |
|--|---|
| Flow | Leak, too high, too low, reverse, two phase |
| Level | Too high, too low |
| Temperature | Too high, too low |
| Pressure | Too high, too low, vacuum |
| Quality | Wrong concentration, impurities, cross contamination, side reactions, inspection and testing, instrument quality and quantity |
| Control | Response speed, sensor and display location, interlocks, SCADA system security, hardware/ software weak links, system node/ comms failure |
| Electrical Safety | Hazardous area classification, earthing, lightning protection |
| Maintenance | Access to plant and equipment, purging of gas, inspection and testing. |
| Mechanical Systems Guidewords (e.g., Conveyors, robot systems, materials handling, etc.) | |
| Position | Too High, Low, Far, Near, Misaligned, Wrong Position |
| Movement | Speed High/Low, No Movement, Reverse Movement, Vibration, Friction, Slip, Obstacles |
| Size | Too Large, Small, Long, Short, Wide, Narrow |
| Load | High/Low Load, High/Low Flow, Loss of Containment |
| Timing | Too Late, Early, Short, Long, Incorrect Sequence |
| Energy | Low, High, Energy Failure |
| Contamination | Water, Oil, Dust, Flammables, Corrosives |
| Process Control | Adequate, Automatic vs Manual, Interlocks, Limits, Trips, Critical variables |

| Process Systems Guidewords (e.g. Pipework Pumps, Tanks, etc.) | |
|--|---|
| Electrical Systems | Area Classification, Isolation, Earthing |
| Maintenance | Isolation, Access, Purging, Inspection and Testing |
| Overview Guidewords | |
| Toxicity | Handling procedures, precautions, exposure and monitoring |
| Physical Damage | Impact, dropped objects, transport collision, vibration, corrosion |
| Fire/Explosion | Prevention systems, detection systems, fire protection, emergency isolation, emergency procedures |
| Environmental Impact | Vapour/gas emissions, dust emissions, effluent, noise, ground seepage, waste minimisation |
| Materials Of Construction | Pipework, valves, fitting, instruments, filters, gaskets, protective systems and coatings |
| Access | Operation, Maintenance, Emergency Escape |
| Utilities And Services | Instrument air/gas, compressed air, breathing air, nitrogen, cooling water, process water, steam, fuel gas, electricity, oxygen, lighting |
| Commissioning | Requirements, sequence, procedures |
| Start-Up | First time, routine, procedures |
| Shut Down | Planned, emergency |
| Safety Equipment | Personnel protection, gas monitoring, breathing apparatus, safety showers, barriers and guards |
| Natural Hazards | Earthquake, Flooding, Thunderstorm, High Winds |
| Inspection And Testing | Alarms and trips, emergency isolation, gas/fire detectors, fire protection systems |
| Procedures | Operations, maintenance, inspection and testing, confined space, emergency, engineering drawings, modification control |
| Quality Control | Inspection and Testing, Quality Assurance System |

2.3 HAZOP Location, Timing and Study Participants

As noted in Section 2.2, the HAZOP was conducted “on-line” using Microsoft Teams. A core team from AECOM, including the services system design engineer, the electrical/instruments design engineer, the study facilitator and minute taker were located in the conference room at the AECOM offices in Warabrook Boulevard, Newcastle, NSW.

The study was conducted over 14 sessions each of around three and a half (3.5) to four (4) hours duration. The sessions were conducted on the following days:

- Thursday 20 January 2022 – Diesel Systems.
- Friday 21 January 2022 – Natural Gas Systems
- Thursday 27 January 2022 – Hydrogen Systems, CO₂ systems, Nitrogen Systems
- Friday 28 January 2022 – Instrument Air Systems, Services Air Systems
- Tuesday 1 February 2022 – Potable Water Systems, Services Water Systems, Demineralised Water Systems, chemical dosing systems
- Wednesday 2 February 2022 – Fire water systems, oily water systems
- Thursday 3 February 2022 - Blade washing systems, trade waste and sewer systems.

The HAZOP team (participants) for each of the HAZOP sessions are listed in Table 3.

Table 3 HAZOP Study Team

| Name | Organisation | Position | Workshop Date | Full/Part Time |
|--|--------------|---|-------------------------|----------------|
| Natural Gas and Diesel Fuel Systems | | | | |
| Jason Lawer | AECOM | Project Manager | 20/01/2022 – 21/01/2022 | FT |
| Chris Treleaven | AECOM | Engineering Manager | 20/01/2022 – 21/01/2022 | FT |
| Kerrie Wells | AECOM | Process Lead (BOP) | 20/01/2022 – 21/01/2022 | FT |
| Jafar Dashtbani | AECOM | Senior Process Engineer | 20/01/2022 – 21/01/2022 | FT |
| Brooke Mackley | AECOM | Process Mechanical Specialist | 20/01/2022 – 21/01/2022 | FT |
| Francis Nadaraju | AECOM | Mechanical Lead (BOP) | 20/01/2022 – 21/01/2022 | FT |
| Blair Murray | AECOM | Process and Mechanical Team Lead (Power Island) | 20/01/2022 – 21/01/2022 | FT |
| Ali Noursadeghi | AECOM | Senior Mechanical Engineer | 20/01/2022 – 21/01/2022 | FT |
| Peter Haines | AECOM | Principal Mechanical Engineer | 20/01/2022 – 21/01/2022 | FT |
| Mike Allan | AECOM | Electrical and Instrumentation Lead (BOP) | 20/01/2022 – 21/01/2022 | FT |
| Steven Sylvester | RiskCon | HAZOP Facilitator (Mech. Eng.) | 20/01/2022 – 21/01/2022 | FT |
| Samantha Grabelli | AECOM | Technical Scribe (Process Engineer) | 20/01/2022 – 21/01/2022 | FT |
| Evan Bayliss | Snowy Hydro | Design and Quality Lead (Hunter Power Project) | 20/01/2022 – 21/01/2022 | FT |
| Dave Bedding | Snowy Hydro | Operator Technician (Maintenance) Colongra | 20/01/2022 – 21/01/2022 | FT |
| Sara Roder | Snowy Hydro | Project Mechanical Engineer | 20/01/2022 – 21/01/2022 | FT |
| Patrick Scholtes | Snowy Hydro | Mechanical Engineer (operations) | 20/01/2022 – 21/01/2022 | FT |
| Karl Ivanusic | Snowy Hydro | Owners Engineer | 20/01/2022 – 21/01/2022 | FT |
| Michael Carton | Snowy Hydro | Electrical engineer | 20/01/2022 – 21/01/2022 | FT |
| Locky Smith | Snowy Hydro | Instrumentation and Controls Engineer | 20/01/2022 – 21/01/2022 | FT |
| Gary Blanch | Snowy Hydro | Area Manager of Snowy Hydro Gas Power stations | 20/01/2022 – 21/01/2022 | FT |
| Mukul Bokil | Snowy Hydro | Engineering Construction | 20/01/2022 – 21/01/2022 | FT |
| Ciaran McGettigan | APA | Process Lead | 20/01/2022 – 21/01/2022 | PT |
| Matthew Walton | APA | Engineering manager | 20/01/2022 – 21/01/2022 | PT |

| Name | Organisation | Position | Workshop Date | Full/Part Time |
|---|--------------|--|-------------------------|----------------|
| Moriguchi Hirofumi | MHI | Project Manager | 20/01/2022 – 21/01/2022 | PT |
| Oshino Yoji | MHI | Senior Manager, Project Engineering | 20/01/2022 – 21/01/2022 | PT |
| Yamasaki Masaaki | MHI | Eng. Manager & Design Eng. (Mechanical & Process) | 20/01/2022 – 21/01/2022 | PT |
| Tsukuda Yuya | MHI | Design Engineer (Mechanical & Process) | 20/01/2022 – 21/01/2022 | PT |
| Process Gas (H₂, CO₂, N₂) and Air Systems (compressed air and instrument air) | | | | |
| Jason Lawer | AECOM | Project Manager | 27/01/2022 – 28/01/2022 | FT |
| Chris Treleaven | AECOM | Engineering Manager | 27/01/2022 – 28/01/2022 | FT |
| Kerrie Wells | AECOM | Process Lead (BOP) | 27/01/2022 – 28/01/2022 | FT |
| Jafar Dashtbani | AECOM | Senior Process Engineer | 27/01/2022 – 28/01/2022 | FT |
| Brooke Mackley | AECOM | Process Mechanical Specialist | 27/01/2022 – 28/01/2022 | FT |
| Francis Nadaraju | AECOM | Mechanical Lead (BOP) | 27/01/2022 – 28/01/2022 | FT |
| Blair Murray | AECOM | Process and Mechanical Team Lead (Power Island) | 27/01/2022 – 28/01/2022 | FT |
| Ali Noursadeghi | AECOM | Senior Mechanical Engineer | 27/01/2022 – 28/01/2022 | FT |
| Peter Haines | AECOM | Principal Mechanical Engineer | 27/01/2022 – 28/01/2022 | FT |
| Mike Allan | AECOM | Electrical and Instrumentation Lead (BOP) | 27/01/2022 – 28/01/2022 | FT |
| Steven Sylvester | RiskCon | HAZOP Facilitator | 27/01/2022 – 28/01/2022 | FT |
| Samantha Grabelli | AECOM | Technical Scribe (Process Engineer) | 27/01/2022 – 28/01/2022 | FT |
| Barry Tyer | AECOM | Process verifier | 27/01/2022 – 28/01/2022 | FT |
| Evan Bayliss | Snowy Hydro | Design and Quality Lead (Hunter Power Project) | 27/01/2022 – 28/01/2022 | PT |
| Dave Bedding | Snowy Hydro | Operator Technician (Maintenance) Colongra | 27/01/2022 – 28/01/2022 | FT |
| Sara Roder | Snowy Hydro | Project Mechanical Engineer | 27/01/2022 – 28/01/2022 | FT |
| Patrick Scholtes | Snowy Hydro | Mechanical Engineer | 27/01/2022 – 28/01/2022 | FT |
| Karl Ivanusic | Snowy Hydro | Owners Engineer | 27/01/2022 – 28/01/2022 | FT |
| Michael Carton | Snowy Hydro | Electrical engineer | 27/01/2022 – 28/01/2022 | PT |
| Locky Smith | Snowy Hydro | Instrumentation and | 27/01/2022 – | FT |

| Name | Organisation | Position | Workshop Date | Full/Part Time |
|--|--------------|--|-------------------------|----------------|
| | | Controls Engineer | 28/01/2022 | |
| Gary Blanch | Snowy Hydro | Area Manager of Snowy Hydro Gas Power stations | 27/01/2022 – 28/01/2022 | PT |
| Mukul Bokil | Snowy Hydro | Engineering Construction | 27/01/2022 – 28/01/2022 | PT |
| Damien Cooper | Snowy Hydro | Colongra Manager | 27/01/2022 – 28/01/2022 | PT |
| Paul Hill | Snowy Hydro | Site superintendent | 27/01/2022 – 28/01/2022 | PT |
| Isaac Strachan | Snowy Hydro | Health, Safety and Environmental Lead | 27/01/2022 – 28/01/2022 | PT |
| Moriguchi Hirofumi | MHI | Project Manager | 27/01/2022 – 28/01/2022 | PT |
| Oshino Yoji | MHI | Senior Manager, Project Engineering | 27/01/2022 – 28/01/2022 | PT |
| Yamasaki Masaaki | MHI | Eng. Manager & Design Eng. (Mechanical & Process) | 27/01/2022 – 28/01/2022 | PT |
| Tsukuda Yuya | MHI | Design Engineer (Mechanical & Process) | 27/01/2022 – 28/01/2022 | PT |
| Water, Waste-Water and Sewage Systems | | | | |
| Jason Lawer | AECOM | Project Manager | 1/02/2022 - 3/02/2022 | PT* |
| Chris Treleaven | AECOM | Engineering Manager | 1/02/2022 - 3/02/2022 | FT |
| Kerrie Wells | AECOM | Process Lead (BOP) | 1/02/2022 - 3/02/2022 | FT |
| Jafar Dashtbani | AECOM | Senior Process Engineer | 1/02/2022 - 3/02/2022 | FT |
| Brooke Mackley | AECOM | Process Mechanical Specialist | 1/02/2022 - 3/02/2022 | FT |
| Francis Nadaraju | AECOM | Mechanical Lead (BOP) | 1/02/2022 - 3/02/2022 | FT |
| Ali Noursadeghi | AECOM | Senior Mechanical Engineer | 1/02/2022 - 3/02/2022 | FT |
| Peter Haines | AECOM | Principal Mechanical Engineer | 1/02/2022 - 3/02/2022 | FT |
| Mike Allan | AECOM | Electrical and Instrumentation Lead (BOP) | 1/02/2022 - 3/02/2022 | FT |
| Steven Sylvester | RiskCon | HAZOP Facilitator | 1/02/2022 - 3/02/2022 | FT |
| Samantha Grabelli | AECOM | Technical Scribe (Process Engineer) | 1/02/2022 - 3/02/2022 | FT |
| Marco Van Winden | AECOM | Water Engineer | 1/02/2022, 3/02/2022 | PT |
| Deni Estiville-Dredge | AECOM | Civil/Water Engineer | 1/02/2022 - 3/02/2022 | PT |
| Neil Shen | AECOM | Mechanical Engineer | 1/02/2022 - 3/02/2022 | FT |

| Name | Organisation | Position | Workshop Date | Full/Part Time |
|--------------------|--------------|--|-----------------------|-----------------|
| Ian Leach | AECOM | Civil Engineer | 2/02/2022 | FT |
| Evan Bayliss | Snowy Hydro | Design and Quality Lead (Hunter Power Project) | 2/02/2022 | PT* |
| Dave Bedding | Snowy Hydro | Operator Technician (Maintenance) Colongra | 1/02/2022 - 2/02/2022 | FT |
| Sara Roder | Snowy Hydro | Project Mechanical Engineer | 1/02/2022 - 3/02/2022 | FT |
| Patrick Scholtes | Snowy Hydro | Mechanical Engineer | 1/02/2022 - 3/02/2022 | FT |
| Karl Ivanusic | Snowy Hydro | Owners Engineer | 2/2/2022 - 3/02/2022 | PT* |
| Michael Carton | Snowy Hydro | Electrical engineer | 1/02/2022 - 3/02/2022 | PT |
| Locky Smith | Snowy Hydro | Instrumentation and Controls Engineer | 1/02/2022 - 3/02/2022 | FT |
| Gary Blanch | Snowy Hydro | Area Manager of Snowy Hydro Gas Power stations | 1/02/2022 - 3/02/2022 | PT |
| Mukul Bokil | Snowy Hydro | Engineering Construction | 1/02/2022 - 3/02/2022 | PT |
| Tim Gotts | Snowy Hydro | Project Engineer - Civil | 1/02/2022 - 3/02/2022 | PT |
| Mariam Biglari | Snowy Hydro | Process Engineer | 1/02/2022 - 3/02/2022 | PT |
| Damien Cooper | Snowy Hydro | Colongra Manager | 3/02/2022 | PT# |
| Moriguchi Hirofumi | MHI | Project Manager | 1/02/2022 - 3/02/2022 | PT [∅] |
| Oshino Yoji | MHI | Senior Manager, Project Engineering | 1/02/2022 - 3/02/2022 | PT [∅] |
| Yamasaki Masaaki | MHI | Eng. Manager & Design Eng. (Mechanical & Process) | 1/02/2022 - 3/02/2022 | PT [∅] |
| Tsukuda Yuya | MHI | Design Engineer (Mechanical & Process) | 1/02/2022 - 3/02/2022 | PT [∅] |

* Did not attend Tuesday 1/2 during Service water and demin nodes.

Attended during trade waste and sewer nodes

∅ Did not attend on Wednesday 2/2 during Fire Water and Oily water nodes

As part of the compilation of the HAZOP team, Hazardous Industry Planning Advisory Paper No.8 (Ref.2) was consulted to confirm the HAZOP participants comprised team members with the appropriate experience.

Section 2.5.1 of HIPAP 8 (Ref.2) indicates the following team members should be considered for inclusion as HAZOP participants. Names of the relevant participants have been placed against each of the positions to confirm the appropriate personnel attended and participated in the HAZOP.

- **Chairperson** - Chairperson was Steve Sylvester, ICI HAZOP trained with over 100 HAZOP facilitation studies completed in 30 years risk engineering experience. He has conducted a number of Gas Turbine HAZOP studies including Colongra (NSW) and Ichthys Project (NT).

- **Design Engineer** - Chris Treleavan was AECOM's design Engineering Manager, he attended all sessions of the HAZOP. The owners design representative, Karl Ivanusic attended all HAZOP sessions. Evan Baylis, Snowy Hydro Design and Quality Lead Engineer also attended the HAZOP sessions with the exception of water systems. To ensure disturbances from the Kurri Kurri Gas Lateral were understood, Matthew Walton, APA Engineering Manager attended the Fuel Gas session.
- **Process Engineer** - Kerrie Wells was AECOM's lead process engineer, she attended all sessions of the HAZOP, Jafar Dashtbani, AECOM senior process engineer was in the HAZOP sessions at all times, Mariam Bilgary and Tim Gotts from Snowy Hydro attended the HAZOP sessions on a part time basis, with one of the engineers being present at all of the HAZOP sessions. Karl Ivanusic, owners Process Engineering representative attended all HAZOP sessions. Ciaran McGettigan, APA's Lead Process Engineer, attended the Fuel Gas session.
- **Electrical/Instruments Engineer** - Mike Allen, AECOM instrument/Electrical Engineer attended all HAZOP sessions and Locky Smith, Snowy Hydro's instrument/Electrical Engineer attended all sessions.
- **Plant Operator** - Dave Bedding, Snowy Hydro operations at Colongra GT Power Station attended all sessions.
- **Operations Manager** - Gary Blanch, Snowy Hydro Area Manager Gas Power Stations attended sessions on a part time bases, Damien Cooper, Colongra Operations Manager attended sessions on a part time bases, one of the operations managers was in the HAZOP sessions at all times.
- **Maintenance/Mechanical Engineer** - Patrick Scholtes, Snowy Hydro Mechanical and Maintenance Engineer was in the HAZOP sessions at all times, Francis Nadaraju, AECOM Mechanical Lead Engineer was in the HAZOP sessions at all times, Ali Noursadeghi, AECOM Mechanical Engineer, was in the HAZOP sessions at all times,

Other representatives and participants from Snowy Hydro, AECOM, APA (Kurri Kurri Gas Lateral developers) and Mitsubishi Heavy Industries (GT Manufacturers) attended the HAZOP sessions at various times. These participants and their involvement (full time or part time) are listed in Table 3.

2.4 Drawings Used and Nodes Selected for the HAZOP

A list of P&IDs used in the HAZOP is provided in Table 4. Prior to the commencement of the HAZOP, the facilitator reviewed the P&IDs and developed Nodes for assessment during the HAZOP workshop. The P&IDs showing the Nodes are provided in Appendix C to Appendix J.

Table 4 HAZOP Master Drawings (or Marked up P&IDs)

| Drawing Number | Revision | Description |
|---|----------|---|
| Diesel Systems (drawings provided in Appendix B) | | |
| HPP-AEC-MEC-DS-LLS-DRG-1064 | B | Diesel Fuel Unit Loading System |
| HPP-AEC-MEC-DS-LLS-DRG-1065 | B | Diesel Fuel Unit Un-loading System |
| HPP-AEC-MEC-DS-LLS-DRG-1066 | B | Diesel Fuel Unit Storage Tanks |
| HPP-AEC-MEC-DS-LLS-DRG-1067 | B | Diesel Fuel Unit Forwarding Pumps |
| HPP-AEC-MEC-DS-LLS-DRG-1068 | B | Diesel Fuel Unit Polishing & Forwarding Filters |

| Drawing Number | Revision | Description |
|--|----------|---|
| HPP-AEC-MEC-DS-LLS-DRG-1069 | B | Diesel Fuel Unit Diesel Storage Tanks |
| Natural Gas Supply (drawings provided in Appendix C) | | |
| HPP-AEC-MEC-GA-KOO-DRG-1090 | B | Natural Gas Supply NG Knock Out Drum GT Unit 1 |
| HPP-AEC-MEC-GA-DTV-DRG-1091 | B | Natural Gas Supply - NG Filter Coalescer No. 1GT Unit 1 |
| HPP-AEC-MEC-GA-DTV-DRG-1092 | B | Natural Gas Supply - NG Filter Coalescer No.2 GT Unit 1 |
| HPP-AEC-MEC-GA-DTV-DRG-1093 | B | Natural Gas Supply – NG Metering & Heating GT Unit 1 |
| HPP-AEC-MEC-GA-DTV-DRG-1094 | B | Natural Gas Supply - Drip Tanks and Vent GT Unit 1 |
| HPP-AEC-MEC-GA-DTV-DRG-1095 | B | Natural Gas Supply – Turbine Supply Unit GT Unit 1 |
| HPP-AEC-MEC-GA-DTV-DRG-1096 | B | Natural Gas Supply – Calorie Meter & Battery Limit |
| HPP-AEC-MEC-GA-DTV-DRG-1097 | B | Natural Gas Supply – NG Cartridge Filter & Isolation GT1 |
| Instrument Air (drawings provided in Appendix D) | | |
| HPP-AEC-MEC-CP-IAS-DRG-1060 HPP-AEC-MEC-CP-IAS-DRG-1118 | B B | Instrument Air – Air Compressors |
| HPP-AEC-MEC-CP-IAS-DRG-1061 HPP-AEC-MEC-CP-IAS-DRG-1120 | B B | Instrument Air – Air Dryers |
| HPP-AEC-MEC-CP-IAS-DRG-1062 | B | Instrument Air – Air Receivers |
| HPP-AEC-MEC-CP-IAS-DRG-1063 | B | Instrument Air – Air Distribution |
| Service Air (drawings provided in Appendix E) | | |
| HPP-AEC-MEC-CP-PAS-DRG-1026 HPP-AEC-MEC-CP-PAS-DRG-1110 | B B | Service Air Unit – Air Compressors |
| HPP-AEC-MEC-CP-PAS-DRG-1027 HPP-AEC-MEC-CP-PAS-DRG-1111 | B B | Service Air Unit – Air Dryers |
| HPP-AEC-MEC-CP-PAS-DRG-1112 | B | Service Air Unit – Air Receivers |
| HPP-AEC-MEC-CP-PAS-DRG-1113 | B | Service Air Unit – Air Distribution |
| Hydrogen, N₂ & CO₂ System (drawings provided in Appendix F) | | |
| HPP-AEC-MEC-HY-GEN-DRG-1100 | B | Hydrogen Facility – Trailer Cylinder & Backup Bottles (1) |

| Drawing Number | Revision | Description |
|---|----------|---|
| HPP-AEC-MEC-HY-GEN-DRG-1102 | B | Process Gas Facility – N ₂ & CO ₂ Press. Regulator Panels |
| HPP-AEC-MEC-HY-GEN-DRG-1124 | B | Hydrogen Facility – Pressure Reduction panels and Vent |
| Demineralised Water ((drawings provided in Appendix G) | | |
| HPP-AEC-MEC-DW-SFP-DRG-1057 | B | Demin Water - Storage Tank |
| HPP-AEC-MEC-DW-SFP-DRG-1058 | B | Demin Water - Forwarding Pumps |
| HPP-AEC-MEC-DW-SFP-DRG-1055 | B | Demin Water - Pre-Treatment System |
| HPP-AEC-MEC-DW-SFP-DRG-1056 | B | Demin Water - Treatment Systems |
| HPP-AEC-MEC-DW-SFP-DRG-1059 | B | Demin Water - Treatment System |
| Water Systems (drawings provided in Appendix H) | | |
| HPP-AEC-MEC-PW-FPS-DRG-1051 | B | Service Water Unit - Forwarding Pumps |
| HPP-AEC-MEC-PW-SMS-DRG-1050 | B | Service Water Unit - Storage and Metering |
| HPP-AEC-MEC-PW-SMS-DRG-1052 | B | Service Water Unit - Storage Tank |
| Fire Water (drawings provided in Appendix I) | | |
| HPP-AEC-MEC-PW-SMS-DRG-1070 | B | Fire Water Unit - Storage Tanks |
| HPP-AEC-MEC-PW-SMS-DRG-1071 | B | Fire Water Unit - Fire Pumps |
| Effluent Treatment (drawings provided in Appendix J) | | |
| HPP-AEC-MEC-GN-GEN-DRG-1085 | C | Effluent Treatment - Storm & Oily Water Treatment |
| HPP-AEC-MEC-GN-GEN-DRG-1086 | C | Effluent Treatment - Sewer Transfer Pit & Pumps |
| HPP-AEC-MEC-GN-GEN-DRG-1087 | C | Effluent Treatment - Neutralisation Pit & Transfer Pumps (1) |
| HPP-AEC-MEC-GN-GEN-DRG-1123 | B | Effluent Treatment - Neutralisation Pit & Transfer Pumps (2) |
| HPP-AEC-MEC-GN-GEN-DRG-1088 | C | Effluent Treatment - pH Adjustment Injection Packages (1) |
| HPP-AEC-MEC-GN-GEN-DRG-1128 | B | Effluent Treatment - pH Adjustment Injection Packages (2) |

3.0 Brief Description of the Services Systems

3.1 Hunter Power Project Regional Location

The Hunter Power Project is proposed to be located in a newly created industrial zone on the site of the previous Aluminium Smelter at Kurri Kurri. Figure 1 shows the regional location of the proposed industrial zone.



Figure 1 Regional Location of the Hunter Power Project

3.2 Brief Description of the Services Systems – Hunter Power Project

Snowy Hydro proposes to construct and operate a Gas Turbine Peaking Power Station in the Hunter Valley, NSW. The Hunter Power Station is expected to have a nominal capacity of approximately 660 megawatts (MW) and will be generated via two heavy-duty ‘F Class’ open cycle gas turbines (OCGT).

The plant includes diesel fuel facilities for unloading/loading of tankers, storage and supply to the gas turbines. Two 1840 m³ diesel storage tanks located within a bunded area, store sufficient diesel for three (3) consecutive days turbine operation on diesel with a minimum delivery of six diesel tankers per day. There are also two diesel unloading/loading pumps and three diesel forwarding pumps to supply the gas turbine.

Figure 2 shows a layout of the proposed plant on the land.




Figure 2 Site Layout Showing Gas Turbine Locations

3.3 Natural Gas Supply System

Gas Pipeline

A new gas lateral is required to service the power station and this will tee-off from the existing Jemena JGN Trunk line pipeline. The new gas lateral will be constructed by APA who is the gas lateral proponent. The gas lateral will also consist of a 'storage bottle' which will provide storage capacity for operation of the power station. The design of the pipeline and storage bottle is expected to include approximately 6-7 hours' worth of gas storage.

The length of pipeline to the site is dependent on the route and is still being developed and could be approximately 15-20km. The pipeline will be buried below ground level within an easement and will be connected to the Gas Receiving Station at the power station.

External gas compression equipment will be required and will be the responsibility of APA. The proposed location currently being assessed for the gas compressor equipment is within the buffer zone on the southern boundary of the power station site.

Natural Gas Supply System

The gas delivery and metering station, designed by APA, takes gas directly from the gas supply line or the "storage bottle" to provide gas to the power station turbines. The equipment includes automated valves, flow meters, heaters and pressure control valves. The details of this equipment will be provided by APA.

The gas pressure delivered to the power station will be from 3,800 to 4,700 kPag, normally 4,400 kPag and the temperature will normally be 30 °C, with a minimum of 5 °C and a maximum of 60 °C.

The flowrate can vary between 3,600 to 73,800 kg/h, depending on the requirements of the gas turbine. The flowrate is specified by Mitsubishi.

The gas line will be isolatable at the power station boundary by a manual isolation valves. There will be line venting and nitrogen purging facilities also located to safely vent the natural gas to an elevated safe location. An MHI supplied pressure reduction unit and natural gas calorie meter downstream of the isolation facilities will measure the heating value of the gas and a monitoring tool.

The common gas supply runs along the western boundary of the plant before splitting on the northern side of Gas turbine (unit 2, southern unit). Each gas turbine will have separate gas isolation valves with downstream facilities for venting to a cold vent and nitrogen purging facilities to allow safe isolation for maintenance work.

A knockout vessel for removal of any condensed liquid in the gas supply line to each turbine is provided downstream of the unit isolation valve. The liquid is drained to a condensate collection tank which is connected to a small vent stack for separation of entrained gases. Downstream of the knockout vessel there are two filter/coalescer vessels arranged as a duty/standby to remove carry over oil and hydrocarbon condensates from the gas compressor and any solid particles carried over from the storage bottle and gas receiving station. Downstream of the filter / coalescers is a MHI supplied flow meter and fuel gas heater with heater bypass valve.

An MHI supplied gas cartridge filter is located downstream of the fuel gas heater to provide “last chance” filtration for the gas. After the cartridge filter, there are three fuel gas purge credit shutoff valves to allow quick purging of the fuel gas line for start-up and shutdown. The gas then enters the gas turbine fuel gas pressure control unit.

3.4 Diesel Fuel System

Diesel Fuel Storage Tanks

Two storage tanks, with nominal capacity of 2120 m³ and useable capacity of 1845 m³ each, are designed to storage and supply fuel to both turbines when running on diesel fuel for 10 hours per day for 3 consecutive days including six deliveries of a B- double tanker (50 m³) per day.

Whilst the storage tanks are connected by common inlet and outlet lines, the tanks operate as separate (non-connected) supplying the gas turbine as individual tanks isolated by actuated valves. The tanks are located within a common bunded area which is designed to hold 110% capacity of one .storage tanks.

Diesel Forwarding Pumps and Filters

The diesel forwarding pumps have a design capacity to supply the peak demand flow required for GT main fuel oil pumps as per the MHI Utility list plus 10% margin. Three (3) centrifugal pumps each of 100 m³/hr capacity are installed with a duty/duty/standby arrangement

Two (2) diesel forwarding filters, with a capacity of 200 m³/hour, are installed in supply line to the GT to remove any suspended solids and to deliver clean fuel to the turbines. The floating suction arrangement reduces the likelihood of free water being supplied to the gas turbines.

Diesel Polishing System

The diesel polishing system comprises a 200 m³/hour duty cartridge/coalescer filter unit which allows recirculation of the tank contents to remove sediment and water from diesel periodically, or in the case of having off-spec fuel at the storage tanks, due to stagnant conditions. The polishing package includes a cartridge and coalescing filters. The package capacity is equal to the capacity of two forwarding pumps running simultaneously to minimise the polishing time.

Diesel Loading/Unloading System

There is one unloading station including related equipment, piping, adaptors, instrumentation, and a flowmeter with totaliser. The station is designed to unload and transfer a B-Double tanker with approximately 50 m³ diesel fuel into the storage tanks. The arrangement comprises two (2) off 75 m³/h Duty/Standby pumps, 1-off single bottom loading arm package and one set of unloading system with 5 dry break hose connections.

A loading bay with a single bottom loading arm with necessary pipework, valving, instrumentation, and control unit is installed adjacent to the unloading station in order to load diesel from the storage tanks into the road tankers if required. The pumps for unloading and loading are two common positive displacement vane pumps used for both operations.

3.5 Process Gas and Air Systems

A sufficient supply of hydrogen, carbon dioxide and nitrogen will be stored on site to meet the demands of operating the gas turbines.

Hydrogen

The hydrogen cooled generator on each power island requires a continual supply of hydrogen. Hydrogen is used as cooling media for the generators and continually leaks from the system requiring replacement. Hydrogen storage is expected to consist of a least one hydrogen tube trailer (400 kg) and 30 hydrogen gas bottles.

The hydrogen pressure is reduced from the trailer or cylinder storage pressure to 5000 kPag before being supplied to the MHI pressure reduction panel where the pressure is further reduced to around 500 kPag.

Nitrogen

Nitrogen will be used for purging the gas turbine and fuel gas system to remove natural gas and air before maintenance or recommissioning. The nitrogen purging systems will consist of a fixed rack of 15 cylinders manifolded and connected to fixed pressure reduction sets and pipework. The natural gas pipework and vessels will be purged with nitrogen prior to introducing natural gas to eliminate the risk of mixing natural gas and air within the pipework. The expected storage of nitrogen is 8 pallets of 15 bottles (120 bottles in total).

Carbon Dioxide

Carbon dioxide is used as purging gas in order to remove air and safely add and remove the hydrogen to/from the generator. The CO₂ purging system is a fixed rack of 15 cylinders manifolded and connected to fixed pressure reduction panels and pipework connected to each GTG cooling circuit. The expected storage of carbon dioxide is 4 pallets of 15 bottles (60 bottles in total).

Instrument Air

The instrument air system consists of two air compressor/dryer packages where each package includes a compressor, filters, a knock-out drum, and air dryers. Downstream of the instrument air dryers will be three air receivers that are sized to hold a 3-minute supply of the instrument air required during operation.

The compressor/dryer skids and the filters within the packages will operate in a duty/standby arrangement to allow for redundancy.

Each instrument air compressor will deliver 360 Nm³/h with a controlled supply pressure range between 650 kPag to 800 kPag.

Services Air

The service air system consists of two air compressor/dryer packages where each package includes a compressor, filters, a knock-out drum, and air dryers. Downstream of the service air dryer will be one receiver (one duty) that is sized to hold a 3-minute supply of the instrument air required during operation.

The compressor/dryer skids and the filters within the packages will operate in a duty/standby arrangement to allow for redundancy.

Each service air compressor has a capacity of 1716 Nm³/h with a controlled supply pressure range between 650 kPag to 800 kPag.

3.6 Potable Water and Service Water Systems

Potable water at a maximum flow of 20 L/s will be supplied to the plant by Hunter Water by a new connection from the potable water network on the eastern boundary. The flow will be metered on the site with the main users being the evaporative cooler for the air intake for the gas turbines, demineralised water plant, supply to the on-site fire water tanks, safety showers and general domestic consumption for the control room and workshop. A 1700 m³ tank will provide buffer storage for water demand in case of interruptions to the supply network. Three forwarding pumps supply water to the gas turbines and other service water users. Water supply to the other users (amenities), safety showers and fire water tank will be upstream of the service water tank from the main water line into the plant.

Demineralised Water Plant and System

Two demineralised water plants with a capacity of 33m³/h, one 1700 m³ storage tank and three forwarding pumps will supply demineralised water for injection to the gas turbines for NO_x suppression. The demineralised water plant treats potable water to remove salts. The expected demin plant type is reverse osmosis/ electro-deionisation. Demin water will be supplied from the demin plant to the storage tank with facilities to allow recirculation of stored demin water to the demin plant for removal of absorbed carbon dioxide. Wastewater and "Clean in Place" chemicals from the demin plants will be neutralised in an on-site collection pit by pH adjustment with either acid or caustic before being discharged to the Hunter Water trade waste system.

Fire Water Tanks and Pumps

The onsite firefighting protection system consists of two tanks (500 m³ each), two pumps, deluge systems for the transformers, fire hydrants and catch pits for the Facility. The design and capacity of the fire water reticulation system will also consider the fire protection requirements of the adjacent 132 kV electrical switchyard and Gas Receiving Station and gas compressor house.

Oily Water Collection & Treatment System

A centralised oily water pit and treatment area will collect and separate oil and water for discharge. The drains from a number of areas including, transformer oil bund, tanker unloading, fuel storage tank bund, diesel fire water pump and gas turbine control and lubricating oil areas, will have drain connections to the oily water pit. The oily water separator which is a centrifugal type separator uses centrifugal forces to separate water and oil. The oily water is collected in a tank for disposal by truck and the clean water is directed to stormwater for discharge to the environment.

The oily water separator is a standalone vendor supplied package that is capable of achieving a water discharge quality of less than 5mg light liquids per litre i.e., treated water can be discharged directly into the stormwater drainage system.

3.7 Trade Waste System

The trade wastewater collection system has been designed to collect wastewater generated from the blade washing drain pit and demin plant.

Wastewater will be collected from each power island and discharged to the neutralisation pit at the Balance of Plant Island. It shall be treated at this location prior discharging to the Hunter Water trade waste connection proposed at the eastern side of the site. The neutralisation pit is used to collect and correct the pH of the wastewater so that it meets the requirements provided in Hunter Water Standard Trade Wastewater prior to discharge. The treated wastewater will then be pumped into the Hunter water trade waste system.

3.8 Storm Water System

The stormwater collection system for the site will collect rainwater from clean plant areas and direct to a separator which uses hydrodynamic and gravitational separation to remove suspended solids and entrained hydrocarbons. Clean stormwater is discharged from the north-western boundary into an existing water courses. Any entrained solids or oil are contained in the separator for later disposal by truck.

4.0 HAZOP Study Results

4.1 Introduction

The nature of the HAZOP study results in the discussion of many points that relate to hazard and operational issues associated with the operation of the facility under analysis. The recording of every discussion item, at length, would result in an un-necessarily long workshop, leading to frustration among the HAZOP study participants whilst time was wasted recording minor issues requiring no action.

To ensure the most effective recording of results was achieved, for the Hunter Power Services Systems, or Balance of Plant, HAZOP study, the following recording format was adopted:

1. For the issues identified in the assessment, where a discussion issue was clearly identified to result in no hazard or operability issue, no entry was made in the HAZOP minutes sheet. This entry approach was followed to minimise the recording requirements of the study.
2. Where a hazard and operability issue may have a potential to occur as a result of the process design or operation, the deviation from normal operations was reviewed and where the safeguards were considered adequate to control the identified hazard/operability issue, a part record was made with “no action required” recorded.
3. Where a discussion point was identified to result in a potential hazard/operations issue, and safeguards were identified to be insufficient to control the hazard/operability issue, a full minute point was recorded, identifying deviation cause, consequence, proposed safeguards and action required to prevent, detect, protect and/or mitigate the operations consequences.

The summary of HAZOP Minutes recorded during the workshop sessions are presented in Appendix A.

4.2 Summary of HAZOP Study Results

The meeting was able to review the proposed design in a satisfactory manner, including the impact of disturbances from the Kurri Kurri Gas Lateral on the Hunter Power site (design representatives from the Kurri Kurri Gas Lateral Project Team, APA, participated in the relevant session). Adequate information was available, and the HAZOP participants had a sound range of relevant design and production experience.

The HAZOP study did not reveal any significant hazards that would compromise the safety or integrity of the project and that could not be managed. The project can proceed, subject to satisfactory resolution of the HAZOP recommendations.

There were 316-minute points discussed during the HAZOP study, with a number of these requiring no action or follow up item. However, there were a number of issues raised due to the specific requirements of the systems and the proposed operation.

A total of 213-minute points were recorded requiring action, which are listed in the HAZOP minutes at Appendix A. Many of these were related to the requirement for update of P&IDs, procedures, detailed operation of the isolation function, access requirements, relocation or addition of valves when in use or when isolated and fail-safe valve failure position, etc. The drawings used in the HAZOP are included at Appendix B, showing the nodes applied during the workshop study.

The implementation phase for each of the recorded actions is included in the HAZOP Minutes.

5.0 References

1. Kletz, TA 1999, *Hazop and Hazan: Identifying and Assessing Process Industry Hazards*, Institution of Chemical Engineers, Warwickshire.
2. NSW Government, Department of Planning 2011, *Hazardous Industry Advisory Paper 8 (HAZOP Guidelines)*.
3. Standards Australia 2017, *AS IEC 61882:2017 – Hazard and Operability Studies (HAZOP studies) – Application Guide*.

Appendix A

HAZOP Workshop
Minutes Including Action
Record & Date
Completed

Appendix A HAZOP Workshop Minutes

Notes to Workshop Minutes:

1. "No additional issues" is used in the "Cause" column to reflect that some causes have been identified via another Guide Word (this often occurs between flow and pressure because they are related).
2. "No significant issues" is used in the "Cause" column to reflect that while some deviation is possible the consequence is trivial and managed through Administrative Controls.
3. "No additional action" is used in the "Recommendations" column to reflect that a Recommendation to address an issue identified elsewhere will also address the current issue (the source of the first instance of a Recommendation is cross-referenced).
4. "Design Development" is used in the "Cause" column where an aspect of the Design is still "Preliminary" i.e. incomplete. It may be necessary for the HAZOP Team to reconvene to review those aspects in the Final Design to ensure that no new risks have been introduced.
5. "Nil", as used in the "Existing Safeguards" column, shall be interpreted as the Team being unable to identify obvious Safeguards (often there is a contribution to safeguarding through standard site operational and maintenance practices).

DIESEL SYSTEM

Table 5 Diesel System - Node 1.1

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Unloading | Node # | 1.1 |
| Node Boundaries: | Tanker, Unloading arm unloading pump and pipework, Diesel Tanks | Revision Date: | 20-Jan-22 |
| Design Intent: | Unloading facility for B double tankers, 6 per day | Material / Chemical: | Diesel |
| Design Conditions, Operating Envelope | Discharge Pressure of Unloading Pump: 2.5 Barg. Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1065 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------|---|--|---|--|-------------|--|-----------|---------------|-------------|---------------|
| 1.1.1 | Flow - Quantity | Inconsistency between different methods of measurement from truck gauge dip and site flow meter because of different level of accuracy. | The truck dip gauge and site diesel flowmeter may not match | N/A | Requirement to be clear in procedures that quantity delivered is based on tanker dip gauges. | Snowy Hydro | | Ph.2 | | | |
| 1.1.2 | Flow - High Flow | Both unloading pumps running simultaneously. | Pump damage due to overheating. | LAHH 90EGB01CG901A and 90EGB01CG9041A on Diesel Storage Tanks close inlet actuated valves SDV **EGD01CG929* and 90EGD01CG905A | Refer to action of 1.1.15. | AECOM | | Ph.1 | | | |
| 1.1.3 | Flow -Low Flow | Pump isolation valves closed (Blocked in pump). | Pump overheats and possible damage to the pump. | Low flow switches FS 90EGB01CG001A and 90EGB02CG001A on pump discharges stop pumps after 20 seconds. | Check with the pump vendor if the selected pump can operate for 20 seconds with low flow. | AECOM | | Ph.1 | | | |
| 1.1.4 | Flow - No flow | Tanker compartment empty and pump draws air from empty compartment. | Air drawn into pump suction. Possible air lock in piping when pump is restarted next time. | Sight glass on unloading hose. | Review requirement of bleed valve on suction line to the pump. | AECOM | Note, not all compartments in the tanker have the same volume. | Ph.1 | | | |
| 1.1.5 | Flow -Reverse flow | Diesel flowing backwards to pump. | Pump damage because of reverse flow. | NRVs 90EGB01AA005 and 90EGB02AA005 in discharge line from pumps. | No action | | | | | | |
| 1.1.6 | Flow -Reverse flow | Diesel directed to wrong tank. | No significant issues if the other tank is filled when supply diesel to the GT. | Inlet valves to tank are automatically opened when tank is selected on control panel. Valves are interlocked with the control system to prevent incorrect valve opening. High level on tank closes inlet valve. | No action | | | | | | |
| 1.1.7 | Pressure - High pressure | Valve on pump outlet closed (Blocked in pump). | High pressure in discharge line - Overpressure causing pipe rupture and loss of containment. | Diesel unloading pumps have internal pressure relief valve and low flow switches (see 1.1.3). | Show internal relief of pumps on P&IDs. | AECOM | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|--|---|---|----------------------|--|--------------|---------------|-------------|---------------|
| | | | | During the design, review will be done to ensure the piping design pressure to be higher than the pump stall head. | | | | | | | |
| 1.1.8 | High Temperature | Valve on pump outlet closed. | Pump overheats – possible damage to the pump. | Same as 1.1.7 | No action | | | | | | |
| 1.1.9 | Contaminants | Truck may contain other type of fuel than diesel. | Gas Turbine receives incorrect fuel leading to equipment damage. | Operating procedures to order correct fuel and operator checks prior to the tanker unloading. | Operating Procedures to include a check of the diesel quality delivered to site. | Snowy Hydro | | Ph.2 | | | |
| 1.1.10 | Contaminants | Water ingress from adsorption from air into the storage tanks. | Possible damage to gas turbines. | Water is removed by the polishing filters and circulation of tank through the filters. | Diesel should be regularly tested to ensure the water level is suitable for the Gas turbine. Included regular sampling for quality testing in the operating procedures. | Snowy Hydro | | Ph.2 | | | |
| 1.1.11 | Contaminants | Foreign material/objects remaining in pipe after construction. | Blockages in pipe, potential for damage to equipment. | Pump strainers, polishing filter, and forwarding filters to be regularly cleaned. Commissioning procedures and piping/equipment cleanliness checks. | Review requirement for commissioning strainers. Construction ITPs to include cleanliness checks. | AECOM Snowy Hydro | | Ph.1 Ph.2 | | | |
| 1.1.12 | Loss of containment - leak | Diesel spill from flange or hose connection. | Diesel spill from the unloading bund flows to oily water system. | Oily water system (200 m3) is large enough to hold full load of B double tanker (50m3) | Review requirement for valve with position indicator in diesel unloading bund. | AECOM | | Ph.1 | | | |
| 1.1.13 | Loss of containment - leak | Failure of hose during unloading. | Spill of diesel to bund area. | Local E stop. Local bund directed to oily water pit. Volume in Oily water containment is 200 m3. | Review requirement for bund size as per AS 1940. Consider making bund big enough for all compartments on B double. | AECOM | AS1940 requirement of one compartment volume is for loading tanker (not unloading) | Ph.1 | | | |
| 1.1.14 | Loss of containment - leak | Leaking pump. | Spill of diesel at pumps. | Pumps contained inside the bunded area. | Review where pump spill containment is discharged to. Preference is to keep in the pump bund area rather than being discharged into larger road containment bund. | AECOM | Tanker bund does not have valve to oily water pit | Ph.1 | | | |
| 1.1.15 | Instrument and control system | Both pumps running at the same time. | System may not be designed for this. High flow in system potentially causing damage to piping/equipment. | Flow indication on discharge line of pumps. | Process interlock to be reviewed/ designed to not allow running both pumps at the same time. Include permissive that valve should be opened before running pump. | AECOM | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|---|---|--|-------|----------|-----------|---------------|-------------|---------------|
| 1.1.16 | Instrument and control system | Pumps running when on/off valves downstream are closed (Blocked in pumps). | Pump overheats leading to possible damage. | Inlet valves to selected tank are automatically opened/closed when tank is selected on control panel. Also see 1.1.3. | Review process interlock that on/off valves to tank inlet are opened prior to starting the pump. | AECOM | | Ph.1 | | | |
| 1.1.17 | Instrument and control system | Flow meter failure i.e. flow meter not indicating flow. | Operators observing fuel loading unable to see if fuel is going through hose/pipe. Hose could be suctioning from empty tank. Air suction into piping may cause an air lock. | None | Review requirement for sight glass downstream of flexible couplings. See 1.1.4 | AECOM | | Ph.1 | | | |
| 1.1.18 | Maintenance - maintainability | Pump not functioning properly/requires maintenance and needs to be taken offline. | Unable to maintain pumps whilst operating. | Isolation valves for all pump inlets/outlets. Pumps can be isolated from each other. | No action | | | | | | |
| 1.1.19 | Maintenance - accessibility | Inadequate access to equipment . | Unable to maintain pumps. | Access for fork lifts considered. | No action | | | | | | |

Table 6 Diesel System - Node 1.2

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Loading | Node # | 1.2 |
| Node Boundaries: | Diesel Tank, Loading pump, Loading connection and tankers | Revision Date: | 20-Jan-22 |
| Design Intent: | Loading facility for B double tankers in case of off specification fuel | Material / Chemical: | Diesel |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1064 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-----------|---|--|--|--|-------|---|-----------|---------------|-------------|---------------|
| 1.2.1 | Low Flow | Low flow into tanker being loaded when loading pumps start-up/shutdown. | Unknown, review consequence to tanker loading. | FCV in diesel loading skid to control flow. | Review impacts of ramp up and ramp down of delivery to trucks. Review impacts on PD pumps and whether PSV will lift when FCV closes. Could replace PSV with Pressure Reducing Valve. Review if the FCV in the diesel loading skid is required. | AECOM | Note this is inside of a vendor package and this may change after vendor has been selected. | Ph.1 | | | |
| 1.2.2 | High Flow | Both loading pumps running. | Damage to pipes/equipment due to overpressure. | Scully connection on tanker to loading bay controller. | Process interlock to be reviewed/designed to prevent running both pumps at the same time. | AECOM | | Ph.1 | | | |
| 1.2.3 | High Flow | Worker filling tanks walks away from | Overfilling and spilling of tanks. | Operating procedures: Tanker filling is a | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|--|--|---|-------------|----------|-----------|---------------|-------------|---------------|
| | | tanker while its being loaded. | | supervised operation. Two staff members to supervise unloading operations. Tanks are also filled by selecting volume to be filled into the tankers. | | | | | | | |
| 1.2.4 | Instrument and control system | Integration failure between unloading pumps and diesel loading skid. | High, low or no flow to tankers due to pumps and loading package not being integrated properly | None | Integrate the vendor package with the loading pumps E stop required for Load bay controller. Check if control should be independent of DCS e.g. Removal of air will close valves and stop the flow. | AECOM | | Ph.1 | | | |
| 1.2.5 | Reverse Flow | Flow from tanker flowing back to unloading pumps. | Pump damage because of reverse flow. | There is possibly a check valve included inside the tanker loading point. Check valves installed on the unloading pumps discharge lines. | Check tanker loading connection (dry break connection), valving isolation and check valves. Check if there is a sight glass include in line | Snowy Hydro | | Ph.1 | | | |
| 1.2.6 | High Pressure | System pressure reaches higher than 5 bar at the coupling (coupling design pressure). | Difficult to open dry break coupling. | Preliminary PSV set pressure on the unloading pumps discharge is 300 kPag. | Review pump head to maintain pressure of the loading arm below 5 barg. | AECOM | | Ph.1 | | | |
| 1.2.7 | High Pressure | TRV on filling line relieves back to blocked in section. | Overpressure of line when line is closed leading to leaks at flanges. | | Review location of discharge of TRV to ensure section that is relieved will not exceed design pressure. | AECOM | | Ph.1 | | | |
| 1.2.8 | High Pressure | Diesel loading skid valves suddenly shut. | Fluid hammer in system. | A surge checklist has been done. Velocity is low and pump head is low. Pipe lengths are short. Surge is unlikely. Pipework will be adequately supported. Valves are closed slowly 5-8 seconds i.e. will not slam shut. | No action | | | | | | |
| 1.2.9 | High Pressure | Filling tank. | Over pressure in tanker | Preliminary PSV set pressure on the unloading pumps discharge is 300 kPag | Confirm if tanker can be over pressured or has lid open. Ensure tanker vent system is interlocked to avoid over pressure in tanker. | Snowy Hydro | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------------------|---|--|---|---|-------------|--|-----------|---------------|-------------|---------------|
| 1.2.10 | Contaminants | Contaminants in fuel | Damage to pumps | Selection of pumps/equipment that will not be affected by contaminants that could be present in off spec fuel | No action | | | | | | |
| 1.2.11 | Contaminants | Strainers blocked | No flow through strainers. | None required. No large pieces of contaminant expected to be in fuel. | No action | | | | | | |
| 1.2.12 | Loss of containment - leak | Unloading arm hit by/damaged by vehicle. | Damage to arm and spilling of diesel being loaded. | Unloading arm inside bunded area to catch spills | Consider bollards in unloading area | AECOM | | Ph.1 | | | |
| 1.2.13 | Instruments and control systems | Incorrect flow measurement by flow meter. | Charged incorrect amount for fuel removal. | Metering systems. Flow meter installed on diesel loading system. | Consider whether a weigh bridge or other mechanism to measure amount of fuel being loaded | Snowy Hydro | | Ph.1 | | | |
| 1.2.14 | Maintenance | Inadequate access to equipment. | Unable to maintain valves and equipment. | Plant does not run 24/7 allowing time for maintenance if required. | No action | | | | | | |
| 1.2.15 | Impurities | Tanker being filled on site has residual impurities i.e. unleaded fuel. | Potential creation of hazardous area zone. | None | No action | | Not a major issue. This is not required to be controlled as per AS 1940. | | | | |

Table 7 Diesel System - Node 1.3

| | | | |
|--|--|-----------------------------|--------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Storage | Node # | 1.3 |
| Node Boundaries: | Diesel Tanks and connected equipment e.g. drainage system, bunding | Revision Date: | 20-Jan-22 |
| Design Intent: | Storage and containment of diesel | Material / Chemical: | Diesel |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1066/69 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------|--|--|---|---|-------|---|-----------|---------------|-------------|---------------|
| 1.3.1 | Impurities | Ignition sources and vapours in tank. | Ignition of vapour in tank. | Tank vents to relieve pressure. Ignition sources in the tank are unlikely. | Add a flame arrestor to diesel storage tanks (as per Colongra site) | AECOM | Flame arrestor not required as per AS 1940. Decision to include is SH preference. | Ph.1 | | | |
| 1.3.2 | Instruments and controls | Mixing up of tanks, Fuel goes to/comes from wrong tank. | No significant issue. Batching and testing will not be completed | Tanks control philosophy i.e. tanks selection by the operator from DCS opens selected tank suction valve. | No action | | | | | | |
| 1.3.3 | High flow | Air supply to quick flush pump. | Unregulated supply - unnecessary pump operation | None | Consider needle control valve in air supply to operate the pump. | AECOM | | Ph.1 | | | |
| 1.3.4 | High level | Tank filled above high high level. Failure of high high level switch | Overfilling of tank. Single shutdown from high level switch | High high level switch LAHH 90EGB01CG90 4A and 90EGB01CG90 1A shut down filling pumps. High level alarms LAH 90EGB01CG90 1A and 90EGB01CG90 4A. | Use level transmitter as pump shutdown as well as the level switch. | AECOM | | Ph.1 | | | |
| 1.3.5 | Low Level | Tank falls below low low level. Failure of low low level switch | Tank level too low, pump running dry - damage to the pump. Single shutdown of tank unloading pumps from low level switch | Low low level switch LALL 90EGB01CG90 3A and 90EGB01CG90 1A shut down diesel forwarding pumps and closes the tank outlet SDVs. | Use level transmitter as pump shutdown as well as the level switch. | AECOM | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|------------------|--|---|--|--|-------------|--|-----------|---------------|-------------|---------------|
| | | | | Low level alarms LAL 90EGB01CG90 1A and 90EGB01CG90 4A. | | | | | | | |
| 1.3.6 | Low Level | Failure of the low low level switch. | No diesel fuel to turbines - Turbine trip or unable to operate. | Unlikely to have level switch failure in both tanks, could operate the other tank. | Review the employer requirements to have one or two transmitters. Review how critical this instrument is to the operation of the GT. | AECOM | Existing operations (at Colongra) are using two transmitters | Ph.1 | | | |
| 1.3.7 | High pressure | Overfilling of tank. | Tank damage/failure because of overpressure | Three vents (normal vent, emergency vent and vacuum vent) installed In tanks. | No action | | | | | | |
| 1.3.8 | High temperature | Heating from the sun or other external heat source i.e. fire | As diesel is a C1 DG heating above 60 degC would require the diesel tank area to be a hazardous area. Diesel return from GT is approximately 60 deg C. | Tanks have temperature indicator and transmitter. | Review of AS 1940 to determine if any additional temperature control are required | AECOM | | Ph.1 | | | |
| 1.3.9 | Low temperature | Cold weather | Potential wax formation of fuel. | Tanks have temperature indicator and transmitter | SH to provide fuel specification (pour point) of selected fuel to determine if wax formation is likely at the minimum expected storage temperature . | Snowy Hydro | Review against Mitsubishi Specification for Liquid fuel requirements | Ph.1 | | | |
| 1.3.10 | Contaminants | Solid contaminants in diesel stored. | Damage to GT | Impurities in diesel will drop to the base of the tank. | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-----------------------|---|--|--|--|-------------|--|-----------|---------------|-------------|---------------|
| | | | | Tank unloading pumps are not drawing off base of tank (Floating suction) | | | | | | | |
| 1.3.11 | Contaminants | Water in the tank | Damage to GT | Drain and quick flush system, Polishing filter will remove water. | No action | | | | | | |
| 1.3.12 | Contaminants | Corrosion of drain lines, vents on tank, and tank. | Lines/vents/tank will have accelerated corrosion. | Material selection | Review drain/vent material selection to minimise corrosion. Review coating of tank. | AECOM | | Ph.1 | | | |
| 1.3.13 | Composition change | Cold weather | Viscosity/density outside limits for GT specification. | Diesel system winterisation, large inventory in storage tank will not cool down quickly. | Determine if density/viscosity of diesel change significantly with temperature. To be confirmed with fuel supplier. | Snowy Hydro | Review against Mitsubishi Specification for Liquid fuel requirements | Ph.1 | | | |
| 1.3.14 | Loss of containment | Tank damage/overfilling. | Spill of diesel. | Spills contained in bund sized as per requirements in AS 1940 (110% of the tank). See 1.3.4 for overfilling scenario. See 1.3.7 for tank damage because of overpressure. See 1.3.12 for tank damage because of corrosion. | No action | | | | | | |
| 1.3.15 | Electrical - earthing | Nearby lightning strike or tank filling/drainin g causing static charge on tanks. | No diffusion of static discharge voltage to earth or ground. | Four earthing stakes. | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------|--|---|---|--|-------|---|-----------|---------------|-------------|---------------|
| 1.3.16 | Maintenance | Tank not functioning properly/one of the tanks needs to be taken offline for maintenance | Unable to access tanks because systems still running. | Isolation valves have been provided for all tank inlets/outlets. Tanks can be isolated from each other. | No action | | | | | | |
| 1.3.17 | Maintenance | Rain event | Control systems underwater. | None | Confirm that a potential rain event (i.e. 1 in 100 rainfall event) will not cause instrumentation and control systems to be covered in water. Considering including float switch to alert before control switches are under water. | AECOM | Site will only be unmanned for 3 or 4 days (over public holidays) | Ph.1 | | | |
| 1.3.18 | Maintenance | Corrosion of tank internal surface. | More frequent maintenance than preferred. | Bottom plate and up to 1 m height is coated. | Consider the internal surface of diesel tank to be fully coated. | AECOM | SH preference is to coat entire tank. Inspection every 10 years | Ph.1 | | | |

Table 8 Diesel System - Node 1.4

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Polishing | Node # | 1.4 |
| Node Boundaries: | Diesel tank , Pumps, Polishing filter coalescers return to tank | Revision Date: | 20-Jan-22 |
| Design Intent: | Removes sediment and water from the diesel by recirculating the contents of the tank through the filters. | Material / Chemical: | Diesel |
| Design Conditions, Operating Envelope | Design assumes ambient conditions. Polishing system designed for 200 m3/h | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1068 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------------|---|---|--|---|-------|--|-----------|---------------|-------------|---------------|
| 1.4.1 | High flow | All three pumps running together. The second pump starts if the duty pump fails. Operator selects one or two pumps. | No major foreseeable negative consequences. Potential to increase temperature of fluid. | Pump selection from DCS. | Interlock to prevent 3 pumps running at the same time. | AECOM | | Ph.1 | | | |
| 1.4.2 | Low flow | Polishing filters blocked | Potential for high pressure however pumps have a minimum flow line with PRV. | PDG across diesel polishing package. However, operator may not be monitoring this continually. Flow measurement FS for Diesel pumps. | Check diesel polishing package has alarm for the differential pressure across filters to alert operators of blocked filters in DCS. | AECOM | Include DP alarm for whole polishing package if needed | Ph.1 | | | |
| 1.4.3 | Reverse flow | Higher pressure downstream of pump. | Damage to pumps because of reverse flow. | NRV downstream of pump. | No action | | | | | | |
| 1.4.4 | Misdirected flow | Incorrect tank inlet valves open. | Flow to wrong tank - No safety concern | DCS only allows valve to be opened to tank selected | No action | | | | | | |
| 1.4.5 | High Pressure | Blockage or closed valve | Damage to pipes/equipment because of high pressure. | Pipework designed for dead head of the pumps. | No action | | | | | | |
| 1.4.6 | Contaminants | Contaminants collection in polishing filters | Blocked filters. | Package to automatically switch to clean filter when a filter is dirty or high DP. | No action | | | | | | |
| 1.4.7 | Loss of containment | Leak in system | Diesel spill | Diesel polishing package inside bunded area connected to oily water system. Maintenance ITPs to ensure flange integrity. | No action | | | | | | |
| 1.4.8 | Instruments and control system | Sufficient instrumentation | Pump damage because of running dry or blocked in. | Pump is sufficiently protected by instrumentation | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------------|--|--|--|--|------------|--|-----------|---------------|-------------|---------------|
| | | | | including low flow switch downstream of pumps. | | | | | | | |
| 1.4.9 | Instruments and control system | Low flow switch downstream of pumps | Pump damage failure due to blockage of pump kickback line or valves on pump kickback line closed. | Low flow switch downstream of pumps to forwarding filters. | No action | | | | | | |
| 1.4.10 | Maintenance | Inadequate access to equipment | Unable to maintain equipment. | Plant does not run 24/7 allowing time for maintenance if required. | No action | | | | | | |
| 1.4.11 | Maintenance | Running diesel through polishing package could impact GT starting times if need to quickly start the GT on diesel. GT can operate on gas | Requirement to start GT's as quickly as possible. Seconds can have an impact on profitability with spot electricity prices | Polishing of diesel can be scheduled. | Consider an additional separate pump for polishing package. Look at automated prioritised control of forwarding pumps. | SH & AECOM | Reduce start times - anything that reduces start time by 20 seconds is considered to have a big impact by Snowy Hydro. Suction valve on tank (from bottom to floating suction) and auto valves to polisher and auto valve needs to change position quickly. | Ph.1 | | | |

Table 9 Diesel System - Node 1.5

| | | | |
|--|---|-----------------------------|----------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Delivery to Gas Turbines | Node # | 1.5 |
| Node Boundaries: | Diesel tank, Pumps, Polishing filter coalescers return to tank | Revision Date: | 20-Jan-22 |
| Design Intent: | Delivers diesel from the tanks through filters to suction of main Fuel oil pumps at Gas Turbine Unit 1 and Unit 2 | Material / Chemical: | Diesel |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1067/1068 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------|--|--|---|--|-------|---|-----------|---------------|-------------|---------------|
| 1.5.1 | High Flow | All three pumps running at the same time | Damage to piping/equipment | Inlet return valves from pump discharge to storage tank | <ul style="list-style-type: none"> - One inlet return valve to each storage tank to be open at all times. Set fail action to fail last. - Oil is returned after GT shutdown. Ensure the inlet line is open for the fuel return to tanks. - Keep at least one inlet valve open for diesel return from GT after shutdown. | AECOM | 90EGC01AA001100 or equivalent on tank 1 | Ph.1 | | | |
| 1.5.2 | Low Flow | The duty pump trips | Insufficient flow to GT's when both GT's running | Standby pump available if pump trips | <p>Redundancy and reliability issues need review. Consider running the standby pump at all times so if a single pump trips no loss of flow or pressure to the GT . Perform a dynamic study to determine if only running two pumps and time required for a third pump to start and compensate for loss of flow of tripped pump. How many pumps need to be running if there is a pump trip. Consider n+1 where n is the number of units.</p> | AECOM | | Ph.1 | | | |
| 1.5.3 | Reverse flow | Diesel flowing back towards | Pump damage because of reverse flow. | Pumps are protected by NRVs | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------------------|---|---|---|---|-------|----------|-----------|---------------|-------------|---------------|
| | | forwarding pump. | | | | | | | | | |
| 1.5.4 | High Pressure | Valves on filter outlet closed. | Filter damage because of high pressure. | Filters designed for dead head from forwarding pumps. Minimum flow line opens on high pressure in pump discharge. | No action | | | | | | |
| 1.5.5 | Low Pressure | Pump trip/not running properly, blockage in pipe. | Low flow to GT. | Pressure indicators will show low pressure High Flow and low pressure will start second pump if only running one pump. | No action | | | | | | |
| 1.5.5a | Contaminants | Collection of contaminants in the filter. | Blocked filters. | Filters can be changed over on line when a filter is blocked. | No action | | | | | | |
| 1.5.6 | Loss of containment | Leak in system / damage to equipment. | Diesel spill. | Pumps inside bunded skid with roof. Maintenance ITPs to ensure flange integrity. | Consider installing a small sump and weir in bund to contain smaller leak quantities at pump skid bund. | AECOM | | Ph.1 | | | |
| 1.5.7 | Instruments and control systems | On - off Valve failure action. Diesel supply valve downstream of filters is currently fail close for fire protection. | Loss of Fuel supply to Gas turbines if valve fails closed. Closure prevents feeding fuel to a fire. | Keep isolation valve to supply diesel to GT as FC to lessen duration of a fire. | No action | | | | | | |
| 1.5.8 | Instruments and control systems | Lack of facilities for remote monitoring. | Inability to identify system deviations remotely when no one is on site. No ability to create alarms for system deviations. | PT should be shown upstream of flowmeters but is incorrectly shown as PI currently | Change PI upstream of flowmeter to be PT | AECOM | | Ph.1 | | | |
| 1.5.9 | Maintenance - isolation | Inability for system to be isolated for maintenance. | System not able to be maintained. | Can isolate both filters and flow meter is removable. | No action | | | | | | |
| 1.5.10 | Maintenance | Maintenance of flow meter required. | Inability to access the flowmeter due to process streams still running | Flow meter can be isolated and maintained. | No action | | | | | | |

Table 10 Diesel System - Overview

| | | | |
|--|---|-----------------------------|----------------------------------|
| Project / Facility: | 6066845 Hunter Valley Power Station - Diesel Delivery to Gas Turbines | Node # | OVERVIEW |
| Node Boundaries: | | Revision Date: | 20-Jan-22 |
| Design Intent: | | Material / Chemical: | Diesel |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1067/1068 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--|---|---|--|---|--------------|---|-----------|---------------|-------------|---------------|
| 1.6.1 | Materials of construction - Tanks, piping, pumps, valves | Incompatible material used with diesel. | Premature corrosion of materials due to inadequate materials of construction. | Galvanized steel used for structures. Specialised materials are required for diesel. | No action | | | | | | |
| 1.6.2 | Utilities and services | Lighting may be insufficient for the task. | Pedestrians injury, trips/falls. | Adequate lighting supplied i.e. Roadway and loading lighting area. Lighting design as per AS standards. Safety shower with activation alarms provided at both diesel pumps and unloading area. | No action | | Yellow lighting is preferred to white to reduce attraction for insects. Insects have blocked drains at other sites. | | | | |
| 1.6.3 | Hazardous substances | Hazardous substances stored | Requirement for Hazardous Area classification. | Diesel only. No other hazardous substances. | No action | | | | | | |
| 1.6.4 | Physical damage | Moving unloading hose on trolley skid to loading point. | Damage to equipment | Curb to diesel loading/unloading area to allow trolley access. | Review the interaction of the loading/unloading interaction with curb and lighting. | AECOM | | Ph.1 | | | |
| 1.6.5 | Fire/explosion | No installed fire detection | A fire could start on site undetected. This is unlikely. | None | Review causes of fire/consequences. A fire could start on site undetected. Review fire protection and remote monitoring of critical areas e.g. use of cameras | SH and AECOM | Fire safety study currently being undertaken. | Ph.1 | | | |
| 1.6.6 | Shutdown | Emergency requiring system shutdown. | Plant not able to be safely shutdown in emergency or loss of process control. | Emergency stops provided. | No action | | | | | | |
| 1.6.7 | System testing | Trips and alarms not working. | Overfilling of tanks. | Trips and alarm tests to be performed as part of regular testing. | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--|---|---|--|--|-------|---|-----------|---------------|-------------|---------------|
| 1.6.8 | Environmental impact | Overflow of diesel from vents. | Spilling of diesel into bund area. | All diesel vents going to bund which drains to oily water waste system. High level alarms and trips. | No action | | | | | | |
| 1.6.9 | Environmental impact - waste management | Diesel mixing with stormwater. | Release of diesel into environment. | Oily water separator system will separate oil from stormwater discharge system | No action | | | | | | |
| 1.6.10 | Natural hazards | Bushfires due to large amount of natural bushland in the site area. | Ignition/loss of diesel tanks during bushfire. | Site maintenance and clearance of combustible vegetation close to the process areas. | Review bushfire impacts on the fuel tanks. Assess best materials for fencing etc. to minimise this risk. (NOTE: A fence will not prevent ember attack which comes from an elevated height higher than normal fence height). | AECOM | Vegetation near site to be cleared in the future when site is operable. The EIS Bushfire Risk Assessment. Figure 4-2 estimates the radiant heat flux impacts on the site. It is estimated that the Diesel Tanks could be exposed to between 12kW/m2 and 19kW/m2 primarily from the North-East. The recommended Fire Protection criteria for Bulk Tanks at 8kW/m2 is the ability to deploy cooling water from a mobile appliance should be planned. At 32kW/m2 exposure a tank should be fitted with its own deluge system, which is automatically activated. Therefore the estimated radiant heat flux indicates cooling should be deployed but can be from a mobile appliance or portable equipment, especially onto the upper unwetted surfaces of the tanks with direct line of sight to the flames. No predicted flooding even including climate change. | Ph.1 | | | |
| 1.6.11 | Natural hazards | Earthquake | Destruction of tanks, equipment | Designed to earthquake standard. | No action | | | | | | |
| 1.6.12 | Procedures - development & documentation | O&M manual for system. | Operation/Maintenance documentation for system. | None | O&Ms to be created by SH | SH | | Ph.2 | | | |
| 1.6.13 | Quality Control | Systems not designed to specification. | System failure. | Systems within the design to be checked by TQR. | No action | | | | | | |

Natural Gas Systems

Table 11 Natural Gas System - Node 2.1

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Natural Gas supply - Inlet skid and Split Junction to Gas Turbines | Node # | 2.1 |
| Node Boundaries: | Power station boundary to tee junction at each gas turbine | Revision Date: | 21-Jan-22 |
| Design Intent: | Deliver NG to each gas turbine, includes Calorie Meter (MHI supplied) | Material / Chemical: | Natural gas |
| Design Conditions, Operating Envelope | Pressure: 4400 kPag, Temperature: 5 to 60 deg C, Flowrate: 150,000 Kg/h | Drawing: | HPP-AEC-MEC-GA-DTV-DRG-1096 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|------------------|--|--|--|--|-------------|---|-----------|---------------|-------------|---------------|
| 2.1.1 | Low Flow | Loss of supply of gas/leak in pipe. Unlikely event unless valve is closed. | Gas turbine stops on low pressure or will not start. | Procedures for checking flanges tightness after maintenance and pressure test and purge with N2 after maintenance. | No action | | | | | | |
| 2.1.2 | Misdirected flow | Vent or drain valves open | Gas flowing to high point vents. Gas Turbine may not start. | Operating procedures for checking valves are closed after maintenance and pressure test and purge with N2 after maintenance. | No action | | | | | | |
| 2.1.3 | Contaminants | Potential for N2 to be introduced with NG if N2 connections left open. | Flame out and potential damage to Gas Turbine caused by intermittent firing. | Operating procedures for checking valves are closed after purging. | Use temporary flexible connection for N2 purging with hoses and only connected when required for maintenance. Covered under operating procedures for only connecting N2 when purging is required. | Snowy Hydro | | Ph.2 | | | |
| 2.1.4 | High Pressure | Battery inlet ESD EKG01DF001A closed | Gas line pressurised. | Gas supply line design for 5700 kPag with allowance above maximum operating pressure of gas supply skid (5300 kPag) High high trip pressure of APA equipment is 5500 kPag | <ul style="list-style-type: none"> SH have requested to add facilities for a remote operated vent for each pipe section to be opened remotely by operators to reduce pressure in the pipeline over a selected time period e.g. 15 minutes in case of fire. Two vents will be required one for first section between battery limit ESD and SDV upstream of knockout drum and second vent required downstream of gas KO drum ESD for downstream equipment. Consider damage to the packing in the filter coalescer vessel from a high differential pressure across the filter material during venting. Change valve to ESD (currently SDV). Vent valve interlocked to not open until ESD is closed to prevent loss of gas. Review the operation of vent in conjunction with remote operation philosophy i.e., effect of ignition of vent and possibility of air entering the gas line when line depressurised. May effect ability for remote start-up. Vent valve will only close in emergency. | AECOM | APA agreed that vent for gas pipeline can be collocated with cold vent for gas receiving station. AECOM to look at radiation from new vent co-located with cold vent. APA permit system requires all lines connected to vent to be purged and lock on isolation valves. Confirm there is a DBB on vent line to new vent in APA area. | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|---|---|---|---------------|---|-----------|---------------|-------------|---------------|
| 2.1.5 | High Pressure | ESD valve closed in a process upset (trip) or fire scenario. | Transient impacts on pipeline-damage/rupture of piping. | Shut off valves closure time at gas turbine are less than 1 second. APA valves will also need to close quickly. ESD at power station battery limit and knockout drum will close more slowly to prevent sudden pressure increases. | Perform dynamic study of the system based on closure times of the valves. Consider all system shutdown (trip) scenarios. | APA and AECOM | Note: A gas system does experience the same pressure surges as a liquid system | Ph.1 | | | |
| 2.1.6 | High Pressure | Pipe blocked in | Damage to equipment/piping. | Relief valves, high pressure alarms and trips, shut off valves position indication. | Confirm there is a safety relief valve in pressure reduction units supplied by MHI. | MHI | | Ph.1 | | | |
| 2.1.7 | High temperature | Heating of gas in pipeline due to high ambient temperature. | Expansion of gas potentially causing damage to piping/equipment | High temperature alarm and a trip set at 60 deg C at APA receiving station to trip outlet gas valve. Relief device sizing overpressure scenarios include checks for gas expansion due to fire. | No action | | Design Temperature set at 65 deg C. | | | | |
| 2.1.8 | Contaminants | Liquid carryover gas at APA receiving station. | Damage to GT's | Filter/Coalescer in APA receiving station removes particulate and droplet contaminants (up to 10 ppb wt). Off-spec gas composition unlikely. | No action | | APA Filter Coalescer specification is 10 ppb weight | | | | |
| 2.1.9 | Loss of containment | Large discharge of gas to remote located vent near APA vent due to depressurisation | High flow through a cold vent causing potentially a gas cloud that could ignite | High pressure trips will stop further gas supply. Vent lines have reduced bore valves and a restriction orifice to minimise the maximum flow into the vent. | Review location of vent stack with regard to radiation from ignition of NG. Review potential to co-locate new vents required in APA's vent area | AECOM | | Ph.1 | | | |
| 2.1.10 | Instrument and control system | Inadequate instrumentation | No indication of pressure in line to identify deviation from process pressure. | Pressure transmitters with a high-pressure alarm provided at Fuel Gas Knockout Pots. Pressure transmitters with high- and low-pressure alarms within the APA gas station. Pressure transmitters within the MHI package. | Include pressure transmitter and local pressure indicator on main line. Provide additional tapping points for gauges if required. | AECOM | | Ph.1 | | | |
| 2.1.11 | Maintenance | Isolation for maintenance | Unable to maintain valves and equipment. | All equipment can be isolated with double block arrangement. Vents are double block only. | Review whether integral DBB valves can be used instead of separate valves to save cost. | AECOM | | Ph.1 | | | |
| 2.1.12 | Maintenance | Inadequate access to equipment. | Unable to maintain valves and equipment. | All equipment are located at ground level with easy access. | No action | | | | | | |
| 2.1.13 | Maintenance | Equipment for maintenance. | Calibration gas availability. | Calibration gases for calorimeter does not need to be permanently connected. | Update PID to show not permanently connected. | AECOM | | Ph.1 | | | |

Table 12 Natural Gas System - Node 2.2

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Natural Gas supply - Knock Out Drum | Node # | 2.2 |
| Node Boundaries: | Gas Turbine inlet supply isolation to Gas Knock Out Drum and liquid drains | Revision Date: | 21-Jan-22 |
| Design Intent: | Remove liquid from NG delivery to each Gas Turbine | Material / Chemical: | Natural gas |
| Design Conditions, Operating Envelope | Pressure: 4400 kPagX, Temperature: 5 to 60 deg C, Flowrate: 75,000 Kg/h | Drawing: | HPP-AEC-MEC-GA-DTV-DRG-1090 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|------------------------------|--|---|--|--|-------|--|-----------|---------------|-------------|---------------|
| 2.2.1 | High flow | Control valve EKG03AA046 on drain line may remain open (Does not shut on low level). | Gas blow through to condensate tank and vent | SDV EKGDF03001A will close with independent low-level switch. Downstream restriction orifice will limit flow to condensate tank and vent is sized for the maximum gas blow through case. | No action | | | | | | |
| 2.2.2 | Reverse Flow | High flow to Station vent through Knock drum. | Possible damage to demister pad. | | Review potential impact on reverse flow through KO pot and demister pad. | AECOM | | Ph.1 | | | |
| 2.2.3 | Instrumentation and controls | Unnecessary automated valves | Excess complication | N/A | <ul style="list-style-type: none"> Review requirement for Emergency shut off valve EKG01AA161 upstream of KO drum. Consider changing to a manual valve as remote operation of the valve is not required (by SH) ESD can remotely isolate each GT if fire on one unit Provide a schematic drawing (updated PFD) of ESD and vent valves on gas supply line to each gas turbine. | AECOM | MHI say the valve is only required for maintenance. Name of valve has been changed in new revision of the drawing to emergency shut off valve | Ph.1 | | | |
| 2.2.4 | Instrumentation and controls | Level gauge/transmitter in incorrect locations on Gas Knock Out Drum. | Level in the vessel not accurately measures/controlled. | none | Change location of level transmitter on the Gas Knock Out Drum of upper tapping point to below filter media. | AECOM | | Ph.1 | | | |
| 2.2.5 | Instrumentation and controls | High level switch LSHH EKG01CP001B faulty. | High level in fuel gas KO pot may trip gas turbine. Faulty LS may cause unnecessary trip of gas turbine | LSHH will trip gas turbine on high level. | <ul style="list-style-type: none"> -Remove LSHH trip to shut turbine -Include LSH on maintenance schedule Frequent tests to make sure it's working). Do not require duplicate drainage system because LSHH trip deleted. | AECOM | MHI say do not normally have a HH trip on liquid level in upstream vessel. In combustion chamber there is a pressure fluctuation trip if liquid carried into the inlet that will protect the GT. | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------|---|---|---|---|-------|----------|-----------|---------------|-------------|---------------|
| 2.2.6 | Low temperature | Low ambient temperature. | Hydrate formation, lower than expected fluid temperature. | Designed according to specifications i.e., piping and equipment design temperatures selected accordingly, winterisation included in the design. | No action | | | | | | |
| 2.2.8 | Maintenance | Access to Gas Knock Out Drum for cleaning and inspection. | Cleaning via manway. | | Show a Manhole on Knock Out Drum on P&ID (HPP-AEC-MEC-GA-KOO-DRG-1090). | AECOM | | Ph.1 | | | |
| 2.2.9 | Loss of containment | Relief valve EKG09AA02040 discharges into the vent stack. | Venting of gas near people on site. | All gas vents and relief valves discharge into the common vent stack located on the Power island. Location will be finalised after fire safety study. | No action | | | | | | |

Table 13 Natural Gas System - Node 2.3

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Natural Gas supply - Gas Meter & Heater Skid (MHI equipment) | Node # | 2.3 |
| Node Boundaries: | Natural gas flow meter, temperature bypass valve and gas heater | Revision Date: | 21-Jan-22 |
| Design Intent: | Measures the NG flowrate and heats the Natural gas to at least 11 deg C above the dew point to ensure no liquid is condensed when entering the Gas Turbine | Material / Chemical: | Natural gas |
| Design Conditions, Operating Envelope | Pressure: 4400 kPag, Temperature: 5 to 60 deg C, Flowrate: 75,000 Kg/h | Drawing: | HPP-AEC-MEC-GA-DTV-DRG-1094 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------|--|---|---|--|-------|--|-----------|---------------|-------------|---------------|
| 2.3.1 | Pressure | Blocked in System | Damage of equipment/piping | Relief valve downstream of gas heater | No Action | | Raised an RFI to obtain details about the MHI heater MHI have responded to RV sizing in discussion that RV blocked in case is not a concern as gas will expand into up and downstream piping. Calculations have confirmed that RV sizing is small | | | | |
| 2.3.2 | High Temperature | Temperature control valve fails last with flow through heater | Potential damage of equipment/piping | Equipment designed to cope with maximum temperature of 220 deg C. Design temperature is 340 deg C. Casing air is cooled from 500 to 210 deg C | No action | | | | | | |
| 2.3.3 | Instruments and control | Control valve failure. No positioner on temperature control valve EKG06AA003 | All gas directed through the Fuel Gas Heater and high temperature could trip the Gas Turbine. | MHI Gas Turbine gas high temperature alarm | Raise an RFI to MHI on whether the position of the temperature flow control valve is important. Difficult to know | AECOM | Clarified with MHI. No possibility of overheating gas to gas turbine. A low temperature will generate an alarm at the GT inlet and will alert operations to check valve operation | Ph.1 | 21/01/2022 | | Closed |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------|--|----------------------|---------------------|---|-------|----------|-----------|---------------|-------------|---------------|
| | | | | | that TCV has failed. | | | | | | |
| 2.3.4 | Maintenance Access | Impact of hot air of people accessing ladder to stack. | Possible injury. | | Check distance from MHI heater to ladder access on stack. | MHI | | Ph.1 | | | |

Table 14 Natural Gas System - Node 2.4

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Natural Gas supply - Dual Filter Coalescers | Node # | 2.4 |
| Node Boundaries: | Dual Coalescers and liquid drainage | Revision Date: | 21-Jan-22 |
| Design Intent: | Removes remaining liquid or solid particles before entering gas turbine | Material / Chemical: | Natural gas |
| Design Conditions, Operating Envelope | Pressure: 4400 kPag, Temperature: 5 to 60 deg C, Flowrate: 75,000 Kg/h | Drawing: | HPP-AEC-MEC-GA-FCS-DRG-1091 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-----------------------------|--|---|---|--|-------|--|-----------|---------------|-------------|---------------|
| 2.4.1 | Low Flow | Blockage in Filter Coalescer. | No gas to GTs. | DP measurement and alarm across filter coalescer, MHI Gas Turbine supply low pressure alarm and trip. | No action | | | | | | |
| 2.4.2 | Instruments and control | Filter Coalescer pressure drop increasing across filter | Reduced or no flow to GTs. GT will trip on low pressure | DP alarm on Filter Coalescer. | Review setting level of DP alarm level value on Filter Coalescers to ensure sufficient time to swap to other filters (Duty/Standby). | AECOM | Automatic valves for 300mm valves difficult to obtain. | Ph.1 | | | |
| 2.4.3 | Reverse flow | GT inlet gas supply ESD valve 90EKG1ODFOO1D open upstream of gas knock out drum and remote vent at gas piping at battery limit is opened to allow vent down. | Gas drawn through KO drum at a large rate potentially causing damage to filter elements. | none | Review potential impact on reverse flow through Knock Out Drum and demister when opening the remote vent at the station battery limit. | AECOM | See 2.1.4 | Ph.1 | | | |
| 2.4.4 | Changes in quantity - level | Unable to identify condition of filter coalescer | Difficult to inspect inside filter coalescer potentially causing inefficient operation of filter coalescer due to poor condition. | none | Consider adding sight glass on side of filter coalescers to determine condition of elements. | AECOM | | Ph.1 | | | |
| | Instruments and control | High level switch LSHH EKG02CL001B faulty. | High level in filter coalescer to trip gas turbine. Faulty LS may cause | LSHH will trip gas turbine on high level. | <ul style="list-style-type: none"> Remove LSHH trip to shut turbine Include LSH on maintenance schedule | AECOM | MHI say do not normally have a HH trip on liquid level in upstream vessel. | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|---|---|--|-------|--|-----------|---------------|-------------|---------------|
| | | | unnecessary trip of gas turbine. | | (Frequent tests to make sure it's working). <ul style="list-style-type: none"> Do not require duplicate drainage system because LSHH trip deleted. | | In combustion chamber there is a pressure fluctuation trip if liquid passed to the inlet that will protect the GT. | | | | |
| 2.4.5 | High Pressure | Blocked in system | Damage to filter coalescer because of high pressure. | Overpressure relief device installed. High DP alarm. | No action | | | | | | |
| 2.4.6 | Contaminants | Contaminated gas supply | Liquid droplets or solid particulates cause damage to GTs. | Filter Coalescer to remove liquid and solid particulate contaminants. | No action | | | | | | |
| 2.4.7 | Loss of containment | Leaks from drainage lines flanges containing liquid to drips tank. | Liquid leak from filter/coalescer flanges or drains to ground area. | No significant accumulation expected. All leaks will be contained to immediate area on impervious surface. | No action | | | | | | |
| 2.4.8 | Instruments and control | Pressure instrumentation | | PI EKG09DF001D upstream of the vessel, and differential pressure transmitter across the Filter Coalescer. | Change PI to PT upstream of filter for DCS indication. | AECOM | | Ph.1 | | | |
| 2.4.9 | Maintenance - access | Access into the Filter unit | | Platform is provided to access the filters. | Consider stairs instead of ladders for access. | AECOM | | Ph.1 | | | |
| 2.4.10 | Maintenance - maintainability | Unable to isolate the Filter Coalescer and changeout filters | | Duty/Standby Filter Coalescer arrangement has been provided to be able to changeover/maintain filters. Manual changeover so automated valves have not been provided. Differential pressure alarm to be set sufficiently low enough to give time to switch over. | No action | | | | | | |

Table 15 Natural Gas System - Node 2.5

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Natural Gas supply - Cartridge Filter skid and Final Drawing | Node # | 2.5 |
| Node Boundaries: | Last chance cartridge filter (MHI supplied) and three purge credit valves with vent facilities | Revision Date: | 21-Jan-22 |
| Design Intent: | Final protective filter for gas turbine and quick purge supply valves | Material / Chemical: | Natural gas |
| Design Conditions, Operating Envelope | Pressure: 4400 kPag, Temperature: 5 to 60 deg C, Flowrate: 75,000 Kg/h | Drawing: | HPP-AEC-MEC-GA-DTV-DRG-1095 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|--|--|---|-------|---|-----------|---------------|-------------|---------------|
| 2.5.1 | Low flow | Blockage in filter. | Low fuel supply to GTs causing a turbine trip. | Filter differential pressure measurement. MHI low gas pressure and low flow alarms. | No action | | | | | | |
| 2.5.2 | Contaminants | Impurities in gas. | Solid particulates or oil cause damage to GTs | Upstream gas filtration vessels and the last change filter provided. | No action | | | | | | |
| 2.5.3 | Loss of containment | Bleeding of gas line to unsafe location. | Creation of Hazardous area zone. | Individual gas vents to be discharged into a common vent stack located in a safe area. | Review where vents are discharge to e.g. Local High point vent | AECOM | RO in vent line is for noise suppression. | Ph.1 | | | |
| 2.5.4 | Maintenance - maintainability | Isolation and access the filter for maintenance. | Clean/changeout filter elements. | The filter unit can be isolated for maintenance. Isolation is provided upstream of gas knock out drum. Gas turbine to be off line. | No action | | | | | | |
| 2.5.5 | Maintenance | Purging at the filter not currently provided. | N2 connection | Nitrogen purging connections and high point vents have been provided at the knock out pot and filter coalescers. | Review requirements for nitrogen purge and vent connection between heater and filter to be used during maintenance of filter. | AECOM | | Ph.1 | | | |

Table 16 Natural Gas System - Node 2.6

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Natural Gas supply - Condensate tank and vent | Node # | 2.6 |
| Node Boundaries: | Condensate tank and connected vent stack | Revision Date: | 21-Jan-22 |
| Design Intent: | Collection tank for drains from Knock out pot and filter coalescers with high point vent stack | Material / Chemical: | Natural gas |
| Design Conditions, Operating Envelope | Design Pressure: 600 kPag, Design Temperature: -5 to 80 deg C, Operating Pressure: atmospheric, Operator Temperature: 30 deg C | Drawing: | HPP-AEC-MEC-GA-DTV-DRG-1093 |

| +Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|----------|-------------------------------|---|--|--|--|-------|----------|-----------|---------------|-------------|---------------|
| 2.6.1 | High flow | Gas blow through from Filter Coalescer or KO pot. Two phase flow into tank due failure of LT or control valve and SDV or two phase due to lower pressure after CV leading to effervescing of gas coming out of solution | High pressure in the tank. | Restriction orifice in upstream drain line. Relief valve on tank to prevent overpressure. No high flow possible. | No action | | | | | | |
| 2.6.2 | Loss of containment | Tank overfilling | Potential spillage of tank contents | Currently designed to be a double skinned tank. Material selection and vessel design, maintenance and regular inspections. | No action | | | | | | |
| 2.6.3 | Reverse flow | High pressure in the tank from nitrogen system. Reverse flow of Nitrogen into Filter Coalescer via drain line. | Damage to gas turbine due to N2 mixed with natural gas causing misfiring. | NRV at Filter Coalescer and Knock Out Drum. Nitrogen not used in tank when system is operating. | No action | | | | | | |
| 2.6.4 | Maintenance - maintainability | Tank drain or sampling point. | Unable to sample if no local drain. | Existing connection from the bottom of the tank to tanker loading connection. | Add small tank drain to allow sampling and flow to drain | AECOM | | Ph.1 | | | |
| 2.6.5 | Level | Low level in tank. | Tank does not drain into a tanker via tanker loading connection by gravity flow. | Nitrogen injection is to be used to load a tanker. | No action | | | | | | |
| 2.6.6 | Low pressure | Ambient Temperature changes in tank i.e. low temperatures at night time will create low pressure. | Tank damage from slight vacuum due to the tank not being design for vacuum conditions. | Vacuum unlikely due to small amount of condensation of hydrocarbons. | Update datasheet to include a full vacuum conditions that may be caused by condensation of hydrocarbons. | AECOM | | Ph.1 | | | |
| 2.6.7 | Instruments and controls | Level indication should be visible. | Visual check of tank level to allow verification of LG. | Level instrument LT EGC00CF251A and level gauge LG EKG09DF002D. | Sight glass to be added on drips tank. Add to P&ID. | AECOM | | Ph.1 | | | |

| +Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|----------|-----------------------------|--|--|---|--|-------|----------|-----------|---------------|-------------|---------------|
| 2.6.8 | Maintenance - accessibility | Tank access if located below ground. | Inability to maintain tank. | Hatch to allow access. Tank to be above ground. | No action | | | | | | |
| 2.6.9 | No flow | No flow through tank vent due to valves in vent line being closed. | Pressure relief valve on tank may lift. | Manual valves normally to be open. | Ball valves on P&IDs upstream of NRV to be locked open. | AECOM | | Ph.1 | | | |
| 2.6.10 | Drains from Vent pipe | Water flowing from gas vent pipe to drips tank | Filling of tank with water that will require the drips tank to be emptied more frequently. | none | Redirect drain from vent pipe away from drips tank to another location to avoid filling drips tank with water. | AECOM | | Ph.1 | | | |

Table 17 Natural Gas System - Overview

| | | | |
|--|--|-----------------------------|----------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Delivery to Gas Turbines | Node # | Overview |
| Node Boundaries: | | Revision Date: | 21-Jan-22 |
| Design Intent: | | Material / Chemical: | Natural Gas |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1067/1068 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---|---|--|---|---|--------------|----------|-----------|---------------|-------------|---------------|
| 1.6.1 | Materials of construction - pumps, valves | Incompatible material used with gas | Premature corrosion of materials due to inadequate material of construction. | All pipes, vessels constructed of steel. Structures made of galvanized steel. Pipe is to be painted as per specification. | No action | | | | | | |
| 1.6.2 | Physical damage | Vehicle impact of gas delivery pipeline or equipment. | Damage to gas piping and loss of containment. | Set back off the road to avoid physical damage from vehicles and Hazardous Areas. Bollards to prevent impacts to the pipelines. | No action | | | | | | |
| 1.6.3 | Fire/explosion | Fire protection on site. | Natural gas ignition and plant/equipment damage. | Fire ring main with hydrants for control of fires within plant. Hazardous area classification. Site hot work permit system and other administrative controls to eliminate ignition sources. | Review requirement for ignition source control entry into hazardous areas e.g. separation barrier, post, chain. SH to provide procedures and training for entry to HA and ignition sources. | AECOM and SH | | Ph.1 | | | |
| 1.6.4 | Start up | Start-up of system if process is outside of specified operating conditions. | GTs not running, damage to equipment. | Start-up procedures to be followed. MHI turbine start-up permissive. | No action | | | | | | |
| 1.6.5 | Noise | High gas velocities through vents and relief valves. | Loud noise from venting and potential hearing loss of personnel | Some vents have ROs to reduce flow/noise. Relief device datasheets to specify noise requirements and minimise if possible. Consider discharge silencers. | No action | | | | | | |

Process Gas & Air Systems

Table 18 Process Gas (Hydrogen) - Node 1.1

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Process Gas (H2) | Node # | 1.1 |
| Node Boundaries: | Hydrogen Trailer and Hydrogen Bottles to High Pressure panel | Revision Date: | 27-Jan-22 |
| Design Intent: | Pressure reduction from Trailer and Bottle pressure (180 barg , 137 barg) to 50 barg | Material / Chemical: | Hydrogen |
| Design Conditions, Operating Envelope | Design Pressure - 245 barg, Design Temperature - 5 - 80 deg C | Drawing: | HPP-AEC-MEC-HY-GEN-DRG-1100 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|---|---|---|-----------------------|---|-----------|---------------|-------------|---------------|
| 1.1.1 | Flow - Quantity | No supply of H2 when changing from trailer to cylinders because cylinders are empty. | No H2 supply to generator may stop GT operating. | Five-day bottle supply of H2 currently included in design (2 pallets of 15 bottles each). | Review amount of H2 required. Consider using less H2 gas bottles. (Raise RFI to SH to ask about minimum requirement for H2 storage cylinders). | AECOM/ Snowy Hydro | 15-cylinder rack will cover 2.7 days of normal leakage from 2xGT. @\2 racks will give 5 days coverage. If generators are not topped up the pressure will drop from nominal operating pressure of 4.5 barg to minimum operating pressure of 4.3 barg in 24 hours | Ph.1 | | | |
| 1.1.2 | Flow -Low Flow/ No flow | Leak from gas cylinders losing H2 backup supply. | Cylinders might be empty when required as backup for trailer. | There are valves downstream of tube trailer and gas bottles which can be closed. There is a pressure transmitter with a low alarm downstream of both the trailer and gas bottles. | Review timing for H2 trailer delivery and determine if leakage rate from generator is low enough to not reach low pressure trip whilst H2 trailer is being delivered and changeover. | Snowy Hydro | Add new PTs to first point on the fixed inlet pipework before the DBB valves to transmit actual pressure in storage cylinders and tube trailer. | Ph.1 | | | |
| 1.1.3 | Instrument and control system | Insufficient instruments to detect leak/low flow from H2 supply. | Unable to determine H2 supply source (i.e. trailer or bottles) remotely. | Local pressure indicators downstream of trailer and bottles only. A pressure transmitter on common outlet only. | Review requirement for pressure transmitters on cylinder and trailer H2 supply lines. Considering adding a position indicator on DBB valves on each H2 supply line - This option is not preferred because the position indicator will be in a Hazardous area from the H2 flanges. | AECOM | See item 1.1.1 - addition of 2x PITs will give required information. | Ph.1 | | | |
| 1.1.4 | Flow-High | Potential for high flow if PRV fails. | Loss of large quantities of H2 due to venting as a result of PSV opening on high pressure. | Pressure transmitter upstream of PRV will not indicate high flow. Local Pressure indicator only downstream of the PRV. | Add pressure transmitter with alarm inside the H2 HP regulator panel downstream of PRV. | AECOM | Change PI immediately downstream of PRV to a PIT with high pressure alarm set at 5400kPag or just below relief setting of the 5500kPag PSV. | Ph.1 | | | |
| 1.1.5 | Flow -Reverse flow | Valves on hydrogen supply line for bottles left open when H2 is being supplied from trailer. | High pressure to H2 gas bottles from H2 trailer because storage on the trailer it at a higher pressure. | NRV on N2 connection prevents backflow to N2 bottles. | Add NRVs to hydrogen supply line to lines adjoining trailer outlet and cylinder outlet. | AECOM | Insert NRVs between isolation valves EKG01AA002 and 016 and the incoming nitrogen tee so hydrogen cannot flow back from the trailer to the cylinders | Ph.1 | | | |
| 1.1.6 | Pressure - low | Valve downstream of PRV to the vent line might be open. | H2 venting to H2 vent pipe. Loss of large quantity of H2. | Operating Procedures to close valve after maintenance. | Review purpose of valve on line connected to hydrogen vent pipe (downstream of PRV). | AECOM and MHI | Lock 15NB NC valve closed. Connection to vent is allow line to be depressurised and vent to local vent. The valve is required. | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|---|---|---|-------------|---|-----------|---------------|-------------|---------------|
| | | | | | Consider locking bypass valve on PRV. | | | | | | |
| 1.1.7 | Contaminants | Nitrogen supply attached to H2 line will introduce N2 into H2 line. | Potential for lower purity of H2 than required at the generator. | Nitrogen not normally connected when H2 is used. Valve on N2 supply line to be closed after purging for maintenance. | SH to provide operating procedures to close valve. | Snowy Hydro | | Ph.2 | | | |
| 1.1.8 | Contaminants | H2 supply purity less than required by MHI for generator. | Heat generation within generator. | Gas purity monitor with alarm at generator indicates if H2 purity is less than 90%. | no action | | | | | | |
| 1.1.9 | Contaminants | Condensation in vent lines causing accelerated corrosion. | Potential failure of vent pipes or requiring earlier replacement. | Carbon steel to be used for vent lines. Vents lines, flame arrestors and vent stack on maintenance schedule and inspected on a regular basis. | no action | | | | | | |
| 1.1.10 | Instrument and control system | ESD (SDV) valve fails to close. | Potential fire with gas continuing to flow. | Fire safety system to shut ESD (SDV) valve, Emergency shutdown button at H2 pressure reduction panel. | no action | | | | | | |
| 1.1.11 | Instrument and control system | PRV fails shut (NB Normally fails open). | Loss of H2 flow. | PI downstream of PRV. | Consider a PT (downstream of the shutdown valve) that closes the shutdown valve. Review what the "shutdown" valve will be called from control perspective | AECOM | A PIT has been installed (see 1.1.4 above) with high and low alarms. A high high alarm has been added to shut the ESD (SDV) should that situation occur. | Ph.1 | | | |
| 1.1.12 | Pressure - low | Filter downstream of ESD is blocked. | Low flow of H2 to generator. | PIT downstream of strainer would indicate low pressure. | No action | | | | | | |
| 1.1.13 | Flow - no | Unavailability of H2 delivery (especially in large quantities such as the maxi trailer). | Limited or low H2 supply. | A normal H2 trailer delivery is required once every 100 days. | Discuss with the Hydrogen supplier (BOC) availability and reliability of H2 supply. | Snowy Hydro | | Ph.2 | | | |
| 1.1.14 | Contaminants | Carbon steel for Nitrogen supply line (that connects to common H2 line). | Rust particles carried over into H2 pipeline. | Filter upstream of PRV. | Review if small filter in N2 line is required to prevent any potential contamination carry over from N2 lines. Consider moving Nitrogen bottles to Hydrogen area to decrease the length of Nitrogen pipeline so this can be relatively cheaply changed to stainless steel. | AECOM | Filter upstream of the PRV to be 5-micron particulate filter to arrest any dirt or scale. Nitrogen racks do not need to be permanently connected as used infrequently so fork hoist a rack to the N2 connection point and purge out oxygen before allowing gas to pass into the hydrogen system. | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|------------|----------------|--|----------------------|--|--|-------|-----------------------------------|-----------|---------------|-------------|---------------|
| 1.1.1 5 | Pressure - low | Leakage of gas from PSV set at 5500 kPag | Loss of H2 gas. | PSV set pressure was selected to be between 15 to 150 barg | Review PSV set point downstream of PRV. Identify suitable set point based on the design pressure the downstream piping. Review pipe specification. | AECOM | PSV set at 5500 kPag is adequate. | Ph.1 | | | |

Table 19 Process Gas (Hydrogen - H₂) - Node 1.2

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Process Gas (H2) | Node # | 1.2 |
| Node Boundaries: | Hydrogen from High Pressure panel MHI pressure control | Revision Date: | 27-Jan-22 |
| Design Intent: | Pressure reduction from 50 barg to 15 barg to supply MHI (Melco unit) | Material / Chemical: | Hydrogen |
| Design Conditions, Operating Envelope | Design Pressure - TBC, Design Temperature - TBC | Drawing: | HPP-AEC-MEC-HY-GEN-DRG-1124 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------|---|--|--|--|-------|---|-----------|---------------|-------------|---------------|
| 1.2.1 | Flow - High | Pressure reduction unit fails open. | High flow of Hydrogen to generator. | PSV set at 900 kPag. Pressure Transmitter with high pressure alarm downstream of H2 pressure reduction unit. | No action | | | | | | |
| 1.2.2 | Flow - Misdirected | Valve downstream of PRV to vent line open. | H2 venting to vent pipe. Loss of H2. | The vent valve is normally closed. | Review valve fail positions and requirements of locking valves closed. Add valve Failure positions to the PID | AECOM | Lock normally closed valve in question closed. | Ph.1 | | | |
| 1.2.3 | Pressure - High | PSV vents into common vent header. Very unlikely to have both RV's opening at the same time. | High back pressure at PSV outlet which may impact PSV operation. | 40mm Vent line is connected to 80mm vent line and larger vent stack so high backpressure is unlikely. | Review vent line size and confirm large enough size for the number of RVs connected. Review choke velocity in vertical vent pipe and common vent header Review design pressure of vent line, | AECOM | Size of the PSV and the exhaust line to be based on the PRV orifice nozzle being sized on passing 150% of the GTG recharging rate of 715 Nm ³ /hr at 1500 kPag | Ph.1 | | | |
| 1.2.4 | Flow - Reverse flow | Air reverse flow into vent lines from vent stack. | Possible explosive mixture of air and gas. | None | Review vent stack design - potential for liquid seal at base of vent stack to avoid reverse flow of air. | AECOM | A liquid seal and combined flame trap to be installed at the base of the vent stack to isolate H2 from air entering the stack | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------------|--|---|---|--|------------------|---|------------------|---------------|-------------|---------------|
| 1.2.5 | Instruments and control system | Location of ESD on common supply to both generators and will shut off supply to both generators if closed. | If ESD is too far away from the end supply panel there may be a larger quantity of H2 that supplies a fire due to quantity in the line. | H2 lines are small and will not hold a significant amount of H2 so consequence is expected to be minor. | Review the best location for ESD valve isolating H2 supply from GTs. Consider two ESD valves, one on the supply to each generator. | AECOM | ESDs for each GT should be located at the start of the branch lines to each GT so the ESD closure is only to the GTG with the problem so a GT running normally is not affected by the other's abnormal operation. | Ph.1 | | | |
| 1.2.6 | Instruments and control system | Remote operated depressurising. | Allows remote depressurising of the line in event of a fire. | The volume in the 25mm line is small compared to the volume in the trailer and cylinders. | Review requirement for remote line depressurising in event ESD valves closing. | AECOM | H2 line depressurisation is a last resort action and should not be carried routinely for a GT shutting down as the gas supply is continuously required for topping up each generator. Venting the line down risks introducing air and water vapour into the H2 gas line with associated explosion risk. Additionally it may risk expensive damage to the GTG internals in the presence of CO2 and water vapour. | Ph.1 | | | |
| 1.2.7 | Maintenance | Hydrotesting and then blow through with dry air. | Water ingress to the generator. | | Hydrotest only to be done up to removable spool for each generator. Procedures for testing to prevent water being carried into the generator. | Snowy Hydro | | Ph.2 | | | |
| 1.2.8 | Pressure - High | PRV of MHI pressure reduction panel has been increased to 800 kPag from 700 kPag to allow for pressure drop between the process gas area and the generator. PSV set point has also been increased from 800 to 900 kPag | Changes in design may not be captured properly between AECOM and MHI | | Advise MHI of distance between process gas area and generator at each unit. MHI to advise whether pressure increase is acceptable for the pressure reduction panel | AECOM MHI | | Ph.1 Ph.1 | | | |

Table 20 Process Gas (Carbon Dioxide - CO₂) - Node 1.3

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Process Gas (CO ₂) | Node # | 1.3 |
| Node Boundaries: | CO ₂ Bottles to Pressure regulating panel and to MHI supplied (Melco) panel | Revision Date: | 27-Jan-22 |
| Design Intent: | Pressure reduction from Bottle pressure (137 barg) to 50 barg | Material / Chemical: | Carbon Dioxide |
| Design Conditions, Operating Envelope | Design Pressure - TBC, Design Temperature - TBC | Drawing: | HPP-AEC-MEC-HY-GEN-DRG-1102 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|--|--|---|-------|---|-----------|---------------|-------------|---------------|
| 1.3.1 | Flow - Reverse | Reverse flow from generator if Bottles empty/low . | Flow from pipes back into bottles. | Pressure in supply line is normally higher | Review requirement for NRV in system. | AECOM | Additional check valves to be installed immediately downstream of the first fixed pipework isolation valve (32NB Note 2) and immediately before the 40NB branch isolation valves upstream of the removable spools. | Ph.1 | | | |
| 1.3.2 | Pressure - High | High pressure from CO ₂ gas cylinders. | Overpressure of downstream equipment. | PSV set at 770 kPag. | Review piping spec to ensure piping downstream of the PRV and inside the CO ₂ high pressure regulating panel is designed for maximum pressure supplied by cylinders. | AECOM | Pipework from the cylinders to be rated for 200 barg CL1500 to allow for HP PRV failure or leakage. From the 700barg PRV the weight of pipe can be reduced to CL600 as there is adequate protection from two LP PSVs. | Ph.1 | | | |
| 1.3.3 | Maintenance | Hydrotest - drains/connections to drain water from the piping. Upstream isolation valve provided upstream of pressure reduction panel. | Water remaining in pipework. | Sufficient outlets provided in current design. N ₂ not connected when not in use. This connection is accessible (above ground) and can be used. | no action | | | | | | |
| 1.3.4 | Maintenance | Access to replace cylinder pack | Fork lift access under roof cover. | | Review method for getting CO ₂ cylinders from under roof cover (when cylinder packs are being replaced). | AECOM | CO ₂ cylinders will be racked and the racks are designed to be handled by fork hoists, hiab lifts or craned. Building roof line of covering building must be high enough to allow fork hoist access. | Ph.1 | | | |
| 1.3.5 | Flow - low | CO ₂ quantity stored/connected. | Insufficient quantity for generator purging. | CO ₂ storage of 4 pallets in current design allows for purging of H ₂ and then purging of air for 2 generators. | No action | | | | | | |
| 1.3.6 | Loss of containment | Leaks will be vented to atmosphere. | CO ₂ will dissipate - no major consequence. | none | No action | | | | | | |
| 1.3.7 | Instrument and control system | Local pressure Indication on system | Cannot be monitored remotely. | Pressure transmitter on outlet of pressure | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------------|---|------------------------------------|--|--|-------|---|-----------|---------------|-------------|---------------|
| | | pressure reduction panel. | | reduction panel. CO2 used for purging only and used infrequently. Purging is a manned operation. | | | | | | | |
| 1.3.8 | Instruments and control system | No provision for automatic addition of CO2 to be activated in an emergency. | CO2 system is controlled manually. | CO2 always connected but only used during maintenance. | <p>Is an emergency activation of CO2 purging required? (i.e. can this wait until an operator is present which maybe an hour later) To be confirmed in the MHI HAZOP. MHI to review operating manual and confirm. Emergency venting of CO2 on the MHI Malco panel upstream of the generator.</p> <p>If there is a fire is venting of the Hydrogen and purging with CO2 for the generator required.</p> <p>CO2 is added to the generator via manual valves (no automated valves)</p> | MHI | There is no automatic emergency venting of the GTG cooling circuit. Venting of H2 and purging with CO2 is a manual operation under the control of an operator at all times. Emergency venting of hydrogen is not recommended - the gas is safer locked inside the GTG cooling circuit where it cannot ignite. | Ph.1 | | | |

Table 21 Process Gas (Nitrogen - N₂) - Node 1.4

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Process Gas(N2) | Node # | 1.4 |
| Node Boundaries: | N2 Bottles to Pressure regulating panel | Revision Date: | 27-Jan-22 |
| Design Intent: | Pressure reduction from Bottle pressure (137 brag) to 8 brag | Material / Chemical: | Nitrogen |
| Design Conditions, Operating Envelope | Design Pressure - TBC, Design Temperature - TBC | Drawing: | HPP-AEC-MEC-HY-GEN-DRG-1102 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-----------------|---|---|--|--|-------|---|-----------|---------------|-------------|---------------|
| 1.4.1 | Flow - no flow | Requirements for BOP N2 supply. | Currently no supply of N2 to Balance of plant area. | none | Review requirement for N2 supply to the NG equipment and other areas on the Balance of Plant. Confirm whether forklifts can be used to take N2 bottles to the BOP when needed. | AECOM | | Ph.1 | | | |
| 1.4.2 | Pressure - High | High pressure from N2 cylinders. | Overpressure of downstream equipment. | Two pressure reduction valves. Relief valves downstream of PRV. The piping is designed for the maximum pressure of gas cylinders | Review piping spec to ensure piping downstream of the PRV and inside the N2 high pressure regulating panel is designed for maximum pressure supplied by cylinders | AECOM | Extra high pressure gas cylinders usually used at Colongra site | Ph.1 | | | |
| 1.4.3 | Contaminants | Reverse flow of N2 to diesel tank. | N2 flowing to diesel tank. No major consequence expected | There is a vent on diesel tank to remove N2. | No action | | | | | | |
| 1.4.4 | Maintenance | Time for shutdown/maintain general system equipment. | No significant consequence. System is run infrequently. Adequate downtime for maintenance of equipment. | Order enough N2 bottles before a shutdown. | No action | | | | | | |
| 1.4.5 | Flow - no flow | Quantity of N2 required for purging the diesel system may be too low. | Only very small volume of N2 is required to ensure there is an air gap in the pipe. | Volume of N2 is small between purge credit valves B and C. Required to meet AS for purging fuel lines. | No action | | As per AS purging requirements | | | | |
| 1.4.6 | Maintenance | Access to replace cylinder pack. | Fork lift access under roof cover. | | Review method for getting N2 cylinders from under roof cover (when cylinder packs are being replaced). | AECOM | 1.4.7 | Ph.1 | | | |

Table 22 Process Gas (H₂, CO₂, N₂) - Overview

| | | | |
|--|--|-----------------------------|---------------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Process gas | Node # | Overview |
| Node Boundaries: | | Revision Date: | 27-Jan-22 |
| Design Intent: | | Material / Chemical: | Hydrogen/ Carbon Dioxide/ Nitrogen |
| Design Conditions, Operating Envelope | | Drawing: | HPP-AEC-MEC-HY-GEN-DRG-1100/1102/1124 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--|--|--|--|--|--------------------------|----------|------------------|---------------|-------------|---------------|
| 1.5.1 | Materials of construction - piping, valves | Potential for leaks from H2 piping. | Loss of H2 and potential fire if ignited. | Appropriate procedures for tightening connections used for H2 and other gases. Piping is generally welded for H2 service. | No action | | | | | | |
| 1.5.2 | Hazardous substances | H2, N2, CO2 stored away from other chemicals. | Chemical interactions of DGs. | No incompatible Dangerous Goods or hazardous substances stored in the same area as the process gases. | No action | | | | | | |
| 1.5.3 | Physical damage | Pressure regulating panels by impact with vehicles. | Damage to pressure regulating panels by impact from vehicles. | none | Review requirement for separation bollards between H2 trailer and reduction panels. | AECOM | | Ph.1 | | | |
| 1.5.4 | Hazardous substances | Second H2 Trailer causing an additional hazardous area when replacing empty trailer with full trailer. | Potential to create hazardous area in another area of the site. | Talk to BOC to provide two trucks to move the trailer. Backup supply of H2 bottles provide 5 days supply and generator can operate for 24 hours without the pressure reaching the low alarm. | Talk to BOC about changeover of the H2 trailers and timing of delivery. Look at possibility of providing two trailer parking spaces next to each other to allow for easier changeover with one prime mover. | Snowy Hydro AECOM | | Ph.2 Ph.1 | | | |
| 1.5.5 | System testing | H2 vent pipe | Thermal radiation from H2 vent pipe. | Fire safety study is being undertaken to determine radiation impacts. | Review if any barricade are required for the H2 vent area. | AECOM | | Ph.1 | | | |
| 1.5.6 | Natural hazards | Ember attack from bushfire. | No major consequence expected as materials of construction will not be effected by embers. | Materials of construction. | no action | | | | | | |
| 1.5.7 | Procedures - development and documentation | O&M manual for system. | Incorrect operation and maintenance of system. | | O&Ms to be developed | Snowy Hydro | | Ph.2 | | | |

Table 23 Process Gas (Instrument Air) - Node 1.1

| | | | |
|--|---|-----------------------------|--|
| Project / Facility: | 60666845 Hunter Valley Power Station - Instrument Air | Node # | 1.1 |
| Node Boundaries: | Instrument air from Instrument air Package to Air Receivers | Revision Date: | 28-Jan-22 |
| Design Intent: | Deliver Inst air to IA Receiver (1 at each GT and 1 at BOP) | Material / Chemical: | Instrument Air |
| Design Conditions, Operating Envelope | Op Pressure: 900 kPag (Design Pressure:1000 kPag Op Temperature: 40 deg C (Design Temperature: 65 deg C) | Drawing: | HPP-AEC-MEC-CP-IAS-DRG-1060-B/1118-B, HPP-AEC-MEC-CP-IAS-DRG-1061-B/1120-B |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|---|---|--|---------------|----------|-----------|---------------|-------------|---------------|
| 1.1.1 | Flow - low | Purge air flow for gas turbine cooling air pipe too low. | Inadequate air for purging and other requirements on the PI. | Air receivers are sized to provide adequate air to power islands and BOP. Receivers have a 5 minute hold up time. | Confirm hold up time of 5 min of receivers is adequate. Check RFI response from MHI. Confirm all GT air consumptions with MHI. | AECOM and MHI | | Ph.1 | | | |
| 1.1.2 | Instrument and control system | Overuse of one air compressor. | Higher maintenance or failure rate of one compressor. | Lead/lag control of duty/standby compressors. | Review the lead/lag control by doing a setback in the control system. | AECOM | | Ph.1 | | | |
| 1.1.3 | Flow - reverse | Valves downstream of compressor closed. | Potential damage to compressor. | There is usually a NRV on discharge side of compressor. | No action | | | | | | |
| 1.1.4 | High level | Build-up of condensate in KO drum within the compressed air package. | KO drum may have a high level of water which could lead to carry over of water. | There is usually automatic drainage on the knock out drum. | Confirm there is an automatic system for removing water level in air knock out drum downstream of the compressor. | AECOM | | Ph.1 | | | |
| 1.1.5 | High Pressure | Blockage in compressor outlet. | Overpressure of downstream equipment/piping. | Package will include a PSV . | No action | | | | | | |
| 1.1.6 | Instrument and control system | Instrument information transmitted from package. | Operators unable to diagnose the problem with the IA package remotely. | Normally a run/or not running and fault code is output from the package. The spare compressor will start automatically. | Review the need to provide detailed instrument information from the compressors/dryer packages to the DCS for remote analysis. The aim is to provide enough information as to whether to send an operator to the site after hours. | AECOM | | Ph.1 | | | |
| 1.1.7 | Contaminants | Filters not adequately specified for site | Air filter may block. | Filters on inlet and outlet of dryers. | Review specification to check the full range of ambient | AECOM | | Ph.1 | | | |

| | | | | | | | | | | | |
|-------|--------------|---------------------|-----------------------|-----------------------------------|--|--|--|--|--|--|--|
| | | ambient conditions. | | | conditions are covered including wet air so vendor will select the appropriate type of filter. | | | | | | |
| 1.1.8 | Contaminants | Oil in Inst Air. | Fouling of equipment. | Oil less compressor is specified. | No action | | | | | | |

Table 24 Process Gas (Instrument Air) - Node 1.2

| | | | |
|--|---|-----------------------------|--|
| Project / Facility: | 60666845 Hunter Valley Power Station - Instrument Air | Node # | 1.2 |
| Node Boundaries: | Instrument air from Instrument air Receivers to users at GT and BOP | Revision Date: | 28-Jan-22 |
| Design Intent: | Deliver Inst air to users | Material / Chemical: | Instrument Air |
| Design Conditions, Operating Envelope | Op Pressure: 700 kPag (Design Pressure:1000 kPag Op Temperature: 40 deg C (Design Temperature: 65 deg C) | Drawing: | HPP-AEC-MEC-CP-IAS-DRG-1063-B, HPP-AEC-MEC-GN-GEN-DRG-1160-A |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|---|--|---|-------|---|-----------|---------------|-------------|---------------|
| 1.2.1 | Pressure - High | Pressure control valve fails open. | Pressure too high in downstream equipment. | PSV on IA distribution lines after PCV on header. | No action | | | | | | |
| 1.2.2 | Level - high | High level of condensate in air receivers. | Water accumulation in air receivers if the air dryers aren't working properly. | Automatic liquid traps on instrument air receivers. Only very small amounts of liquid are expected in these tanks. | No action | | | | | | |
| 1.2.3 | Pressure - High | Blockage on outlet of air receiver while compressor is running. | Overpressure of tanks. | PSV on each receiver tank. | No action | | | | | | |
| 1.2.4 | Loss of containment | Leak at flanges or valves. | Loss of air pressure in pipe. | Low pressure alarms. | No action | | | | | | |
| 1.2.5 | Maintenance | Receiver maintenance. | No duty receiver. GT cannot operate when corresponding receiver needs to be maintained. | Maintenance on the AR scheduled when the GT are serviced. AR will have infrequent maintenance only. (10 yearly). | No action | | | | | | |
| 1.2.6 | Instrument and control system | Plant trip on low IA pressure. | Unnecessary plant trip. | Low low pressure trips on IA supply lines downstream of receivers. | Remove low low pressure trips on IA supply lines downstream of air receivers. Leave low pressure alarms. MHI have a low pressure alarm on instrument air system. On the GT there are 3 bleed valves that are kept shut. If the air pressure drops the air valves open and the GT trips. | AECOM | PID updated | Ph.1 | 28/01/2022 | | |
| 1.2.7 | Flow - low | Potential to large flow of IA to CEMS required. | Reduced IA flow to other users. | none | Review CEMS IA consumption requirements. Add CEMS usage to IA consumption calculation if a large IA consumption is required. | AECOM | No large use expected - CEMS unit could be calibrated with IA. Package may also have valves that require IA. TBC by CEMS supplier | Ph.1 | | | |

Table 25 Process Gas (Service Air) - Node 1.3

| | | | |
|--|---|-----------------------------|---|
| Project / Facility: | 6066845 Hunter Valley Power Station - Service Air | Node # | 1.3 |
| Node Boundaries: | Service air from Service air Package to Service Air Receivers | Revision Date: | 28-Jan-22 |
| Design Intent: | Deliver Service air to Receiver (1 at BOP) | Material / Chemical: | Service Air |
| Design Conditions, Operating Envelope | Op Pressure: 900 kPag (Design Pressure:1000 kPag Op Temperature: 40 deg C (Design Temperature: 65 deg C) | Drawing: | HPP-AEC-MEC-CP-PAS-DRG- 1110/1111/1112/1126/1127 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|---|---|--|-----------------------|---|-----------|---------------|-------------|---------------|
| 1.3.1 | High level | Build-up of condensate in KO drum within the compressed air package. | KO drum may have a high level of water which could lead to carry over of water. | Usually there is automatic drainage on the knock out drum. | Confirm there is an automatic system for removing water level in air knock out drum downstream of the compressor. | AECOM | | Ph.1 | | | |
| 1.3.2 | High flow | Liquid build-up in refrigerated dryer package. | Water carry over to service air. | Drain on evaporator to remove water. | Confirm there is the facility for water removal in the evaporator in package. | AECOM | | Ph.1 | | | |
| 1.3.3 | Instrument and control system | Instrument information transmitted from package. | Operators unable to diagnose the problem with the SA package remotely. | Normally a run/or not running and fault code is output from the package The spare compressor will start automatically. | Review the need to provide detailed instrument information from the compressors/dryer packages to the DCS for remote analysis. The aim is to provide enough information as to whether to send an operator to the site after hours. | AECOM | | Ph.1 | | | |
| 1.3.4 | Instrument and control system | Overuse of one air compressor. | Higher maintenance or failure rate of one compressor. | Lead/lag control of duty/standby compressors. | Review the lead/lag control by doing a setback in the control system. | AECOM | | Ph.1 | | | |
| 1.3.5 | Contaminants | Filters not adequately specified for site ambient conditions. | Air filter may block. | Filters on inlet and outlet of dryers. | Review specification to check the full range of ambient conditions are covered including wet air so vendor will select the appropriate type of filter. | AECOM | | Ph.1 | | | |
| 1.3.6 | Contaminants | Oil in Service Air. | Fouling of equipment. | Oil less compressor is specified. | No action | | | | | | |
| 1.3.7 | Maintenance | Commonality of service provider. | Different service provider for each compressor. | SA and IA packages are likely to be provided by the same vendor. | Consider common vendor for IA and SA packages to reduce need for multiple service agents. | AECOM/ Snowy Hydro | | Ph.1 | | | |
| 1.3.8 | Temperature-Low | Dew point of Service air is 4 deg C. | Service air maybe too wet for the purging service of the air nozzles. | | | | MHI has no specific requirement for a maximum dew point temperature for the service air | | | | |

Table 26 PROCESS GAS (SERVICE AIR) - NODE 1.4

| | | | |
|--|---|-----------------------------|----------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Service Air | Node # | 2.4 |
| Node Boundaries: | Service air from Air Receivers to users at GT and BOP | Revision Date: | 28-Jan-22 |
| Design Intent: | Deliver Service air to users | Material / Chemical: | Service Air |
| Design Conditions, Operating Envelope | Op Pressure: 700 kPag (Design Pressure:1000 kPag Op Temperature: 40 deg C (Design Temperature: 65 deg C) | Drawing: | HPP-AEC-MEC-CP-PAS-DRG-1112/1113 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------|--|---|--|---|--------------|---|-----------|---------------|-------------|---------------|
| 1.4.1 | Low Flow | Service air compressor sizing for maximum demand, | If the air flow is not sufficient the air nozzles on the GT may have excessive coking which will lead to high demand for maintenance. | The service air compressor is sized for the maximum flow demand. Large purge air requirement for GT is to cool the air nozzles for the fuel oil system and prevent the coke build up. | No action | | MHI confirmed that 1200 nm ³ /h for two GT is required for 960 minutes. 16 hours is the maximum purge time. It could be a common occurrence that both GTs are shutdown at the same time and the fuel oil line purging is required. | | | | |
| 1.4.2 | Flow - Reverse | Purge air flowing from the piping to receiver due to closed valves downstream of air receiver. | No air purging of system . | NRV upstream of air receiver. | Confirm with MHI there are NRVs at the fuel module to prevent backflow into the SA system from high pressure purge air. | AECOM / MHI | | Ph.1 | | | |
| 1.4.3 | Level - high | High level of condensate in air receivers. | Water accumulation in air receivers if the air dryers aren't working properly . | Automatic liquid traps on instrument air receivers. Only very small amounts of liquid are expected in these tanks. | No action | | | | | | |
| 1.4.4 | Temperature - low | Low ambient temperature. | Corrosion in the service air pipes from condensation in line at low temperatures Lines are carbon steel. | none | Include drainage of water in the long length of pipeline to the GT and also operation during cold temperatures i.e. freezing. | AECOM | | Ph.1 | | | |
| 1.4.5 | Temperature - low | Water accumulation in SA piping. | Corrosion in carbon steel pipes which could lead to rust/ scale in pipelines. | none | Consider using stainless steel for SA pipes. | AECOM - MECH | | Ph.1 | | | |
| 1.4.6 | Pressure - High | Blockage on outlet of air receiver while compressor is running. | Overpressure of air receiver. | PSV on the air receiver. | No action | | | | | | |
| 1.4.7 | Pressure - Low | Leak at flanges or valves. | Loss of air pressure in pipe. | Low pressure alarms | No action | | MHI said the pressure is not critical | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------|---|---|---|---|-------|---|-----------|---------------|-------------|---------------|
| 1.4.8 | Instruments and control | Both duty/standby compressor not working. | No flow to cooling purge which could cause coke formation on the air nozzles which may block. | Two 100% duty compressor/dryer packages. | Confirm there is triple redundant pressure indication on instrument and service air purging to the diesel system for pre start condition. | MHI | The system at the gas turbine has a strainer. However, there is not pressure measurement or DP alarm For start-up on diesel the availability of service air is a permissive for starting the gas turbine. | Ph.1 | | | |
| 1.4.9 | Flow - low | One common air receiver for service air. | Air supply for purging of the air nozzles after shutdown. | Sizing of compressors to meet the maximum demand of service air flow. | Review requirement for using individual air receivers on the power island compared to one receiver on the BOP. | AECOM | | Ph.1 | | | |
| 1.4.10 | Flow - low | Both duty/standby compressor not working. | No flow to cooling purge which could cause coke formation on the air nozzles which may block. | Two 100% duty compressor/dryer packages. | Consider installation of a temporary compressor fittings for attachment of hire compressors for IA and SA. | AECOM | Assume dryer operating and only compressors have failed. Connection point for portable compressor added upstream of the air dryers on one of the IA and one of the SA packages. RFI to be raised with SH if a temporary dryer is also to be bought onto site or if only a compressor that will be installed upstream of the IA and SA dryer will be required. | Ph.1 | | | |

Table 27 Process Gas (Instrument And Service Air) - Overview

| | | | |
|--|---|-----------------------------|---|
| Project / Facility: | 60666845 Hunter Valley Power Station - Instrument and Service Air | Node # | Overview |
| Node Boundaries: | | Revision Date: | 28-Jan-22 |
| Design Intent: | | Material / Chemical: | Inst and Service Air |
| Design Conditions, Operating Envelope | | Drawing: | HPP-AEC-MEC-CP-IAS-DRG-1060/1061/1062/1118/1120, HPP-AEC-MEC-CP-IAS-DRG-1063 HPP-AEC-MEC-GN-GEN-DRG-1160, HPP-AEC-MEC-CP-PAS-DRG-1110/1111/1112/1126/1127, HPP-AEC-MEC-CP-PAS-DRG-1113 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|------------------------------------|---|---|--|---|-------|--|-----------|---------------|-------------|---------------|
| 1.5.1 | Materials of construction - piping | Corrosion | Damage to pipework and loss of instrument/service air. | | See comments | AECOM | note on material made on node 1.4 Consider using stainless steel for SA pipes | Ph.1 | | | |
| 1.5.2 | Physical damage | Rain/wind severe weather events. | Damage to equipment due to weather. | Compressors/dryers are inside enclosure | No action | | | | | | |
| 1.5.3 | Maintenance | No access to the top of receiver tanks. | Difficulties of maintaining the PSVs on receivers. | none | Ensure there is access for EWP to remove PSV's for maintenance. | AECOM | | Ph.1 | | | |
| 1.5.4 | Environmental impact | Liquid effluent (water) | Oil less compressors specified. | Effluent discharged to trade waste system. | No action | | | | | | |
| 1.5.5 | Procedures | Confined space inside air receiver. | Entry and egress while inspecting the internal surface. | Manhole shown on receivers on P&ID. | Review vessel dimensions to cater for inspection entry and requirement for confined space access. | AECOM | | Ph.1 | | | |

Service Water, Demin. Water, Waste & Effluent Systems

Table 28 Service Water System - Node 1.1

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Service water | Node # | 1.1 |
| Node Boundaries: | Potable water supply to Service water tank and other users e.g. amenities and safety showers | Revision Date: | 01-Feb-22 |
| Design Intent: | Supply of potable water to service water tank and other site users of potable water | Material / Chemical: | Water |
| Design Conditions, Operating Envelope | Supply pressure: TBC A booster pump may be required to allow water to be supplied to the service water tank | Drawing: | HPP-AEC-MEC-PW-SMS-DRG-1050 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------|--|--|---|--|-------|---|-----------|---------------|-------------|---------------|
| 1.1.1 | Flow - High Flow | Higher flow than expected in HWC supply connection header. | Unlikely to occur, pressure from HWC connection is not capable of flows higher than the system is rated for . | HWC metering system and site metering system. | No action | | | | | | |
| 1.1.2 | Flow - No Flow | Interruption to HWC supply | No water supply to site. Interruptions to site operation. | HWC metering system and site metering system. Water storage tank is sized to allow 10 hours of GT operation with the demin plant operating. | Review the requirements for backup water supply in event of loss of water. | AECOM | Water supply to site is critical. Header tank on the roof could be used for water to toilets. | Ph.1 | | | |
| 1.1.3 | Flow -Low Flow | Loss of water supply from HWC connection | Loss of water supply to safety showers. Site cannot operate. | Water storage tanks on site. | Review back up water supply for critical services i.e. safety showers. | AECOM | Safety showers are supplied from the potable water supply upstream of service water tank so if supply is lost there will be no supply to the safety showers | Ph.1 | | | |
| 1.1.4 | Temperature - low | Low ambient temperature at site | Freezing of water in small diameter pipelines. It is not expected the large diameter lines would freeze. However, the water pipelines are above ground which , increases the risk of freezing. | Winterisation considerations included in the detailed design (for example insulation) | Review potential impacts of extreme cold weather event and the impact of small drain lines freezing would have on site operation. Drain lines to be kept short to reduce risk of freezing. | AECOM | Supply line to service water tank is underground | Ph.1 | | | |
| 1.1.5 | Temperature - high | High ambient temperature at site. | Hot water heated by solar radiation to safety showers may cause a burn injury. | Safety shower design as per the AS standards. AS states water temperature should be tepid (16 to 38 deg C) | Consider underground PE piping to safety showers and whether a heater is required in winter. | AECOM | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|---|---|---|------------------------|--|-----------|---------------|-------------|---------------|
| 1.1.6 | Contaminants | Service water may be mistaken as potable water and used for drinking water. | Service water used as potable water. | Site operating instructions and piping labelling. | Construction partner to check the Snowy hydro standard for labelling pipeline and label pipes after construction and before commissioning. | UGL/ Snowy Hydro | | Ph.2 | | | |
| 1.1.7 | Contaminants | Ability to sample the potable water supply line due to low water use. | Water aging and low residual chlorine. | Potable water tank has a sample point. Closed system. | Add a sampling point to potable water line downstream of the site water meter and upstream of the service water tank. Consider facility for potable water lines to be flushed through into the service water tank to replace aged water in the line with fresh water. Potable water to be tested at periodic times as specified by SH. | AECOM | | Ph.1 | | | |
| 1.1.8 | Maintenance - Maintainability | Valves not functioning properly/requires maintenance and needs to be taken offline. | Unable to maintain valves on supply line if they cannot be taken offline. | Most valving/equipment can be bypassed for maintenance as per current P&ID. | Consider isolation immediately after HW metering facility to allow ability to maintain downstream valves. | AECOM | First valve in series will always be difficult to maintain | Ph.1 | | | |

Table 29 Service Water System - Node 1.2

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Service water | Node # | 1.2 |
| Node Boundaries: | Service Water tank | Revision Date: | 01-Feb-22 |
| Design Intent: | Storage of service water on site in case of supply interruptions from Hunter Water | Material / Chemical: | Water |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-PW-FPS-DRG-1052 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|--|---|---|-------|----------|-----------|---------------|-------------|---------------|
| 1.2.1 | Maintenance - maintainability | Tank taken out of service for maintenance. | Isolation of tank causing loss of water from tank. | Valves shown on all tank nozzles except for the overflow, supply line and the LALL switch. Overflow line and Instrumentation would not require isolation if tank were taken out of service. | Review tank outlets/connections - all nozzles to be fitted with valves for isolation | AECOM | | Ph.1 | | | |
| 1.2.2 | High level | Level transmitter fails. | Tank overfilled. | High level alarm and High High level switch and overflow line. | Replace level switch (LS/LAHH) with another LT because of critical service of tank and add HH to level transmitter. | AECOM | | Ph.1 | | | |
| 1.2.3 | Contaminants | Biocide chemicals dosed into water for | Chemicals dosed could corrode tank | Carbon steel and painted internals including the roof. | Confirm tank paint internals on datasheet is compatible with anti-algacide chemicals | AECOM | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|----------------------------|--------------------------------------|--|--|--|-------|----------|-----------|---------------|-------------|---------------|
| | | prevention of algae growth. | material of construction. | | | | | | | | |
| 1.2.4 | Loss of containment - leak | Leaks from tank connections/flanges. | Water leak from tank. | Drains under tanks. | Ensure that drains from tank are separated on model as per P&ID. | AECOM | | Ph.1 | | | |
| 1.2.5 | Maintenance | Manhole diameter. | Diver entry to tank. | 900 mm diameter M/H on the side of the tank. | Review size of hatch on tank roof to facilitate access for diving. Consider 900mm opening. | AECOM | | Ph.1 | | | |
| 1.2.6 | Maintenance | Tank hatch open during maintenance. | Access into tank hatch for unauthorised personnel. | Site procedures for confined space access. | Confirm that there are facilities to install a barriers around hatch. | AECOM | | Ph.1 | | | |

Table 30 Service Water System - Node 1.3

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Service water | Node # | 1.3 |
| Node Boundaries: | Service water pumps to Gas turbines Evaporative Coolers | Revision Date: | 01-Feb-22 |
| Design Intent: | Supply of service water to gas turbine air inlet evaporative coolers | Material / Chemical: | Water |
| Design Conditions, Operating Envelope | Discharge Pressure of service water pumps is 750 kPag (TBC) | Drawing: | HPP-AEC-MEC-PW-FPS-DRG-1051 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------|---|--|--|--|-------|----------|-----------|---------------|-------------|---------------|
| 1.3.1 | Low flow | Loss of a pump. | Loss of GT efficiency, running at lower capacity. | Duty/Duty/Standby arrangement of pumps. | No action | | | | | | |
| 1.3.2 | High flow | Three pumps running. | PCV for minimum flow kick back will open at high pressure. | Duty/Duty/Standby arrangement of pumps. | No action | | | | | | |
| 1.3.3 | Low flow | Standby pump takes too long to supply water. | GT running at lower capacity. | None | Confirm timing of third forwarding pump starting and affecting GT operation. Provide buffer time in evaporative cooler tank at GT | MHI | | Ph.1 | | | |
| 1.3.4 | High flow | Shut off valve downstream of Forwarding Pumps at evaporative water tank closes. | Potential water hammer in piping. | There are other users of service water e.g. Demin plant. The pipe sizes are designed for low velocities so piping hammer analysis is not required. | No action | | | | | | |
| 1.3.5 | Contaminants | Larger sizes of solids in water to pumps. | Pump damage. | Strainers on pump inlet. | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------------|---|---|---|--|------------------|---|------------------|---------------|-------------|---------------|
| 1.3.6 | Contaminants | Reduction of Chlorine level in the service water over time. | Growth of algae in the water. | Potable chemical injection package included in current design. | Review use and quantities of portable chemical injection package. Check the quantities of chemicals in this package are kept under the DG minor storage thresholds. | AECOM | Package can be brought to site on a temporary basis for dosing. | Ph.1 | | | |
| 1.3.7 | High pressure | PCV in pump kick back closed. | Measurement of pressure in pump kickback line during commissioning. | Local pressure indicator on pump discharge. | Review the requirements for pressure indicator upstream of kickback PCV in minimum pump flow line. | AECOM | | Ph.1 | | | |
| 1.3.8 | Instruments and control system | In the event of fluctuating pressures pumps may stop/start regularly. | Pump reliability issues. | Control philosophy includes parameters for pumps starting/stopping sequence | Review methods for smoothing or minimising the number of pumps starts. Contemplate scenario of leakage and no other flow . Consider whether an accumulator or jockey pump is required for small flows. Check if there is a signal from the GT whether the evaporative cooler is operating and the need for 1 or 2 pumps operating | AECOM MHI | | Ph.1 Ph.1 | | | |

Table 31 Demineralised Water System - Node 1.4

| | | | |
|--|---|-----------------------------|---|
| Project / Facility: | 60666845 Hunter Valley Power Station - Demin Plant | Node # | 1.4 |
| Node Boundaries: | Service water pumps to Demin Plant (RO Pumps) | Revision Date: | 01-Feb-22 |
| Design Intent: | Supply of service water to RO pumps | Material / Chemical: | Water |
| Design Conditions, Operating Envelope | Discharge Pressure of service water pumps is 750 kPag (TBC) | Drawing: | HPP-AEC-MEC-PW-FPS-DRG-1051, HPP-AEC-MEC-DW-WTS-DRG-1055 HPP-AEC-MEC-DW-WTS-DRG-1056 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------------|--|--|--|--|-------|---|-----------|---------------|-------------|---------------|
| 1.4.1 | Low flow | Service water supply to demin package from discharge of pumps. | No water supplied to demin package. | 3 service water pumps. | Review potential to provide direct connection from potable water supply upstream of service water tank to demin package. | AECOM | Minimum pressure required for Demin package is 200 kPag. Consider if flow is restricted to the demin plant when filling the FW tanks | Ph.1 | | | |
| 1.4.2 | Instruments and control system | Instruments from demin package interface with DCS. | Operators at remote location unaware of alarms from demin package. | Vendor packages have common alarm provided in DCS. | Measured values and alarms from demin package PLC to be available for mimic on the DCS for monitoring remotely by operators. | AECOM | PLC based skid The DCS will mimic the status and alarms of the demin plant skid DCS will have supervisory control over the skid | Ph.1 | | | |
| 1.4.3 | Reverse flow | Backwash water flowing to service water tank via the recycle line. | Backwash water to service water tank. | NRVs between service water lines. Automated valves on inlet to sand bed filter switch position during backwash. | No action | | | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------|---|---|--|-----------------|-------|----------|-----------|---------------|-------------|---------------|
| | | | | PCV is set at a higher pressure than back wash pump pressure. | | | | | | | |
| 1.4.4 | Loss of containment | Breakthrough of contaminants through filter caused by rat-holing. | Low pressure differential measurement across filters. | Indication of break through via pressure differential measurement. | No action | | | | | | |

Table 32 Demineralised Water System - Node 1.5

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Demin Plant | Node # | 1.5 |
| Node Boundaries: | RO System pumps and units to demin tank including RO reject water to neutralisation pit | Revision Date: | 01-Feb-22 |
| Design Intent: | Supply of Demin water to Demin water tank | Material / Chemical: | Demin Water |
| Design Conditions, Operating Envelope | Discharge Pressure of RO pumps (TBC) | Drawing: | HPP-AEC-MEC-DW-WTS-DRG-1056 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------------------|--|---|--|---|-------|--|-----------|---------------|-------------|---------------|
| 1.5.1 | Low Flow | Failure of pump inside package. | Loss of 50% of supply. | Site maintenance procedures. | Review requirements for duty/standby pumps within the packages or requirement to keep uninstalled spares. Alternatively, increase capacity of package to 55m ³ /h which removes the need for 2 packages to operate simultaneously to supply demin for 3 days continuous operation of GT on diesel. | AECOM | Note: It is usually not practical to source demin water from outside sources. However, facilities have been provided to fill the demin tank from a tankers. Both packages can run simultaneously to supply demin water if the level is low. | Ph.1 | | | |
| 1.5.2 | Low Flow | High flow to neutralisation pit. | Loss of flow to demin tank. | Flow transmitter on demin line to demin storage. Low DP on RO units. | No action | | | | | | |
| 1.5.3 | Contaminants | Leaks from equipment. | Potential for trips or slips. | All equipment inside contained area. | No action | | | | | | |
| 1.5.4 | Instruments and control systems | Ability of Demin Plant to be started/stopped remotely. | If site is unmanned SH prefers the ability to start the package remotely. | Starting/stopping of demin package will be interfaced with DCS. | No action | | | | | | |
| 1.5.5 | Composition | Biocide dosed into service water tank. | Biocide could potentially impact RO plant. | RO plant specification will include water quality information. | Notify the RO vendor of potential biocide use in the water supplied to demin package. Include in demin package specification. | AECOM | | Ph.1 | | | |
| 1.5.6 | Maintenance | Demin plant may not used for long periods of time. | Equipment may not work when required. | Site operating procedures and maintenance procedures. | Notify the vendor that demin plant may not be used for long periods of time. Confirm demin plant can cope with periods of standby. | AECOM | Demin water will require polishing. Demin plant could be run for a few hours a day to help with maintenance of the system (as per other SH plants). | Ph.1 | | | |

Table 33 Demineralised Water System - Node 1.6

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Demin Plant | Node # | 1.6 |
| Node Boundaries: | Demin tank | Revision Date: | 01-Feb-22 |
| Design Intent: | Storage of Demin water | Material / Chemical: | Demin Water |
| Design Conditions, Operating Envelope | Ambient Conditions | Drawing: | HPP-AEC-MEC-DW-SFP-DRG-1057 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|---|--|--|-------|--|-----------|---------------|-------------|---------------|
| 1.6.1 | Level - high | Level transmitter fails. | Tank overfilled. | High level alarm and High high level switch and overflow line. | Include two level transmitters instead of a LSH and LT. | AECOM | | Ph.1 | | | |
| 1.6.2 | Level - overflow | Failure of high level switch. | Demin water overflows to stormwater - pH of demin water too low to be sent to stormwater/environment. | Overflow currently shown going to storm water. | Review the overflow discharge location based on pH of demin and relocate to trade waste. | AECOM | | Ph.1 | | | |
| 1.6.3 | Low Pressure | CO2 filter on tank vent blocked. | Vacuum created in tank and not designed for vacuum. | None | Review the possibility of CO2 filter (on tank vent) blocking and causing tank to be under vacuum. Consider adding an N2 blanket in tank. | AECOM | NOTE: SH confirmed they prefer not to have N2 blanketing CO2 filter can be installed at ground level for ease or replacement and have duty / stand by arrangement | Ph.1 | | | |
| 1.6.4 | Containment | Demin water from drains. | pH too low to be sent straight to stormwater/environment. | None | Review location of tank drains from storm water to trade waste | AECOM | | Ph.1 | | | |
| 1.6.5 | Containment | Demin from drains. | Could also be harmful to operators if demin water comes into contact with their skin/eyes. | Operators to wear PPE e.g. Safety glasses pH of demin water is likely to only be 5 (slightly acidic). | No action | | | | | | |
| 1.6.6 | Maintenance | Manhole diameter. | Diver entry to tank. | 900 mm diameter M/H on the side of the tank. | Review size of hatch on tank roof to facilitate diving access. Consider 900mm opening | AECOM | SH commented they would put a RO camera into the tank in preference to a person | Ph.1 | | | |
| 1.6.7 | Maintenance | Manhole opened during maintenance. | Potential for workers to fall into open manhole. Access into tank hatch for unauthorised personnel. | Site confined space entry procedures. | Confirm that there are facilities to install a barrier around hatch and locking facility. | AECOM | | Ph.1 | | | |
| 1.6.8 | Maintenance - maintainability | Tank taken out of service for maintenance. | Water leak from tank. | Valves on tank nozzles. | Review tank outlets/connections - all nozzles to be fitted with valves for isolation. | AECOM | | Ph.1 | | | |

Table 34 Demineralised Water System - Node 1.7

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Demin Plant | Node # | 1.7 |
| Node Boundaries: | Demin Water Pumps to gas turbines and demin return | Revision Date: | 01-Feb-22 |
| Design Intent: | Supply of Demin water to Gas turbines for NOX Suppression | Material / Chemical: | Demin Water |
| Design Conditions, Operating Envelope | Discharge Pressure of Demin water pumps : 750 kPag (TBC) | Drawing: | HPP-AEC-MEC-DW-SFP-DRG-1058 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------------------|---|--|---|---|------------------|--|------------------|---------------|-------------|---------------|
| 1.7.1 | Low flow | Flow drops off when spare pump turns on. | GT trips or NOX suppression is not adequate. | Spare pump will be started firstly by a fault on the running pump. Secondly spare pump will be started by low flow and low pressure. | Confirm if one pump is lost there is sufficient time for another pump to turn on before the flow switch trips the GT. RFI to be raised to MHI. | AECOM MHI | SH commented at other sites there is 15 minutes before the GT stops. MHI commented there is a low pressure switch at the GT demin pump that will trip the pump. | Ph.1 Ph.1 | | | |
| 1.7.2 | High flow | Three pumps running. | No major consequence, line is sized large enough for this. | Third pump would shut down based on control. | No action | | | | | | |
| 1.7.3 | Low flow | Orifice in demin return line from MHI scope. | MHI orifice (in return line to demin tank) may be too small to facilitate commissioning. | None | Consider bypass line around MHI orifice plate to facilitate commissioning. Raise an RFI to MHI. | AECOM MHI | | Ph.1 Ph.1 | | | |
| 1.7.4 | Instruments and control systems | Manual valves to direct demin water from forwarding pumps to treatment package or distribution. | No ability to switch between demin polishing/forwarding remotely through DCS. | None | Review potential to install automated valves on lines from forwarding pumps to demin treatment package for polishing and demin distribution to allow remote switchover between lines. Add polishing sequence to DCS to allow for remote operation. | AECOM | The pump is not sized to do both polishing and supplying water to the GT. Mode of operation to be selected by changing position of automated valves. | Ph.1 | | | |
| 1.7.5 | Pressure | Leaks from pumps/seals. | Loss of demin water to environment. | All releases of demin water to go to drains to trade waste. | No action | | | | | | |
| 1.7.6 | High pressure | PCV in pump kick back closed. | Measurement of pressure in pump kickback line during commissioning. | Local pressure indicator on pump discharge. | Review requirement of pressure indicator upstream of PCV. | AECOM | | Ph.1 | | | |
| 1.7.7 | Maintenance - isolation | Pumps access for maintenance. | Ability to service pumps. | Maintenance isolation valves either side of all pumps. | No action | | | | | | |

Table 35 Demineralised Water System - Node 1.8

| | | | |
|--|--|-----------------------------|--|
| Project / Facility: | 60666845 Hunter Valley Power Station - Demin Plant | Node # | 1.8 |
| Node Boundaries: | Demin water to Filter backwash and effluent | Revision Date: | 01-Feb-22 |
| Design Intent: | Supply of Demin water to Demin plant for filter backwash | Material / Chemical: | Demin Water |
| Design Conditions, Operating Envelope | Discharge Pressure of Demin Pumps : 750 kPag (TBC) | Drawing: | HPP-AEC-MEC-DW-SFP-DRG-1057, HPP-AEC-MEC-DW-WTS-DRG-1059 HPP-AEC-MEC-DW-WTS-DRG-1055, HPP-AEC-MEC-DW-WTS-DRG-1056 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------|---------------------------------|---|---|-----------------|-------|-------------------------------------|-----------|---------------|-------------|---------------|
| 1.8.1 | Low Flow | Pump failure. | Loss of supply. | Standby pump/package available (TBC with Demin plant supplier). | No action | | Pump control from Demin package PLC | | | | |
| 1.8.2 | Level - high | Overfilling of tank. | Spilling to ground. | Demin system contained and sent to neutralisation pit. | No action | | | | | | |
| 1.8.3 | High Pressure | Valve closed on outlet of pump. | Damage to pump/piping. | System designed for deadhead of pump. | No action | | | | | | |
| 1.8.4 | Contaminants | Too many chemicals dosed | Wasting chemicals - no safety consequence | Chemicals and quantities to be dosed will be proposed by a water treatment vendor as required by the system | No action | | | | | | |
| 1.8.5 | Loss of containment | Leaks from pumps/seals. | Spilling to ground. | Demin system contained and sent to neutralisation pit. | No action | | | | | | |

Table 36 DEMINERALISED WATER SYSTEM - NODE 1.9

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Demin Plant | Node # | 1.9 |
| Node Boundaries: | Cleaning chemicals from demin plant to neutralisation pit | Revision Date: | 01-Feb-22 |
| Design Intent: | Cleaning chemicals from demin plant to treatment in neutralisation pit | Material / Chemical: | Demin Water, Citric Acid |
| Design Conditions, Operating Envelope | Discharge Pressure of CIP pumps (TBC) | Drawing: | HPP-AEC-MEC-DW-WTS-DRG-1059 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------------------|---|--|---------------------------------|---|-------|----------|-----------|---------------|-------------|---------------|
| 1.9.1 | Instruments and control systems | Package output to show if chemicals quantity are low. | Potential to run low on chemicals - no safety consequence. | Instrumentation within package. | Chemicals and the dosing will be proposed by a water treatment vendor as required by the system. Check there is indication for low levels of chemicals | AECOM | | Ph.1 | | | |
| 1.9.2 | High flow | Automated valves directing CIP chemicals to RO or waste to neutralisation pit not in correct position . | Large flow of waste water to neutralisation pit. | Control flow sizing. | Confirm if automated valves are not in position and there is an output into the DCS to show this. Confirm with package supplier if these valves are interlocked. | AECOM | | Ph.1 | | | |

Table 37 Service Water & Demineralised Water Systems - Overview

| | | | |
|--|--|-----------------------------|--------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Service Water and Demin | Node # | Overview Water and demin |
| Node Boundaries: | | Revision Date: | 01-Feb-22 |
| Design Intent: | | Material / Chemical: | Water and Demin Water |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | See previous Tabs |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--|--|--|---|--|-------|---|-----------|---------------|-------------|---------------|
| 1.10.1 | Materials of construction - pumps, valves, tanks | Demin water can cause corrosion in incompatible materials. | Corrosion | All pumps/valves used for demin to be specified for demin water. | Raise RFI to SH to confirm stainless steel grade required (304 or 316). | AECOM | AECOM piping is specified as 316. MHI has put 304 SS on their PIDS for Demin water lines/equipment 316 is more expensive than 304 SS. | Ph.1 | | | |
| 1.10.2 | Physical damage | Vehicle impact to equipment. | Breaking/damage of equipment. | Demin water skid is not located near roads or large vehicles access. | No action | | | | | | |
| 1.10.3 | Shutdown | Emergency shutdown requirement. | Impact of emergency shutdown of the demin plant on electricity network security. | Demin tank of 1.6 ML has capacity to allow running of both GT on diesel for 10 hours. | Determine desired system response in emergency shutdown (from safety perspective). Apply this to all subsystems Provide a list of impacts of any system shutdowns on ability of GT to operate. | AECOM | Demin package stoppage does not stop GT | Ph.1 | | | |
| 1.10.4 | Environmental impact | Demin water from drains may have lower pH. | The demin water pH is too low to be sent to stormwater/environment. | Action Ref 1.6.4 to review drains that are not shown to go to neutralisation pit. | Review location of all demin drains to ensure they all go to neutralisation pit. | AECOM | | Ph.1 | | | |

Table 38 FIRE WATER - NODE 1.1

| | | | |
|--|--|-----------------------------|--|
| Project / Facility: | 6066845 Hunter Valley Power Station - Fire Water | Node # | 1.1 |
| Node Boundaries: | Water supply to Fire water Tanks | Revision Date: | 02-Feb-22 |
| Design Intent: | Water supply to Fire water Tanks | Material / Chemical: | Water |
| Design Conditions, Operating Envelope | TBC | Drawing: | HPP-AEC-MEC-PW-SMS-DRG-1050, HPP-AEC-MEC-FP-FWS-DRG-1070 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|----------------------|--|---|--|--|-------|--|-----------|---------------|-------------|---------------|
| 1.1.1 | Low flow | Leaks from flanges. | Loss of water visible. Non-Hazardous. | Tanks hold sufficient water for firefighting protection and AS2419 | No action | | | | | | |
| 1.1.2 | Reverse flow | Reverse flow from tank to water supply. | No flow to tanks. | RPZ valves in water supply line | No action | | | | | | |
| 1.1.3 | High level | Float valve stays open. | Tank overflows. | High level alarm on tanks. | No action | | | | | | |
| 1.1.4 | Low level | Float valve sticks shut. | Insufficient water in tank to fight fires. | Low level alarm on tanks. | No action | | | | | | |
| 1.1.5 | No flow | Valves that are critical to supplying fire water to plant are accidentally closed. | No firewater flow to site. | Site operating procedures. | Update critical valves to be locked open e.g. for valves on fire fighting system (Show on P&ID). | AECOM | Discussion was referring about whether the drain valves on the FW tanks should be locked closed. | Ph.1 | | | |
| 1.1.6 | Low Pressure | Pressure at water supply connection too low. | Tanks cannot be filled quickly enough to satisfy AS2419 requirements. | One Tank to be filled within 24 hours. | Confirm the pressure drop to the tank and flowrate meet the requirements of AS2419. | AECOM | | Ph.1 | | | |
| 1.1.7 | No flow | Interruption to water supply and tank to be filled by tanker. | Low level in tanks. | Spare nozzle on tank. | Review requirement for nozzle fill point on tanks for emergency tank filling by tanker. | AECOM | There is a bypass around the water fill valve | Ph.1 | | | |
| 1.1.8 | No flow | RFS attending fire on/near site require access to water in tanks. | Escalation of fire near/on site. | Spare nozzle on tank. | Confirm that RFS connection standards are met. | AECOM | | Ph.1 | | | |
| 1.1.9 | Contamination | Water sitting in tanks for long periods. | Bacteria or sediments in tanks. | None | Review need for sample point on firewater system. Review best location for sample point i.e. one on each tank or upstream of fire water pumps. | AECOM | SH prefer the ability to sample from each tank | Ph.1 | | | |
| 1.1.10 | Maintenance - access | Restriction of inspection of tank due to tank liner. | Cannot maintain/inspect tank. | Bladders normally connected to the wall at manway. | Review access provisions through tank liner and manhole access. | AECOM | | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|--|--|---|--|-------|----------|-----------|---------------|-------------|---------------|
| 1.1.11 | Maintenance | Fire water availability when tanks are out of service. | Insufficient fire water during fire event. | One tank to be taken offline at a time only to ensure 50% of firewater is always available. | No action | | | | | | |
| 1.1.12 | Maintenance - maintainability | Tank taken out of service for maintenance. | Isolation of tank causing loss of water from tank . | Valves on tank nozzles. | Review tank outlets/connections - all nozzles to be fitted with valves for isolation. | AECOM | | Ph.1 | | | |
| 1.1.13 | Contamination | Biocide dosing to tank. | Damage to tank bladder. | None | Confirm tank bladder is compatible with biocides that may be required for water treatments. | AECOM | | Ph.1 | | | |
| 1.1.14 | Maintenance | Maintenance of auto fill valve. | Requirement to drain a large quantity of water from the upstream line. | Upstream isolation valve at flow meter. | Provide description of how the auto fill valve will be maintained, isolated and bypass used. | AECOM | | Ph.1 | | | |

Table 39 Fire Water - Node 1.2

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 6066845 Hunter Valley Power Station - Fire Water | Node # | 1.2 |
| Node Boundaries: | Fire water pumps to Fire water ring main | Revision Date: | 02-Feb-22 |
| Design Intent: | Water supply to Fire water ring main | Material / Chemical: | Water |
| Design Conditions, Operating Envelope | TBC | Drawing: | HPP-AEC-MEC-FP-FWS-DRG-1071 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-------------------------------|---|--|---|--|-------|----------|-----------|---------------|-------------|---------------|
| 1.2.1 | Maintenance - maintainability | Diesel tank need to be refilled / topped up. | Difficult to refill / top up diesel tanks. | Tank has a manual fill connection. | Review the potential to provide auto fill from site diesel storage tanks to the smaller diesel tank near diesel driven firewater pump. If diesel tank for pump is filled manually consider manual handling requirements of how this tank is filled. | AECOM | | Ph.1 | | | |
| 1.2.2 | Maintenance | No isolation on diesel pump relief valve line return to tank. | Inability to take one tank out of service with no isolation valve. | Vendor package indicative drawing only - detailed package design to include isolation valves. | Add locked open valve on relief line. Review AS2941 to see if this is permitted. | AECOM | | Ph.1 | | | |
| 1.2.3 | Flow - low | Accumulation of silt in the balance line between tanks . | Possible blockage of balance line. | Piping design. | Review the position of balance line to minimise potential of silting in line. Confirm height of line above tank base. | AECOM | | Ph.1 | | | |
| 1.2.4 | Flow - high | Additional hydrants used during fire fighting. | Two fire pumps maybe operating. | The line will be sized for two firewater pumps operating. | No action | | | | | | |

| | | | | | | | | | | | |
|-------|-------------------------------|---|--|--|---|-------|--|------|--|--|--|
| 1.2.5 | Maintenance | Valve downstream of diesel pump PSV closed for maintenance of diesel pump. | Valve accidentally left shut after maintenance. | Single PSV on diesel pump outlet because of over speed. The relief valve is not required for the electric pump. | No action | | | | | | |
| 1.2.6 | Instrumentations and controls | Integration of pump package with DCS system. | Inability to remotely monitor package system alarms. | Currently common alarm and pumps status displayed in DCS. Relay of low battery alarm back to alarm panel. | Review battery system monitoring alarm interface with DCS for monitoring. | AECOM | | Ph.1 | | | |
| 1.2.7 | Temperature - high | Heating of water in firewater pump discharge. | Person standing near the TRV impacted by hot water. | Discharge directed to ground. | Review where the outlet of TRV on firewater pump outlet is to be directed and select a suitable location. | AECOM | | Ph.1 | | | |
| 1.2.8 | Flow - no | Pumps functioning (failing to start) affected due to filtering of air to the engine of the diesel pumps. | Engine overheats. | Pumps are inside a container with a ventilation system. | Review the potential for embers and overloading the air intake system in the event of a bushfire. | AECOM | | Ph.1 | | | |

Table 40 OILY WATER COLLECTION & TREATMENT - NODE 1.3

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Oily Water Collection and Treatment | Node # | 1.3 |
| Node Boundaries: | Oily water drains and Oily Water Pit | Revision Date: | 02-Feb-22 |
| Design Intent: | Collection of oily water drain, storage and preliminary separation to oil water separator | Material / Chemical: | Water / Oil |
| Design Conditions, Operating Envelope | Ambient Conditions | Drawing: | HPP-AEC-MEC-GN-GEN-DRG-1085 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|------------|---|--|--|-----------------|-------|---|-----------|---------------|-------------|---------------|
| 1.3.1 | High flow | Transformers oil leak. | Large flow of oil to oily water pit | Pit is sized for spill of one transformer which is the largest expected volume of oil (100,000L) that could flow to this system. Spill of oil from 2 transformers at the same time is very unlikely. | No action | | Transformer is banded and can contain all the oil from the transformer. Drain to oily water pit has a flame arrestor to prevent transfer of any flame. Discharge valve from transformer bund is always open in case of a storm event. | | | | |
| 1.3.2 | High level | Heavy rain event with large water inflow. | Potential for overflow of oily water pit | Emergency overflow line from the bottom of pit to overflow clean water to storm water. There will be a designated pit for overflow | No action | | Pit Sized for the 100-year storm event | | | | |

| | | | | | | | | | | | | |
|-------|-------------------------------|--|--|--|---|-------|---|------|--|--|--|--------|
| 1.3.3 | Composition | Variations in oily water flow depending on where in the plant this is coming from. | No consequence | Oily water system designed for flow composition variations | No action | | | | | | | Closed |
| 1.3.4 | Contamination | Algae growth due to lack of coverage of pits and sunlight. | Blocking filters upstream of pumps. | None | Review management of algae in pit. Include in package spec and discuss potential options with vendors. | AECOM | Pit is not covered presently to prevent inflow of rain in the area of the pit | Ph.1 | | | | |
| 1.3.5 | Loss of containment | Leaking from tanks/equipment due to leaks on flanges. | Spills outside of equipment. | System is designed with concrete aprons that drain to oily water pit | No action | | | | | | | |
| 1.3.6 | Maintenance - access | Difficulty in access pit via ladder. | Potential injury of personnel on ladder. | None | Review use of stairs instead of ladder into pit. Look at removable type of stairs to prevent fouling of stairs. | AECOM | Pit to be maintained annually. | Ph.1 | | | | |
| 1.3.7 | Maintenance - maintainability | Oily water flowing into pit while maintenance workers are in the pit. | Potential injury of personnel in pit due to slips. | Permit to work procedures. | Review requirement for isolation of incoming drains to allow access to pit to provide correct isolation. | AECOM | | Ph.1 | | | | |
| 1.3.8 | Maintenance - access | No (or limited) access for trucks to come in when required. | Cannot remove oil from decanting pit. | Adequate access for sucker truck. | No action | | | | | | | |

Table 41 Oily Water Collection & Treatment - Node 1.4

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Oily Water Collection and Treatment | Node # | 1.4 |
| Node Boundaries: | Oily water separator and discharge to oily water pit | Revision Date: | 02-Feb-22 |
| Design Intent: | Separation of oil and water to allow disposal | Material / Chemical: | Water / Oil |
| Design Conditions, Operating Envelope | Ambient Conditions | Drawing: | HPP-AEC-MEC-GN-GEN-DRG-1085 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|------------------------------|---|--|---|---|-------|----------|-----------|---------------|-------------|---------------|
| 1.4.1 | Instrumentation and controls | Instruments from oil/water package interface with DCS. | Inability to remotely monitor package system operation and alarms. | Vendor packages have common alarm provided in DCS | Confirm interface of package with DCS. Determine what information needs to be transferred to DCS. | AECOM | | Ph.1 | | | |
| 1.4.2 | Low flow | Pump failure | Flow out of oil skimmer too low. | Standby pump | No action | | | | | | |
| 1.4.3 | Pressure - vacuum | Blockage upstream of filter. Positive Displacement pump creates vacuum. | Pumps continue to run and causes a vacuum in filter. | Design pressure of filter. | Confirm if piping between filter and pumps and filter is designed for a vacuum conditions. | AECOM | | Ph.1 | | | |

| | | | | | | | | | | | |
|-------|-------------------------------|---|--|--|---|-------|---|------|--|--|--|
| 1.4.4 | Maintenance - maintainability | System may not be used for extended period of time. | Equipment may not work as expected e.g. sludge build up in system. | Vendor package design | Vendor supplier to confirm if oil water separator does not operate for a period of time what (if any) effects this would cause on the reliability of the unit. Specification of package to include mention of extended periods on downtime. | AECOM | Separator package may need to be run when not required to keep all equipment working properly | Ph.1 | | | |
| 1.4.5 | Temperature - low | Low ambient temperature and infrequent operation. | Freezing of water in small diameter pipework or instrument lines. | Vendor package design | Review potential impacts of winter operation. Include in specification that unit needs to operate during low ambient conditions | AECOM | | Ph.1 | | | |
| 1.4.6 | Maintenance - maintainability | Low flows causing sludge build up in pit. | Difficult to clean thick sludge from pit. | None | Review the operational area of the skimmer pit. Consider sloped floor on main pit to concentrate sludge for ease of cleaning and allow oil/ water to be diluted. | AECOM | | Ph.1 | | | |
| 1.4.7 | Contaminants | Leaks from flanges in package. | Spills of oil to ground. | Slop tank and oily water separator package to be located inside self-bunded concrete apron to catch spills | No action | | | | | | |
| 1.4.8 | Electrical safety | Decomposition of biological material producing H2S in slops tank. | Affect on workers and possible creation of Hazardous area. | None | Ensure vent location is at an adequate height to disperse any hazardous vapours. | AECOM | This isn't expected as this does not occur at Colongra. | Ph.1 | | | |

Table 42 Oily Water Collection & Treatment - Node 1.5

| | | | |
|--|---|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Oily Water Collection and Treatment | Node # | 1.5 |
| Node Boundaries: | Discharge of waste water to Stormwater | Revision Date: | 02-Feb-22 |
| Design Intent: | Discharge of clean water to stormwater | Material / Chemical: | Water / Oil |
| Design Conditions, Operating Envelope | Ambient Conditions | 1 | HPP-AEC-MEC-GN-GEN-DRG-1085 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---------------------|--|--|--|---|-------|----------|-----------|---------------|-------------|---------------|
| 1.5.1 | Loss of containment | Diesel spilling out of vent valve at gas turbine due to valves being left open (operator error). | Diesel / oil being discharged in turbine hall. | All diesel / oil vents should drain to oily water pit. | Review oil and diesel vent points in the GT area to ensure no diesel can flow to the stormwater discharge point. All oil vents to drain to oily water system with concrete apron. | AECOM | | Ph.1 | | | |
| 1.5.2 | Loss of containment | Big rain event during construction. | Potential for sediments to be discharged to environment. | Preliminary earthworks channel and then seal the channel quickly during construction. | Review requirements for capture during construction for containment of drainage carryover. To be reviewed in CHAIR. | AECOM | | Ph.1 | | | |
| 1.5.3 | Loss of containment | Large spill of oil due to mis-operation or failure of equipment. | Potential for oil release to the environment. | Equipment that is filled with oil is connected to the oily water system and has concrete aprons. | No action | | | | | | |

Table 43 Oily Water Collection & Treatment - Overview

| | | | |
|--|--|-----------------------------|----------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Diesel Delivery to Gas Turbines | Node # | OVERVIEW |
| Node Boundaries: | | Revision Date: | 21-Jan-22 |
| Design Intent: | | Material / Chemical: | Natural Gas |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1067/1068 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|----------------------|--|--|---|---|---------------------------------------|----------|------------------------------|---------------|-------------|---------------|
| 1.6.1 | Fire/explosion | Ignition of oil in oily water system | Damage to personnel and plant/ equipment. | May already be considered in fire safety study. | Confirm if oily water system is considered in fire safety study. | AECOM | | Ph.1 | | | |
| 1.6.2 | Fire/explosion | Flame trap maintenance is not frequent enough. | Fire traps not working when required. | Plant maintenance routines and operator checks. | Review the requirement for monitoring of fire traps liquid level and regular maintenance of fire traps. | AECOM | | Ph.1 | | | |
| 1.6.3 | Loss of containment | Concentrated spill of oil flowing to oily water pit. | Large accumulation of oil in decanting tank. | Level instrument in decanting pit. | Review potential to install a smaller initial volume within decanting pit for concentrated spills. Consider interface level detection. Review operational response to a high-level oil in the decanting pit. Review requirement for detection of high-level oils in the observation pit and how this can be achieved. | AECOM SNOWY HYDRO AECOM | | Ph.1 Ph.1 Ph.1 | | | |
| 1.6.4 | Natural hazards | Humeceptor discharge level could be underwater if/when site is flooding . | Stormwater from site might be below flood level. | The flood study showed the site flood level was below site level. | Review location of humeceptor in location to highest flood level. | AECOM | | Ph.1 | | | |
| 1.6.5 | Natural hazards | Embers from bush fire can land oily water pit . | No major consequence likely. Ember unlikely to ignite oily water. | None | No action | | | | | | |
| 1.6.6 | Environmental Impact | Firefighting foam from fire fighting. Large flow of liquids from the site due to storm. | Contaminants being discharged into environment. Large surge of liquid into creek. | None | Seek further guidance from SH environmental team on whether a penstock valve is required on humeceptor discharge line to the environment. | SNOWY HYDRO | | Ph.1 | | | |

Table 44 Trade Waste & Sewer - Node 1.1

| | | | |
|--|--|-----------------------------|--------------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Trade waste | Node # | 1.1 |
| Node Boundaries: | Blade washing effluent and Blade washing Pits on each Power Island | Revision Date: | 03-Feb-22 |
| Design Intent: | Collection tank for blade washing effluent | Material / Chemical: | Water/ Detergent/ Contaminants |
| Design Conditions, Operating Envelope | Ambient condition | Drawing: | HPP-AEC-MEC-GN-GEN-DRG-1087 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------|---|---|---|---|-------|--|-----------|---------------|-------------|---------------|
| 1.1.1 | High flow | Wash water pit sizing too small for peak flow during blade washing. | Pit overflows | none | Confirm final pit volume is sufficient to contain all the flows from blade washing and closed loop cooling water volumes. | AECOM | Evaporative cooler blowdown water currently drains to the neutralisation pit downstream of the blade wash pit. Offline water maximum water volume with detergent is 1.5m3 (without detergent, maximum volume is 1 m3) During on-line washing there is no water drained from the exhaust duct. | Ph.1 | | | |
| 1.1.2 | Temperature - High | Compressor blades are hot when during on-line washing. | No high temperature are expected because on-line wash water will exit via the stack because the water evaporates. | The piping is designed for 60 deg C. MHI waste water list has 35 deg C | No action | | | | | | |
| 1.1.3 | Contaminants | Detergent is used during off line blade washing. | Waste water from blade washing including detergent (high chemical oxygen demand and high iron) might not be suitable for neutralisation pit / sewer connection. | There is the facility for the blade washing water to be removed by truck. | Determine if the blade washing water with detergent can be disposed to the trade waste (HWC criteria for maximum concentration). When detergent is used for off-line blade washing (approx. once a year) the GT compressor wash pit should be isolated and removed by sucker truck. | AECOM | Laverton blade washing pit is not connected to trade waste system and is pumped out by a truck. Blade washing with detergent is likely to be infrequent (once a year). MHI confirmed that detergent is used during off-line blade washing. SH confirmed detergent is used for the best clean to remove residue. The wash water is removed by a truck. Blade washing is a supervised procedure. | Ph.1 | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------|-----------------------|--|--|--|------------------------|----------|------------------|---------------|-------------|---------------|
| | | | | | Test the blade wash water after commissioning to check analysis meets HWC criteria for trade waste. Confirm the iron concentration in wash water. Is 220 mg/l the normal concentration during off line washing? | SNOWY HYDRO MHI | | Ph.3 Ph.1 | | | |
| 1.1.4 | Contaminants | Stagnant water in pit | Algae growth. No major consequence expected. | Pit will not have water in it very often | No action | | | | | | |

Table 45 Trade Waste & Sewer - Node 1.2

| | | | |
|--|--|-----------------------------|--|
| Project / Facility: | 60666845 Hunter Valley Power Station - Trade waste | Node # | 1.2 |
| Node Boundaries: | Blade washing effluent Neutralisation Pit and discharge to trade waste | Revision Date: | 03-Feb-22 |
| Design Intent: | pH adjustment for blade washing and demin effluent | Material / Chemical: | Water/ Detergent/ Contaminants |
| Design Conditions, Operating Envelope | Ambient condition | Drawing: | HPP-AEC-MEC-GN-GEN-DRG-1087, HPP-AEC-MEC-GN-GEN-DRG-1123 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-----------|---|---|---|---|-------|--|-----------|---------------|-------------|---------------|
| 1.2.1 | High flow | HW limitations on connection to trade waste | Neutralisation pit will not have the ability to pump out at all times | The neutralisation pit is sized to retain 2 hrs of flow capacity. | Review the neutralisation pit capacity to cater for emergency storage in the event of not having access to pump out to the trade waste. | AECOM | Maximum pump out rate maybe 17 LPS (61 m3/h) to existing 60-year-old rising main. There was an earlier pump station that was at 17 LPS pumping rate. Expected flow rate from the PS is 6 -8 LPS (25-28 m3/h). Pump out rate should be approximately 1.5 times the production rate. In future there will be a new pressurised shared sewer main (several years in the future). | Ph.1 | | | |
| 1.2.2 | High flow | Rain water collection in pit. | Potential to overflow the neutralisation pit. | Shelter over pit. | No action | | If there is no cover water can be used for dilution, however discharge to TW will be charged by volume. | | | | |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|-----------------------------|--|--|--|---|-------|--|-----------|---------------|-------------|---------------|
| 1.2.3 | Level high | Transfer pumps stop operating OR SDV downstream of pumps closed. | Overflow of water from pit. | High level alarm | No action | | | | | | |
| 1.2.4 | Temperature | Ambient temperatures. | No consequence | | | | | | | | |
| 1.2.5 | Contaminants | Clean in Place chemicals used in demin plant. (Citric Acid, Ethylene diamine tetra Acetic acid, Potassium Hydroxide). | Possible chemical interactions. | Quantities will be small in volume. | Confirm the impacts of chemicals used in demin plant CIP to neutralisation pit Confirm if the concentration of COD from the CIP chemicals from the demin plant will be suitable for discharge to trade waste or whether removal by tanker is more appropriate. | AECOM | Volumes of CIP water is likely to be small (1-2 m3). HW may sample the waste from time to time Trade Waste limit on COD is 1500 mg/L. | Ph.1 | | | |
| 1.2.6 | High pressure | Overpressure of the old HWC trade waste main. | Damage to the trade waste main. | Local pressure indicator downstream of transfer pumps. | Replace local PI with pressure transmitter downstream of transfer pumps to prove there is no damage to HWC trade waste main from the transfer pump. Review best location for this PT to measure discharge pressure. | AECOM | | Ph.1 | | | |
| 1.2.7 | Instruments and controls | Valves failure action. | Accidentally discharging from neutralisation pit to trade waste caused by valve failure. | Detailed design. | SDV's downstream of the transfer pumps to HWC line to fail closed. SDV's downstream of the transfer pumps returning to pit fail open to prevent dead heading of pump. | AECOM | During discharge to the trade waste both valves can be open to maintain circulation | Ph.1 | | | |
| 1.2.8 | Maintenance - accessibility | Pump removal for maintenance. | A roof will make pump removal more difficult. | Detailed design. | Consider removal of pump with a roof above the pit | AECOM | | Ph.1 | | | |
| 1.2.9 | Concentration of chemicals | Acid and caustic dosing. | Damage to materials of construction. | Design will consider pH and materials of pit. | Materials of pit to consider acid and caustic dosing. (Epoxy coating). | AECOM | | Ph.1 | | | |
| 1.2.10 | Concentration of chemicals | Acid and caustic dosing location too close to pump suction | High concentration of acid or caustic is discharge water | Location of dosing and pump suction. | Ensure dosing of acid and caustic is located at opposite end of pump suction and adequate recirculation time to ensure good mixing of neutralisation chemicals. | AECOM | | Ph.1 | | | |

Table 46 Trade Waste & Sewer - Node 1.3

| | | | |
|--|--|-----------------------------|--|
| Project / Facility: | 60666845 Hunter Valley Power Station - Trade waste | Node # | 1.3 |
| Node Boundaries: | Acid/caustic injection packages | Revision Date: | 03-Feb-22 |
| Design Intent: | dosing of acid and caustic to neutralisation pit | Material / Chemical: | acid, caustic |
| Design Conditions, Operating Envelope | Ambient condition | Drawing: | HPP-AEC-MEC-GN-GEN-DRG-1128, HPP-AEC-MEC-GN-GEN-DRG-1088 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|----------------------|---|---|--|--|-------|----------|-----------|---------------|-------------|---------------|
| 1.3.1 | High flow | Pump fault e.g. pump left running. | Chemical tank emptied in short time. | none | Include either an alarm for continual operation of the pump (or too frequent operation) or investigate other solutions to reduce overdosing (Review requirement for two pH meters for checking that pH is moving in the expected direction). | AECOM | | Ph.1 | | | |
| 1.3.2 | Temperature - low | Low ambient temperature. | Potential for freezing of caustic at 2 deg C in small diameter lines. | Vendor package - design | Chemicals to be dosed are TBC. If caustic is used potential for freezing in lines needs to be considered. Include in the package specification the range of ambient temperature. | AECOM | | Ph.1 | | | |
| 1.3.3 | Loss of containment | Overfilling of tanks, physical damage to tanks, leaks from flanges. | Spilling of chemicals to the bund. | Spills contained within the bund with separate bunds for acid and caustic to prevent chemical reaction. Drain to neutralisation pit. | No action | | | | | | |
| 1.3.4 | Maintenance | Decanting of acid/caustic to refill dosing drum. | Chemical burn to personnel when decanting chemicals. | Wearing PPE | Review the replacement process for the chemicals (tank or drum) and if minimal contact with the chemical for the operator. | AECOM | | Ph.2 | | | |
| 1.3.5 | Maintenance - access | Accessibility to pumps for maintenance. | Unable to maintain pumps and interruption to dosing | Pumps are small and easily accessible/removeable | No action | | | | | | |
| 1.3.6 | Maintenance | Calibration of equipment. | Incorrect acid/caustic dosage. | Requirement of calibration equipment (flow tube or calibration cylinder) should be included in chemical injection package specification. | No action | | | | | | |
| 1.3.7 | Flow- Low | Vapour locking in line due to HCL vaporisation. | Vapour locking and inability to dose. | Vendor package - design | Consider the type of acid and potential to vaporise. Dilute sulphuric acid is preferred. | AECOM | | Ph.1 | | | |
| 1.3.8 | Flow - Low | PSV opens and stays open. | Dosing of acid/caustic too low. | Vendor package - design | FS is sometimes included in the line downstream of the PSV to indicate the PSV has lifted. Check the vendor package includes this. | AECOM | | Ph.1 | | | |

Table 47 Trade Waste & Sewer - Node 1.4

| | | | |
|--|--|-----------------------------|-----------------------------|
| Project / Facility: | 60666845 Hunter Valley Power Station - Sewer | Node # | 1.4 |
| Node Boundaries: | Sewer Collection | Revision Date: | 03-Feb-22 |
| Design Intent: | Collection tank for sewer and pump out | Material / Chemical: | Sewer waste |
| Design Conditions, Operating Envelope | Ambient condition | Drawing: | HPP-AEC-MEC-GN-GEN-DRG-1086 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|--------------------------|--|--|--|--|-------|--|-----------|---------------|-------------|---------------|
| 1.4.1 | High flow | Large number of people on site with large amounts of water being used in office and workshop and discharge to sewer. | Overflow | The sewage pit is sized for maximum flowrate. The capacity is 5000 L with a 10,000 L overflow. | No action | | Peak flow is proportional to the number of fixtures. There is an overflow tank included in the onsite sewage system. A pump with a steep curve is usually selected so when capacity to pump out is available the pump will be operating on circulation and then pump out to the trade waste system. | | | | |
| 1.4.2 | Reverse flow | Higher pressure in HWC sewer main header than pump outlet. | Reverse flow from the trade waste to the sewer pit. | NRV on outlet of the pumps and at the boundary kit. | No action | | | | | | |
| 1.4.3 | Contaminants | Oil poured down kitchen sinks to sewer. | Unlikely to occur as cooking is not expected to be done on site. | none | No action | | | | | | |
| 1.4.4 | Maintenance | A GT scheduled outage may increase people on site and the need for extra toilets. | Not sufficient toilets for personnel on site. | none | Consider providing a sewer connection in temporary offices/facilities area. Review potential to use temporary toilet blocks on site. | AECOM | Portable toilets are not preferred by SH because of industrial relations issues. Maximum number of people on site is expected to be 50 during a scheduled outage. | Ph.1 | | | |
| 1.4.5 | Instruments and controls | High/low level alarm activated. | No one aware of high/low level in pit. | none | Alarms from sewerage pit to DCS so operators are aware of high/low level in sewerage pit when no one on site | AECOM | | Ph.1 | | | |
| 1.4.6 | Maintenance | Pump maintenance. | Inability to maintain pumps. | Pumps can be lifted out | No action | | | | | | |
| 1.4.7 | Flow - Low | Low flow of water through the system. | Generation of odour from the tank. | Vent to safe location. | Consider odour from the tank and a filter. | AECOM | Note: Usually filters are used on larger municipal facilities. | Ph.1 | | | |


Table 48 Trade Waste & Sewer - Overview

| | | | |
|--|--|-----------------------------|----------------------------------|
| Project / Facility: | 6066845 Hunter Valley Power Station - Trade Waste -Sewer | Node # | Overview Trade waste and Sewer |
| Node Boundaries: | | Revision Date: | 03-Feb-22 |
| Design Intent: | | Material / Chemical: | Sewer waste |
| Design Conditions, Operating Envelope | Design assumes ambient conditions | Drawing: | HPP-AEC-MEC-DS-LLS-DRG-1067/1068 |

| Ref No: | Guideword | Possible Cause | Possible Consequence | Existing Mitigation | Recommendations | Owner | Comments | Action by | Date complete | Verified By | Action Status |
|---------|---|--|--|--|---|-------|----------|-----------|---------------|-------------|---------------|
| 1.5.1 | Materials of construction - pumps, valves | Pumps/valves materials incompatible with chemicals used. | Corrosion of pumps. | Appropriate materials of construction listed in specifications (especially with acid and caustic) | No action | | | | | | |
| 1.5.2 | Utilities and services | Service water is a long distance from sewage pit. | Difficulties get service water to sewage pit. | none | Review application of flushing water to the pit and potential to use potable water and a garden hose | AECOM | | Ph.1 | | | |
| 1.5.3 | Physical damage | Vehicle collision with equipment. | Damage to dosing pumps. | None of the pits and associated equipment are directly adjacent to roads within site. Pits have raised edges. | No action | | | | | | |
| 1.5.4 | Environmental impact - noise | Sewer pumps could be noisy and close to boundary. | Noise pollution and impact on neighbours. Industrial area. | Noise limits to be included in package specs | Confirm noise limits included in the package specifications | AECOM | | Ph.1 | | | |
| 1.5.5 | Safety systems | Safety shower location. | Too long to reach safety shower. | none | Ensure safety shower is no further than 10 m from chemical storage if dosing chemicals are being decanted | AECOM | | Ph.1 | | | |

Appendix B

Diesel System P&IDs
Showing Nodes Applied
in the HAZOP




NOTES:
 1. ALL SAMPLE RETURN AND DRAINS WILL BE COLLECTED IN THE IBC TANK AND WILL BE TRANSFERRED TO STORAGE TANK OR REMOVED BY VACUUM TRUCK FROM SITE DEPENDS ON QUALITY.

HOLDS:
 1. DETAIL INSIDE THE PACKAGE IS INDICATIVE ONLY AND WILL BE FINALIZED BY SUPPLIER.
 2. ALL PSV AND TRV SET PRESSURE WILL BE FINALISED LATER.
 3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | |
|----------------------------|--|--|-----------------|-----------------|---|
| THIS DRG SUPPLIED BY | | | DRAWN | DRAWING CHECKED | |
| AECOM | | | CAR | BVA | |
| AECOM Australia Pty Ltd | | | 14.01.2022 | 14.01.2022 | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM DIESEL FUEL UNIT - LOADING SYSTEM |
| DRAWING No. | | | DESIGNED | DESIGN CHECKED | |
| HPP-AG-MEC-05-LLS-DRG-1004 | | | 14.01.2022 | KW | 14.01.2022 |
| REV: B | | | SCALE | APPROVED | |
| | | | WORK ORDER No. | CDT | |
| | | | 14.01.2022 | | |
| | | | SECTION No./KKS | A1 | SHEET |
| | | | EDA | SIZE | B SH 1 OF 1 |



NOTES:
 1. TROLLEY SKID TO BE PROVIDED FOR UNLOADING HOSES.
 2. OILY WATER DRAIN VALVE IS NORMALLY OPEN, HOWEVER SHOULD BE KEPT CLOSED DURING TANKER LOADING/ UNLOADING.

HOLDS:
 1. ALL PSV AND TRV SET POINT ARE HOLD AND WILL BE FINALISED LATER.
 2. PUMP CAPACITY AND HEAD WILL BE FINALIZED AFTER FINALIZING THE PIPE ROUTES AND 3D MODEL.
 3. THE USE OF **WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|------------|--------------------|
| B | AECOM | 14.01.2022 | ISSUED FOR HAZOP |
| A | AECOM | 30.11.21 | 30% CONCEPT DESIGN |

THIS DRG SUPPLIED BY
AECOM
 AECOM Australia Pty Ltd
 DRAWING No.
 HPP-AEC-MED-BS-LLS-DRG-1000
 REV: B


| DRANN | DESIGNED | SCALE | SECTION No/NO |
|------------|------------|-------|---------------|
| 14.01.2022 | 14.01.2022 | 1:1 | E01 |

| DRAWING CHECKED | DESIGN CHECKED | APPROVED | CDT |
|-----------------|----------------|----------|------------|
| 14.01.2022 | 14.01.2022 | KW | 14.01.2022 |

HUNTER POWER STATION
 PIPING & INSTRUMENTATION DIAGRAM
 DIESEL FUEL UNIT - UNLOADING SYSTEM

B | SH 1 OF 1





**NODE 4 &
NODE 5**

NOTES:


1. FLOW SWITCH WILL STOP THE PUMP IN CASE OF ACTIVATION WITH TIME DELAY.

HOLDS:

1. PUMP CAPACITY WAND HEAD WILL BE FINALIZED AFTER FINALIZING PIPE ROUTES AND 3D MODEL.
2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
5. ALL PSV AND TRV SET POINTS AND SIZES ARE ON HOLD AND WILL BE FINALIZED LATER.

**ISSUED FOR
INFORMATION ONLY**

| REV | NAME | DATE | DESCRIPTION | THIS DRG SUPPLIED BY | DRAWN | DRAWING CHECKED | |
|-----|-------|------------|--------------------|-------------------------|---------------|-----------------|---|
| | | | | AECOM | LAF | BVA | |
| | | | | AECOM Australia Pty Ltd | 14.01.2022 | 14.01.2022 | |
| B | AECOM | 14.01.2022 | ISSUED FOR HAZOP | | DESIGNED | DESIGN CHECKED | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM DIESEL FUEL UNIT – FORWARDING PUMPS |
| A | AECOM | 20.11.21 | 30% CONCEPT DESIGN | | 14.01.2022 | 14.01.2022 | |
| | | | | REV: B | SCALE | APPROVED | |
| | | | | | WORK ORDER No | CDT | |
| | | | | | SECTION No/NO | 14.01.2022 | |
| | | | | | EDC | A1 | SHEET |
| | | | | | | SIZE | |
| | | | | | | | B SH 1 OF 1 |




- NOTES:**
1. PUMPS SEQUENCING SYSTEM WILL BE BASED ON SUPPLY LINE PRESSURE AND FLOW, LOW PRESSURE OR HIGH FLOW WILL START THE NEXT PUMP.
- HOLDS:**
1. DETAIL INSIDE THE PACKAGE IS INDICATIVE ONLY AND WILL BE FINALIZED BY SUPPLIER.
 2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
 5. ALL PSV AND TRV SET PRESSURES ARE HOLD AND WILL BE FINALISED LATER.

ISSUED FOR INFORMATION ONLY


| REV | NAME | DATE | DESCRIPTION | THIS DRG SHIPPED BY | SCALE | SECTION No/MAX EGT | GRAPHIC CHECKED | APPROVED | DATE | CDT | SHEET | SIZE |
|-----|-------|----------|--------------------|-------------------------|-------|--------------------|-----------------|----------|------------|-----|-------|------|
| B | AECOM | 14.01.22 | ISSUED FOR HAZOP | AECOM Australia Pty Ltd | 1:1 | | BVA | | 14.01.2022 | | A1 | 82E |
| A | AECOM | 30.11.21 | 30% CONCEPT DESIGN | | | | KW | | 14.01.2022 | | | |

HUNTER POWER STATION
 PIPING & INSTRUMENTATION DIAGRAM
 DIESEL FUEL UNIT - POLISHING & FORWARDING FILTERS

SH 1 OF 1



90EGB01BR002
 DIESEL FUEL STORAGE TANK
 NOMINAL CAPACITY: 2121 m³
 WORKING CAPACITY: 1845 m³
 DIMENSION: 1D15m x H12m
 OP. PRESSURE: ATM+FOL



- HOLDS:**
1. ALL TRV SET POINTS ARE HOLD AND WILL BE FINALIZED LATER.
 2. TANK EMERGENCY AND FREE VENT SIZES TO BE VERIFIED AND CONFIRMED BY TANK MANUFACTURER.
 3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

- NOTES:**
1. DIESEL TO GTG TO BE SUPPLIED FROM FLOATING SUCTION AND FOR PUSHING TO BE SUPPLIED FROM TANK BOTTOM, ONLY ONE OF OUTLET VALVE TO BE OPEN AT THE TIME.
 2. RETURN AND INLET LINE TO BE INSTALLED BELOW TANK LOW LOW LEVEL.
 3. LSHH WILL CLOSE BOTH VALVES IN INLET AND RETURN LINES AND WILL STOP THE UNLOADING RUNNING PUMPS.
 4. LSLI WILL CLOSE THE OUTLET LINE VALVES AND STOP THE FORWARDING PUMPS.
 5. FREE VENT WITH FLAME ARRESTOR.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|------------|--------------------|
| B | AECOM | 14.01.2022 | ISSUED FOR HAZOP |
| A | AECOM | 30.11.21 | 30% CONCEPT DESIGN |

THIS DRG SUPPLIED BY
AECOM
 AECOM Australia Pty Ltd
 DRAWING No. HPP-AEC-REC-DS-STG-DRG-1066
 REV: B

| SECTION No/REV | DATE | SIZE |
|----------------|------------|------|
| E01 / E02 | 14.01.2022 | A1 |


DRAWN LAF 14.01.2022
 DESIGNED JD 14.01.2022
 SCALE
 WORK ORDER No
 APPROVED GDT 14.01.2022
 DRAWING CHECKED BVA 14.01.2022
 DESIGN CHECKED KW 14.01.2022



HUNTER POWER STATION
 PIPING & INSTRUMENTATION DIAGRAM
 DIESEL FACILITY - DIESEL STORAGE TANKS

Appendix C

Natural Gas P&IDs
Showing Nodes Applied
in the HAZOP




- HOLDS:**
- RV XXX SET PRESSURE AND INLET AND OUTLET LINE SIZE TBC

- NOTES:**
- REMOVABLE PIPE SPOOL FOR POSITIVE ISOLATION.
 - THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 - THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 - KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | DATE | DESCRIPTION | THIS DRG SUPPLIED BY | BRAWN | DRAWING CHECKED | snowyhydro LIMITED |
|-----|------------|--------------------|--|-------------------------|---------------------|--------------------|
| B | 16/01/2022 | ISSUED FOR HAZOP | AECOM AECOM Australia Pty Ltd | 16/01/2022 | 16/01/2022 | |
| A | 15/11/21 | 30% CONCEPT DESIGN | DRAWING No. HPP-AEC-MEC-GA-K00-DRG-1090 | 16/01/2022 | 16/01/2022 | |
| REV | NAME | DATE | DESCRIPTION | SCALE WORK ORDER No. | APPROVED CDT | |
| | | | | SECTION No/KKS DRG | A1 SHEET SIZE | B SH 1 OF 1 |




- HOLDS:**
- RELIEF VALVE SET PRESSURE TO BE CONFIRMED

- NOTES:**
- DAVIT FOR LID REMOVAL
 - THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED
 - THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 90% SUBMISSION
 - IKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED
 - MANUAL BYPASS GLOBE VALVE TO HAVE A MAXIMUM CV NOT TO EXCEED THE CONTROL VALVE CV FULLY OPEN
IN CASE THE CONTROL VALVE HAS AN INTERNAL STOP THE GLOBE VALVE CV WILL NOT EXCEED THE RESTRICTED CV FOR THE CONTROL VALVE
 - DBB UP AND DOWNSTREAM OF ESO TO ALLOW REPLACEMENT

ISSUED FOR INFORMATION ONLY

| | | | | | | |
|---|------|----------|--------------------|---|---|---|
| THIS ORG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No: HPP-AEC-MET-GA-FCS-ORG-091 REV: B | | | | DRAWN: 14.01.2022 DESIGNED: 14.01.2022 SCALE: WORK ORDER No SECTION No/NO OF DWS: A1 | DRAWING CHECKED: 14.01.2022 DESIGN CHECKED: 14.01.2022 APPROVED: 14.01.2022 SHEET SIZE: A1 | snowyhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM NATURAL GAS SUPPLY - NATURAL GAS FILTER COALESCER FOR GAS TURBINE UNIT 1 |
| REV | NO | DATE | DESCRIPTION | | | |
| B | ADDN | 14.01.22 | ISSUED FOR HAZOP | | | |
| A | ADDN | 09.11.21 | IKS CONCEPT DESIGN | | | |




- HOLDS:**
- 1 SET PRESSURE TO BE CONFIRMED
 - 2 RELIEF VALVE SET PRESSURE TO BE CONFIRMED

- NOTES:**
1. DAVIT FOR LID REMOVAL.
 2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
 5. MANUAL BYPASS GLOBE VALVE TO HAVE A MAXIMUM CV NOT TO EXCEED THE CONTROL VALVE CV (FULLY OPEN). IN CASE THE CONTROL VALVE HAS AN INTERNAL STOP THE GLOBE VALVE CV WILL NOT EXCEED THE RESTRICTED CV FOR THE CONTROL VALVE
 6. DBB UP AND DOWNSTREAM OF ESD TO ALLOW REPLACEMENT

ISSUED FOR INFORMATION ONLY

| | | | | |
|--|--|--|--|--|
| THIS DRS SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No HPP-AEC-ME-GA-RS-DRG-0192 REV: B | | DRAWN 14.01.2022 DESIGNED 14.01.2022 SCALE WORK ORDER No SECTION No/REV ENG | DRAWING CHECKED DVA 14.01.2022 DESIGN CHECKED RW 14.01.2022 APPROVED CUT 14.01.2022 SHEET SIZE A1 | snowyhydro LIMITED HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM NATURAL GAS SUPPLY - NATURAL GAS FILTER COALESCER FOR GAS TURBINE UNIT 1 B SH 1 OF 1 |
|--|--|--|--|--|



NODE 6

HOLDS:
1 STACK HEIGHT AND DIAMETER TO BE FINALISED DEPENDING ON LARGEST RELIEF VALVE FLOWRATE


NOTES:
1 DRIPS TANK WILL BE ABOVE GROUND (TBC)
2 THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
3 THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
4 MKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 14.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 08.11.21 | 30% CONCEPT DESIGN |

| | | |
|---|--|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-GA-DTV-086-1093 REV. B | DRAWN 14.01.2022 DESIGNED 14.01.2022 SCALE WORK ORDER No. 14.01.2022 | DRAWING CHECKED BVA 14.01.2022 DESIGN CHECKED RW 14.01.2022 APPROVED CDT 14.01.2022 |
|---|--|---|

| | |
|--|------------------|
| snowyhydro <small>LIMITED</small> | |
| HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM NATURAL GAS SUPPLY - DRIPS TANKS AND VENT GAS TURBINE 1 | |
| SECTION No/MS DRG | A1 SHEET SIZE |
| B 1 SH 1 OF 1 | |




HOLDS:
1 RV XXXX SET PRESSURE TBC BY MH

- NOTES:
1. PIPING MATERIAL AND THICKNESS SHALL BE DETERMINED BY EPC IN CONSIDERATION OF H₂S CONTENT IN FUEL GAS
 2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED
 3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED
 5. EQUIPMENT IN VENDOR PACKAGE WILL BE DETERMINED AND SUPPLIED BY SUPPLIER.

ISSUED FOR INFORMATION ONLY

| | | | | | | | | |
|-----|-------|----------|--------------------|--|--|---|------------------------------|--|
| | | | | THIS DPG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No: HPP-AEC-MEC-GA-GDI-DRG-1094 REV: B | DRAWN RS 14.01.2022 DESIGNED JD 14.01.2022 SCALE WORK ORDER No: | DRAWING CHECKED DW 14.01.2022 DESIGN CHECKED BWT 14.01.2022 APPROVED CDT 14.01.2022 | snowyhydro LIMITED | |
| REV | NAME | DATE | DESCRIPTION | | | | | |
| B | ALDPM | 14.01.22 | ISSUED FOR HAZOP | | | | | |
| A | ALDPM | 08.01.21 | PRELIMINARY DESIGN | | | | | |
| | | | | SECTION No/PAGES ENG / GRA | A1 | SHEET SIZE | B SH 1 OF 1 | |



NODE 5

11.31 MEC-GA-GEN-1027
NATURAL GAS FROM GT FUEL
GAS CARTRIDGE FILTER

SERVICE AIR


GT FUEL GAS NOZZLE
PURGE AIR SUPPLY FILTER

NOTES

- 1. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED
- 2. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
- 3. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED
- 4. SHORT SPOOL FOR CLEANING OF PIPING.

**ISSUED FOR
INFORMATION ONLY**

| | | | | | | |
|---|------|------|-------------|------------------------------|-------------------------------------|--|
| THIS DRS SUPPLIED BY AECOM AECOM Australia Pty Ltd | | | | DRAWN RS 14.01.2022 | DRAWING CHECKED DW 14.01.2022 | |
| DRAWING No: HPP-AEC-MEC-GA-GEN-1025 | | | | DESIGNED JD 14.01.2022 | DESIGN CHECKED SWT 14.01.2022 | |
| REV: B | | | | SCALE: WORK ORDER No. | APPROVED CDT 14.01.2022 | NATURAL GAS SUPPLY - TURBINE SUPPLY UNIT FOR GAS TURBINE UNIT 1 |
| REV | NAME | DATE | DESCRIPTION | SECTION NAME/NO ENG / QFB | A1 | SHEET SIZE |




NODE 1

NOTES:

1. MINIMISE LENGTH OF LINE BETWEEN FUEL GAS CALORIC METER AND MAIN LINE.
2. ** WILL BE USED AS A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | | | | | | |
|-----|------|---------------------------|-------------|-----------------|---------------|-----------------|----|---|-----------|--|
| | | THIS DRG SUPPLIED BY | | DRAWN | | DRAWING CHECKED | | | | |
| | | AECOM | | M.B. | | D.W. | | | | |
| | | AECOM Australia Pty Ltd | | 14.01.2022 | | 14.01.2022 | | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM NATURAL GAS SUPPLY CALORIE METER AND POWER STATION BATTERY LIMIT | | |
| | | DRAWING No. | | SCALE | | APPROVED | | | | |
| | | 1FP-AEC-ME-GA-GDI-DRG-10% | | WORK ORDER No. | | C.D.T. | | | | |
| | | REV: B | | SECTION No/PAGE | | A1 | | | | |
| REV | NAME | DATE | DESCRIPTION | | SHEET No/PAGE | | A1 | | SH 1 OF 1 | |



HOLDS

NOTES:

1. THIS PIPING ARRANGEMENT SHALL BE DRAWN BY AECOM AND INSTALLED BY CONSTRUCTION CONTRACTOR
2. FLANGED CONNECTION SHALL BE PROVIDED FOR PIPE CLEANING
3. SHORT SPOOL FOR CLEANING OF PIPE
4. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
5. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
6. KNS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED
7. REMOVABLE SPOOL FROM INSTALLATION OF TEMPORARY COMMISSIONING FILTER.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 14.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 08.01.21 | MIN CONCEPT DESIGN |

THIS DRG SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No: HPP-AEC-MEC-GA-GCN-1095
REV: B

| DRAWN | DESIGNED | SCALE | SECTION No/PAGES |
|------------|------------|-------|------------------|
| ME | ME | SCALE | MEP |
| 14.01.2022 | 14.01.2022 | | |
| 14.01.2022 | 14.01.2022 | | |
| 14.01.2022 | 14.01.2022 | | |

| DRAWING CHECKED | DESIGN DEGREE | APPROVED | SHEET SIZE |
|-----------------|---------------|------------|------------|
| BWT | BMT | CBT | A1 |
| 14.01.2022 | 14.01.2022 | 14.01.2022 | |
| 14.01.2022 | 14.01.2022 | 14.01.2022 | |




HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
NATURAL GAS SUPPLY - NATURAL GAS CARTRIDGE FILTER
AND ISOLATION FOR GAS TURBINE UNIT 1

B | SH 1 OF 1

Appendix D

Instrument Air System
P&IDs Showing Nodes
Applied in the HAZOP



NOTES:


- TWO CENTRIFUGAL COMPRESSOR PACKAGES ARE REQUIRED FOR THE PROJECT. IN NORMAL OPERATION ONE IS IN SERVICE (DUTY) AND THE SECOND ONE IS STAND-BY.

HOLDS:

- DESIGN CAPACITY AND OPERATING PRESSURE TO BE DETERMINED.
- DETAIL INSIDE PACKAGES IS SCHEMATIC ONLY. DETAIL DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT.
- SUITABLE PRESSURE CONTROL METHOD SHALL BE FINALISED DURING DETAIL DESIGN BY VENDOR.
- SIZE OF INSTRUMENT AIR LINES FOR AIR COMPRESSOR PACKAGE WILL BE FINALIZED IN DETAIL DESIGN AFTER RECEIVING VENDOR DATA.
- THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
- THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
- KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | |
|---|----------------|---|---|--|
| THIS DGS SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-IP-IAS-DRG-1061 | | DRAWN: BPP 30.11.2021 DESIGNED: KW 30.11.2021 SCALE: WORK ORDER No. SECTION No./PKS: 0FB | DRAWING CHECKED: BVA 30.11.2021 DESIGN CHECKED: BWT 30.11.2021 APPROVED CUT: 30.11.2021 SHEET SIZE: A1 | snowyhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM INSTRUMENT AIR UNIT - AIR COMPRESSORS |
| REV: B | DATE: 27.01.22 | DESCRIPTION: ISSUED FOR HAZOP | REV: B | |
| REV: A | DATE: 08.11.21 | DESCRIPTION: 30% CONCEPT DESIGN | | |
| REV: NAME | DATE | DESCRIPTION | | |



NOTES:


- TWO CENTRIFUGAL COMPRESSOR PACKAGES ARE REQUIRED FOR THE PROJECT. IN NORMAL OPERATION ONE IS IN SERVICE (DUTY) AND THE SECOND ONE IS STAND-BY.

HOLDS:

- DESIGN CAPACITY AND OPERATING PRESSURE TO BE DETERMINED
- DETAIL INSIDE PACKAGES IS SCHEMATIC ONLY. DETAIL DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT
- SUITABLE PRESSURE CONTROL METHOD SHALL BE FINALISED DURING DETAIL DESIGN BY VENDOR.
- SIZE OF INSTRUMENT AIR LINES FOR AIR COMPRESSOR PACKAGE WILL BE FINALIZED IN DETAIL DESIGN AFTER RECEIVING VENDOR DATA.
- THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
- THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
- KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | | | | | |
|--|------|----------------------------|-------------------------------|------------------------|--------------------------------------|-------------------------------------|-------------------------------|---|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No: HPP-AEC-MEC-IP-IAS-DRG-11B REV B | | DRAWN RPP 30.11.2021 | DESIGNED RWT 30.11.2021 | SCALE WORK ORDER No | DRAWING CHECKED BYA 30.11.2021 | DESIGN CHECKED RWT 30.11.2021 | APPROVED CDT 30.11.2021 | snowyhydro <small>POWER</small> | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM INSTRUMENT AIR UNIT - AIR COMPRESSORS |
| REV | NAME | DATE | DESCRIPTION | SECTION NO/NO'S 0/0 | A1 | SHEET SIZE | B | | |




NOTES:
1. PIPING BETWEEN THE COMPRESSOR DISCHARGE AND DRYER INLET SHALL HAVE AUTOMATIC CONDENSATE DRAINING FACILITIES AT ALL LOW POINTS.

HOLDS:
1. CAPACITY IS BASED ON PRODUCED INSTRUMENT AIR. PRELIMINARY DATA FOR THE CAPACITY TO BE CONFIRMED BY VENDOR.
2. DETAIL INSIDE THE PACKAGES IS SCHEMATIC ONLY. DETAIL DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT.
3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | |
|---|-------|---|---|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING NO. HPP-AEC-MEL-CP-IAS-DRG-1061 | | DRAWN LAF 30.11.2021 DESIGNED KW 30.11.2021 SCALE WORK ORDER NO. APPROVED LST 30.11.2021 SECTION NUMBER A1 SHEET SIZE A1 | DRAWING CHECKED BVA 30.11.2021 DESIGN CHECKED BWT 30.11.2021 APPROVED LST 30.11.2021 SHEET SIZE A1 | snowyhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM INSTRUMENT AIR UNIT - AIR DRYERS |
| REV | NAME | DATE | DESCRIPTION | |
| B | AECOM | 27.01.22 | ISSUED FOR HAZOP | |
| A | AECOM | 08.11.21 | REV CONCEPT DESIGN | |



NOTES:

1. PIPING BETWEEN THE COMPRESSOR DISCHARGE AND DRYER INLET SHALL HAVE AUTOMATIC CONDENSATE DRAINING FACILITIES AT ALL LOW POINTS.

HOLDS:


1. CAPACITY IS BASED ON PRODUCED INSTRUMENT AIR. PRELIMINARY DATA FOR THE CAPACITY TO BE CONFIRMED BY VENDOR.
2. DETAIL INSIDE THE PACKAGES IS SCHEMATIC ONLY. DETAIL DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT.
3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 21.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 08.11.21 | 30% CONCEPT DESIGN |

| | | | |
|---|--|------------------------------|--------------------------------------|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd | | DRAWN LAF 30.11.2021 | DRAWING CHECKED BVA 30.11.2021 |
| DRAWING No. HPP-AEC-MEC-CP-IAS-ORG-1020 | | DESIGNED KW 30.11.2021 | DESIGN CHECKED BWT 30.11.2021 |
| REV: B | | SCALE WORK ORDER No. | APPROVED CDT 30.11.2021 |
| | | SECTION No/PKS 0PB | SHEET A1 SIZE |

| | |
|--|-----------|
| snowyhydro <small>UNITED</small> | |
| HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM INSTRUMENT AIR UNIT - AIR DRYERS | |
| B | SH 2 OF 2 |



- NOTES:**
1. TO BE LOCATED ON BOP.
 2. TO BE LOCATED ON POWER ISLAND 1.
 3. TO BE LOCATED ON POWER ISLAND 2.
 4. FLOW ORIFICE TYPE FLOW METER.
 5. LOW LOW PRESSURE ALARM TO INITIATE BOTH GT% SHUTDOWN AND CLOSE THE NG SUPPLY SDV.
 6. LOW LOW PRESSURE ALARM TO INITIATE POWER ISLAND 1 SHUTDOWN.
 7. LOW LOW PRESSURE ALARM TO INITIATE POWER ISLAND 2 SHUTDOWN.


- HOLDS:**
1. SIZE OF PSV WILL BE FINALIZED IN DETAIL DESIGN AFTER RECEIVING VENDOR DATA FOR COMPRESSOR PACKAGE.
 2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | RECEN | 27.03.22 | ISSUED FOR HAZOP |
| A | RECEN | 28.11.21 | 30% CONCEPT DESIGN |

| | | |
|----------------------|--|---------------------------|
| THIS DRG SUPPLIED BY | | |
| DRAWING No | | HPP-4EC-MEL-IP-WS-URS-042 |

| | | |
|--|---|---------------|
| DRAWN LAF 28.11.2021 DESIGNED KW 30.11.2021 SCALE WORK ORDER No SECTION No/PKGS 0FB | DRAWING CHECKED SVA 28.11.2021 DESIGN CHECKED DWT 28.11.2021 APPROVED CBT 28.11.2021 SHEET SIZE A1 | |
| HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM INSTRUMENT AIR UNIT - AIR RECEIVERS | | B SH 1 OF 1 |



NOTES:
 1. HEADER DEAD LEG TO BE CLOSED TO LAST TAKE OFF TO PREVENT DEAD LEG IN THE SYSTEM.

HOLDS:
 1. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 2. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 3. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
 4. PRESSURE REGULATOR SET PRESSURE TO BE CONFIRMED.
 5. PRESSURE RELIEF VALVE SET PRESSURE TO BE CONFIRMED.

ISSUED FOR INFORMATION ONLY


| | | | | | |
|----------------------------|--|-----------------|--|-----------------|--|
| THIS DRG SUPPLIED BY | | DRAWN | | DRAWING CHECKED | |
| AECOM | | SR | | DVA | |
| AECOM Australia Pty Ltd | | 30.11.2021 | | 30.11.2021 | |
| DRAWING No | | DESIGNED | | DESIGN CHECKED | |
| HPP-AE-MEC-CP-IAS-DRG-1063 | | RW | | RW1 | |
| REV B | | 30.11.2021 | | 30.11.2021 | |
| REV NAME | | SCALE | | APPROVED | |
| DATE | | WORK ORDER No | | CDT | |
| DESCRIPTION | | SECTION NUMBERS | | SHEET SIZE | |
| | | A1 | | A1 | |
| | | SH 1 | | OF 1 | |

snowyhydro
UNITED

HUNTER POWER STATION
 PIPING & INSTRUMENTATION DIAGRAM
 INSTRUMENT AIR UNIT - AIR DISTRIBUTION

Appendix E

Service Air System
P&IDs Showing Nodes
Applied in the HAZOP



NOTES:

1. TWO CENTRIFUGAL COMPRESSOR PACKAGES ARE REQUIRED FOR THE PROJECT. IN NORMAL OPERATION ONE IS IN SERVICE (DUTY) AND THE SECOND ONE IS STAND-BY.
2. DETAIL INSIDE THE PACKAGES IS SCHEMATIC ONLY. DETAIL DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT.
3. SUITABLE PRESSURE CONTROL METHOD SHALL BE FINALIZED DURING DETAIL DESIGN BY VENDOR.
4. SIZE OF INSTRUMENT AIR LINES FOR AIR COMPRESSOR PACKAGE WILL BE FINALIZED IN DETAIL DESIGN AFTER RECEIVING VENDOR DATA.
5. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
6. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
7. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

HOLDS:

1. VENDOR TO CONFIRM IF COOLING IS TO BE SUPPLIED THROUGH BATTERY LIMITS OR IF PACKAGE HAS ITS OWN COOLING UNIT.
2. PACKAGE DETAILS TO BE CONFIRMED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 27.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 08.11.21 | 10% CONCEPT DESIGN |


THIS DRS SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No: HPP-AEC-MEC-CP-PAS-DRG-1110
REV: B

| DATE | BY | DESCRIPTION |
|------------|----|----------------|
| 30.11.2021 | | DESIGN CHECKER |
| 30.11.2021 | | APPROVED |
| 30.11.2021 | | CDT |

snowyhydro LIMITED

HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
SERVICE AIR UNIT - AIR COMPRESSORS
SHEET 1

| | | | |
|---------------------|----|------------|---------------|
| SECTION No/NO'S OFF | A1 | SHEET SIZE | B SH 1 OF 1 |
|---------------------|----|------------|---------------|



NOTES:
1. PIPING BETWEEN THE COMPRESSOR DISCHARGE AND DRYER INLET SHALL HAVE AUTOMATIC CONDENSATE DRAINING FACILITIES AT ALL LOW POINTS.

HOLDS:
1. CAPACITY IS BASED ON PRODUCED SERVICE AIR. PRELIMINARY DATA FOR THE CAPACITY TO BE CONFIRMED BY VENDOR.
2. DETAIL INSIDE THE PACKAGES IS SCHEMATIC ONLY. DETAILED DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT.
3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 27.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 28.11.21 | 30% CONCEPT DESIGN |


THIS OPS SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No
HPP-AEC-MEC-CP-PAS-DBG-1111
REV: B

| DESIGNED | SCALE | SECTION No/RXKS |
|------------|-------|-----------------|
| 30.11.2021 | 100 | 001 |

| DRAWING CHECKED | APPROVED | SHEET |
|-----------------|------------|-------|
| 30.11.2021 | 30.11.2021 | A1 |



HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
SERVICE AIR UNIT - AIR DRYERS
SHEET 1
B 1 SH 1 OF 1



NOTES:
1. FLOW ORIFICE TYPE FLOWMETER.

HOLDS:
1. VENDOR SIZING OF SERVICE AIR RECEIVER TO BE CONFIRMED BASED ON RESULTS OF SERVICE AIR CONSUMPTION CALC.
2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 11/01/22 | ISSUED FOR HAZOP |
| A | AECOM | 08/11/21 | 30% CONCEPT DESIGN |

THIS DRG SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No.
HPP-AEL-MEL-CP-PAS-DRG-1112
REV: B


| DESIGNED | SCALE | WORK ORDER No |
|------------|-------|---------------|
| 30/11/2021 | | |
| 30/11/2021 | | |
| 30/11/2021 | | |

| DRAWN | DESIGN CHECKED | APPROVED |
|------------|----------------|------------|
| 30/11/2021 | 30/11/2021 | 30/11/2021 |
| 30/11/2021 | 30/11/2021 | 30/11/2021 |
| 30/11/2021 | 30/11/2021 | 30/11/2021 |



HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
SERVICE AIR UNIT - AIR RECEIVER

SECTION No/PAGES OFF: A1 SHEET SIZE: B 1/1 SH 1 OF 1




NODE 4

- HOLDS:**
- 1 THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 - 2 THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 - 3 KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED

ISSUED FOR INFORMATION ONLY

| | | | | |
|--|-------|--|---|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No: HPP-AEC-MEC-IP-PAS-DRG-1193 REV: B | | DRAWN: SP1 30.11.2021 DESIGNED: KW 30.11.2021 SCALE: WORK ORDER No SECTION No/PKS OFF: A1 | DRAWING CHECKED: DVA 30.11.2021 DESIGN CHECKED: DWT 30.11.2021 APPROVED: CDT 30.11.2021 SHEET SIZE: A1 | snowyhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM SERVICE AIR UNIT - AIR DISTRIBUTION B SH 6 OF 6 |
| REV | NAME | DATE | DESCRIPTION | |
| B | AECOM | 23.01.22 | ISSUED FOR HAZOP | |
| A | AECOM | 30.11.21 | 30% CONCEPT DESIGN | |




NODE 4

- HOLDS:**
- 1 THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 - 2 THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 - 3 KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED

ISSUED FOR INFORMATION ONLY

| | | | | |
|--|---------------|--|---|--|
| THIS DRS SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No: HPP-AEC-MEC-CP-PAS-DRG-1113 REV: B | | DRAWN: SFI 30.11.2021 DESIGNED: HWP 30.11.2021 SCALE: WORK ORDER No SECTION No/NOs: OFF | DRAWING CHECKED: BVA 30.11.2021 DESIGN CHECKED: DWP 30.11.2021 APPROVED: CDT 30.11.2021 SHEET SIZE: A1 | |
| HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM SERVICE AIR UNIT - AIR DISTRIBUTION | B SH 6 OF 6 | | | |



- NOTES:**
1. PIPING BETWEEN THE COMPRESSOR DISCHARGE AND DRYER INLET SHALL HAVE AUTOMATIC CONDENSATE DRAINING FACILITIES AT ALL LOW POINTS.
 2. PART OF THE SAME SERVICE AIR DRYER PACKAGE FROM DRAWING HPP-AEC-MEC-CP-PAS-DRG-1126.


- HOLDS:**
1. CAPACITY IS BASED ON PRODUCED SERVICE AIR, PRELIMINARY DATA FOR THE CAPACITY TO BE CONFIRMED BY VENDOR.
 2. DETAIL INSIDE THE PACKAGES IS SCHEMATIC ONLY, DETAILED DESIGN SHALL BE DESIGNED, MANUFACTURED, PURCHASED AND FABRICATED INSIDE THE PACKAGES IN ACCORDANCE WITH ENGINEERING CODES AND STANDARDS DEFINED FOR THE PROJECT.
 3. THE USE OF "*" WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | |
|---|------|---|---|--|---------------|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-CP-PAS-DRG-1127 | | DRAWN CAP 30.11.2021 DESIGNED RHW 30.11.2021 SCALE WORK ORDER No. SECTION No/KKS OFF | DRAWING CHECKED DVA 30.11.2021 DESIGN CHECKED DWT 30.11.2021 APPROVED COT 30.11.2021 A1 SHEET SIZE | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM SERVICE AIR UNIT - AIR DRYERS SHEET 2 | |
| REV | NAME | DATE | DESCRIPTION | REV. B | B SH 4 OF 6 |

Appendix F

H₂, CO₂ & N₂ Systems
P&IDs Showing Nodes
Applied in the HAZOP




- NOTES:**
- 1 VALVES ARE OPEN ONLY DURING GENERATOR RECHARGE VIA TRAILER OR H2 MAKE-UP THROUGH H2 BOTTLES.
 - 2 EMERGENCY SHUTDOWN VALVE.
 - 3 ALL VALVES TO BE FIRE SAFE.

- HOLDS:**
- 1 TRAILER DATA INCLUDING CAPACITY, SUPPLY AND DESIGN PRESSURE AND RUPTURE DISCS RELEASE RATE WILL BE FINALIZED WITH SUPPLIER.
 - 2 DISCHARGE TO SAFE LOCATION, AT LEAST 3m ABOVE ADJACENT STRUCTURE AND BUILDINGS (TBC).
 - 3 CYLINDER PACK DATA INCLUDING CAPACITY, SUPPLY AND DESIGN PRESSURE WILL BE FINISHED WITH SUPPLIER.
 - 4 PRESSURE REDUCTION STAGES WILL BE FINALIZED BY CONTROL VALVE SUPPLIER.
 - 5 ALL PSV AND PCV SET PRESSURES ARE HOLD AND WILL BE FINALIZED WITH SUPPLIER.
 - 6 THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 - 7 THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 - 8 KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | |
|--|--|--|--|--|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No VPP-AE-MEE-HY-GEN-1124-1101 REV: B | | DRAWN SFR 30.11.2021 DESIGNED K/W 30.11.2021 SCALE WORK ORDER No 30.11.2021 SECTION No/PKS DRG | DRAWING CHECKED BVA 30.11.2021 DESIGN CHECKED BWT 30.11.2021 APPROVED COT 30.11.2021 A1 SHEET SIZE | snowhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM HYDROGEN FACILITY TRAILER CYLINDER AND BACKUP BOTTLES - SHEET 1 B SH 1 OF 1 |
|--|--|--|--|--|



NOTES:


- ALL VALVES TO BE FIRE SAFE
- MHI H2 PRESSURE REDUCTION UNIT WILL BE SUPPLIED BY MITSUBISHI.

HOLDS:

- DISCHARGE TO SAFE LOCATION, AT LEAST 3m ABOVE ADJACENT STRUCTURE AND BUILDINGS (TBC).
- ALL PSV AND PCV SET PRESSURES ARE HOLD AND WILL BE FINALISED BY MITSUBISHI.
- THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
- THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
- KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION | THIS DPG SUPPLIED BY | DESIGNED | DESIGN CHECKED | snowyhydro | |
|-----|------|------|-------------|----------------------------|------------|----------------|--|------------|
| | | | | AECOM Australia Pty Ltd | 30.11.2021 | 30.11.2021 | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM | |
| | | | | HPP-AEC-MEC-HY-GEN-DRG-104 | 30.11.2021 | 30.11.2021 | HYDROGEN FACILITY TRAILER CYLINDER AND BACKUP BOTTLES - SHEET 2 | |
| | | | | | | | SECTION No/PAGES | SHEET SIZE |
| | | | | | | | B / 2 | SH 1 OF 1 |



- NOTES:**
1. VALVES ARE OPEN ONLY DURING PURGING OPERATION WHEN THERE IS DEMAND FOR.
 2. DISCHARGE TO SAFE LOCATION.


- HOLDS:**
1. CYLINDER PACK DATA INCLUDING CAPACITY, SUPPLY AND DESIGN PRESSURE WILL BE FINALIZED WITH SUPPLIER.
 2. PRESSURE REDUCTION STAGES WILL BE FINALIZED BY CONTROL VALVE SUPPLIER.
 3. ALL PCV AND PSV SET POINTS ARE ON HOLD AND WILL BE FINALISED LATER.
 4. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 5. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 6. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | | |
|-----|------|---|-------------|---|---|--|
| | | THIS ORG SUPPLIED BY AECOM AECOM Australia Pty Ltd | | DRAWN: BPP 30.11.2021 DESIGNED: KW 30.11.2021 SCALE: WORK ORDER No 30.11.2021 | DRAWING CHECKER: BVA 30.11.2021 DESIGN CHECKER: BWT 30.11.2021 APPROVED: CUT 30.11.2021 | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM PROCESS GAS FACILITY N2 AND CO2 PRESSURE REGULATOR PANELS |
| REV | NAME | DATE | DESCRIPTION | REV: B | SECTION No/PKS GJA | |

Appendix G

Demin. Water System
P&IDs Showing Nodes
Applied in the HAZOP



- NOTES:**
1. RETURN NOZZLE TO BE INSTALLED FAR FROM PUMP OUTLET NOZZLE.
 2. TANK INLET AND RETURN LINE NOZZLE TO BE INSTALLED BELOW TANK LOW LOW LEVEL.
 3. DEMIN WATER TANK TO BE EQUIPPED WITH CO2 ABSORBER/BREATHERS FILTERS ON VENT LINE.
 4. SIPHON ARRANGEMENT SHOULD BE CONSIDERED FOR OVERFLOW LINE WITH MINIMUM 1m HEIGHT TO PREVENT AIR ENTRANCE TO THE DEMIN WATER TANK.

- HOLDS:**
1. CONSIDERATION TO APPLY WINTERIZATION FOR SMALL SIZE PIPE WILL BE FINALIZED LATER.
 2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 28.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 20.11.21 | 30% CONCEPT DESIGN |


THIS DRG SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No.
HPP-AC-ME-DW-SFP-IRG-1057
REV: B

| | | |
|--------------------------------------|------------------------------------|--------------------------------------|
| DRAWN LAF 28.01.2022 | DESIGNED JD 28.01.2022 | SCALE WORK ORDER No 28.01.2022 |
| DRAWING CHECKED BVA 28.01.2022 | DESIGN CHECKED KW 28.01.2022 | APPROVED CDT 28.01.2022 |
| SECTION No/NOs GIB / GIC | | SHEET A1 5/21 |

snowyhydro LIMITED

HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
DEMIN WATER - STORAGE TANK

B SH 1 OF 1




- HOLDS:**
1. FILTERING REQUIREMENT ON RETURN LINE WILL BE FINALIZED LATER.
 2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
 5. ALL TRV SET PRESSURES ARE HOLD AND WILL BE FINALISED LATER.

- NOTES:**
1. DEMIN PUMP CAPACITY AND HEAD BASED ON MHI UTILITY LIST.
 2. FLOW SWITCH WILL STOP THE PUMP IN CASE OF ACTIVATION WITH TIME DELAY.
 3. PUMPS SEQUENCING SYSTEM WILL BE BASED ON SUPPLY LINE PRESSURE AND FLOW, LOW PRESSURE OR HIGH FLOW WILL START THE NEXT PUMP.

ISSUED FOR INFORMATION ONLY

| | | | | | |
|--|--|---|--|---|--|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AD-WC-DW-SFP-DRG-1058 REV: B | | DRAWN: CAR 28.01.2022 DESIGNED: JD 28.01.2022 SCALE: WORK ORDER No. SECTION No./SWS: GIB / SHC | | DRAWING CHECKED: BVA 28.01.2022 DESIGN CHECKED: KW 28.01.2022 APPROVED: CDT 28.01.2022 A1 SHEET SIZE | |
| REV NAME DATE DESCRIPTION | | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM DEMIN WATER - FORWARDING PUMPS | | | |
| B AECOM 28.01.22 ISSUED FOR HAZOP A AECOM 30.11.21 30% CONCEPT DESIGN | | B SH 1 OF 1 | | | |



NOTES:
1. SAFETY SHOWER AND EYE WASH SHOULD BE INSTALLED NEAR THE CHEMICAL INJECTION PACKAGES OR BESIDE THE TREATMENT PACKAGE.


HOLDS:
1. DETAILS INSIDE PACKAGE IS SCHEMATIC ONLY, PACKAGE SUPPLIER TO OFFER BEST AND EFFICIENT ARRANGEMENT FOR PACKAGE INSIDE.
2. REQUIREMENT FOR INLET FILTERS AND TYPE WILL BE SPECIFIED BY PACKAGE SUPPLIER.
3. REQUIREMENT FOR CHEMICAL INJECTION PACKAGES AND TYPE OF CHEMICALS WILL BE FINALIZED BY PACKAGE SUPPLIER.
4. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
5. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS.
6. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 28.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 30.11.21 | 30% CONCEPT DESIGN |

| | | |
|--|--|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. IPT-AC-MEC-DW-WTS-IRC-1056 REV: B | DRAWN LAF 28.01.2022 DESIGNED LD 28.01.2022 SCALE WORK ORDER No | DRAWING CHECKED BVA 28.01.2022 DESIGN CHECKED KW 28.01.2022 APPROVED CDT 28.01.2022 |
|--|--|---|

| | |
|--------------------------------------|--|
| snowyhydro LIMITED | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM DEMIN WATER - PRE-TREATMENT SYSTEM |
| SECTION No/NO'S (GHC / EGB / EGC) | A1 SHEET SIZE |
| B SH 1 OF 1 | |




HOLDS:

1. DETAILS INSIDE PACKAGE IS SCHEMATIC ONLY, PACKAGE SUPPLIER TO OFFER BEST AND EFFICIENT ARRANGEMENT FOR PACKAGE INSIDE.
2. THE USE OF WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | | |
|-----|-------|---|----------------------------|--|--|--|
| | | THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No: HPP-AEC-PEC-DW-WTS-DRG-1056 REV. B | | DRAWN CAP: 28.01.2022 DESIGNED: 28.01.2022 SCALE: WORK ORDER #: SECTION MARKS: USA / SHE / GLOB | DRAWING CHECKED: SVA DESIGN CHECKED: K/W APPROVED: EDT DATE: 28.01.2022 SHEET: A1 SIZE: | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM DEMIN WATER - TREATMENT SYSTEM |
| REV | NAME | DATE | DESCRIPTION | | | |
| B | AECOM | 28.01.22 | ISSUED FOR HAZOP | | | |
| A | AECOM | 28.11.21 | PRELIMINARY CONCEPT DESIGN | | | |



NOTES:
1. SAFETY SHOWER AND EYE WASH SHOULD BE INSTALLED NEAR THE CHEMICAL INJECTION PACKAGES.


HOLDS:
1. DETAILS INSIDE PACKAGE IS SCHEMATIC ONLY, PACKAGE SUPPLIER TO OFFER BEST AND EFFICIENT ARRANGEMENT FOR PACKAGE INSIDE.
2. REQUIREMENT FOR INLET FILTERS AND TYPE WILL BE SPECIFIED BY PACKAGE SUPPLIER.
3. REQUIREMENT FOR CHEMICAL INJECTION PACKAGES AND TYPE OF CHEMICALS WILL BE FINALIZED BY PACKAGE SUPPLIER.
4. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
5. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
6. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | | |
|-----|------|------|---|------------------------------|------------------------------------|--|
| | | | THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd | DRWNG CAP 28.01.2022 | DRWNG DESKID BVA 28.01.2022 | snowyhydro LIMITED |
| | | | DRWNG No. HPP-AEC-MEC-DW-WTS-DRG-1059 | DESIGNED JD 28.01.2022 | DESIGN CHECKED HW 28.01.2022 | |
| | | | REV: B | SCALE WORK ORDER No. | APPROVED COT 28.01.2022 | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM DEMIN WATER - TREATMENT SYSTEM |
| REV | NAME | DATE | DESCRIPTION | SECTION NUMBER DWT / GSD | A1 | SHEET SIZE |

Appendix H


Water System P&IDs
Showing Nodes Applied
in the HAZOP



- HOLDS:**
1. DETAIL INSIDE THE METERING STATION PACKAGE TO BE FINALIZED BY HUNTER WATER.
 2. CONSIDERATION TO APPLY WINTERIZATION FOR SMALL SIZE PIPE WILL BE FINALIZED LATER.
 3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
 6. REQUIREMENT FOR BOOSTER PUMP ON POTABLE WATER INLET LINE WILL BE FINALISED AFTER RECEIVING DETAIL SUPPLY INFORMATION FROM HUNTER WATER.

ISSUED FOR INFORMATION ONLY

| | | | | |
|---|--|--|---|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AC-MEC-PW-SMS-DRG-1050 REV: B | | DRAWN LAF 28.01.2022 DESIGNED KW 28.01.2022 SCALE WORK ORDER No SECTION No/KKS QKB / CHU | DRAWING CHECKED BVA 28.01.2022 DESIGN CHECKED GWI 28.01.2022 APPROVED CDT 28.01.2022 A1 SHEET SIZE | snowyhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM SERVICE WATER UNIT - STORAGE AND METERING SH 1 OF 1 |
| REV NAME DATE DESCRIPTION | B AECOM 28.01.22 ISSUED FOR HAZOP | A AECOM 20.11.22 30% CONCEPT DESIGN | | |



HOLDS:


1. CONSIDERATION TO APPLY WINTERIZATION FOR SMALL SIZE PIPE WILL BE FINALIZED LATER.
2. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED
3. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
4. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

NOTES:

1. INLET PIPE TO BE DIPPED BELOW TANK LOW-LOW LEVEL.
2. BREATHING HOLES TO BE PROVIDED ON THE INLET PIPES.
3. OUTLET, RETURN, AND EMERGENCY UNLOADING NOZZLES TO BE LOCATED BELOW LOW LOW LEVEL.
4. TANK AUTOMATIC FILLING SYSTEM TO BE SUPPLIED WITH FLOATING VALVE INSIDE THE TANK.

ISSUED FOR INFORMATION ONLY

| | | | | | | |
|--------------------------|--|-----------------|--|-----------------|--|---|
| THIS DRG SUPPLIED BY | | DRAWN | | DRAWING CHECKED | | |
| AECOM | | LAF | | BVA | | |
| AECOM Australia Pty Ltd | | 28.01.2022 | | 28.01.2022 | | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM SERVICE WATER UNIT – STORAGE AND METERING |
| DRAWING No. | | DESIGNED | | DESIGN CHECKED | | |
| IPR-HEC-PCS-SIS-DRG-1002 | | KW | | SWT | | |
| REV: B | | SCALE | | APPROVED | | |
| REV NAME | | WORK ORDER No | | CDT | | |
| DATE | | SECTION No/NO'S | | 28.01.2022 | | B SH 1 OF 1 |
| DESCRIPTION | | Q/B / Q/U | | A1 SHEET SIZE | | |



NODE 3

- HOLDS:**
1. DETAILS INSIDE PACKAGE IS SCHEMATIC ONLY, PACKAGE SUPPLIER TO OFFER BEST AND EFFICIENT ARRANGEMENT FOR PACKAGE INSIDE.
 2. SERVICE WATER PUMP HEAD WILL BE FINALISED AFTER FINALISING PIPE ROUTES AND 3D MODEL.
 3. REQUIREMENT FOR CHEMICAL INJECTION PACKAGES AND TYPE OF CHEMICALS TO PREVENT ALGAE AND BACTERIA GROWING IN POTABLE WATER TANK WILL BE FINALIZED IN LATER DESIGN STAGE.
 4. CONSIDERATION TO APPLY WINTERIZATION FOR SMALL SIZE PIPE WILL BE FINALIZED LATER.
 5. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEED TO BE CONFIRMED.
 6. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 7. KVS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.
 8. PCV SET POINT IS HOLD AN WILL BE SPECIFIED AFTER RECEIVING PUMP PERFORMANCE CURVE FROM SUPPLIER.


- NOTES:**
1. SAFETY SHOWER AND EYE WASH SHOULD BE PROVIDED NEAR THE CHEMICAL INJECTION PACKAGES.
 2. PUMPS SEQUENCING SYSTEM WILL BE BASED ON SUPPLY LINE PRESSURE AND FLOW, LOW PRESSURE OR HIGH FLOW WILL START THE NEXT PUMP.
 3. FLOW SWITCH WILL STOP THE PUMP IN CASE OF ACTIVATION WITH TIME DELAY.

ISSUED FOR INFORMATION ONLY

| | | | | |
|---|--|---|---|--|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-DC-WCS-PW-FPS-WG-1001 REV: B | | DRAWN 28.01.2022 DESIGNED 28.01.2022 SCALE WORK ORDER No. SECTION No/KVS QCB / QNU | DRAWING CHECKED BVA 28.01.2022 DESIGN CHECKED BWT 28.01.2022 APPROVED GDT 28.01.2022 SHEET A1 SIZE | |
| HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM SERVICE WATER UNIT - FORWARDING PUMPS | | B SH 1 OF 1 | | |

Appendix I

Fire Water System
P&IDs Showing Nodes
Applied in the HAZOP




- NOTES:**
- TANK AUTOMATIC FILLING SYSTEM WITH MANUAL BYPASS TO BE INSTALL ON INLET LINE AND LEVEL CONTROL VALVE WITH ALL ACCESSORIES AND FLOAT VALVE TO BE PROVIDED BY SUPPLIER.
 - VORTEX PLATE SHALL BE INSTALLED AT ENTRANCE OF OUTLET NOZZLE.
 - INLET AND RETURN PIPES TO BE DIPPED BELOW TANK OUTLET NOZZLE, PROVIDE BREATHING HOLES ON TOP OF THE LINES.

- HOLDS:**
- TANKS CAPACITY WILL BE FINALIZED AFTER COMPLETION OF FIRE SAFETY STUDY.
 - TANK NOZZLE SIZES, SPECIALLY VENT, LEVEL GAUGE, FLOAT VALVE AND MANHOLES TO BE FINALISED BY TANK MANUFACTURER
 - THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 - THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 - KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | | |
|---------------------------|--|---------------|---------------|----------------|---|
| THIS Dwg SUPPLIED BY | | DRAWN | DESIGNED | DESIGN CHECKED | |
| AECOM | | LAF | LAF | BVA | |
| AECOM Australia Pty Ltd | | 28.01.2022 | 28.01.2022 | 28.01.2022 | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM FIRE WATER UNIT - STORAGE TANKS |
| DRAWING No. | | SCALE | WORK ORDER No | APPROVED | |
| IHF-AD-MC-TP-FWS-DRG-1070 | | 1:1 | | CDT | |
| REV: B | | SECTION No/NO | SIZE | SHEET | B SH 1 OF 1 |
| REV NAME DATE DESCRIPTION | | SGG | A1 | 9/2 | |



NODE 2 - Fire Water to FW pumps and distribution

- NOTES:**
1. CONNECTION FOR CHEMICAL / BIOCIDES INJECTION TO PREVENT BACTERIA AND ALGAE GROWING.
 2. NUMBER OF PRESSURE TRANSMITTER WILL BE FINALIZED LATER.
 3. LARGE BORE SUCTION CONNECTION AND 4 INLET BOOSTER CONNECTION TO BE PROVIDED FOR FIRE BRIDGE.
 4. FLOWMETER TO BE VISIBLE FROM GROUND AND ADJUSTING VALVE ON TEST LINE.
 5. FLOWMETER SHALL COVER UP TO 175% OF DUTY FLOW AS MINIMUM.
 6. TEMPORARY STRAINER FOR PRE-COMMISSIONING, TO BE REMOVED AFTER THAT.
 7. VENT TO OUTDOOR AT SAFE LOCATION, WITH FLAME ARRESTOR.
 8. LG TO BE READABLE FROM FILLING VALVE.

- HOLDS:**
1. DETAIL INSIDE THE PACKAGES ARE INDICATIVE ONLY AND WILL BE FINALIZED BY SUPPLIER.
 2. FIRE PUMPS CAPACITY WILL BE FINALIZED AFTER COMPLETION OF FIRE SAFETY STUDY.
 3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 5. MMS SYSTEM ON PAID ARE INDICATIVE ONLY AS THE PAID GET FINALIZED.
 6. REQUIREMENT FOR DIESEL PUMP RELIEF LINE AND SIZE WILL BE FINALIZED BY PUMP SET SUPPLIER.
 7. REQUIREMENT FOR TRV AND RELATED SET PRESSURE WILL BE FINALIZED LATER.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|--------------------|
| B | AECOM | 28.01.22 | ISSUED FOR HAZOP |
| A | AECOM | 30.11.21 | 30% CONCEPT DESIGN |

THIS DRG SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No.
HPP-NEC-MEC-FP-FWS-DRG-1071
REV: B

| DATE | BY | DESCRIPTION |
|------------|-----|-----------------|
| 28.01.2022 | BYA | DRAWING CHECKED |
| 28.01.2022 | LD | DESIGN CHECKED |
| 28.01.2022 | KW | DESIGN CHECKED |
| 28.01.2022 | CDT | APPROVED |

SECTION No/NO'S
506


SHEET
A1

SIZE

snowyhydro
LIMITED
HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
FIRE WATER UNIT - FIRE PUMPS

Appendix J


Effluent Treatment
System P&IDs Showing
Nodes Applied in the
HAZOP



- NOTES:**
- REFER TO CIVIL DRAWING HPP-CIV-DW-DRG-1600 FOR OILY WATER DRAINAGE SYSTEM AND SIZING
 - TEE-PIPE OVERFLOW TO BE INSTALLED TO TRANSFER OILY WATER FROM BOTTOM OF DECANTING PIT TO MAIN PIT.
 - DECANTING PIT IS DESIGNED TO CAPTURE SPILL BULK OIL/FUEL FROM SOURCES OTHER THAN TRANSFORMERS, IN CASE OF RELEASE FROM TRANSFORMERS MORE THAN 15 m³, OIL WILL BE OVERFLOW TO THE OILY WATER PIT.
 - OILY WATER MAIN PIT LEVEL TO BE KEPT BELOW 500 mm TO HAVE ENOUGH SPACE TO CAPTURE OIL IN CASE OF TRANSFORMER FAILURE
 - OBSERVATION PIT OVERFLOW TO MAIN PIT TO BE INSTALLED ABOVE THE PIT NORMAL DISCHARGE PIPE
 - OILY WATER TRANSFER PUMP, SKIMMER AND START/STOP LEVEL SWITCH TO BE SUPPLIED BY OILY WATER TREATMENT PACKAGE SUPPLIER.
- HOLDS:**
- EQUIPMENT INSIDE THE PACKAGE IS INDICATIVE ONLY, TYPE AND EQUIPMENT INSIDE WILL BE FINALIZED BY SUPPLIER.
 - OILY WATER PIT CAPACITY AND ARRANGEMENT TO BE FINALIZED BY CIVIL TEAM.
 - STORMWATER HUMECEPTOR CAPACITY AND ARRANGEMENT WILL BE FINALIZED BY CIVIL TEAM.
 - THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 - THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 - KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | |
|--|---------------------------------------|---|---|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-GR-GEN-DRG-108 | | DRAWN SFL 28.01.2022 DESIGNED ID 28.01.2022 SCALE WORK ORDER No. SECTION No./KKS MVA | DRAWING CHECKED BVA 28.01.2022 DESIGN CHECKED HW 28.01.2022 APPROVED CDT 28.01.2022 | snowhydro HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM EFFLUENT TREATMENT STORM AND OILY WATER TREATMENT |
| REV: C NAME DATE DESCRIPTION | REV: C NAME DATE DESCRIPTION | REV: C NAME DATE DESCRIPTION | REV: C NAME DATE DESCRIPTION | REV: C NAME DATE DESCRIPTION |



NODE 4 - Sewer

90GNB01PT001
SEWAGE PIT
DIMENSION 2.0m X 2.0m X 1.8m
WORKING CAPACITY: 6.0 M³
MATERIAL: CONCRETE
HOLD 1


90GNB01AP001
90GNB01AP002
SEWAGE PUMPS
ARRANGEMENT: DUTY/STANDBY
TYPE: SUBMERSIBLE
RATED CAPACITY: 6.0 M³ / HR
DIFF. PRESSURE: 20 M
RATED POWER: 1 kW
HOLD 1
NOTE 1

- HOLDS:**
1. PUMP OPERATION IS INTERMITTENT, START IN HIGH LEVEL TO EMPTY THE PIT AND THEN STOP IN LOW LEVEL.
 2. NO FLOW WILL STOP THE OPERATING PUMP.
 3. VENT TO SAFE LOCATION, VENT TO BE EQUIPPED WITH ODOOR FILTER
 4. SEWAGE PIT TO BE FLUSHED WITH WATER AND PUMPED OUT EVERY 3 DAYS WHEN FACILITY IS UNMANNED
 5. UTILITY CONNECTION FOR LINE FLUSHING

- NOTES:**
1. SEWAGE PIT AND TRANSFER PUMP WILL BE REQUIRED IF GRAVITY FLOW FROM SITE TO HUNTER SEWAGE SYSTEM IS NOT POSSIBLE. TO BE FINALIZED BY CIVIL TEAM.
 2. REQUIREMENT FOR METERING WILL BE FINALIZED BY HUNTER WATER.
 3. THE USE OF " " WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| | | | | |
|---|--|---|--|--|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd | | DRAWN: CAR 28.01.2022 DESIGNED: JD 28.01.2022 SCALE: WORK ORDER No. SECTION: HPP-AEC-HEC-GH-GEN-DRG-1066 | DRAWING CHECKED: BVA 28.01.2022 DESIGN CHECKED: HW 28.01.2022 APPROVED: CDT 28.01.2022 | <p>HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM EFFLUENT TREATMENT SEWER TRANSFER PIT AND PUMPS</p> |
| REV: C NAME: DATE: DESCRIPTION: | REV: C SECTION: HPP-AEC-HEC-GH-GEN-DRG-1066 SHEET: A1 SIZE: SH 1 OF 1 | | | |



NOTES:
1. PUMP STARTS/ STOPS MANUALLY BY OPERATOR.
2. NO FLOW WILL STOP THE OPERATING PUMP.
3. IN CASE OF COMPRESSOR WASHING WITH BARE DEMIN WATER, THE WASTE TO BE SENT TO NEUTRALIZATION PIT, HOWEVER IN CASE OF WASHING WITH CHEMICALS, OPERATING AGENT HAS TO DECIDE WHETHER DISCHARGE IT INTO THE NEUTRALIZATION PIT OR REMOVE FROM SITE BY VACUUM TRUCK DEPENDS ON TYPE OF CHEMICALS.

HOLDS:
1. THE USE OF ** WILL BE A PLACEHOLDER INFORMATION THAT NEEDS TO BE CONFIRMED.
2. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
3. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|------------------------|
| C | AECOM | 28.01.22 | ISSUED FOR HAZOP |
| B | AECOM | 28.01.21 | 30% CONCEPT DESIGN |
| A | AECOM | 16.11.21 | PIV_02 FOR INFORMATION |


THIS Dwg SUPPLIED BY
AECOM
AECOM Australia Pty Ltd
DRAWING No: HPP-AEC-MEC-GN-GEN-DRG-1007
REV: C

| DESIGNED | DESIGN CHECKED | APPROVED |
|------------|----------------|------------|
| 28.01.2022 | 28.01.2022 | 28.01.2022 |
| 28.01.2022 | 28.01.2022 | 28.01.2022 |
| 28.01.2022 | 28.01.2022 | 28.01.2022 |

snowy hydro LIMITED

HUNTER POWER STATION
PIPING & INSTRUMENTATION DIAGRAM
EFFLUENT TREATMENT
NEUTRALISATION PIT AND TRANSFER PUMPS - SHEET 1

SECTION No/NO. PPG A1 SHEET SIZE SH 1 OF 1




NOTES:
1. CAUSTIC INJECTION PUMP TO BE STARTED WHEN PH BELOW 6.5 AND THEN WILL STOP WHEN PH BACK TO ABOVE 7.


HOLDS:
1. DETAILS INSIDE PACKAGE IS SCHEMATIC ONLY, PACKAGE SUPPLIER TO OFFER BEST AND EFFICIENT ARRANGEMENT FOR PACKAGE INSIDE, DILUTED CAUSTIC TO BE USED FOR PH ADJUSTMENT
2. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
3. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|-------|----------|-----------------------|
| C | AECOM | 20/01/22 | ISSUED FOR HAZOP |
| B | AECOM | 16/11/21 | REV CONCEPT DESIGN |
| A | AECOM | 16/11/21 | IT_02 FOR INFORMATION |

| | | | |
|---|--|---|---|
| THIS DRG SUPPLIED BY AECOM AECOM Australia Pty Ltd DRAWING No. HPP-AEC-MEC-SH-GEN-DRG-1008 REV: C | | DRAWN: SFI 20/01/2022 DESIGNED: HW 20/01/2022 SCALE: WORK ORDER No: SECTION No/KKS: GNL DRAWING CHECKED: SVA 20/01/2022 DESIGN CHECKED: HW 20/01/2022 APPROVED: CDT 20/01/2022 A1 SHEET SIZE | HUNTER POWER STATION PIPING & INSTRUMENTATION DIAGRAM EFFLUENT TREATMENT PH ADJUSTMENT INJECTION PACKAGES - SHEET 1 C E SH 1 OF 1 |
|---|--|---|---|





NOTES:
 1. ACID INJECTION PUMP TO BE STARTED WHEN PH ABOVE 10 AND THEN WILL STOP WHEN PH BACK TO BELOW 9.5

HOLDS:
 1. DETAILS INSIDE PACKAGE IS SCHEMATIC ONLY, PACKAGE SUPPLIER TO OFFER BEST AND EFFICIENT ARRANGEMENT FOR PACKAGE INSIDE
 2. TYPE OF ACID WILL BE FINALIZED BY PACKAGE SUPPLIER CONSIDERING HEALTH AND SAFETY ISSUES.
 3. THE USE OF ** WILL BE A PLACEHOLDER FOR INFORMATION THAT NEEDS TO BE CONFIRMED.
 4. THIS P&ID IS STILL A WORK IN PROGRESS AND THE INTEND TO DATE IS TO SHOW THE PROCESS FOR 30% SUBMISSION.
 5. KKS SYSTEM ON P&ID ARE INDICATIVE ONLY AS THE P&ID GET FINALIZED.

ISSUED FOR INFORMATION ONLY

| REV | NAME | DATE | DESCRIPTION |
|-----|------|----------|--------------------|
| B | AACM | 08.01.22 | ISSUED FOR HAZOP |
| A | AACM | 08.11.21 | 30% CONCEPT DESIGN |

THIS DRS SUPPLIED BY
AECOM
 AECOM Australia Pty Ltd
 DRAWING No.
 HPP-AEC-MEC-GN-GEN-DRG-1129
 REV. B

| DRAWN | DESIGNED | SCALE | WORK ORDER No. | SECTION No/KKS | GNL | DRAWING CHECKED | DESIGN CHECKED | APPROVED | CUT | DATE |
|-------|------------|-------|----------------|----------------|-----|-----------------|----------------|----------|-----|------------|
| SFI | 20.01.2022 | 1:1 | | | | BVA | 20.01.2022 | | | 20.01.2022 |



HUNTER POWER STATION
 PIPING & INSTRUMENTATION DIAGRAM
 EFFLUENT TREATMENT
 PH ADJUSTMENT INJECTION PACKAGES - SHEET 2

Appendix E

HAZOP Recommendations Completion Schedule by Project Phase

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|--------------|--|-----------------|---|-------------|---------------------------|
| Power Island | 1 - Fuel Oil - High pressure Pump | 3 | Confirm forwarding pump deadhead pressure and prv | SNOWY HYDRO | 1 |
| Power Island | 1 - Fuel Oil - High pressure Pump | 4 | Review bunding requirements around FO pumps | SNOWY HYDRO | 1 |
| Power Island | 1 - Fuel Oil - High pressure Pump | 5 | Confirm \$ cost per unit trip / 1 hr outage | SNOWY HYDRO | 1 |
| Power Island | 1 - Fuel Oil - High pressure Pump | 6 | All ball valves to be lockable | SNOWY HYDRO | 1 |
| Power Island | 1 - Fuel Oil - High pressure Pump | 7 | SHL to review who supplies instrumentation at MHI interfaces | SNOWY HYDRO | 1 |
| Power Island | 1 - Fuel Oil - High pressure Pump | 12 | AECOM to consider heat tracing for FO dwg 2of 5. Start up temperature should be 11 deg C. Alternative may be an enclosure for the pump and piping | SNOWY HYDRO | 1 |
| Power Island | 2 - Fuel Oil - Manifold pressure control | 36 | The screw pump has no min flow bypass return line. The HP pump only starts when burners are to be lit. When no burner flow the manifold pressure control valve acts as the min flow control. MHI to confirm forwarding pump flow rate through HP screw pump when shutdown | MHI | 1 |
| Power Island | 5 - Fuel Oil - Flow divider | 95 | MHI manual ball valves should all be lockable | SNOWY HYDRO | 1 |
| Power Island | 6 - Fuel Oil - Burners | 124, 517, 565 | Pantac to review blade path flameout voting logic. One or multiple burners, adjacent burners, single or duplex t/c. No optical flame detectors | SNOWY HYDRO | 2 |
| Power Island | 6 - Fuel Oil - Burners | 127 | MHI to advise combustion frequency sensor criticality. Commissioning tool or protection | MHI | 2 |
| Power Island | 6 - Fuel Oil - Burners | 129 | SHL investigating additional diesel fuel quality reports | SNOWY HYDRO | 2 |
| Power Island | 7 - Fuel Oil - Drain tank | 144 | MHI to confirm if there is a drain tank Hi level start permissive. Unit won't start with high level | MHI | 1 |
| Power Island | 7 - Fuel Oil - Drain tank | 147 | SHL to confirm with operations to see if small lines have been problematic with non-return valves failing / passing | SNOWY HYDRO | 1 |
| Power Island | 7 - Fuel Oil - Drain tank | 148 | AECOM to consider drain pit discharge hi alarm to start pump and hi hi to alarm to remote operations | AECOM | 1 |
| Power Island | 7 - Fuel Oil - Drain tank | 149 | AECOM Fuel oil discharge to oily water pit detection to be considered in design | AECOM | 1 |
| Power Island | 8 - Fuel Oil - Water injection | 159 | MHI to confirm at what load level water injection is enabled. Also when water injection is not correct the unit would go to run back load, where water injection is turned off. | MHI | 1 |
| Power Island | 8 - Fuel Oil - Water injection | 160 | SHL to confirm action required when water injection is off, i.e. valley will try to restart water injection 3 times and max operating time without water injection is 15 minutes. Automatic shutdown required, tbc and advise to MHI or add into station controls | SNOWY HYDRO | 2 |
| Power Island | 8 - Fuel Oil - Water injection | 161 | Oily water pit to be covered with rain shelter | AECOM | 1 |
| Power Island | 8 - Fuel Oil - Water injection | 169 | AECOM to consider valve failure, excessive flow to oily water pit overflow during runback time. Flow balance required. MHI to advise oily water flow rate and volumes expected during normal operating conditions and if one of the drain valves fails open, MBN13AA735,AA736,AA737 based on SHL RFI document | AECOM | 1 |
| Power Island | 8 - Fuel Oil - Water injection | 170 | Water injection flow transmitter is a single point of failure which would cause diesel outage, so it is critical for operation. Redundancy for valve control per fuel oil control should be considered. MBU02CP531. | SNOWY HYDRO | 1 |
| Power Island | 8 - Fuel Oil - Water injection | 171 | Single point of failure mode analysis should be completed at a suitable time. SHL internal item | SNOWY HYDRO | 3 |
| Power Island | 8 - Fuel Oil - Water injection | 172 | Outage, run back, emergency trip restart time cost analysis required for Risk Assessment decision around device fault tolerance, i.e. trip or 1 hours outage = 800k (330MW x 2500MW/Hr x 1 hr), additional instrument = 20k installed | SNOWY HYDRO | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|--------------|--|-----------------|--|-------------|---------------------------|
| Power Island | 9 - Fuel Oil - Purge credit block valves | 184 | Purge credit details are not well understood by Operations. There is a manual, Operating Procedure(S4-96597), that describes it in more detail. Type B compliance, intermittent or continuous turning and start and re-purge credit are all good questions. Potentially every 8 days the unit needs repurging, which can lead to more blade wear (wobbling in root) and starter problems. This item to be revisited by Operations with MHI detail input. | SNOWY HYDRO | 3 |
| Power Island | 9 - Fuel Oil - Purge credit block valves | 191 | MHI to review if fuel oil from the fuel oil purge credit can go to the tank not the pit as it is clean fuel. Environmental credit | SNOWY HYDRO | 1 |
| Power Island | 9 - Fuel Oil - Purge credit block valves | 192 | Fuel oil purge credit valves only have a single limit switch, preference for both open and closed indication, all valves (block, drain, N2). AECOM supply these valves | SNOWY HYDRO | 1 |
| Power Island | 11 - Fuel Gas - Supply pressure control | 216 | MHI to check logic. Gas vent valve out of position during operation should be a trip. Redundant limit switches may be. | MHI | 2 |
| Power Island | 11 - Fuel Gas - Supply pressure control | 217 | AECOM should review vent valve position failure actions | AECOM | 2 |
| Power Island | 11 - Fuel Gas - Supply pressure control | 218 | AECOM to review appliance manual isolation valve per AS3814 requirements within 5m of the appliance. Paul van Dyk to confirm AS3814 clause requirements | SNOWY HYDRO | 1 |
| Power Island | 11 - Fuel Gas - Supply pressure control | 219 | Tapping points for pressure testing / leak testing valves not shown on P&ID. Additional testing points may be required. SHL to review based on length of pipework and valve locations. | MHI | 1 |
| Power Island | 11 - Fuel Gas - Supply pressure control 17 - Fuel Gas - GT sweep (purge air) | 223, 350 | MHI to review AS3814 section 2.13 requirement for sufficient test points to verify the integrity of shutoff valve / train. | MHI | 1 |
| Power Island | 12 - Fuel Gas - Flow control | 231 | RFI for the purpose of the HAZOP the main question, is there a single point of failure (DPT) and what would be consequence of a critical time pressure excursion explosion. Is DPT control or protection, refer control description fig 2.9.1 | MHI | 1 |
| Power Island | 15 - Fuel Gas - Combustor drain valves | 301 | MHI to confirm temperature rating of pipework after MBA01AA704, burner drain valve. Rating drops from 525 to 60 Celsius | MHI | 1 |
| Power Island | 15 - Fuel Gas - Combustor drain valves | 304, 871, 878 | Water wash procedure has many manual valves which could potentially lead to false start by flooded combustion chamber and subsequently detergent flow into the oil water pit. SHL to develop a water wash procedure with 2 operators to cross check. Water washing drain header could also have small amounts of diesel residue from liquid fuel false start. | SNOWY HYDRO | 3 |
| Power Island | 18 - Fuel Gas - Flow meter | 368 | Commissioning spool required for flow meter, that will need to be removed for pipe blow down activities. Mark up P&ID | AECOM | 2 |
| Power Island | 19 - Fuel Gas - Filter and purge credit | 397 | Add instrument tapping point for Nitrogen entry for valve leak testing, with smaller volume than upstream line | AECOM | 1 |
| Power Island | 20 - Fuel Gas - Calorie meter | 403 | Calorie meter. 1. Cal gas bottles only have single regulator and no relief valve. Potential single point of failure. Is meter rated for cal gas pressure. 2. If reg fails, is it possible to reverse flow cal gas into the gas line? 3. Why is there a flow meter in the vent line? | MHI | 1 |
| Power Island | 21 - Air & Flue Gas - Seal air | 432 | All ball valves to be lockable. Evan to confirm who is responsible for providing the pad locking system for all the manual isolation valves and to ensure the valves have lock tabs, refer also action item 4. Also send sample photos to MHI. The requirement is in the tender specification section 2.3 | SNOWY HYDRO | 1 |
| Power Island | 24 - Air & Flue Gas - GT HP Bleed valve | 506 | MHI to confirm failure mode of IGV, i.e. fail last position, fail ramp closed on loss of control oil or power? | MHI | 2 |
| Power Island | 25 - Air & Flue Gas - Inlet duct flow 27 - Air & Flue Gas - Combustor and Exhaust | 515, 563 | 2oo3 trip voting degradation to be reviewed on a trip by trip basis by SHL, 2oo3, 1oo2 or 2oo2 and 1oo1 = trip or run? | SNOWY HYDRO | 2 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|--------------|--|-----------------|---|-------------|---------------------------|
| Power Island | 29 - Lube Oil - Tank, pumps, prv | 608 | DC Lube oil pump to be tested prior or after each start to prove functionality. Replacing MBV01CP304 DC lube oil pressure gauge with a transmitter would facilitate fast auto test sequence. Requirements to be confirmed by SHL | SNOWY HYDRO | 1 |
| Power Island | 30 - Lube Oil - GT bearings 50 - Generator - Lube oil system | 633, 1060 | SHL to review high temperature alarm shutdown requirements for Hunter. Remote operator may not react in time. | SNOWY HYDRO | 2 |
| Power Island | 30 - Lube Oil - GT bearings | 646 | SHL may request additional oil sampling point downstream of the bearings (generator and turbine). MHI to review installation requirements and advise accordingly | MHI | 1 |
| Power Island | 34 - Control Oil - Tank, pumps, temp control | 724 | There is a wall in the oil tank which may create different tank levels, design to be confirmed by MHI | MHI | 1 |
| Power Island | 35 - Control Oil - Fuel valve position control | 753 | Fuel gas and Fuel Oil control oil dump valves are single point of failure and common cause fraction is high. Is this allowed per the standard. Valves should failsafe and individually actuated?? PVD to review in detail as part of AS3814 compliance | SNOWY HYDRO | 1 |
| Power Island | 36 - Control Oil - Fuel valve trip solenoids & Inlet Guide Vanes | 774 | Control oil dump circuits to be reviewed against SIL requirements and AS3814 compliance | SNOWY HYDRO | 1 |
| Power Island | 37 - Package Enclosure Ventilation | 791 | Note AECOM responsible for Fire protection of the Balance of Plant equipment such as lube oil package, fuel oil pump / valve systems and how that system is interlock or integrated into the plant DCS or MHI GT controls. AECOM is design stage now. Fire safety study is well advanced MHI fire and gas detection limited to GT enclosure and Fuel Gas valve systems. SHL to review final design proposal | SNOWY HYDRO | 1 |
| Power Island | 37 - Package Enclosure Ventilation | 792 | Door tracking isolating the CO2 if someone enters the GT is to be confirmed by vendor and reviewed by SHL | SNOWY HYDRO | 1 |
| Power Island | 38 - Air & Flue Gas - Inlet filter | 805 | Ambient conditions -5 C to +45 C. Anti-icing system was considered in the tender specification but MHI advised at that time it is not required. MHI to revisit the study and reconfirm anti-icing is not required. | MHI | 1 |
| Power Island | 42 - Evaporative Cooler - pump and tank unit | 887 | Valve numbers and instrument numbers and line sizes are not shown on the drawing. Return valve is shown as control valve but is actually a manual lockable isolation valve | MHI | 3 |
| Power Island | 42 - Evaporative Cooler - pump and tank unit | 893 | Evap tank water is potable water. Should overflow or draining be discharged to Trade Waste or Storm Water. AECOM to review and design accordingly | AECOM | 1 |
| Power Island | 42 - Evaporative Cooler - pump and tank unit | 899 | Evap tank has no sample point. MHI to review option to supply | MHI | 1 |
| Power Island | 44 - Generator cooling water | 928 | MELCO interface details required for AECOM water services. Water pressure recently increased to 7.5 Bar. AECOM to advise MELCO final supply pressure. MELCO cooler to be designed accordingly | AECOM | 1 |
| Power Island | 44 - Generator cooling water | 932 | MELCO to provide full list of generator protection settings, trips complete with alarms, auto shutdown and run backs | MELCO | 2 |
| Power Island | 45 - Generator CO2 gas supply | 951 | Manual purging requires strict procedure with 2 people to cross check to confirm successful purge | SNOWY HYDRO | 2 |
| Power Island | 45 - Generator CO2 gas supply | 950 | CO2 site capacity to be assessed against minimum volume required for a successful purge times a safety factor. Potential bottle leak reduces capacity. Is adequate monitoring installed, flow pressure bottle weight | AECOM | 1 |
| Power Island | 45 - Generator CO2 gas supply 53 - Generator - DC seal oil system | 957, 1128 | Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. MHI incorporate in design, logic to action valve | MHI | 1 |
| Power Island | 45 - Generator CO2 gas supply | 958 | Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. AECOM to incorporate automate CO2 supply to the units | AECOM | 1 |
| Power Island | 46 - Generator H2 gas supply | 970 | Unit H2 flow meter can be used for make up flow monitoring, leak and PRV lifting detection. SHL to review | SNOWY HYDRO | 2 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|--------------|--|-----------------|--|-------------|---------------------------|
| Power Island | 46 - Generator H2 gas supply | 983 | AECOM to review H2 pipework for dissimilar metals. MELCO supply all 304 stainless. Potential corrosion and Haz area issue | AECOM | 1 |
| Power Island | 47 - Generator CO2 | 1004 | CO2 line has no filter or strainer. It is rarely used which could create fouling issues. MELCO to consider and quote option | MELCO | 1 |
| Power Island | 48 - Generator H2 | 1013 | MELCO to review automating the Hydrogen make up valve as the site is normally not manned. | MELCO | 1 |
| Power Island | 48 - Generator H2 | 1014 | Hydrogen pressure transmitter PT1 is potentially a single point of failure for an unmanned site. MHI to confirm signal failure response | MHI | 2 |
| Power Island | 48 - Generator H2 | 1026 | Dew point monitoring is currently not part of the scope. SHL to request a quotation from MDI to add dew point monitoring | SNOWY HYDRO | 1 |
| Power Island | 48 - Generator H2 | 1022 | MELCO to confirm what happens to the purity meter if CV-1 fails and flow is too low or no flow or needle valve set incorrectly. Hydrogen purity is important for purging requirements | MHI | 2 |
| Power Island | 48 - Generator H2 | 1029 | SHL to develop written procedure for sampling purity with portable analyser to confirm main analyser reading is correct. Drain sampling and valve switching is manual to select top or bottom of the generator sampling. Note sampling drain point is within hazardous area | SNOWY HYDRO | 2 |
| Power Island | 48 - Generator H2 | 1017 | Site wide review of field mounted instrumentation junction boxes and field panels required. These are normally fitted with heaters to prevent condensation | SNOWY HYDRO | 1 |
| Power Island | 48 - Generator H2 | 1018 | MHI to supply instrumentation datasheets for action item 66. To confirm field instrumentation ratings, i.e. +5 - +45 non- condensing?? | MHI | 1 |
| Power Island | 48 - Generator H2 | 1020 | AECOM to study hydrogen detection requirements for this open area plant area and that location is under exciter which probably has cooling fans that could draw H2 into enclosure | AECOM | 1 |
| Power Island | 48 - Generator H2 | 1024 | MELCO to add check valve before CO2 manual isolation valve | MELCO | 1 |
| Power Island | 49 - Generator H2 drying system | 1045 | Hydrogen dryer blower intake is open to atmosphere and in close proximity to the Operator swinging the 3-ways valves. Incorrect procedure (monthly) or Operator error would vent Hydrogen out of air intake. Operator exposure to fire / explosion (static). Design review required. Air intake pipe to safe area to seal system or automated double block and bleed per combustion standard | SNOWY HYDRO | 1 |
| Power Island | 49 - Generator H2 drying system | 1040, 1051 | MELCO to quote additional double block and vent isolation valves for on-line maintenance of heater system, to eliminate H2 purge of complete system. Snowy standard maintenance requirement | MELCO | 1 |
| Power Island | 50 - Generator - Lube oil system | 1064 | There is a discrepancy between MELCO pipe sizes and MHI drawing A-21022 page 2 of 4. MHI to review and correct | MHI | 1 |
| Power Island | 50 - Generator - Lube oil system | 1056 | MELCO design is heavily reliant on Operator alarm response and on site Operator rounds. This is not how Snowy normally operate. Additional instrumentation would be likely be installed on future upgrades. MELCO design to be reviewed for potential instrumentation upgrades | SNOWY HYDRO | 1 |
| Power Island | 51 - Generator - Seal oil vacuum pump and tank | 1084 | AECOM to incorporate seal oil system drip / leak tray overflow to oily water system in their design | AECOM | 2 |
| Power Island | 51 - Generator - Seal oil vacuum pump and tank | 1084 | Seal oil system drip tray or banded area should be remotely monitored for large leaks and potentially auto draining function of sight glass. Similar to fuel oil / lube oil bunds | SNOWY HYDRO | 1 |
| Power Island | 51 - Generator - Seal oil vacuum pump and tank | 1085 | Seal oil vacuum tank fill valve is a single point of failure which can lead to lube oil overfilling the tank and lube oil discharging via the vent stack, potential large quantities due to unmanned site. Alarm response cannot prevent this consequence and would happen quite quickly. Design review required | SNOWY HYDRO | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|--------------|--|-----------------|--|-------------|---------------------------|
| Power Island | 53 - Generator - DC seal oil system | 1116 | MELCO to review design to define the potential consequences of an unmanaged seal oil system failure and loss of hydrogen containment. Snowy will use this information to risk assess the installation per HAZOP guidelines | MELCO | 1 |
| Power Island | 53 - Generator - DC seal oil system | 1123 | Change DC pressure PI-5 to pressure transmitter for DC pump test run and linking to H2 automatic venting system. MELCO team suggest change is technically possible but may cause delays. Snowy to review schedule impact and instruct MELCO accordingly | SNOWY HYDRO | 1 |
| Power Island | 53 - Generator - DC seal oil system | 1124 | MELCO team to confirm DC pump recirc line size. The large size valve passing may result in very low DC seal oil pressure | MELCO | 1 |
| Power Island | 53 - Generator - DC seal oil system | 1126 | AC and DC suction pressure indicators not shown on drawing but will be provided. MELCO to update drawing | MELCO | 2 |
| Power Island | 53 - Generator - DC seal oil system | 1125 | DC pump inlet (suction side) check valve stuck closed resulting in no oil pressure in a demand scenario. Why do we need this valve and is it normally open or closed. Confirm also design of this valve, i.e. spring, lockable, power cylinder?? | MELCO | 1 |
| Power Island | 53 - Generator - DC seal oil system | 1141 | Snowy to review redundant AC seal oil pump configuration requirement and work with MELCO on solution | SNOWY HYDRO | 1 |
| Power Island | 54 - Generator - Gland seal oil system | 1145 | Gland seal system if currently a manually operated procedure that is required during hydrogen fill and 'potentially at full speed to centre the seal rings to reduce shaft vibration. Remotely operated solenoid would be the ideal solution. MELCO to confirm the design requirements and schedule impact to be confirmed | MELCO | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 3 | Add drain points and vibration sensors to P&ID Sht 1 of 4 | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 4 | Piping ratings on drawings need to be corrected | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 5 | Pumps have not been specified yet. System pressure with 2 pumps running to be checked against MHI supplied heat exchangers and the fin fan cooler design pressure | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 6 | Delete upstream individual header pressure indicators and change the downstream individual header pressure indicators to temperature sensors to assist with flow balancing | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 7 | Add fin fan overall dP sensor | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 8 | Add helper cooler discharge pressure and temperature transmitter to P&ID | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans 2 - Helper cooler and booster pump | 9 | Review system design for thermal expansion to assess if a flexible connection is required | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 10 | Review which sensor is better to control the fin fans, CT102 or CT103 | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 11 | Review sensor failure on loss of signal for fin fans, CT102 and CT103 | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 12 | Temperature sensors should be dual elements, even if only 1 is used. Consistent with MHI design | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 13 | Flow balancing valves should be set and forget. Not move with water vibration. Valve selection to consider locking or rigid stem packing to hold commissioned position | AECOM | 1 |
| Power Island | Closed Cooling Water - 1 - Fin fans | 23 | Grease points access needs a lift. SHL to review site requirements hire or buy a scissor lift | SNOWY HYDRO | 3 |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 25 | Add duty standby pumps to drawing | AECOM | 1 |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 26 | Confirm piping pressure rated for two pumps running | AECOM | 1 |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 30 | Review instrument impulse lines for low ambient temp. Threaded socket direct to pipe is probably the best approach. | AECOM | 1 |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 39 | Potential forwarding pressure is sufficient to continuously leak out of helper spray nozzles. Review booster pump or spray bar isolation requirements | AECOM | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|---|-----------------|--|-------------|---------------------------|
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 45 | Helper Cooler spray water is demin that needs to flow (if any) to Trade waste. System is not covered so rain water catchment would also flow to trade waste. To be considered in the design. | AECOM | 1 |
| Power Island | Closed Cooling Water - 3 - Expansion tank | 57 | Water consumption of pump gland seals and leakage to be estimated to evaluate automating tank filling and pump discharge pressure stability. More than 1 x per mth suggest automation required. | AECOM | 1 |
| Power Island | Closed Cooling Water - 3 - Expansion tank | 47 | Add PRVs to instrument air and forwarding demin supplies to prevent overpressure, Press Reg, Sight glass, manifold suction pressure transmitter and level switch to P&ID and suitably rated | AECOM | 1 |
| Power Island | Closed Cooling Water - 5 - GT HP Purge air coolers | 97 | MHI to review HP compressor protection requirements. What are the consequences if the closed cooling water temperature increases above 40 C. Do we need to shutdown the compressors to protect them from damage? | MHI | 2 |
| Power Island | Closed Cooling Water - 5 - GT HP Purge air coolers | 105 | MHI to confirm HP compressor oil pressure and if there is an exchanger leak, will the water flow into the compressor and cause damage? How is this detected? | MHI | 2 |
| Power Island | Closed Cooling Water - 6 - GTG H2 air coolers | 115 | P&ID line 100mm to be updated to 125mm | AECOM | 2 |
| Power Island | Closed Cooling Water - 6 - GTG H2 air coolers | 116 | Pressure regulation wont work as shown. AECOM to review water pressure balancing system. It is important to maintain 5.5 Bar cooling water at exchangers to inhibit H2 leak | AECOM | 1 |
| Power Island | Closed Cooling Water - 6 - GTG H2 air coolers | 135 | AECOM to review and confirm with MHI if any closed cooling water commissioning strainer / removal spool requirements | AECOM | 1 |
| Power Island | Closed Cooling Water - 7 - GT Control oil coolers | 147 | AECOM to review check valve quantity and location. Control oil only has 1 common NRV but other exchangers are individually controlled. Do we need them? | AECOM | 1 |
| Power Island | Closed Cooling Water - 3 - Expansion tank | 61, 69 | Expansion tank bladder inspection and repair access and maintenance requirements to be specified | AECOM | 1 |
| Power Island | Closed Cooling Water - 4 - Cooling water pumps | 71, 91 | Pump discharge manifold PRV to discharge to trade waste system. All (all nodes) CW system drain points need to go to trade waste | AECOM | 1 |
| Power Island | Closed Cooling Water - 4 - Cooling water pumps | 87 | On loss of AC supply, does the closed cooling water system (fans and / or pumps) need to be operational for any specified period time after a black stop. MHI to confirm any run down time requirements | MHI | 1 |
| Balance of Plant | Diesel | 1.1.1 | Requirement to be clear in procedures that quantity delivered is based on tanker dip gauges. | SNOWY HYDRO | 2 |
| Balance of Plant | Diesel | 1.1.2 | Refer to action of 1.1.15. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.3 | Check with the pump vendor if the selected pump can operate for 20 seconds with low flow. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.4 | Review requirement of bleed valve on suction line to the pump. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.7 | Show internal relief of pumps on P&IDs. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.9 | Operating Procedures to include a check of the diesel quality delivered to site. | SNOWY HYDRO | 2 |
| Balance of Plant | Diesel | 1.1.10 | Diesel should be regularly tested to ensure the level is suitable for the Gas turbine. Included regular sampling for quality testing in the operating procedures. | SNOWY HYDRO | 2 |
| Balance of Plant | Diesel | 1.1.11 | Review requirement for commissioning strainers. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.11 | Construction ITPs to include cleanliness checks. | SNOWY HYDRO | 2 |
| Balance of Plant | Diesel | 1.1.12 | Review requirement for valve with position indicator in diesel unloading bund. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.13 | Review requirement for bund size as per AS 1940. Consider making bund big enough for all components on B double. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.14 | Review where pump spill containment is discharged to. Preference is to keep in the pump bund area rather than being discharged into larger road containment bund. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.15 | Process interlock to be reviewed/designed to not allow running both pumps at the same time. Include permissive that valve should be opened before running pump. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.16 | Review process interlock that on/off valves to tank inlet are opened prior to starting the pump. | AECOM | 1 |
| Balance of Plant | Diesel | 1.1.17 | Review requirement for sight glass downstream of flexible couplings. See 1.1.4 | AECOM | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|----------------------|-----------------|--|-------------|---------------------------|
| Balance of Plant | Diesel | 1.2.1 | Review impacts of ramp up and ramp down of delivery to trucks. Review impacts on PD pumps and whether PSV will lift when FCV closes. Could replace PSV with Pressure Reducing Valve. Review if the FCV in the diesel loading skid is required. | AECOM | 1 |
| Balance of Plant | Diesel | 1.2.2 | Process interlock to be reviewed/designed to prevent running both pumps at the same time. | AECOM | 1 |
| Balance of Plant | Diesel | 1.2.4 | Integrate the vendor package with the loading pumps. E stop required for Load bay controller. Check if control should be independent of DCS e.g. Removal of air will close valves and stop the flow. | AECOM | 1 |
| Balance of Plant | Diesel | 1.2.5 | Check tanker loading connection (dry break connection), valving isolation and check valves. Check if there is a sight glass include in line. | SNOWY HYDRO | 1 |
| Balance of Plant | Diesel | 1.2.6 | Review pump head to maintain pressure of the loading arm below 5 barg | AECOM | 1 |
| Balance of Plant | Diesel | 1.2.7 | Review location of discharge of TRV to ensure section that is relieved will not exceed design pressure. | AECOM | 1 |
| Balance of Plant | Diesel | 1.2.9 | Confirm if tanker can be over pressured or has lid open. Ensure tanker vent system is interlocked to avoid overpressure in the tanker. | SNOWY HYDRO | 1 |
| Balance of Plant | Diesel | 1.2.12 | Consider bollards in unloading area | AECOM | 1 |
| Balance of Plant | Diesel | 1.2.13 | Consider whether a weigh bridge or other mechanism to measure amount of fuel being loaded | SNOWY HYDRO | 1 |
| Balance of Plant | Diesel | 1.3.1 | Add a flame arrestor to diesel storage tanks (as per Colongra site) | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.3 | Consider needle control valve in air supply to operate the pump. | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.4 | Use level transmitter as pump shutdown as well as the level switch. | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.5 | Use level transmitter as pump shutdown as well as the level switch. | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.6 | Review the employer requirements to have one or two transmitters. Review how critical this instrument is to the operation of the GT. | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.8 | Review of AS 1940 to determine if any additional temperature control are required | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.9 | SH to provide fuel specification (pour point) of selected fuel to determine if wax formation is likely at the minimum expected storage temperature. | SNOWY HYDRO | 1 |
| Balance of Plant | Diesel | 1.3.12 | Review drain/vent material selection to minimise corrosion. Review coating of tank. | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.13 | Determine if density/viscosity of diesel change significantly with temperature. To be confirmed with fuel supplier | SNOWY HYDRO | 1 |
| Balance of Plant | Diesel | 1.3.17 | Confirm that a potential rain event (i.e. 1 in 100 rainfall event) will not cause instrumentation and control systems to be covered in water. Considering including float switch to alert before control switches are under water. | AECOM | 1 |
| Balance of Plant | Diesel | 1.3.18 | Consider the internal surface of diesel tank to be fully coated. | AECOM | 1 |
| Balance of Plant | Diesel | 1.4.1 | Interlock to prevent 3 pumps running at the same time. | AECOM | 1 |
| Balance of Plant | Diesel | 1.4.2 | Check diesel polishing package has alarm for the differential pressure across filters to alert operators of blocked filters in DCS. | AECOM | 1 |
| Balance of Plant | Diesel | 1.4.11 | Consider an additional separate pump for polishing package. Look at automated prioritised control of forwarding pumps. | AECOM | 1 |
| Balance of Plant | Diesel | 1.5.1 | One inlet return valve to each storage tank to be open at all times. Set fail action to fail last. Oil is returned after GT shutdown. Ensure the inlet line is open for the fuel return to tanks. Keep at least one inlet valve open for diesel return from GT after shutdown. | AECOM | 1 |
| Balance of Plant | Diesel | 1.5.2 | Redundancy and reliability issues need review. Consider running the standby pump at all times so if a single pump trips no loss of flow or pressure to the GT. Perform a dynamic study to determine if only running two pumps and time required for a third pump to start and compensate for loss of flow of tripped pump. How many pumps need to be running if there is a pump trip. Consider n+1 where n is the number of units. | AECOM | 1 |
| Balance of Plant | Diesel | 1.5.6 | Consider installing a small sump and weir in bund to contain smaller leak quantities at pump skid bund. | AECOM | 1 |
| Balance of Plant | Diesel | 1.5.8 | Change PI upstream of flowmeter to be PT | AECOM | 1 |
| Balance of Plant | Diesel | 1.6.4 | Review the interaction of the loading/unloading interaction with curb and lighting. | AECOM | 1 |
| Balance of Plant | Diesel | 1.6.5 | Review causes of fire/consequences. A fire could start on site undetected. Review fire protection and | AECOM | 1 |
| Balance of Plant | Diesel | 1.6.10 | Review bushfire impacts on the fuel tanks. Assess best materials for fencing etc. to minimise this risk. (NOTE: A fence will not prevent ember attack which comes from an elevated height higher than normal fence height). | AECOM | 1 |
| Balance of Plant | Diesel | 1.6.12 | O&Ms to be created by SH | SNOWY HYDRO | 2 |
| Balance of Plant | Natural Gas | 2.1.3 | Use temporary flexible connection for N2 purging with hoses and only connected when required for maintenance. Covered under operating procedures for only connecting N2 when purging is required. | SNOWY HYDRO | 2 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|------------------------|-----------------|---|-------------|---------------------------|
| Balance of Plant | Natural Gas | 2.1.4 | SH have requested to add facilities for a remote operated vent for each pipe section to be opened remotely by operators to reduce pressure in the pipeline over a selected time period e.g. 15 minutes in case of fire. Two vents will be required one for first section between battery limit ESD and SDV upstream of knockout drum and second vent required downstream of gas KO drum ESD for downstream equipment. Consider damage to the packing in the filter coalescer vessel from a high differential pressure across the filter material during venting. Change valve to ESD (currently SDV). Vent valve interlocked to not open until ESD is closed to prevent loss of gas. Review the operation of vent in conjunction with remote operation philosophy i.e., effect of ignition of vent and possibility of air entering the gas line when line depressurised. May effect ability for remote start-up. Vent valve will only close in emergency. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.1.5 | Perform dynamic study of the system based on closure times of the valves. Consider all system shutdown (trip) scenarios. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.1.6 | Confirm there is a safety relief valve in pressure reduction units supplied by MHI. | MHI | 1 |
| Balance of Plant | Natural Gas | 2.1.9 | Review location of vent stack with regard to radiation from ignition of NG. Review potential to co-locate new vents required in APA's vent area | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.1.10 | Include pressure transmitter and local pressure indicator on main line. Provide additional tapping points for gauges if required. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.1.11 | Review whether integral DBB valves can be used instead of separate valves to save cost. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.1.13 | Update PID to show not permanently connected. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.2.2 | Review potential impact on reverse flow through KO pot and demister pad. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.2.3 | Review requirement for Emergency shut off valve EKG01AA161 upstream of KO drum. Consider changing to a manual valve as remote operation of the valve is not required (by SH)ESD can remotely isolate each GT if fire on one unit. Provide a schematic drawing (updated PFD) of ESD and vent valves on gas supply line to each gas turbine. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.2.4 | Change location of level transmitter on the Gas Knock Out Drum of upper tapping point to below filter media | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.2.5 | Remove LSHH trip to shut turbine -Include LSH on maintenance schedule. Frequent tests to make sure it's working. Do not require duplicate drainage system because LSHH trip deleted. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.2.7 | Show a Manhole on Knock Out Drum on P&ID (HPP-AEC-MEC-GA-KOO-DRG-1090). | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.3.3 | Raise an RFI to MHI on whether the position of the temperature flow control valve is important. Difficult to know that TCv has failed. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.3.4 | Check distance from MHI heater to ladder access on stack. | MHI | 1 |
| Balance of Plant | Natural Gas | 2.4.2 | Review setting level of DP alarm level value on Filter Coalescers to ensure sufficient time to swap to other filters (Duty/Standby). | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.4.3 | Review potential impact on reverse flow through Knock Out Drum and demister when opening the remote | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.4.4 | Consider adding sight glass on side of filter coalescers to determine condition of elements. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.4.5 | Remove LSHH trip to shut turbine. Include LSH on maintenance schedule (Frequent tests to make sure it's working). Do not require duplicate drainage system because LSHH trip deleted. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.4.9 | Change PI to PT upstream of filter for DCS indication. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.4.10 | Consider stairs instead of ladders for access. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.5.3 | Review where vents are discharge to e.g. Local High point vent | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.5.5 | Review requirements for nitrogen purge and vent connection between heater and filter to be used during maintenance of filter. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.6.4 | Add small tank drain to allow sampling and flow to drain | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.6.6 | Update datasheet to include a full vacuum conditions that may be caused by condensation of hydrocarbons | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.6.7 | Sight glass to be added on drips tank. Add to P&ID. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.6.9 | Ball valves on P&IDs upstream of NRV to be locked open. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.6.10 | Redirect drain from vent pipe away from drips tank to another location to avoid filling drips tank with water. | AECOM | 1 |
| Balance of Plant | Natural Gas | 2.7.3 | Review requirement for ignition source control entry into hazardous areas e.g. separation barrier, post, chain. SH to provide procedures and training for entry to HA and ignition sources. | SNOWY HYDRO | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.1 | Review amount of H2 required. Consider using less H2 gas bottles. (Raise RFI to SH to ask about minimum requirement for H2 storage cylinders). | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.2 | Review timing for H2 trailer delivery and determine if leakage rate from generator is low enough to not reach low pressure trip whilst H2 trailer is being delivered and changeover. | SNOWY HYDRO | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|-----------------------------|-----------------|---|-------------|---------------------------|
| Balance of Plant | Process Gas (Hydrogen) | 1.1.3 | Review requirement for pressure transmitters on cylinder and trailer H2 supply lines. Considering adding a position indicator on DBB valves on each H2 supply line - This option is not preferred because the position indicator will be in a Hazardous area from the H2 flanges. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.4 | Add pressure transmitter with alarm inside the H2 HP regulator panel downstream of PRV. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.5 | Add NRVs to hydrogen supply line to lines adjoining trailer outlet and cylinder outlet. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.6 | Review purpose of valve on line connected to hydrogen vent pipe (downstream of PRV). Consider locking bypass valve on PRV. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.7 | SH to provide operating procedures to close valve. | SNOWY HYDRO | 2 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.11 | Consider a PT (downstream of the shutdown valve) that closes the shutdown valve. Review what the "shutdown" valve will be called from control perspective | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.13 | Discuss with the Hydrogen supplier (BOC) availability and reliability of H2 supply. | SNOWY HYDRO | 2 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.14 | Review if small filter in N2 line is required to prevent any potential contamination carry over from N2 lines. Consider moving Nitrogen bottles to Hydrogen area to decrease the length of Nitrogen pipeline so this can be relatively cheaply changed to stainless steel. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.15 | Review PSV set point downstream of PRV. Identify suitable set point based on the design pressure the downstream piping. Review pipe specification. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.2 | Review valve fail positions and requirements of locking valves closed. Add valve Failure positions to the PID. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.3 | Review vent line size and confirm large enough size for the number of RVs connected. Review choke velocity in vertical vent pipe and common vent header. Review design pressure of vent line. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.4 | Review vent stack design - potential for liquid seal at base of vent stack to avoid reverse flow of air. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.5 | Review the best location for ESD valve isolating H2 supply from GTs. Consider two ESD valves, one on the supply to each generator. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.6 | Review requirement for remote line depressurising in event ESD valves closing. | AECOM | 1 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.7 | Hydrotest only to be done up to removable spool for each generator. Procedures for testing to prevent water being carried into the generator. | SNOWY HYDRO | 2 |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.8 | Advise MHI of distance between process gas area and generator at each unit. MHI to advise whether pressure increase is acceptable for the pressure reduction panel. | AECOM | 1 |
| Balance of Plant | Process Gas (CO2) | 1.3.1 | Review requirement for NRV in system. | AECOM | 1 |
| Balance of Plant | Process Gas (CO2) | 1.3.2 | Review piping spec to ensure piping downstream of the PRV and inside the CO2 high pressure regulating panel is designed for maximum pressure supplied by cylinders. | AECOM | 1 |
| Balance of Plant | Process Gas (CO2) | 1.3.4 | Review method for getting CO2 cylinders from under roof cover (when cylinder packs are being replaced). | AECOM | 1 |
| Balance of Plant | Process Gas (CO2) | 1.3.8 | Is an emergency activation of CO2 purging required? (i.e. can this wait until an operator is present which maybe an hour later) To be confirmed in the MHI HAZOP. MHI to review operating manual and confirm. Emergency venting of CO2 on the MHI Malco panel upstream of the generator. If there is a fire is venting of the Hydrogen and purging with CO2 for the generator required. CO2 is added to the generator via manual valves (no automated valves) | MHI | 1 |
| Balance of Plant | Process Gas (Nitrogen) | 1.4.1 | Review requirement for N2 supply to the NG equipment and other areas on the Balance of Plant. Confirm whether forklifts can be used to take N2 bottles to the BOP when needed. | AECOM | 1 |
| Balance of Plant | Process Gas (Nitrogen) | 1.4.2 | Review piping spec to ensure piping downstream of the PRV and inside the N2 high pressure regulating panel is designed for maximum pressure supplied by cylinders | AECOM | 1 |
| Balance of Plant | Process Gas (Nitrogen) | 1.4.6 | Review method for getting N2 cylinders from under roof cover (when cylinder packs are being replaced). | AECOM | 1 |
| Balance of Plant | Process Gas (All) | 1.5.3 | Review requirement for separation bollards between H2 trailer and reduction panels. | AECOM | 1 |
| Balance of Plant | Process Gas (All) | 1.5.4 | Talk to BOC about changeover of the H2 trailers and timing of delivery. | SNOWY HYDRO | 2 |
| Balance of Plant | Process Gas (All) | 1.5.4 | Look at possibility of providing two trailer parking spaces next to each other to allow for easier changeover with one prime mover. | AECOM | 1 |
| Balance of Plant | Process Gas (All) | 1.5.5 | Review if any barricade are required for the H2 vent area. | AECOM | 1 |
| Balance of Plant | Process Gas (All) | 1.5.7 | O&Ms to be developed | SNOWY HYDRO | 2 |
| Balance of Plant | Compressed Air (Instrument) | 1.1.1 | Confirm hold up time of 5 min of receivers is adequate. Check RFI response from MHI. Confirm all GT air consumptions with MHI. | AECOM | 1 |
| Balance of Plant | Compressed Air (Instrument) | 1.1.2 | Review the lead/lag control by doing a setback in the control system. | AECOM | 1 |
| Balance of Plant | Compressed Air (Instrument) | 1.1.4 | Confirm there is an automatic system for removing water level in air knock out drum downstream of the compressor. | AECOM | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|------------------------------|-----------------|--|-------------------|---------------------------|
| Balance of Plant | Compressed Air (Instrument) | 1.1.6 | Review the need to provide detailed instrument information from the compressors/dryer packages to the DCS for remote analysis. The aim is to provide enough information as to whether to send an operator to the site after hours. | AECOM | 1 |
| Balance of Plant | Compressed Air (Instrument) | 1.1.7 | Review specification to check the full range of ambient conditions are covered including wet air so vendor will select the appropriate type of filter. | AECOM | 1 |
| Balance of Plant | Compressed Air (Instrument) | 1.2.6 | Remove low low pressure trips on IA supply lines downstream of air receivers. Leave low pressure alarms. MHI have a low pressure alarm on instrument air system. On the GT there are 3 bleed valves that are kept shut. If the air pressure drops the air valves open and the GT trips. | AECOM | 1 |
| Balance of Plant | Compressed Air (Instrument) | 1.2.7 | Review CEMS IA consumption requirements. Add CEMS usage to IA consumption calculation if a large IA consumption is required. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.3.1 | Confirm there is an automatic system for removing water level in air knock out drum downstream of the compressor. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.3.2 | Confirm there is the facility for water removal in the evaporator in package. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.3.3 | Review the need to provide detailed instrument information from the compressors/dryer packages to the DCS for remote analysis. The aim is to provide enough information as to whether to send an operator to the site after hours. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.3.4 | Review the lead/lag control by doing a setback in the control system. | SNOWY HYDRO | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.3.5 | Review specification to check the full range of ambient conditions are covered including wet air so vendor will select the appropriate type of filter | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.3.7 | Consider common vendor for IA and SA packages to reduce need for multiple service agents. | SNOWY HYDRO | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.4.2 | Confirm with MHI there are NRVs at the fuel module to prevent backflow into the SA system from high pressure purge air. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.4.4 | Include drainage of water in the long length of pipeline to the GT and also operation during cold temperatures i.e. freezing. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.4.5 | Consider using stainless steel for SA pipes. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.4.8 | Confirm there is triple redundant pressure indication on instrument and service air purging to the diesel system for pre start condition. | MHI | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.4.9 | Review requirement for using individual air receivers on the power island compared to one receiver on the BOP. | AECOM | 1 |
| Balance of Plant | Compressed Air (Service Air) | 1.4.10 | Consider installation of a temporary compressor fittings for attachment of hire compressors for IA and SA. | AECOM | 1 |
| Balance of Plant | Compressed Air (All) | 1.5.1 | See comments | AECOM | 1 |
| Balance of Plant | Compressed Air (All) | 1.5.3 | Ensure there is access for EWP to remove PSV's for maintenance. | AECOM | 1 |
| Balance of Plant | Compressed Air (All) | 1.5.5 | Review vessel dimensions to cater for inspection entry and requirement for confined space access. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.1.2 | Review the requirements for backup water supply in event of loss of water. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.1.3 | Review back up water supply for critical services i.e. safety showers. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.1.4 | Review potential impacts of extreme cold weather event and the impact of small drain lines freezing would have on site operation. Drain lines to be kept short to reduce risk of freezing. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.1.5 | Consider underground PE piping to safety showers and whether a heater is required in winter. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.1.6 | Construction partner to check the Snowy hydro standard for labelling pipeline and label pipes after construction and before commissioning. | SNOWY HYDRO (UGL) | 2 |
| Balance of Plant | Water (Service) | 1.1.7 | Add a sampling point to potable water line downstream of the site water meter and upstream of the service water tank. Consider facility for potable water lines to be flushed through into the service water tank to replace aged water in the line with fresh water. Potable water to be tested at periodic times as specified by SH. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.2.1 | Review tank outlets/connections - all nozzles to be fitted with valves for isolation | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.2.2 | Replace level switch (LS/LAHH) with another LT because of critical service of tank and add HH to level transmitter. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.2.3 | Confirm tank paint internals on datasheet is compatible with anti-algacide chemicals | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.2.4 | Ensure that drains from tank are separated on model as per P&ID. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.2.5 | Review size of hatch on tank roof to facilitate access for diving. Consider 900mm opening. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.2.6 | Confirm that there are facilities to install a barriers around hatch. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.1.8 | Consider isolation immediately after HW metering facility to allow ability to maintain downstream valves. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.3.3 | Confirm timing of third forwarding pump starting and affecting GT operation. Provide buffer time in evaporative cooler tank at GT. | MHI | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|---------------------------|-----------------|--|-------|---------------------------|
| Balance of Plant | Water (Service) | 1.3.6 | Review use and quantities of portable chemical injection package. Check the quantities of chemicals in this package are kept under the DG minor storage thresholds. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.3.7 | Review the requirements for pressure indicator upstream of kickback PCV in minimum pump flow line. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.3.8 | Review methods for smoothing or minimising the number of pumps starts. Contemplate scenario of leakage and no other flow. Consider whether an accumulator or jockey pump is required for small flows. | AECOM | 1 |
| Balance of Plant | Water (Service) | 1.3.8 | Check if there is a signal from the GT whether the evaporative cooler is operating and the need for 1 or 2 pumps operating. | MHI | 1 |
| Balance of Plant | Water (Demin) | 1.4.1 | Review potential to provide direct connection from potable water supply upstream of service water tank to demin package. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.4.2 | Measured values and alarms from demin package PLC to be available for mimic on the DCS for monitoring remotely by operators. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.5.1 | Review requirements for duty/standby pumps within the packages or requirement to keep uninstalled spares. Alternatively, increase capacity of package to 55m3/h which removes the need for 2 packages to operate simultaneously to supply demin for 3 days continuous operation of GT on diesel. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.5.5 | Notify the RO vendor of potential biocide use in the water supplied to demin package. Include in demin package specification. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.5.6 | Notify the vendor that demin plant may not be used for long periods of time. Confirm demin plant can cope with periods of standby. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.1 | Include two level transmitters instead of a LSH and LT. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.2 | Review the overflow discharge location based on pH of demin and relocate to trade waste. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.3 | Review the possibility of CO2 filter (on tank vent) blocking and causing tank to be under vacuum. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.4 | Review location of tank drains from storm water to trade waste | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.6 | Review size of hatch on tank roof to facilitate diving access. Consider 900mm opening | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.7 | Confirm that there are facilities to install a barrier around hatch and locking facility. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.6.8 | Review tank outlets/connections - all nozzles to be fitted with valves for isolation. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.7.1 | Confirm if one pump is lost there is sufficient time for another pump to turn on before the flow switch trips the GT. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.7.1 | Confirm if one pump is lost there is sufficient time for another pump to turn on before the flow switch trips the GT. RFI to be raised to MHI. | MHI | 1 |
| Balance of Plant | Water (Demin) | 1.7.3 | Consider bypass line around MHI orifice plate to facilitate commissioning. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.7.3 | Consider bypass line around MHI orifice plate to facilitate commissioning. Raise an RFI to MHI. | MHI | 1 |
| Balance of Plant | Water (Demin) | 1.7.4 | Review potential to install automated valves on lines from forwarding pumps to demin treatment package for polishing and demin distribution to allow remote switchover between lines. Add polishing sequence to DCS to allow for remote operation. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.7.6 | Review requirement of pressure indicator upstream of PCV. | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.9.1 | Chemicals and the dosing will be proposed by a water treatment vendor as required by the system. Check there is indication for low levels of chemicals | AECOM | 1 |
| Balance of Plant | Water (Demin) | 1.9.2 | Confirm if automated valves are not in position and there is an output into the DCS to show this. Confirm with package supplier if these valves are interlocked. | AECOM | 1 |
| Balance of Plant | Water (Service and Demin) | 1.10.1 | Raise RFI to SH to confirm stainless steel grade required (304 or 316). | AECOM | 1 |
| Balance of Plant | Water (Service and Demin) | 1.10.3 | Determine desired system response in emergency shutdown (from safety perspective). Apply this to all subsystems. Provide a list of impacts of any system shutdowns on ability of GT to operate. | AECOM | 1 |
| Balance of Plant | Water (Service and Demin) | 1.10.4 | Review location of all demin drains to ensure they all go to neutralisation pit. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.5 | Update critical valves to be locked open e.g. for valves on fire fighting system (Show on P&ID). | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.6 | Confirm the pressure drop to the tank and flowrate meet the requirements of AS2419. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.7 | Review requirement for nozzle fill point on tanks for emergency tank filling by tanker. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.8 | Confirm that RFS connection standards are met. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.9 | Review need for sample point on firewater system. Review best location for sample point i.e. one on each tank or upstream of fire water pumps. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.10 | Review access provisions through tank liner and manhole access. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.12 | Review tank outlets/connections - all nozzles to be fitted with valves for isolation. | AECOM | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|----------------------|-----------------|---|-------------|---------------------------|
| Balance of Plant | Fire Water | 1.1.13 | Confirm tank bladder is compatible with biocides that may be required for water treatments. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.1.14 | Provide description of how the auto fill valve will be maintained, isolated and bypass used. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.2.1 | Review the potential to provide auto fill from site diesel storage tanks to the smaller diesel tank near diesel driven firewater pump. If diesel tank for pump is filled manually consider manual handling requirements of how this tank is filled. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.2.2 | Add locked open valve on relief line. Review AS2941 to see if this is permitted | AECOM | 1 |
| Balance of Plant | Fire Water | 1.2.3 | Review the position of balance line to minimise potential of silting in line. Confirm height of line above tank | AECOM | 1 |
| Balance of Plant | Fire Water | 1.2.6 | Review battery system monitoring alarm interface with DCS for monitoring. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.2.7 | Review where the outlet of TRV on firewater pump outlet is to be directed and select a suitable location. | AECOM | 1 |
| Balance of Plant | Fire Water | 1.2.8 | Review the potential for embers and overloading the air intake system in the event of a bushfire. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.3.4 | Review management of algae in pit. Include in package spec and discuss potential options with vendors. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.3.6 | Review use of stairs instead of ladder into pit. Look at removable type of stairs to prevent fouling of stairs. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.3.7 | Review requirement for isolation of incoming drains to allow access to pit to provide correct isolation. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.4.1 | Confirm interface of package with DCS. Determine what information needs to be transferred to DCS. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.4.3 | Confirm if piping between filter and pumps and filter is designed for a vacuum conditions. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.4.4 | Vendor supplier to confirm if oil water separator does not operate for a period of time what (if any) effects this would cause on the reliability of the unit. Specification of package to include mention of extended periods on downtime. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.4.5 | Review potential impacts of winter operation. Include in specification that unit needs to operate during low ambient conditions | AECOM | 1 |
| Balance of Plant | Oily Water | 1.4.6 | Review the operational area of the skimmer pit. Consider sloped floor on main pit to concentrate sludge for ease of cleaning and allow oil/ water to be diluted. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.4.8 | Ensure vent location is at an adequate height to disperse any hazardous vapours. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.5.1 | Review oil and diesel vent points in the GT area to ensure no diesel can flow to the stormwater discharge point. All oil vents to drain to oily water system with concrete apron. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.5.2 | Review requirements for capture during construction for containment of drainage carryover. To be reviewed in CHAIR. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.6.1 | Confirm if oily water system is considered in fire safety study. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.6.2 | Review the requirement for monitoring of fire traps liquid level and regular maintenance of fire traps. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.6.3 | Review potential to install a smaller initial volume within decanting pit for concentrated spills. Consider interface level detection. Review requirement for detection of high-level oils in the observation pit and how this can be achieved. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.6.3 | Review operational response to a high-level oil in the decanting pit. | SNOWY HYDRO | 1 |
| Balance of Plant | Oily Water | 1.6.4 | Review location of humeceptor in location to highest flood level. | AECOM | 1 |
| Balance of Plant | Oily Water | 1.6.6 | Seek further guidance from SH environmental team on whether a penstock valve is required on humeceptor discharge line to the environment. | SNOWY HYDRO | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.1.1 | Confirm final pit volume is sufficient to contain all the flows from blade washing and closed loop cooling water volumes. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.1.3 | Determine if the blade washing water with detergent can be disposed to the trade waste (HWC criteria for maximum concentration). When detergent is used for off-line blade washing (approx. once a year) the GT compressor wash pit should be isolated and removed by sucker truck. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.1.3 | Test the blade wash water after commissioning to check analysis meets HWC criteria for trade waste. | SNOWY HYDRO | 3 |
| Balance of Plant | Trade Waste & Sewer | 1.1.3 | Confirm the iron concentration in wash water. Is 220 mg/l the normal concentration during off line washing? | MHI | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.2.1 | Review the neutralisation pit capacity to cater for emergency storage in the event of not having access to pump out to the trade waste. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.2.5 | Confirm the impacts of chemicals used in demin plant CIP to neutralisation pit. Confirm if the concentration of COD from the CIP chemicals from the demin plant will be suitable for discharge to trade waste or whether removal by tanker is more appropriate. | AECOM | 1 |

HAZOP Recommendations Completion Schedule by Project Phase

| Design Area | System or Sub-System | Finding Ref No: | Recommendations | Owner | Required Completion Phase |
|------------------|----------------------|-----------------|--|-------------|---------------------------|
| Balance of Plant | Trade Waste & Sewer | 1.2.6 | Replace local PI with pressure transmitter downstream of transfer pumps to prove there is no damage to HWC trade waste main from the transfer pump. Review best location for this PT to measure discharge pressure. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.2.7 | SDV's downstream of the transfer pumps to HWC line to fail closed. SDV's downstream of the transfer pumps returning to pit fail open to prevent dead heading of pump. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.2.8 | Consider removal of pump with a roof above the pit | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.2.9 | Materials of pit to consider acid and caustic dosing. (Epoxy coating). | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.2.10 | Ensure dosing of acid and caustic is located at opposite end of pump suction and adequate recirculation time to ensure good mixing of neutralisation chemicals. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.3.1 | Include either an alarm for continual operation of the pump (or too frequent operation) or investigate other solutions to reduce overdosing (Review requirement for two pH meters for checking that pH is moving in the expected direction). | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.3.2 | Chemicals to be dosed are TBC. If caustic is used potential for freezing in lines needs to be considered. Include in the package specification the range of ambient temperature. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.3.4 | Review the replacement process for the chemicals (tank or drum) and if minimal contact with the chemical for the operator | AECOM | 2 |
| Balance of Plant | Trade Waste & Sewer | 1.3.7 | Consider the type of acid and potential to vaporise. Dilute sulphuric acid is preferred. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.3.8 | FS is sometimes included in the line downstream of the PSV to indicate the PSV has lifted. Check the vendor package includes this. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.4.4 | Consider providing a sewer connection in temporary. offices/facilities area. Review potential to use temporary toilet blocks on site. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.4.5 | Alarms from sewerage pit to DCS so operators are aware of high/low level in sewerage pit when no one on site. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.4.7 | Consider odour from the tank and a filter. | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.5.2 | Review application of flushing water to the pit and potential to use potable water and a garden hose | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.5.4 | Confirm noise limits included in the package specifications | AECOM | 1 |
| Balance of Plant | Trade Waste & Sewer | 1.5.5 | Ensure safety shower is no further than 10 m from chemical storage if dosing chemicals are being decanted | AECOM | 1 |
| Power Island | General | | Design interfaces between 3rd parties (AECOM balance of plant, MELCO hydrogen seal oil systems, Fire and Gas systems) were mostly but not fully developed. Design completion of the 3rd party interfaces will need to be managed carefully. Should the design or system interface change it would be best practice to HAZOP those sections of plant again. Review whether this additional study is required prior to construction. | SNOWY HYDRO | 1 |
| Power Island | HP Air Compressor | | The high-pressure air compressors interlocks and protection is not well understood at this time and action items are with MHI to confirm with their 3rd party vendor. Review this section of the plant again on completion of design and suitable interlock and protection information becomes available. | MHI | 1 |

Appendix F

Current HAZOP Recommendations Status

| Design Area | System or Sub-System | Finding Ref (AECOM report) | Recommendations | Owner | Required Completion Phase | Type | Does it relate to a SHL OI / procedure to be drafted? | Status |
|--------------|--|-------------------------------|--|-------------|---|--|---|---|
| | | | | | 1 - Prior to design completion 2 - Prior to commissioning 3 - Prior to handover | Firm action / recommendation A verification check Further Study For consideration | | |
| Power Island | General | Report | Design interfaces between 3rd parties (AECOM balance of plant, MELCO hydrogen seal oil systems, Fire and Gas systems) were mostly but not fully developed. Design completion of the 3rd party interfaces will need to be managed carefully. Should the design or system interface change it would be best practice to HAZOP those sections of plant again. Review whether this additional study is required prior to construction. | SNOWY HYDRO | 1 | Firm | No | CLOSED. Design interfaces between the various parties have been developed and will continue to be managed accordingly in order to finalise the design and close out the HAZOP actions. |
| Power Island | HP Air Compressor | Report | The high-pressure air compressors interlocks and protection is not well understood at this time and action items are with MHI to confirm with their 3rd party vendor. Review this section of the plant again on completion of design and suitable interlock and protection information becomes available. | MHI | 1 | Verify | No | CLOSED. During the progression of the design development, MHI were able to provide additional information regarding the air compressor interlocks and protection. MHI determined that the compressor's had adequate interlocks and protection for the intended design. |
| Power Island | 1 - Fuel Oil - High pressure Pump | 3 | Confirm forwarding pump deadhead pressure and prv | SNOWY HYDRO | 1 | Verify | No | CLOSED. Dead head pressure of proposed pump (Goulds 3196 MTI Size 1.5 x3-13/5V) is 1098 kPag with a full diesel tank of 11 m. However, supply to GT has two pressure control set at 700 kPag so pressure should not normally exceed 700 kPag. Forwarding pumps also have minimum flow kick back valve which will be set at the pressure equivalent to the minimum flow for the forwarding pumps which will prevent the pumps being dead headed. The minimum flow kick back valve is fail open. (K. Wells) |
| Power Island | 1 - Fuel Oil - High pressure Pump | 4 | Review bunding requirements around FO pumps | SNOWY HYDRO | 1 | Verify | No | CLOSED. General area around Main Fuel oil pump is not bunded. Pump skid has an integral drips tray with discharge point piped to the oily water system. Given the high operating pressure of the outlet a rupture would not be contained in a reasonable sized bund in the case of a major rupture. The area is concrete/ hardstand and any spill will be directed to storm water with provision to impound a spillage via penstock valves. |
| Power Island | 1 - Fuel Oil - High pressure Pump | 5 | Confirm \$ cost per unit trip / 1 hr outage | SNOWY HYDRO | 1 | Verify | No | CLOSED Is this a HAZOP action? Looks commercial |
| Power Island | 1 - Fuel Oil - High pressure Pump | 6 | All ball valves to be lockable | SNOWY HYDRO | 1 | Firm | Yes | CLOSED Manual Valve Spec HPP-AEC-MEC-GN-GEN-SPT-0003_B includes: "All isolation valves must be lockable by padlock." |
| Power Island | 1 - Fuel Oil - High pressure Pump | 7 | SHL to review who supplies instrumentation at MHI interfaces | SNOWY HYDRO | 1 | Study | No | CLOSED as per DOR in P&IDs |
| Power Island | 1 - Fuel Oil - High pressure Pump | 12 | AECOM to consider heat tracing for FO dwg 2of 5. Start up temperature should be 11 deg C. Alternative may be an enclosure for the pump and piping | SNOWY HYDRO | 1 | Consider | No | CLOSED heater provided in FO tank and heat tracing to fuel nozzles. |
| Power Island | 2 - Fuel Oil - Manifold pressure control | 36 | The screw pump has no min flow bypass return line. The HP pump only starts when burners are to be lit. When no burner flow the manifold pressure control valve acts as the min flow control. MHI to confirm forwarding pump flow rate through HP screw pump when shutdown | MHI | 1 | Firm | Yes | Awaiting AECOM response |
| Power Island | 5 - Fuel Oil - Flow divider | 95 | MHI manual ball valves should all be lockable | SNOWY HYDRO | 1 | Firm | Yes | CLOSED MHI to supply complete valve list, SHL to indicate locking type for purchase |
| Power Island | 6 - Fuel Oil - Burners | 124, 517, 565 | Pantac to review blade path flameout voting logic. One or multiple burners, adjacent burners, single or duplex t/c. No optical flame detectors | SNOWY HYDRO | 2 | Study | No | |
| Power Island | 6 - Fuel Oil - Burners | 127 | MHI to advise combustion frequency sensor criticality. Commissioning tool or protection | MHI | 2 | Firm | No | CLOSED Extended operation can lead to catastrophic failure. Combustion components and blades |
| Power Island | 6 - Fuel Oil - Burners | 129 | SHL investigating additional diesel fuel quality reports | SNOWY HYDRO | 2 | Study | No | CLOSED testing complete |
| Power Island | 7 - Fuel Oil - Drain tank | 144 | MHI to confirm if there is a drain tank Hi level start permissive. Unit won't start with high level | MHI | 1 | Firm | Yes | CLOSED SHL to determine drainage or start permissive philosophy. Including environmental risk of overflow. |
| Power Island | 7 - Fuel Oil - Drain tank | 147 | SHL to confirm with operations to see if small lines have been problematic with non-return valves failing / passing | SNOWY HYDRO | 1 | Study | No | |
| Power Island | 7 - Fuel Oil - Drain tank | 148 | AECOM to consider drain pit discharge hi alarm to start pump and hi hi to alarm to remote operations | AECOM | 1 | Consider | Yes | IN PROGRESS Drain pit is gravity system connected directly into the site wide OW gravity system. No level switch/alarm included in the drain pit. Verify when design is complete. |
| Power Island | 7 - Fuel Oil - Drain tank | 149 | AECOM Fuel oil discharge to oily water pit detection to be considered in design | AECOM | 1 | Consider | Yes | IN PROGRESS Noted. Flow switch added to overflow pipe to detect discharge through the Drains tank overflow line. This will detect discharge of fuel oil. Verify when design is complete. |
| Power Island | 8 - Fuel Oil - Water injection | 159 | MHI to confirm at what load level water injection is enabled. Also when water injection is not correct the unit would go to run back load, where water injection is turned off. | MHI | 1 | Firm | Yes | CLOSED WI on at 100MW load at load up operation, Pilot water injection on during start up.WI off at 85MW at load down operation |
| Power Island | 8 - Fuel Oil - Water injection | 160 | SHL to confirm action required when water injection is off, i.e. valley will try to restart water injection 3 times and max operating time without water injection is 15 minutes. Automatic shutdown required, tbc and advise to MHI or add into station controls | SNOWY HYDRO | 2 | Firm | Yes | CLOSED SHL to specify shutdown requirement on water injection fail to operate. |
| Power Island | 8 - Fuel Oil - Water injection | 161 | Oily water pit to be covered with rain shelter | AECOM | 1 | Firm | No | IN PROGRESS Noted. Low profile cover shall be installed off the pit bund. Verify when the design is complete. |
| Power Island | 9 - Fuel Oil - Water injection | 169 | AECOM to consider valve failure, excessive flow to oily water pit overflow during runback time. Flow balance required. MHI to advise oily water flow rate and volumes expected during normal operating conditions and if one of the drain valves fails open, MBN13AA735,AA736,AA737 based on SHL RFI document | AECOM | 1 | Firm | Yes | CLOSED. Drain pit uses a gravity drain system and has been sized matched to flow rate and not expected volume. So if the valves fail open and continue to flow it will be accommodated by the local drainage system. |
| Power Island | 8 - Fuel Oil - Water injection | 170 | Water injection flow transmitter is a single point of failure which would cause diesel outage, so it is critical for operation. Redundancy for valve control per fuel oil control should be considered. MBU02CP531. | SNOWY HYDRO | 1 | Firm | Yes | Awaiting MHI quote for inclusion of additional transmitters |
| Power Island | 8 - Fuel Oil - Water injection | 171 | Single point of failure mode analysis should be completed at a suitable time. SHL internal item | SNOWY HYDRO | 3 | Study | No | Awaiting MHI submission of logic diagrams |
| Power Island | 8 - Fuel Oil - Water injection | 172 | Outage, run back, emergency trip restart time cost analysis required for Risk Assessment decision around device fault tolerance, i.e. trip or 1 hours outage = 800k (330MW x 2500MW/Hr x 1 hr), additional instrument = 20k installed | SNOWY HYDRO | 1 | Study | No | |
| Power Island | 9 - Fuel Oil - Purge credit block valves | 184 | Purge credit details are not well understood by Operations. There is a manual, Operating Procedure(S4-96597), that describes it in more detail. Type B compliance, intermittent or continuous turning and start and re-purge credit are all good questions. Potentially every 8 days the unit needs repurging, which can lead to more blade wear (wobbling in root) and starter problems. This item to be revisited by Operations with MHI detail input. | SNOWY HYDRO | 3 | Study | Yes | CLOSED Purge Credit no longer required. |
| Power Island | 9 - Fuel Oil - Purge credit block valves | 191 | MHI to review if fuel oil from the fuel oil purge credit can go to the tank not the pit as it is clean fuel. Environmental credit | SNOWY HYDRO | 1 | Study | Yes | CLOSED |

| | | | | | | | | |
|--------------|--|---------------|---|-------------|---|--------|-----|--|
| Power Island | 9 - Fuel Oil - Purge credit block valves | 192 | Fuel oil purge credit valves only have a single limit switch, preference for both open and closed indication, all valves (block, drain, N2). AECOM supply these valves | SNOWY HYDRO | 1 | Firm | Yes | PENDING CLOSURE This action superceded by MHI and SHL removing the purge credit system from the Fuel Oil System - TBC by official instruction. Pending RFI on cancellation of purge oil credit system |
| Power Island | 11 - Fuel Gas - Supply pressure control | 216 | MHI to check logic. Gas vent valve out of position during operation should be a trip. Redundant limit switches may be. | MHI | 2 | Verify | Yes | CLOSED MHI to ensure an alarm is set for the incorrect state of the vent valve in their GTC |
| Power Island | 11 - Fuel Gas - Supply pressure control | 217 | AECOM should review vent valve position failure actions | AECOM | 2 | Study | No | CLOSED. Remote operated vent valve is located downstream of filter coalescers and will only be opened in emergency situation by an operator when gas supply needs to be vented down quickly for fire or gas leak. Actuated valve is air failure close. Data sheet will include requirement for duplicate limit switches. On start-up if 1 out of 2 limit switches show the vent valve is open then the GT startup should be prevented. (K. Wells) MHI gas vent points are piped to discharge point at safe location, adjacent to GT enclosure ventilation discharge. 8m above GT enclosure and 17m from ground level. |
| Power Island | 11 - Fuel Gas - Supply pressure control | 218 | AECOM to review appliance manual isolation valve per AS3814 requirements within 5m of the appliance. Paul van Dyk to confirm AS3814 clause requirements | SNOWY HYDRO | 1 | Verify | No | CLOSED 5m is considered remote for individual burners but one lockable handvalve for the unit pre-coalser meets the requirements. AECOM model location is similar to Laverton |
| Power Island | 11 - Fuel Gas - Supply pressure control | 219 | Tapping points for pressure testing / leak testing valves not shown on P&ID. Additional testing points may be required. SHL to review based on length of pipework and valve locations. | MHI | 1 | Study | No | CLOSED SHL provided MHI mark up with tapping points. Additional tapping points were discussed and agreed. |
| Power Island | 11 - Fuel Gas - Supply pressure control 17 - Fuel Gas - GT sweep (purge air) | 223, 350 | MHI to review AS3814 section 2.13 requirement for sufficient test points to verify the integrity of shutoff valve / train. | MHI | 1 | Study | No | CLOSED |
| Power Island | 12 - Fuel Gas - Flow control | 231 | RFI for the purpose of the HAZOP the main question, is there a single point of failure (DPT) and what would be consequence of a critical time pressure excursion explosion. Is DPT control or protection, refer control description fig 2.9.1 | MHI | 1 | Study | No | No reference to 2.9.1 in the HAZOP report CLOSED |
| Power Island | 15 - Fuel Gas - Combustor drain valves | 301 | MHI to confirm temperature rating of pipework after MBA01AA704, burner drain valve. Rating drops from 525 to 60 Celsius | MHI | 1 | Verify | No | CLOSED. Since this valve is always closed during operation and opens after GT stops, the temperature of the drain and air flowing out is considered to be low at that time. In addition, although the piping from the drain valve to the pit depends on the design of the EPC side, the temperature is considered to be sufficiently low considering the heat dissipation during the piping. |
| Power Island | 15 - Fuel Gas - Combustor drain valves | 304, 871, 878 | Water wash procedure has many manual valves which could potentially lead to false start by flooded combustion chamber and subsequently detergent flow into the oil water pit. SHL to develop a water wash procedure with 2 operators to cross check. Water washing drain header could also have small amounts of diesel residue from liquid fuel false start. | SNOWY HYDRO | 3 | Firm | Yes | CLOSED to be considered in Ops Readiness |
| Power Island | 18 - Fuel Gas - Flow meter | 368 | Commissioning spool required for flow meter, that will need to be removed for pipe blow down activities. Mark up P&ID | AECOM | 2 | Firm | No | CLOSED. Note 3 has been added to PIDS 1094 and 1144. |
| Power Island | 19 - Fuel Gas - Filter and purge credit | 397 | Add instrument tapping point for Nitrogen entry for valve leak testing, with smaller volume than upstream line | AECOM | 1 | Firm | No | CLOSED. Nitrogen purge point has been added to PID 1097 for purging of Section of piping from after Filter/ Coalescers isolation valves, through temperature control valve, FGH and last chance cartridge filter. |
| Power Island | 20 - Fuel Gas - Calorie meter | 403 | Calorie meter. 1. Cal gas bottles only have single regulator and no relief valve. Potential single point of failure. Is meter rated for cal gas pressure. 2. If reg fails, is it possible to reverse flow cal gas into the gas line? 3. Why is there a flow meter in the vent line? | MHI | 1 | Verify | No | CLOSED |
| Power Island | 21 - Air & Flue Gas - Seal air | 432 | All ball valves to be lockable. Evan to confirm who is responsible for providing the pad locking system for all the manual isolation valves and to ensure the valves have lock tabs, refer also action item 4. Also send sample photos to MHI. The requirement is in the tender specification section 2.3 | SNOWY HYDRO | 1 | Firm | No | Evan's name should be removed CLOSED SHL have confirmed MHI and AECOM will provide lockable valves. |
| Power Island | 24 - Air & Flue Gas - GT HP Bleed valve | 506 | MHI to confirm failure mode of IGV, i.e. fail last position, fail ramp closed on loss of control oil or power? | MHI | 2 | Verify | No | CLOSED If the GT is tripped due to low control oil pressure, the IGV will not operate. Therefore, the IGV will open and trip, it has possibility to compressor surge. |
| Power Island | 25 - Air & Flue Gas - Inlet duct flow 27 - Air & Flue Gas - Combustor and Exhaust | 515, 563 | 2oo3 trip voting degradation to be reviewed on a trip by trip basis by SHL, 2oo3, 1oo2 or 2oo2 and 1oo1 = trip or run? | SNOWY HYDRO | 2 | Study | ? | Awaiting MHI documentation |
| Power Island | 29 - Lube Oil - Tank, pumps, prv | 608 | DC Lube oil pump to be tested prior or after each start to prove functionality. Replacing MBV01CP304 DC lube oil pressure gauge with a transmitter would facilitate fast auto test sequence. Requirements to be confirmed by SHL. | SNOWY HYDRO | 1 | Firm | Yes | MHI to update relevant documentation to reflect change of instrument to transmitter |
| Power Island | 30 - Lube Oil - GT bearings 50 - Generator - Lube oil system | 633, 1060 | SHL to review high temperature alarm shutdown requirements for Hunter. Remote operator may not react in time. | SNOWY HYDRO | 2 | Study | Yes | CLOSED Requirement has been reviewed in LOPA. Issue addressed in final LOPA report. |
| Power Island | 30 - Lube Oil - GT bearings | 646 | SHL may request additional oil sampling point downstream of the bearings (generator and turbine). MHI to review installation requirements and advise accordingly | MHI | 1 | Verify | No | CLOSED. We will provide the sampling nozzle with hand operated valve(15A) for #1 and #2 GT bearing drain piping. Please confirm the attached P&ID(attachment-2). This is additional request , we will inform our quotation and schedule impact later, so please make a decision as soon as possible. |
| Power Island | 34 - Control Oil - Tank, pumps, temp control | 724 | There is a wall in the oil tank which may create different tank levels, design to be confirmed by MHI | MHI | 1 | Verify | No | CO TANK level condition will be added to GT start permissive condition. |
| Power Island | 35 - Control Oil - Fuel valve position control | 753 | Fuel gas and Fuel Oil control oil dump valves are single point of failure and common cause fraction is high. Is this allowed per the standard. Valves should failsafe and individually actuated?? PVD to review in detail as part of AS3814 compliance | SNOWY HYDRO | 1 | Verify | No | CLOSED MHI existing control oil arrangement will remain, shut off valves will be considered one double block and bleed, purge credit function removed in place of 2x shut off and 2x vent valves. |
| Power Island | 36 - Control Oil - Fuel valve trip solenoids & Inlet Guide Vanes | 774 | Control oil dump circuits to be reviewed against SIL requirements and AS3814 compliance | SNOWY HYDRO | 1 | Verify | No | CLOSED as above |
| Power Island | 37 - Package Enclosure Ventilation | 791 | Note AECOM responsible for Fire protection of the Balance of Plant equipment such as lube oil package, fuel oil pump / valve systems and how that system is interlock or integrated into the plant DCS or MHI GT controls. AECOM is design stage now. Fire safety study is well advanced MHI fire and gas detection limited to GT enclosure and Fuel Gas valve systems. SHL to review final design proposal | SNOWY HYDRO | 1 | Study | No | CLOSED AECOM to include water based fire suppression in FO unit. |
| Power Island | 37 - Package Enclosure Ventilation | 792 | Door tracking isolating the CO2 if someone enters the GT is to be confirmed by vendor and reviewed by SHL | SNOWY HYDRO | 1 | Verify | Yes | CLOSED MHI have provided quote for SHLs consideration |
| Power Island | 38 - Air & Flue Gas - Inlet filter | 805 | Ambient conditions -5 C to +45 C. Anti-icing system was considered in the tender specification but MHI advised at that time it is not required. MHI to revisit the study and reconfirm anti-icing is not required. | MHI | 1 | Study | No | Likely to be N/A CLOSED |
| Power Island | 42 - Evaporative Cooler - pump and tank unit | 887 | Valve numbers and instrument numbers and line sizes are not shown on the drawing. Return valve is shown as control valve but is actually a manual lockable isolation valve | MHI | 3 | Firm | No | CLOSED MHI have updated drawing |

| | | | | | | | | |
|--------------|--|------------|--|-------------|---|--------|-----|--|
| Power Island | 42 - Evaporative Cooler - pump and tank unit | 893 | Evap tank water is potable water. Should overflow or draining be discharged to Trade Waste or Storm Water. AECOM to review and design accordingly | AECOM | 1 | Study | Yes | IN PROGRESS. Part of larger trade waste discussion. Overflows and drains to be ported to trade waste. This is currently directed to the trade waste. AECOM cannot advise SH which is preferred as this should be advised by site Environmental manager. Blowdown is potable water with slight elevation of salts left behind due to evaporation - AECOM request to be advised if blowdown discharge/drainage should be changed as drain design impacted. |
| Power Island | 42 - Evaporative Cooler - pump and tank unit | 899 | Evap tank has no sample point. MHI to review option to supply | MHI | 1 | Firm | Yes | CLOSED sample point added |
| Power Island | 44 - Generator cooling water | 928 | MELCO interface details required for AECOM water services. Water pressure recently increased to 7.5 Bar. AECOM to advise MELCO final supply pressure. MELCO cooler to be designed accordingly | AECOM | 1 | Firm | No | CLOSED |
| Power Island | 44 - Generator cooling water | 932 | MELCO to provide full list of generator protection settings, trips complete with alarms, auto shutdown and run backs | MELCO | 2 | Firm | No | CLOSED |
| Power Island | 45 - Generator CO2 gas supply | 951 | Manual purging requires strict procedure with 2 people to cross check to confirm successful purge | SNOWY HYDRO | 2 | Firm | Yes | "strict" probably 'start' CLOSED to be included in Ops Readiness |
| Power Island | 45 - Generator CO2 gas supply | 950 | CO2 site capacity to be assessed against minimum volume required for a successful purge times a safety factor. Potential bottle leak reduces capacity. Is adequate monitoring installed, flow pressure bottle weight | AECOM | 1 | Firm | No | IN PROGRESS Each generator requires 220 Nm3/time to purge which is equivalent to 15 G size cylinders ie 1 man pack. 4 manpack are to be kept on site which is double the quantity required to purge 2 generators. SH to review this quantity. There is a PIT downstream of the bottle connection. However, there is no FI on the process gas pressure reduction skid or the MHI CO2 supply skid. Weigh scales could be considered when the gas supplier and process gas pressure reduction skid design has been developed. |
| Power Island | 45 - Generator CO2 gas supply 53 - Generator - DC seal oil system | 957, 1128 | Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. MHI incorporate in design, logic to action valve | MHI | 2 | Firm | No | Snowy Hydro has also instructed the Supplier to develop a suitable automated venting and purging design to reduce this risk and are currently working with the Supplier to implement this design. |
| Power Island | 45 - Generator CO2 gas supply | 958 | Automated Hydrogen venting and CO2 purging system required. Not currently in the scope. AECOM to incorporate automate CO2 supply to the units | MELCO | 2 | Firm | No | Snowy Hydro has also instructed the Supplier to develop a suitable automated venting and purging design to reduce this risk and are currently working with the Supplier to implement this design. AECOM CO2 System as currently designed can be permanently connected to generator CO2 supply panel as designed by MHI. |
| Power Island | 46 - Generator H2 gas supply | 970 | Unit H2 flow meter can be used for make up flow monitoring, leak and PRV lifting detection. MELCO to consider adding flow meter to measure H2 consumption | MELCO | 2 | Firm | No | Modification recommended to improve monitoring and detection of H2. Supplier currently reviewing the design change and implementation aspects. |
| Power Island | 46 - Generator H2 gas supply | 983 | AECOM to review H2 pipework for dissimilar metals. MELCO supply all 304 stainless. Potential corrosion and Haz area issue | AECOM | 1 | Firm | No | CLOSED |
| Power Island | 47 - Generator CO2 | 1004 | CO2 line has no filter or strainer. It is rarely used which could create fouling issues. MELCO to consider and quote option | MELCO | 2 | Study | No | Awaiting quote from MELCO |
| Power Island | 48 - Generator H2 | 1013 | MELCO to review automating the Hydrogen make up valve as the site is normally not manned. | MELCO | 2 | Study | No | Snowy Hydro has also instructed the Supplier to develop a suitable automated make-up design to reduce this risk and are currently working with the Supplier to implement this design. |
| Power Island | 48 - Generator H2 | 1014 | Hydrogen pressure transmitter PT1 is potentially a single point of failure for an unmanned site. MELCO will consider multiplexing the transmitter PT1. | MELCO | 2 | Firm | No | Modification recommended to improve monitoring and detection of H2. Supplier currently reviewing the design change and implementation aspects. |
| Power Island | 48 - Generator H2 | 1026 | Dew point monitoring is currently not part of the scope. MELCO will consider adding the dew point monitor to the Gas control unit. | MELCO | 2 | Firm | No | Modification recommended to improve monitoring of H2 performance and quality. Supplier currently reviewing the design change and implementation aspects. |
| Power Island | 48 - Generator H2 | 1022 | MELCO to confirm what happens to the purity meter if CV-1 fails and flow is too low or no flow or needle valve set incorrectly. Hydrogen purity is important for purging requirements | MHI | 2 | Verify | No | CLOSED |
| Power Island | 48 - Generator H2 | 1029 | SHL to develop written procedure for sampling purity with portable analyser to confirm main analyser reading is correct. Drain sampling and valve switching is manual to select top or bottom of the generator sampling. Note sampling drain point is within hazardous area | SNOWY HYDRO | 2 | Firm | Yes | CLOSED to be considered in Ops Readiness |
| Power Island | 48 - Generator H2 | 1017 | Site wide review of field mounted instrumentation junction boxes and field panels required. These are normally fitted with heaters to prevent condensation | SNOWY HYDRO | 1 | Study | No | CLOSED |
| Power Island | 48 - Generator H2 | 1018 | MHI to supply instrumentation datasheets for action item 66. To confirm field instrumentation ratings, i.e. +5 - +45 non-condensing?? | MHI | 1 | Firm | No | CLOSED |
| Power Island | 48 - Generator H2 | 1020 | AECOM to include a fire suppression system in the area around the gas control and seal oil unit to further mitigate and fire risk. Gas detection requirements in this area to be studied. | AECOM | 1 | Firm | No | AECOM has designed a fire suppression system in and around the seal oil and gas control unit. |
| Power Island | 48 - Generator H2 | 1024 | MELCO to consider adding check valve before CO2 manual isolation valve | MELCO | 2 | Verify | No | Modification recommended to reduce potential backflow risk. Supplier currently reviewing the design change and implementation aspects. |
| Power Island | 49 - Generator H2 drying system | 1045 | Hydrogen dryer blower intake is open to atmosphere and in close proximity to the Operator swinging the 3-ways valves. Incorrect procedure (monthly) or Operator error would vent Hydrogen out of air intake. Operator exposure to fire / explosion (static). Design review required. Air intake pipe to safe area to seal system or automated double block and bleed per combustion standard | SNOWY HYDRO | 1 | Study | No | CLOSED to be considered in Ops Readiness |
| Power Island | 49 - Generator H2 drying system | 1040, 1051 | MELCO to quote additional double block and vent isolation valves for on-line maintenance of heater system, to eliminate H2 purge of complete system. Snowy standard maintenance requirement | MELCO | 2 | Firm | No | Modification recommended to improve isolation and maintenance activities. Supplier currently reviewing the design change and implementation aspects. |
| Power Island | 50 - Generator - Lube oil system | 1064 | There is a discrepancy between MELCO pipe sizes and MHI drawing A-21022 page 2 of 4. MHI to review and correct | MHI | 1 | Firm | No | CLOSED |
| Power Island | 50 - Generator - Lube oil system | 1056 | MELCO design is heavily reliant on Operator alarm response and on site Operator rounds. This is not how Snowy normally operate. Additional instrumentation would be likely be installed on future upgrades. MELCO design to be reviewed for potential instrumentation upgrades | SNOWY HYDRO | 1 | Study | Yes | CLOSED |
| Power Island | 51 - Generator - Seal oil vacuum pump and tank | 1084 | AECOM to incorporate seal oil system drip / leak tray overflow to oily water system in their design | AECOM | 2 | Firm | No | CLOSED Seal Oil tank and pump skid is installed within a bund and connected to the Oily water system. Oily water system connection is open in order to manage fire water (added in action 68 above). It is not practical to bund the area around ALL seal oil piping and the generator seals as it would extend to cover the entire generator foundation and has not been requested during design development progress |
| Power Island | 51 - Generator - Seal oil vacuum pump and tank | 1084 | Seal oil system drip tray or bunded area should be remotely monitored for large leaks and potentially auto draining function of sight glass. Similar to fuel oil / lube oil bunds | SNOWY HYDRO | 1 | Firm | Yes | CLOSED. Seal Oil tank and pump skid is installed within a bund and connected to the Oily water system through an open drain/flame trap. Oily water system connection is open in order to manage potential fire water (added in action 68 above), therefore superceding remote monitoring of bund for leaks. |
| Power Island | 51 - Generator - Seal oil vacuum pump and tank | 1085 | Seal oil vacuum tank fill valve is a single point of failure which can lead to lube oil overfilling the tank and lube oil discharging via the vent stack, potential large quantities due to unmanned site. Alarm response cannot prevent this consequence and would happen quite quickly. Design review required | SNOWY HYDRO | 1 | Study | No | MELCO have added level glass, however SHL still require a level switch in Oil Separator tank. |
| Power Island | 53 - Generator - DC seal oil system | 1116 | MELCO to review design to define the potential consequences of an unmanaged seal oil system failure and loss of hydrogen containment. Snowy will use this information to risk assess the installation per HAZOP guidelines | MELCO | 2 | Study | No | Snowy Hydro has also instructed the Supplier to develop a suitable venting design to reduce this risk and are currently working with the Supplier to implement this design. |

| | | | | | | | | |
|------------------|--|--------|---|-------------|---|--------|-----|--|
| Power Island | 53 - Generator - DC seal oil system | 1123 | Change DC pressure PI-5 to pressure transmitter for DC pump test run and linking to H2 automatic venting system. MELCO team suggest change is technically possible but may cause delays. MELCO will consider changing DC pressure indicator PI-5 to pressure transmitter. | MELCO | 2 | Verify | No | The existing pressure indicator will be changed to a pressure transmitter. Snowy Hydro has also instructed the Supplier to develop a suitable venting design to reduce this risk and are currently working with the Supplier to implement this design. |
| Power Island | 53 - Generator - DC seal oil system | 1124 | MELCO team to confirm DC pump recirc line size. The large size valve passing may result in very low DC seal oil pressure | MELCO | 1 | Verify | No | CLOSED |
| Power Island | 53 - Generator - DC seal oil system | 1126 | AC and DC suction pressure indicators not shown on drawing but will be provided. MELCO to update drawing | MELCO | 2 | Firm | No | CLOSED |
| Power Island | 53 - Generator - DC seal oil system | 1125 | DC pump inlet (suction side) check valve stuck closed resulting in no oil pressure in a demand scenario. Why do we need this valve and is it normally open or closed. Confirm also design of this valve, i.e. spring, lockable, power cylinder?? | MELCO | 1 | Verify | No | CLOSED |
| Power Island | 53 - Generator - DC seal oil system | 1141 | Redundant AC seal oil pump configuration requirement reviewed and recommended to MELCO for incorporation. MELCO will show the layout for the installation of the second AC pump. | MELCO | 2 | Firm | No | Modification recommended to improve redundancy. Supplier currently reviewing the design change and implementation aspects. |
| Power Island | 54 - Generator - Gland seal oil system | 1145 | Gland seal system if currently a manually operated procedure that is required during hydrogen fill and 'potentially' at full speed to centre the seal rings to reduce shaft vibration. Remotely operated solenoid would be the ideal solution. MELCO to confirm the design requirements and schedule impact to be confirmed | MELCO | 1 | Verify | No | CLOSED to be considered in Ops Readiness |
| Power Island | Closed Cooling Water - 1 - Fin fans | 3 | Add drain points and vibration sensors to P&ID Sht 1 of 4 | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 4 | Piping ratings on drawings need to be corrected | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 5 | Pumps have not been specified yet. System pressure with 2 pumps running to be checked against MHI supplied heat exchangers and the fin fan cooler design pressure | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 6 | Delete upstream individual header pressure indicators and change the downstream individual header pressure indicators to temperature sensors to assist with flow balancing | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 7 | Add fin fan overall dP sensor | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 8 | Add helper cooler discharge pressure and temperature transmitter to P&ID | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans 2 - Helper cooler and booster pump | 9 | Review system design for thermal expansion to assess if a flexible connection is required | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 10 | Review which sensor is better to control the fin fans, CT102 or CT103 | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 11 | Review sensor failure on loss of signal for fin fans, CT102 and CT103 | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 12 | Temperature sensors should be dual elements, even if only 1 is used. Consistent with MHI design | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 13 | Flow balancing valves should be set and forget. Not move with water vibration. Valve selection to consider locking or rigid stem packing to hold commissioned position | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 1 - Fin fans | 23 | Grease points access needs a lift. SHL to review site requirements hire or buy a scissor lift | SNOWY HYDRO | 3 | Firm | No | |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 25 | Add duty standby pumps to drawing | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 26 | Confirm piping pressure rated for two pumps running | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 30 | Review instrument impulse lines for low ambient temp. Threaded socket direct to pipe is probably the best approach. | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 39 | Potential forwarding pressure is sufficient to continuously leak out of helper spray nozzles. Review booster pump or spray bar isolation requirements | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 2 - Helper cooler and booster pump | 45 | Helper Cooler spray water is demin that needs to flow (if any) to Trade waste. System is not covered so rain water catchment would also flow to trade waste. To be considered in the design. | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 3 - Expansion tank | 57 | Water consumption of pump gland seals and leakage to be estimated to evaluate automating tank filling and pump discharge pressure stability. More than 1 x per mth suggest automation required | AECOM | 1 | Study | No | |
| Power Island | Closed Cooling Water - 3 - Expansion tank | 47 | Add PRVs to instrument air and forwarding demin supplies to prevent overpressure. Press Reg. Sight glass, manifold suction pressure transmitter and level switch to P&ID and suitably rated | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 5 - GT HP Purge air coolers | 97 | MHI to review HP compressor protection requirements. What are the consequences if the closed cooling water temperature increases above 40 C. Do we need to shutdown the compressors to protect them from damage? | MHI | 2 | Study | No | CLOSED There is no interlock system about CCW temperature high. But another interlock systems are equipped in HP purge air compressor control system. -Cooling water temperature rise occurs lub oil viscosity drops, so lub oil pressure low trip is equipped. -Cooling water temperature rise occurs lub oil temperature rise, 1st stage compressor output air temperature rise as a result. When it will rise up above setting value, HP purge air compressor will trip (1st stage air temperature high). |
| Power Island | Closed Cooling Water - 5 - GT HP Purge air coolers | 105 | MHI to confirm HP compressor oil pressure and if there is an exchanger leak, will the water flow into the compressor and cause damage? How is this detected? | MHI | 2 | Verify | No | CLOSED The normal lubricating oil pressure is about 0.2 ~ 0.3 MPaG. When leak occurs at lub oil cooler, cooling water leak into lub oil line. (Cooling water pressure : approx.0.57MPa) It will cause higher compressor outlet air temperature rise. Compressor has the protection of "1st stage compressor outlet air temp high". |
| Power Island | Closed Cooling Water - 6 - GTG H2 air coolers | 115 | P&ID line 100mm to be updated to 125mm | AECOM | 2 | Firm | No | |
| Power Island | Closed Cooling Water - 6 - GTG H2 air coolers | 116 | Pressure regulation wont work as shown. AECOM to review water pressure balancing system. It is important to maintain 5.5 Bar cooling water at exchangers to inhibit H2 leak | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 6 - GTG H2 air coolers | 135 | AECOM to review and confirm with MHI if any closed cooling water commissioning strainer / removal spool requirements | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 7 - GT Control oil coolers | 147 | AECOM to review check valve quantity and location. Control oil only has 1 common NRV but other exchangers are individually controlled. Do we need them? | AECOM | 1 | Verify | No | |
| Power Island | Closed Cooling Water - 3 - Expansion tank | 61, 69 | Expansion tank bladder inspection and repair access and maintenance requirements to be specified | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 4 - Cooling water pumps | 71, 91 | Pump discharge manifold PRV to discharge to trade waste system. All (all nodes) CW system drain points need to go to trade waste | AECOM | 1 | Firm | No | |
| Power Island | Closed Cooling Water - 4 - Cooling water pumps | 87 | On loss of AC supply, does the closed cooling water system (fans and / or pumps) need to be operational for any specified period time after a black stop. MHI to confirm any run down time requirements | MHI | 1 | Verify | No | CLOSED GT roll down to turning gear within 30-40mins after black out trip, and bearing oil is supplied by EOP (DC pump) with bypassing LO-cooler. Therefore, we don't think closed cooling water system is not need to be operational. |
| Balance of Plant | Diesel | 1.1.1 | Requirement to be clear in procedures that quantity delivered is based on tanker dip gauges. | SNOWY HYDRO | 2 | Firm | Yes | |
| Balance of Plant | Diesel | 1.1.2 | Refer to action of 1.1.15. | AECOM | 1 | N/A | | Closed. High flow alarm added on flowmeter at pump discharge header to warn operator. Process interlock to prevent both pumps running, has been added in control philosophy. |
| Balance of Plant | Diesel | 1.1.3 | Check with the pump vendor if the selected pump can operate for 20 seconds with low flow. | AECOM | 1 | Verify | No | Closed. Note has been added to the data sheet for the unloading pump "HPP-AEC-MEC-DS-LLS-DST-3190-Rev B" |

| | | | | | | | | |
|------------------|--------|--------|--|-------------|---|----------|-----|---|
| Balance of Plant | Diesel | 1.1.4 | Review requirement of bleed valve on suction line to the pump. | AECOM | 1 | Verify | No | Closed. Vent/Bleed valve added on each unloading pump suction line, refer PID-1065 Note: Not all compartments in the tanker have the same volume |
| Balance of Plant | Diesel | 1.1.7 | Show internal relief of pumps on P&IDs. | AECOM | 1 | Firm | No | Closed. Internal PRV added to each pump (P&IDs Rev C) |
| Balance of Plant | Diesel | 1.1.9 | Operating Procedures to include a check of the diesel quality delivered to site. | SNOWY HYDRO | 2 | Firm | Yes | |
| Balance of Plant | Diesel | 1.1.10 | Diesel should be regularly tested to ensure the level is suitable for the Gas turbine. Included regular sampling for quality testing in the operating procedures. | SNOWY HYDRO | 2 | Firm | Yes | |
| Balance of Plant | Diesel | 1.1.11 | Review requirement for commissioning strainers. | SNOWY HYDRO | 1 | Verify | No | Strainers have been included for the pumps, during the commissioning the team should install a strainer for this purpose and then replace it after flushing the line. ITPs by Snowy, action to be assigned to SH |
| Balance of Plant | Diesel | 1.1.11 | Construction ITPs to include cleanliness checks. | SNOWY HYDRO | 2 | Firm | Yes | |
| Balance of Plant | Diesel | 1.1.12 | Review requirement for valve with position indicator in diesel unloading bund. | AECOM | 1 | Firm | No | Closed. Valve with positioner has been added for tanker standing bund valve. Shown on PID HPP-AEC-MEC-DS-LLS-DRG-1065 |
| Balance of Plant | Diesel | 1.1.13 | Review requirement for bund size as per AS 1940. Consider making bund big enough for all components on B double compartments on B double. | AECOM | 1 | Verify | No | Closed. Tanker standing area bund has been designed to hold 9000 Litre as per AS1940 (1.5 x compartment). KW: Unloading connection will now only have 2 connected hoses and previously designed for 5. So only a maximum of two compartments connected at one time. HPP-Basis of Design Chapter 5.1.5.1.1 Tanker unloading area |
| Balance of Plant | Diesel | 1.1.14 | Review where pump spill containment is discharged to. Preference is to keep in the pump bund area rather than being discharged into larger road containment bund. | AECOM | 1 | Verify | No | Closed. Note added to PID Rev C "Separate bund with drain to the oily water system to be provided for unloading pump and it should be kept separated from tanker bund area" |
| Balance of Plant | Diesel | 1.1.15 | Process interlock to be reviewed/ designed to not allow running both pumps at the same time. Include permissive that valve should be opened before running pump. | AECOM | 1 | Firm | No | Closed. High flow alarm added on flowmeter at pump discharge header to warn operator. Process interlock to prevent both pumps running, has been added in control philosophy. |
| Balance of Plant | Diesel | 1.1.16 | Review process interlock that on/off valves to tank inlet are opened prior to starting the pump. | AECOM | 1 | Verify | No | Closed. As per current control philosophy valve open position on selected tank and close position on the other tank will give permissive to start the unloading pumps |
| Balance of Plant | Diesel | 1.1.17 | Review requirement for sight glass downstream of flexible couplings. See 1.1.4 | AECOM | 1 | Verify | No | Closed. Sight glass 90EGA01CL001 added on suction header downstream of hose connection |
| Balance of Plant | Diesel | 1.2.1 | Review impacts of ramp up and ramp down of delivery to trucks. Review impacts on PD pumps and whether PSV will lift when FCV closes. Could replace PSV with Pressure Reducing Valve. Review if the FCV in the diesel loading skid is required. | AECOM | 1 | Study | No | Closed. An FCV (flow control system) is required to start the loading at a lower rate to prevent splashing inside the tanker compartment when the tanker is empty. A note has been added to the pump datasheet to specify a slow start operation. A modulating type PRV (90EGD01AA044) is proposed downstream of the PD pumps to relieve the excess supplied fuel to the pump suction side during the ramp up and down to have a smooth operation for the pump if required. The PRV is supplied by PD pump vendor and the vendor is responsible for the sizing. |
| Balance of Plant | Diesel | 1.2.2 | Process interlock to be reviewed/ designed to prevent running both pumps at the same time. | AECOM | 1 | Firm | No | Closed. Process interlock to prevent both pumps running, has been added in control philosophy. |
| Balance of Plant | Diesel | 1.2.4 | Integrate the vendor package with the loading pumps. E stop required for Load bay controller. Check if control should be independent of DCS e.g. Removal of air will close valves and stop the flow. | AECOM | 1 | Firm | No | Closed. The PD pump with a modulating PRV can cope with changes in the flowrate caused by the flow control valve under the Load Bay Controller. Requirement for an E-Stop note added to the PID and included in the Load Bay duty specification. Failure of instrument air supply will close on-off valve to loading arm and stop flow. Requirement for package integration with the site DCS to control the unloading pumps has been added to package duty specification: HPP-AEC-MEC-DS- LLS-SPT-3186 Load bay controller will also be controlled by local PLC which will also stop the loading pump if the on/off valve is closed or the required load has been completed |
| Balance of Plant | Diesel | 1.2.5 | Check tanker loading connection (dry break connection), valving isolation and check valves. Check if there is a sight glass include in line. | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Diesel | 1.2.6 | Review pump head to maintain pressure of the loading arm below 5 barg | AECOM | 1 | Verify | No | Closed. Current TRV system is cascaded to the storage tank with maximum 495 kPag pressure Jafar: Pump discharge pressure is 250 kPag and downstream PRV has set point of 300 kPag . |
| Balance of Plant | Diesel | 1.2.7 | Review location of discharge of TRV to ensure section that is relieved will not exceed design pressure. | AECOM | 1 | Verify | No | Closed. Current TRV system is cascaded to the storage tank with maximum 495 kPag pressure. This is far below the piping design pressure. Jafar: The TRV's are cascaded from loading arm to the storage tanks as following calculation for the worst case scenario and with 10% overpressure in opening for each TRV: (300*1.1+80)+50*1.1+50*1.1=520 kPag |
| Balance of Plant | Diesel | 1.2.9 | Confirm if tanker can be over pressured or has lid open. Ensure tanker vent system is interlocked to avoid overpressure in the tanker. | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Diesel | 1.2.12 | Consider bollards in unloading area | AECOM | 1 | Consider | No | Closed. Loading arms extend beyond line of potential bollards, or guard rail. There will be bollards installed on approach and departure to the facility. No bollards to be installed across the face of the pump area as this could limit unloading arm movement and become a hinderance. Confirm arms are protected with breakaway coupling. |
| Balance of Plant | Diesel | 1.2.13 | Consider whether a weigh bridge or other mechanism to measure amount of fuel being loaded | SNOWY HYDRO | 1 | Consider | No | |
| Balance of Plant | Diesel | 1.3.1 | Add a flame arrestor to diesel storage tanks (as per Colongra site) | AECOM | 1 | Firm | No | Closed. Flame arrestor not required as per AS 1940. Decision to include is SH preference. JD: Flame arresters already shown in P&IDs (90EGB01AT001 and 90EGB02AT001) |
| Balance of Plant | Diesel | 1.3.3 | Consider needle control valve in air supply to operate the pump. | AECOM | 1 | Consider | No | Closed. Air regulator valve with a filter has been added in P&IDs (Rev C) instead of a needle valve. |

| | | | | | | | | |
|------------------|--------|--------|--|-------------|---|----------|----|---|
| Balance of Plant | Diesel | 1.3.4 | Use level transmitter as pump shutdown as well as the level switch. | AECOM | 1 | Firm | No | Closed. Added to control system, for unloading and transfer modes. Level switches have been replaced with transmitters. |
| Balance of Plant | Diesel | 1.3.5 | Use level transmitter as pump shutdown as well as the level switch. | AECOM | 1 | Firm | No | Closed. Low Low level Alarm with pump shutdown has been added to the level transmitter instead of the LSL as a layer of protection for pump shutdown (LSLL has been removed and replaced by LT with LL alarm). The low level alarm will be retained for the tank changeover if the pumps are used for forwarding mode instead of using it for pump shutdown and interrupt GT operation. |
| Balance of Plant | Diesel | 1.3.6 | Review the employer requirements to have one or two transmitters. Review how critical this instrument is to the operation of the GT. | AECOM | 1 | Verify | No | Closed. Existing operations (at Colongra) are using two transmitters JD: LSL replaced with level transmitter with HH, H, L, and LL alarm added to each tank |
| Balance of Plant | Diesel | 1.3.8 | Review of AS 1940 to determine if any additional temperature control are required | AECOM | 1 | Verify | No | Closed. Several Australian diesel supplier SDSs have closed cup flash point higher than 61.5 C. Therefore, the handling and storage temperature is lower than flash point and no need to classify as hazardous area. TT has been added on return line to monitor the return diesel from GT. Update: As per Client request, a heater has been added on the diesel tank to keep the temperature above 19 C. Heater will start when T drops below 19 C and will stop when rises above 25 C. It has been specified in the heater datasheet that the max allowable temperature is 50 C for tank medium. It has also been specified that the heater will be equipped with a skin overheat protection system to prevent diesel overheating. |
| Balance of Plant | Diesel | 1.3.9 | SH to provide fuel specification (pour point) of selected fuel to determine if wax formation is likely at the minimum expected storage temperature. To be confirmed with fuel supplier | SNOWY HYDRO | 1 | Firm | No | |
| Balance of Plant | Diesel | 1.3.12 | Review drain/vent material selection to minimise corrosion. Review coating of tank. | AECOM | 1 | Firm | No | Closed. All tanks will be painted/coated internally. Vent and drain line material has been changed to stainless steel. Please refer to tank Datasheet HPP-AEC-MEC-DW-SFP-DST-3100_Rev B |
| Balance of Plant | Diesel | 1.3.13 | Determine if density/viscosity of diesel change significantly with temperature. To be confirmed with fuel supplier | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Diesel | 1.3.17 | Confirm that a potential rain event (i.e. 1 in 100 rainfall event) will not cause instrumentation and control systems to be covered in water. Considering including float switch to alert before control switches are under water. | AECOM | 1 | Consider | No | Closed. All instrumentation inside the bund are already installed above one meter. Float level switch (high) added to the bund - P&ID RevC. |
| Balance of Plant | Diesel | 1.3.18 | Consider the internal surface of diesel tank to be fully coated. | AECOM | 1 | Consider | No | Closed. All tanks will be painted/coated internally. Please refer to tank Datasheet HPP-AEC-MEC-DW-SFP-DST-3100_Rev B |
| Balance of Plant | Diesel | 1.4.1 | Interlock to prevent 3 pumps running at the same time. | AECOM | 1 | Firm | No | Closed. This action is not valid anymore since pump control philosophy has been updated to run N+1 forwarding pumps. N is number of GT running as per snowy operation team request. |
| Balance of Plant | Diesel | 1.4.2 | Check diesel polishing package has alarm for the differential pressure across filters to alert operators of blocked filters in DCS. | AECOM | 1 | Verify | No | Closed. Monitoring of differential pressure across the filters in DCS with high alarm has been added (P&ID revC) |
| Balance of Plant | Diesel | 1.4.11 | Consider an additional separate pump for polishing package. Look at automated prioritised control of forwarding pumps. | AECOM | 1 | Consider | No | Closed. Separate pump with dedicated supply and return lines connected to the storage tank has been added for polishing package. Package will standalone. UPDATE : Request by client to remove polishing package pump and use forwarding pumps. Actuated valves can change flow from polishing to forwarding in seconds. |
| Balance of Plant | Diesel | 1.5.1 | One inlet return valve to each storage tank to be open at all times. Set fail action to fail last. Oil is returned after GT shutdown. Ensure the inlet line is open for the fuel return to tanks. Keep at least one inlet valve open for diesel return from GT after shutdown. | AECOM | 1 | Firm | No | Closed. 1- Added to the control philosophy - (one of the return valves to the storage tanks should be always open even in IDLE mode) 2- In forwarding mode relevant return valve for the selected tank would give permission to start the pumps and initiate the mode 3- In IDLE mode when no mode is selected one of the return valves to storage tank would be open, added to the control philosophy |
| Balance of Plant | Diesel | 1.5.2 | Redundancy and reliability issues need review. Consider running the standby pump at all times so if a single pump trips no loss of flow or pressure to the GT. Perform a dynamic study to determine if only running two pumps and time required for a third pump to start and compensate for loss of flow of tripped pump. How many pumps need to be running if there is a pump trip. Consider n+1 where n is the number of units. | AECOM | 1 | Study | No | Closed. JD: Pump control philosophy has been updated to run N+1 forwarding pumps. N is number of GT running as per snowy operation team request. PCV with bypass pipework of MFOP has been added to allow excess diesel to be returned to the diesel tank. KW: A dynamic analysis is not now required because of operating an extra pump above the flow requirements of the GT so an analysis of the dynamics of starting a spare pump is not required. KW: A separate RAMS study will address the issue of overall pump reliability |
| Balance of Plant | Diesel | 1.5.6 | Consider installing a small sump and weir in bund to contain smaller leak quantities at pump skid bund. | AECOM | 1 | Consider | No | Closed. Small sump and weir not preferred as this would require mobile equipment to treat spill which is not readily available on site. As bund is connected to oily water system, spills transfer directly to oily water pit and are treated at this location. No further action required. |
| Balance of Plant | Diesel | 1.5.8 | Change PI upstream of flowmeter to be PT | AECOM | 1 | Firm | No | Closed. PI has been changed to PT (P&IDs Rev C) |
| Balance of Plant | Diesel | 1.6.4 | Review the interaction of the loading/unloading interaction with curb and lighting. | AECOM | 1 | Verify | No | Closed. Originally the unloading connection was via a 5 arm trolley that could be moved around. Updated to provide 2 port connection arms. Action is no longer valid because the unloading trolley has changed to an overhead arm. |

| | | | | | | | | |
|------------------|-------------|--------|---|-------------|---|----------|-----|---|
| Balance of Plant | Diesel | 1.6.5 | Review causes of fire/consequences. A fire could start on site undetected. Review fire protection and remote monitoring of critical areas e.g. use of cameras | AECOM | 1 | Study | No | Closed. Refer to Fire Safety Study report for details HPP-AEC-MEC-FP-GEN-REP-0001 regarding causes of fire/consequences and recommended fire protection and monitoring. - Fire detection is included in the Turbine enclosure triggering CO2 suppression, alarm and shutdown - Fire detection(via fusible plug) in the FO unit triggering sprinkler system, alarm and shutdown - Fire detection via CCTV at the GT fuel oil piping (remote or local observation) to enable operator shutdown. - At the fuel forwarding pump the diesel is at ambient temperature, at lower pressures than the GT fuel oil piping and not collocated with other flammable materials so the risk a fire is low. For this reason cameras are not likely to be installed in this area |
| Balance of Plant | Diesel | 1.6.10 | Review bushfire impacts on the fuel tanks. Assess best materials for fencing etc. to minimise this risk. NOTE: A fence will not prevent ember attack which comes from an elevated height higher than normal fence height). | AECOM | 1 | Study | No | Closed. Vegetation near site to be cleared in the future when site is operable. Fire safety study regarding the diesel tanks in bush fire scenario: The bulk fuel oil storage tanks will experience thermal radiation less than 19 kW/m2 but greater than 12.5 kW/m2. The planned storage tanks have been designed in accordance with the requirements of AS1940 and AS1692. The tanks have a fixed roof design, which eliminates the fire risks associated with floating roof designs. The tank vent is designed with a flame arrestor, which will inhibit ember ingress and prevent flame ingress from ignition of any vapour that occurs outside the vent because of any elevation in fuel oil temperature during a bushfire exposure event. Other than the specific design requirements of AS1940 and AS1692, the protection rationale and recommendations for the bulk fuel oil tanks is identical to that described for the potable and demineralised water tanks i.e. dedicated fixed on tank cooling is not recommended but provision of some fixed firewater monitors on the site firewater hydrant system to enable site personnel to direct cooling water onto the exposed surface of the tanks is recommended. No other specific control measures for plant in this area are planned. |
| Balance of Plant | Diesel | 1.6.12 | O&Ms to be created by SH | SNOWY HYDRO | 2 | Firm | No | |
| Balance of Plant | Natural Gas | 2.1.3 | Use temporary flexible connection for N2 purging with hoses and only connected when required for maintenance. Covered under operating procedures for only connecting N2 when purging is required. | SNOWY HYDRO | 2 | Firm | No | |
| Balance of Plant | Natural Gas | 2.1.4 | SH have requested to add facilities for a remote operated vent for each pipe section to be opened remotely by operators to reduce pressure in the pipeline over a selected time period e.g. 15 minutes in case of fire. Two vents will be required one for first section between battery limit ESD and SDV upstream of knockout drum and second vent required downstream of gas KO drum ESD for downstream equipment. Consider damage to the packing in the filter coalescer vessel from a high differential pressure across the filter material during venting. Change valve to ESD (currently SDV). Vent valve interlocked to not open until ESD is closed to prevent loss of gas. Review the operation of vent in conjunction with remote operation philosophy i.e., effect of ignition of vent and possibility of air entering the gas line when line depressurised. May effect ability for remote start-up. Vent valve will only close in emergency. | AECOM | 1 | Firm | No | Closed. - APA agreed that vent for gas pipeline can be collocated with cold vent for gas receiving station. - AECOM will look at radiation from new vent co-located with cold vent. - APA permit system requires all lines connected to vent to be purged and lock on isolation valves. Confirm there is a DBB on vent line to new vent in APA area. Update 4/3/22 See RFID-0000125. SH do not require remote operated vent valve or actuated inlet valve at the PS boundary . Remote operated vent valve has been retained downstream of the last chance cartridge filter . PIDS have been updated Added remote operated vent downstream of MHI cartridge filter. Removed RO vent valve at station boundary on request of SH. Maintenance venting only provided. There will be no actuated isolation valve at the gas inlet to the station. SH will rely on APA gas isolation valve. PIDS have been updated. |
| Balance of Plant | Natural Gas | 2.1.5 | Perform dynamic study of the system based on closure times of the valves. Consider all system shutdown (trip) scenarios. | AECOM | 2 | Consider | No | The gas pipeline dynamic modelling is waiting on the gas connection with APA to be finalised |
| Balance of Plant | Natural Gas | 2.1.6 | Confirm there is a safety relief valve in pressure reduction units supplied by MHI. | MHI | 1 | Verify | No | |
| Balance of Plant | Natural Gas | 2.1.9 | Review location of vent stack with regard to radiation from ignition of NG. Review potential to co-locate new vents required in APA's vent area | AECOM | 1 | Study | No | Closed. NG vent stack will be located in Process gas area will be a maintenance vent only. Radiation modelling has indicated that vent stack should be 17 m tall to limit radiation affects at boundary fence. Maintenance venting will be a controlled activity which will limit access to the area around the vent during operation of the vent. (UPDATE: 16-6-22- NG vent stack will be co-located with H2 vent which is 33m tall so NG vent stack will also be 33m tall) |
| Balance of Plant | Natural Gas | 2.1.10 | Include pressure transmitter and local pressure indicator on main line. Provide additional tapping points for gauges if required. | AECOM | 1 | Firm | No | Closed. Marked up on PID and added PI 90EKG01CP301 and PI 90EKG01CP302 |
| Balance of Plant | Natural Gas | 2.1.11 | Review whether integral DBB valves can be used instead of separate valves to save cost. | AECOM | 1 | Verify | No | Closed. As per AEC ANZ-RFI-000167, SHL have instructed not to use integral DBB valves. |
| Balance of Plant | Natural Gas | 2.1.13 | Update PID to show not permanently connected. | AECOM | 1 | Firm | No | Closed. Marked up on PID - Note 3: Connection for calibration gas cylinder |
| Balance of Plant | Natural Gas | 2.2.2 | Review potential impact on reverse flow through KO pot and demister pad. | AECOM | 1 | Verify | No | Closed. Remote operated vent valve at PS inlet has been removed. RO vent valve downstream of cartridge filter will allow venting of piping downstream of KO drum and ESD valve upstream of KO drum, so no reverse flow is possible |
| Balance of Plant | Natural Gas | 2.2.3 | Review requirement for Emergency shut off valve EKG01AA161 upstream of KO drum. Consider changing to a manual valve as remote operation of the valve is not required (by SH)ESD can remotely isolate each GT if fire on one unit. Provide a schematic drawing (updated PFD) of ESD and vent valves on gas supply line to each gas turbine. | AECOM | 1 | Verify | No | Closed. ESD valve at inlet of KO drum has been retained as required by MHI PIDS and to isolate the gas supply to each GT in case of a fire or other emergency. |
| Balance of Plant | Natural Gas | 2.2.4 | Change location of level transmitter on the Gas Knock Out Drum of upper tapping point to below filter media | AECOM | 1 | Firm | No | Closed. : Marked up on PID (Rev C) |
| Balance of Plant | Natural Gas | 2.2.5 | Remove LSHH trip to shut turbine -Include LSH on maintenance schedule. Frequent tests to make sure it's working. Do not require duplicate drainage system because LSHH trip deleted. | AECOM | 1 | Firm | Yes | Closed. Removed LSHH . Marked up on PID (Rev C) |
| Balance of Plant | Natural Gas | 2.2.7 | Show a Manhole on Knock Out Drum on P&ID (HPP-AEC-MEC-GA-KOO-DRG-1090). | AECOM | 1 | Firm | No | Closed. Marked up on PID (Rev C) Drum diameter is estimated to be 1.5 m so MW is likely |
| Balance of Plant | Natural Gas | 2.3.3 | Raise an RFI to MHI on whether the position of the temperature flow control valve is important. Difficult to know that TCV has failed. | AECOM | 1 | Verify | No | Closed. Clarified with MHI. No possibility of overheating gas to gas turbine. A low temperature will generate an alarm at the GT inlet and will alert operations to check valve operation |
| Balance of Plant | Natural Gas | 2.3.4 | Check distance from MHI heater to ladder access on stack. | MHI | 1 | Verify | No | |

| | | | | | | | | |
|------------------|------------------------|--------|---|-------------|---|----------|-----|--|
| Balance of Plant | Natural Gas | 2.4.2 | Review setting level of DP alarm level value on Filter Coalescers to ensure sufficient time to swap to other filters (Duty/Standby). | AECOM | 1 | Verify | No | Closed. Filter / Coalescer offer has clean differential pressure as < 4kPag and change out differential pressure as 103 kPag. The NG is expected to be clean and oil free. A long run length is expected. The setting of the filter DP is set at 60% of the maximum differential pressure to allow sufficient time for changeover. (Included in the Control Philosophy - Section 10.5) |
| Balance of Plant | Natural Gas | 2.4.3 | Review potential impact on reverse flow through Knock Out Drum and demister when opening the remote vent at the station battery limit. | AECOM | 1 | Verify | No | Closed. Remote operated vent valve at PS inlet has been removed. RO vent valve downstream of filter/coalescers will allow venting of piping downstream of KO drum and ESD valve upstream of KO drum, so no reverse flow is possible |
| Balance of Plant | Natural Gas | 2.4.4 | Consider adding sight glass on side of filter coalescers to determine condition of elements. | AECOM | 1 | Consider | No | Closed. Sight glass has been removed from vessel as vendor has confirmed it is not necessary. Two LIT for each of upper and lower compartments to provide independent shut off of drain valves to prevent gas blow through. |
| Balance of Plant | Natural Gas | 2.4.5 | Remove LSHH trip to shut turbine. Include LSH on maintenance schedule (Frequent tests to make sure it's working). Do not require duplicate drainage system because LSHH trip deleted. | AECOM | 1 | Firm | No | Closed. Removed LSHH . Marked up on PID (Rev C) |
| Balance of Plant | Natural Gas | 2.4.9 | Change PI to PT upstream of filter for DCS indication. | AECOM | 1 | Firm | No | Closed. Marked up on PID , DPI 01EKG01CP101 |
| Balance of Plant | Natural Gas | 2.4.10 | Consider stairs instead of ladders for access. | AECOM | 1 | Consider | No | Closed. A platform access is shown in the model |
| Balance of Plant | Natural Gas | 2.5.3 | Review where vents are discharge to e.g. Local High point vent | AECOM | 1 | Study | No | Closed. Local vents in this area are vented 7-8 m above the GT enclosure so well above location of people or sources of ignition. (See snip at right) |
| Balance of Plant | Natural Gas | 2.5.5 | Review requirements for nitrogen purge and vent connection between heater and filter to be used during maintenance of filter. | AECOM | 1 | Verify | No | Closed. Added N2 connection to PID 1097 downstream of last chance cartridge filter. This can be used to purge backwards from the last chance cartridge filter via fuel gas heater and through vent valve SDV 01MBP01DF006A upstream of the NG flow meter. This will allow better removal of gas as there is no isolation valves at the cartridge filter. |
| Balance of Plant | Natural Gas | 2.6.4 | Add small tank drain to allow sampling and flow to drain | AECOM | 1 | Firm | No | Closed. Marked up on PID (Rev C) |
| Balance of Plant | Natural Gas | 2.6.6 | Update datasheet to include a full vacuum conditions that may be caused by condensation of hydrocarbons | AECOM | 1 | Firm | No | Closed. Added FV to vessel data sheet |
| Balance of Plant | Natural Gas | 2.6.7 | Sight glass to be added on drips tank. Add to P&ID. | AECOM | 1 | Firm | No | Closed. Marked up on PID (Rev C) and added to data sheet |
| Balance of Plant | Natural Gas | 2.6.9 | Ball valves on P&IDs upstream of NRV to be locked open. | AECOM | 1 | Firm | No | Closed. Marked up on PID (Rev C) |
| Balance of Plant | Natural Gas | 2.6.10 | Redirect drain from vent pipe away from drips tank to another location to avoid filling drips tank with water. | AECOM | 1 | Firm | No | Closed. Redirected to local drain (P&ID Rev C) |
| Balance of Plant | Natural Gas | 2.7.3 | Review requirement for ignition source control entry into hazardous areas e.g. separation barrier, post, chain. SH to provide procedures and training for entry to HA and ignition sources. | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.1 | Review amount of H2 required. Consider using less H2 gas bottles. (Raise RF1 to SH to ask about minimum requirement for H2 storage cylinders). | AECOM | 1 | Verify | No | Closed. 15 cylinder rack will cover 2.7 days of normal leakage from 2xGT. @1/2 racks will give 5 days coverage. If generators are not topped up the pressure will drop from nominal operating pressure of 4.5 barg to minimum operating pressure of 4.3 barg in 24 hours |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.2 | Review timing for H2 trailer delivery and determine if leakage rate from generator is low enough to not reach low pressure trip whilst H2 trailer is being delivered and changeover. | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.3 | Review requirement for pressure transmitters on cylinder and trailer H2 supply lines. Considering adding a position indicator on DBB valves on each H2 supply line - This option is not preferred because the position indicator will be in a Hazardous area from the H2 flanges. | AECOM | 1 | Verify | No | Closed. See item 1.1.2 - addition of 2x PITs (90QJH01CP101 and 90QJH02CP101) will give required information |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.4 | Add pressure transmitter with alarm inside the H2 HP regulator panel downstream of PRV. | AECOM | 1 | Firm | No | Closed. Change PI immediately downstream of PRV to a PIT with high pressure alarm set at 5400kPag. |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.5 | Add NRVs to hydrogen supply line to lines adjoining trailer outlet and cylinder outlet. | AECOM | 1 | Firm | No | Closed. Insert NRVs between isolation valves 90QJA01AA010 and 026 and the incoming nitrogen tee so hydrogen cannot flow back from the trailer to the cylinders |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.6 | Review purpose of valve on line connected to hydrogen vent pipe (downstream of PRV). Consider locking bypass valve on PRV. | AECOM | 1 | Verify | No | Closed. Lock 15NB NC valve 90QJH01AA908 closed. KW - Connection to vent is allow line to be depressurised and vent to local vent. The valve is required |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.7 | SH to provide operating procedures to close valve. | SNOWY HYDRO | 2 | Firm | Yes | |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.11 | Consider a PT (downstream of the shutdown valve) that closes the shutdown valve. Review what the "shutdown" valve will be called from control perspective | AECOM | 1 | Consider | No | Closed. A PIT has been installed (see 1.1.4 above) with high and low alarms. A high high alarm has been added to shut the ESD (SDV) should that situation occur. PIT downstream of 2nd stage LP regulator will have a low alarm to show loss of H2 supply pressure. |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.13 | Discuss with the Hydrogen supplier (BOC) availability and reliability of H2 supply. | SNOWY HYDRO | 2 | Study | No | |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.14 | Review if small filter in N2 line is required to prevent any potential contamination carry over from N2 lines. Consider moving Nitrogen bottles to Hydrogen area to decrease the length of Nitrogen pipeline so this can be relatively cheaply changed to stainless steel. | AECOM | 1 | Verify | No | Closed. WBM Filter upstream of the PRV to be 5 micron particulate filter to arrest any dirt or scale. Nitrogen racks do not need to be permanently connected as used infrequently so fork hoist a rack to the N2 connection point and purge out oxygen before allowing gas to pass into the hydrogen system. Refer To N2 Distribution PID HPP-AEC-MEC-PA-GEN-DRG-1103 for connection to this panel |
| Balance of Plant | Process Gas (Hydrogen) | 1.1.15 | Review PSV set point downstream of PRV. Identify suitable set point based on the design pressure the downstream piping. Review pipe specification. | AECOM | 1 | Verify | No | Closed. PSV 90QJH01AA934 set at 15000 kPag which is the design pressure of the MHI pressure reduction panel. The pressure reduction panel reduces the pressure to 50 barg so with a PSV set at 150 barg well above the normal pressure downstream of the PRV so it is unlikely to accidentally lift. KW: MHI during the meeting said it would be no problem to increase the set point up to 150 barg. After HAZOP meeting MHI informed by RF1 58 that pressure can be increased to 200 barg if AECOM preferred. FN: The process gas facility and associated high pressure components to be provided within Vendor scope. This will include complete process design according to duty specification for Process Gas Facility (HPP-AEC-MEC-PA-GEN-SPT-3961). The supply includes mechanical design including strength calculation for all pressure parts, detailed design analysis for attachments, supports, setting bolts, etc. (HPP-AEC-MEC-PA-GEN-SOW-3960). P&ID -1100 has a HOLD to finalise piping classes for high pressure piping with the supplier. |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.2 | Review valve fail positions and requirements of locking valves closed. Add valve Failure positions to the PID. | AECOM | 1 | Verify | No | Closed. Lock normally closed valve in question (90QJH01AA933) closed. |

| | | | | | | | | |
|------------------|------------------------|-------|---|-------------|---|----------|-----|--|
| Balance of Plant | Process Gas (Hydrogen) | 1.2.3 | Review vent line size and confirm large enough size for the number of RVs connected. Review choke velocity in vertical vent pipe and common vent header. Review design pressure of vent line. | AECOM | 1 | Study | No | On Hold. Status update 8.9: Hydrogen pressure reduction and distribution system on HOLD as MHI are in the process of redesigning the GT gas charging and inerting panel to handle possibly up to 200bar inlet pressure direct from the cylinders/tube trailers as well as changing the GT inerting system from CO2 to N2. |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.4 | Review vent stack design - potential for liquid seal at base of vent stack to avoid reverse flow of air. | AECOM | 2 | Study | No | In progress of being closed. A liquid seal and combined flame trap to be installed at the base of the vent stack to isolate H2 from air entering the stack As site will be unmanned for periods a level transmitter will be considered in this package |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.5 | Review the best location for ESD valve isolating H2 supply from GTs. Consider two ESD valves, one on the supply to each generator. | AECOM | 1 | Verify | No | Closed. ESDs (90QJH01AA218KA01 and 90QJH01AA216KA01) for each GT should be located at the start of the branch lines to each GT so the ESD closure is only to the GTG with the problem so a GT running normally is not affected by the other's abnormal operation Note has been added re location in the P&ID (i.e. minimise distance from the tee to ensure these will be installed at the start) |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.6 | Review requirement for remote line depressurising in event ESD valves closing. | AECOM | 1 | Verify | No | Closed. H2 line depressurisation is a last resort action and should not be carried routinely for a GT shutting down as the gas supply is continuously required for topping up each generator. Venting the line down risks introducing air and water vapour into the H2 gas line with associated explosion risk. Additionally it may risk expensive damage to the GTG internals in the presence of CO2 and water vapour. |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.7 | Hydrotest only to be done up to removable spool for each generator. Procedures for testing to prevent water being carried into the generator. | SNOWY HYDRO | 2 | Firm | Yes | |
| Balance of Plant | Process Gas (Hydrogen) | 1.2.8 | Advise MHI of distance between process gas area and generator at each unit. MHI to advise whether pressure increase is acceptable for the pressure reduction panel. | AECOM | 1 | Firm | No | Closed. Distance has been advised in Aconex AEC-ANZ-RFI-000199. Question was asked about increasing PRV setting from 700 kPag to 800 kPag. Meeting 16-9-22. MHI will review. MHI said it was not likely to be a problem |
| Balance of Plant | Process Gas (CO2) | 1.3.1 | Review requirement for NRV in system. | AECOM | 1 | Verify | No | Closed. Additional check valves to be installed immediately downstream of the first fixed pipework isolation valve (32NB) |
| Balance of Plant | Process Gas (CO2) | 1.3.2 | Review piping spec to ensure piping downstream of the PRV and inside the CO2 high pressure regulating panel is designed for maximum pressure supplied by cylinders. | AECOM | 1 | Verify | No | CO2 System on Hold. Pipework from the cylinders to be rated for 200 Barg CL1500 to allow for HP PRV failure or leakage. From the 800 kPag PRV the weight of pipe can be reduced to CL600 as there is adequate protection from two LP PSVs Spec breaks in P&ID to show this? WBM - Yes, but note there is an error in the original comment as CO2 pressure in the cylinders reaches a maximum of only 65barg on a hot day The process gas facility and associated high pressure components to be provided within Vendor scope. This will include complete process design according to duty specification for Process Gas Facility (HPP-AEC-MEC-PA-GEN-SPT-3961). The supply includes mechanical design including strength calculation for all pressure parts, detailed design analysis for attachments, supports, setting bolts, etc. (HPP-AEC-MEC-PA-GEN-SOW-3960). A HOLD has been added to the P&ID "Pipe classes for high pressure piping are to be finalised with supplier". |
| Balance of Plant | Process Gas (CO2) | 1.3.4 | Review method for getting CO2 cylinders from under roof cover (when cylinder packs are being replaced). | AECOM | 1 | Verify | No | CO2 system on HOLD. CO2 cylinders will be racked and the racks are designed to be handled by fork hoists, hiab lifts or craned. Building roof line of covering building must be high enough to allow fork hoist access. Where is this documented to make sure that this happens? It is not, still awaiting further information before |
| Balance of Plant | Process Gas (CO2) | 1.3.8 | Is an emergency activation of CO2 purging required? (i.e. can this wait until an operator is present which maybe an hour later) To be confirmed in the MHI HAZOP. MHI to review operating manual and confirm. Emergency venting of CO2 on the MHI Malco panel upstream of the generator. If there is a fire is venting of the Hydrogen and purging with CO2 for the generator required. CO2 is added to the generator via manual valves (no automated valves) | MHI | 1 | Study | No | |
| Balance of Plant | Process Gas (Nitrogen) | 1.4.1 | Review requirement for N2 supply to the NG equipment and other areas on the Balance of Plant. Confirm whether forklifts can be used to take N2 bottles to the BOP when needed. | AECOM | 1 | Verify | No | Closed. There is no cover at process gas area. Adequate forklift access provided around the gas bottles / cylinder packs |
| Balance of Plant | Process Gas (Nitrogen) | 1.4.2 | Review piping spec to ensure piping downstream of the PRV and inside the N2 high pressure regulating panel is designed for maximum pressure supplied by cylinders | AECOM | 1 | Verify | No | Closed. Piping material spec conforms with pressure stated in PIDs The process gas facility and associated high pressure components to be provided within Vendor scope. This will include complete process design according to duty specification for Process Gas Facility (HPP-AEC-MEC-PA-GEN-SPT-3961). The supply includes mechanical design including strength calculation for all pressure parts, detailed design analysis for attachments, supports, setting bolts, etc. (HPP-AEC-MEC-PA-GEN-SOW-3960). A HOLD "Pipe classes for high pressure piping are to be finalised with supplier" has been added on P&ID |
| Balance of Plant | Process Gas (Nitrogen) | 1.4.6 | Review method for getting N2 cylinders from under roof cover (when cylinder packs are being replaced). | AECOM | 1 | Verify | No | Closed. There is no cover at process gas area. Adequate forklift access provided around the gas bottles / cylinder packs |
| Balance of Plant | Process Gas (All) | 1.5.3 | Review requirement for separation bollards between H2 trailer and reduction panels. | AECOM | 1 | Verify | No | Closed. Bollards are included |
| Balance of Plant | Process Gas (All) | 1.5.4 | Talk to BOC about changeover of the H2 trailers and timing of delivery. | SNOWY HYDRO | 2 | Study | No | |
| Balance of Plant | Process Gas (All) | 1.5.4 | Look at possibility of providing two trailer parking spaces next to each other to allow for easier changeover with one prime mover. | AECOM | 1 | Consider | No | Closed. Two H2 trailer parking areas have been provided for in the design. Equipment and building locations have been adjusted as required to suit min clearance needs. |
| Balance of Plant | Process Gas (All) | 1.5.5 | Review if any barricade are required for the H2 vent area. | AECOM | 1 | Verify | No | Closed. Fence has been included to separate the H2 storage area and vent stack from the other area |
| Balance of Plant | Process Gas (All) | 1.5.7 | O&Ms to be developed | SNOWY HYDRO | 2 | Firm | Yes | |

| | | | | | | | | |
|------------------|------------------------------|--------|--|-------------------|---|----------|-----|---|
| Balance of Plant | Compressed Air (Instrument) | 1.1.1 | Confirm hold up time of 5 min of receivers is adequate. Check RFI response from MHI. Confirm all GT air consumptions with MHI. | AECOM | 1 | Verify | No | Closed. MHI confirmed in the meeting that no specific residence time for the AR on the PI is required so the AR can be reduced in size. Refer to SHL-HPP-MM-000035 |
| Balance of Plant | Compressed Air (Instrument) | 1.1.2 | Review the lead/lag control by doing a setback in the control system. | AECOM | 1 | Verify | No | Closed. Control philosophy and Instrument Air Compressor package specification has a note that each compressor can be set to run an equal amount of time during the week to limit excessive running of one compressor. |
| Balance of Plant | Compressed Air (Instrument) | 1.1.4 | Confirm there is an automatic system for removing water level in air knock out drum downstream of the compressor. | AECOM | 1 | Verify | No | Closed. Section added to IA package tech spec HPP-AE-ME-CP-IAS-DST-0038 for the KO drum to include automatic drainage |
| Balance of Plant | Compressed Air (Instrument) | 1.1.6 | Review the need to provide detailed instrument information from the compressors/dryer packages to the DCS for remote analysis. The aim is to provide enough information as to whether to send an operator to the site after hours. | AECOM | 1 | Verify | No | Closed. SHL have requested as much information as possible from the IA package to enable a decision to be made about a call out for maintenance. A note has been added to Control Philosophy and IA package specification that All package outputs need to be included in DCS. The DCS shall mimic the status and alarms of the package. |
| Balance of Plant | Compressed Air (Instrument) | 1.1.7 | Review specification to check the full range of ambient conditions are covered including wet air so vendor will select the appropriate type of filter. | AECOM | 1 | Verify | No | Closed. Ambient conditions included in air compressor/dryer packages. Maximum humidity of 100% listed in the tech spec. |
| Balance of Plant | Compressed Air (Instrument) | 1.2.6 | Remove low low pressure trips on IA supply lines downstream of air receivers. Leave low pressure alarms. MHI have a low pressure alarm on instrument air system. On the GT there are 3 bleed valves that are kept shut. If the air pressure drops the air valves open and the GT trips. | AECOM | 1 | Firm | No | Closed. PID updated to remove the trips. |
| Balance of Plant | Compressed Air (Instrument) | 1.2.7 | Review CEMS IA consumption requirements. Add CEMS usage to IA consumption calculation if a large IA consumption is required. | AECOM | 1 | Verify | No | Closed. Confirmed with CEMS supplier that there is no large IA use expected. If purge air is required for the CEMS and there is insufficient IA available, purge blowers can be supplied that mount in the stack to supply this air. 8 Nm ³ /h of air has been allowed for each CEMS in the compressor sizing which should be adequate to cover the IA required by the CEMS unit. |
| Balance of Plant | Compressed Air (Service Air) | 1.3.1 | Confirm there is an automatic system for removing water level in air knock out drum downstream of the compressor. | AECOM | 1 | Verify | No | Closed. Section added to SA package tech spec HPP-AE-ME-CP-IAS-DST-0039 for the KO drum to include automatic drainage |
| Balance of Plant | Compressed Air (Service Air) | 1.3.2 | Confirm there is the facility for water removal in the evaporator in package. | AECOM | 1 | Verify | No | Closed. Section added to SA package tech spec HPP-AE-ME-CP-IAS-DST-0039 "The dryer should have a drain or facility of water removal to remove unwanted water in the compressed air stream" |
| Balance of Plant | Compressed Air (Service Air) | 1.3.3 | Review the need to provide detailed instrument information from the compressors/dryer packages to the DCS for remote analysis. The aim is to provide enough information as to whether to send an operator to the site after hours. | AECOM | 1 | Study | No | Closed. A note has been added to Control Philosophy and IA package specification that All package outputs need to be included in DCS. The DCS shall mimic the status and alarms of the package. |
| Balance of Plant | Compressed Air (Service Air) | 1.3.4 | Review the lead/lag control by doing a setback in the control system. | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Compressed Air (Service Air) | 1.3.5 | Review specification to check the full range of ambient conditions are covered including wet air so vendor will select the appropriate type of filter | AECOM | 1 | Verify | No | Closed. Ambient conditions included in air compressor/dryer packages. Maximum humidity of 100% listed in the tech spec. |
| Balance of Plant | Compressed Air (Service Air) | 1.3.7 | Consider common vendor for IA and SA packages to reduce need for multiple service agents. | SNOWY HYDRO | 1 | Consider | No | CLOSED common vendor confirmed |
| Balance of Plant | Compressed Air (Service Air) | 1.4.2 | Confirm with MHI there are NRVs at the fuel module to prevent backflow into the SA system from high pressure purge air. | AECOM | 1 | Verify | No | Closed. See RFI 117 raised on 9-3-22. MHI have confirmed that the shutoff valves for each system will be open at different times and there is a NRV in the line to the service air. Also the shutoff valve for the service air is failure closed. |
| Balance of Plant | Compressed Air (Service Air) | 1.4.4 | Include drainage of water in the long length of pipeline to the GT and also operation during cold temperatures i.e. freezing. | AECOM | 1 | Firm | No | Closed. Pipe material spec revised to 316SS and P&ID marked up accordingly |
| Balance of Plant | Compressed Air (Service Air) | 1.4.5 | Consider using stainless steel for SA pipes. | AECOM | 1 | Consider | No | Closed. Pipe material spec revised to 316SS and P&ID marked up accordingly |
| Balance of Plant | Compressed Air (Service Air) | 1.4.8 | Confirm there is triple redundant pressure indication on instrument and service air purging to the diesel system for pre start condition. | MHI | 1 | Verify | No | |
| Balance of Plant | Compressed Air (Service Air) | 1.4.9 | Review requirement for using individual air receivers on the power island compared to one receiver on the BOP. | AECOM | 1 | Verify | No | Closed. A single SA receiver at the outlet of the compressor on the BOP is considered sufficient as the SA compressor is sized for the max flow case. |
| Balance of Plant | Compressed Air (Service Air) | 1.4.10 | Consider installation of a temporary compressor fittings for attachment of hire compressors for IA and SA. | AECOM | 1 | Consider | No | Closed. Assume dryer operating and only compressors have failed. Connection point for portable compressor added upstream of the air dryers on one of the IA and one of the SA packages. |
| Balance of Plant | Compressed Air (All) | 1.5.1 | See comments | AECOM | 1 | | | |
| Balance of Plant | Compressed Air (All) | 1.5.3 | Ensure there is access for EWP to remove PSV's for maintenance. | AECOM | 1 | Firm | No | Closed. Access ladders have been provided to optimise space and footprint requirements; a platform has also been provided for access to the PSVs in 3D model. |
| Balance of Plant | Compressed Air (All) | 1.5.5 | Review vessel dimensions to cater for inspection entry and requirement for confined space access. | AECOM | 1 | Verify | No | Closed. Access hatch on air receivers are DN600 to allow for internal inspection of the vessels included in P&ID and datasheet |
| Balance of Plant | Water (Service) | 1.1.2 | Review the requirements for backup water supply in event of loss of water. | AECOM | 1 | Verify | No | Closed. The SW tank is large enough to run for 10 hours to supply the demin plants and the GT evaporative coolers for 10 hours No rainwater collection is provided by the building designers. Can be added at a later stage if required Backup supply to safety showers is provided by a connection from the SW tank and pumps |
| Balance of Plant | Water (Service) | 1.1.3 | Review back up water supply for critical services i.e. safety showers. | AECOM | 1 | Verify | No | Closed. Backup supply is provided by a connection from the SW tank and pumps. Emergency water tank was removed from scope because it will have similar quality water as the SW tank |
| Balance of Plant | Water (Service) | 1.1.4 | Review potential impacts of extreme cold weather event and the impact of small drain lines freezing would have on site operation. Drain lines to be kept short to reduce risk of freezing. | AECOM | 1 | Verify | No | Closed. Supply line to service water tank is underground a) Water drain lines will be insulated. b) SW P&IDs marked up with a note to keep the drain lines short. |
| Balance of Plant | Water (Service) | 1.1.5 | Consider underground PE piping to safety showers and whether a heater is required in winter. | AECOM | 1 | Consider | No | Closed. Safety showers underground piping H1 spec used. |
| Balance of Plant | Water (Service) | 1.1.6 | Construction partner to check the Snowy hydro standard for labelling pipeline and label pipes after construction and before commissioning. | SNOWY HYDRO (UGL) | 2 | Verify | No | |
| Balance of Plant | Water (Service) | 1.1.7 | Add a sampling point to potable water line downstream of the site water meter and upstream of the service water tank. Consider facility for potable water lines to be flushed through into the service water tank to replace aged water in the line with fresh water. Potable water to be tested at periodic times as specified by SH. | AECOM | 1 | Firm | Yes | Closed. Sampling point has been added downstream of the metering station. A note has been added to drain and flush the line to replace aged water. |

| | | | | | | | | |
|------------------|-----------------|-------|---|-------|---|----------|-----|--|
| Balance of Plant | Water (Service) | 1.2.1 | Review tank outlets/connections - all nozzles to be fitted with valves for isolation | AECOM | 1 | Firm | No | Closed. Isolation valves shown on instruments. Other tank nozzles already show isolation valves. There is no isolation valve required for inlet line downstream of the fill valve as it is top entry with breathing hole. Included on/off valve upstream of LV and added one gate valve and one RPZ valve downstream. |
| Balance of Plant | Water (Service) | 1.2.2 | Replace level switch (LS/LAHH) with another LT because of critical service of tank and add HH to level transmitter. | AECOM | 1 | Firm | No | Closed. LAHH LS changed to LT |
| Balance of Plant | Water (Service) | 1.2.3 | Confirm tank paint internals on datasheet is compatible with anti-algacide chemicals | AECOM | 1 | Verify | No | Closed. Material spec galvanised carbon steel. Biocide package is deleted from scope as algae growth is not expected to grow without a light source inside a dark tank |
| Balance of Plant | Water (Service) | 1.2.4 | Ensure that drains from tank are separated on model as per P&ID. | AECOM | 1 | Firm | No | Closed. 3D model shows separated drains and overflow as per the P&ID |
| Balance of Plant | Water (Service) | 1.2.5 | Review size of hatch on tank roof to facilitate access for diving. Consider 900mm opening. | AECOM | 1 | Verify | No | Closed. Hatch size on the tank roof has been changed from 600 NB to 900 NB |
| Balance of Plant | Water (Service) | 1.2.6 | Confirm that there are facilities to install a barriers around hatch. | AECOM | 1 | Verify | No | Closed. Tank Datasheet includes hatch with lockable catch and removable safety screen with 1.5kN strength |
| Balance of Plant | Water (Service) | 1.1.8 | Consider isolation immediately after HW metering facility to allow ability to maintain downstream valves. | AECOM | 1 | Consider | No | |
| Balance of Plant | Water (Service) | 1.3.3 | Confirm timing of third forwarding pump starting and affecting GT operation. Provide buffer time in evaporative cooler tank at GT. | MHI | 1 | Verify | Yes | |
| Balance of Plant | Water (Service) | 1.3.6 | Review use and quantities of portable chemical injection package. Check the quantities of chemicals in this package are kept under the DG minor storage thresholds. | AECOM | 1 | Verify | No | Closed. Algae will not grow in a dark tank the SW is unlikely to require dosing with additional chemicals. Package can be brought to site on a temporary basis for dosing if required. Dosing point will be kept on PID |
| Balance of Plant | Water (Service) | 1.3.7 | Review the requirements for pressure indicator upstream of kickback PCV in minimum pump flow line. | AECOM | 1 | Verify | No | Closed. PT and PI added upstream of the PCV |
| Balance of Plant | Water (Service) | 1.3.8 | Review methods for smoothing or minimising the number of pumps starts. Contemplate scenario of leakage and no other flow. Consider whether an accumulator or jockey pump is required for small flows. | AECOM | 1 | Verify | No | Closed. SH agree with use of a jockey pump. A jockey pump has been added to the P&IDs. |
| Balance of Plant | Water (Service) | 1.3.8 | Check if there is a signal from the GT whether the evaporative cooler is operating and the need for 1 or 2 pumps operating. | MHI | 1 | Verify | No | |
| Balance of Plant | Water (Demin) | 1.4.1 | Review potential to provide direct connection from potable water supply upstream of service water tank to demin package. | AECOM | 1 | Verify | No | Closed. Minimum pressure required for Demin package is 200 kPag. Consider if flow is restricted to the demin plant when filling the FW tanks. Pressure drop to be calculated if supply line pressure is adequate. P&IDs have been updated - demin water package water supply upstream of the service water tank. |
| Balance of Plant | Water (Demin) | 1.4.2 | Measured values and alarms from demin package PLC to be available for mimic on the DCS for monitoring remotely by operators. | AECOM | 1 | Firm | No | Closed. PLC based skid The DCS will mimic the status and alarms of the demin plant skid DCS will have supervisory control over the skid Note added to P&IDs and Control Philosophy to include all package outputs in DCS. Redundant communication connection has been specified to the demin plant. SH have confirmed that they want all the information from the demin package to allow remote analysis on whether a call out is required. |
| Balance of Plant | Water (Demin) | 1.5.1 | Review requirements for duty/standby pumps within the packages or requirement to keep uninstalled spares. Alternatively, increase capacity of package to 55m ³ /h which removes the need for 2 packages to operate simultaneously to supply demin for 3 days continuous operation of GT on diesel. | AECOM | 1 | Verify | No | Closed. It is usually not practical to source demin water from outside sources. However, facilities have been provided to fill the demin tank from a tankers. Both packages can run simultaneously to supply demin water if the level is low. |
| Balance of Plant | Water (Demin) | 1.5.5 | Notify the RO vendor of potential biocide use in the water supplied to demin package. Include in demin package specification. | AECOM | 1 | Firm | No | Closed. Vendor package specification has been updated |
| Balance of Plant | Water (Demin) | 1.5.6 | Notify the vendor that demin plant may not be used for long periods of time. Confirm demin plant can cope with periods of standby. | AECOM | 1 | Firm | No | Closed. Demin water will require polishing. Demin plant will be run for a few hours a day to upkeep system (as per other SH plants). Added a note in technical specification that package should include recirculation and flushing system in case of idle periods |
| Balance of Plant | Water (Demin) | 1.6.1 | Include two level transmitters instead of a LSH and LT. | AECOM | 1 | Firm | No | Closed. LSH changed to LT |
| Balance of Plant | Water (Demin) | 1.6.2 | Review the overflow discharge location based on pH of demin and relocate to trade waste. | AECOM | 1 | Verify | No | Closed. P&IDs marked up to show all drains to go to neutralisation pit |
| Balance of Plant | Water (Demin) | 1.6.3 | Review the possibility of CO2 filter (on tank vent) blocking and causing tank to be under vacuum. | AECOM | 1 | Verify | No | Closed. SH confirmed they prefer not to have N2 blanketing - SH prefer a CO2 filter rather than N2 blanketing CO2 filter can be installed at ground level for ease or replacement and have duty / stand by arrangement CO2 filter to be supplied with vendor for Demin tanks. JD: As per item 16 of technical clarification for the Demin tank with Supplier HPP-AEC-MEC-DW-SFP-ERS-0001_B, vendor has confirmed that tank venting system will be designed and finalised considering the pressure drop for CO2 absorber. |
| Balance of Plant | Water (Demin) | 1.6.4 | Review location of tank drains from storm water to trade waste | AECOM | 1 | Verify | No | Closed. P&IDs marked up to show all drains to go to neutralisation pit |
| Balance of Plant | Water (Demin) | 1.6.6 | Review size of hatch on tank roof to facilitate diving access. Consider 900mm opening | AECOM | 1 | Verify | No | Closed. SH commented they would put a RO camera into the tank in preference to a person Hatch size on the tank roof changed to 900 NB |
| Balance of Plant | Water (Demin) | 1.6.7 | Confirm that there are facilities to install a barrier around hatch and locking facility. | AECOM | 1 | Verify | No | Closed. Tank Datasheet includes hatch with lockable catch and removable safety screen with 1.5kN strength |
| Balance of Plant | Water (Demin) | 1.6.8 | Review tank outlets/connections - all nozzles to be fitted with valves for isolation. | AECOM | 1 | Verify | No | Closed. Isolation valves shown on the instrumentation nozzles as well (All other tank inlets and outlets already show an isolation valve). No isolation valve added to the overflow nozzle |
| Balance of Plant | Water (Demin) | 1.7.1 | Confirm if one pump is lost there is sufficient time for another pump to turn on before the flow switch trips the GT. | AECOM | 1 | Verify | Yes | Closed. Minimum pressure for low PS is 30 kPa and PS has a delay of 4 seconds. A PCV has been added at the demin pump suction to maintain the pressure. SH accepts this solution |
| Balance of Plant | Water (Demin) | 1.7.1 | Confirm if one pump is lost there is sufficient time for another pump to turn on before the flow switch trips the GT. RFI to be raised to MHI. | MHI | 1 | Verify | No | |

| | | | | | | | | |
|------------------|---------------------------|--------|---|-------|---|----------|-----|---|
| Balance of Plant | Water (Demin) | 1.7.3 | Consider bypass line around MHI orifice plate to facilitate commissioning. | AECOM | 1 | Consider | No | Closed. Connecting drawing to be marked up accordingly |
| Balance of Plant | Water (Demin) | 1.7.3 | Consider bypass line around MHI orifice plate to facilitate commissioning. Raise an RFI to MHI. | MHI | 1 | Consider | No | |
| Balance of Plant | Water (Demin) | 1.7.4 | Review potential to install automated valves on lines from forwarding pumps to demin treatment package for polishing and demin distribution to allow remote switchover between lines. Add polishing sequence to DCS to allow for remote operation. | AECOM | 1 | Verify | No | Closed. The pump is not sized to do both polishing and supplying water to the GT. Mode of operation to be selected by changing position of automated valves a) To be confirmed with SH if valves are to be actuated. b) Polishing sequence has been added to the control philosophy. |
| Balance of Plant | Water (Demin) | 1.7.6 | Review requirement of pressure indicator upstream of PCV. | AECOM | 1 | Verify | No | Closed. PT with a PI added upstream of the pressure regulator |
| Balance of Plant | Water (Demin) | 1.9.1 | Chemicals and the dosing will be proposed by a water treatment vendor as required by the system. Check there is indication for low levels of chemicals | AECOM | 1 | Verify | Yes | Closed. Included in the vendor package specification that there are instruments for low level of chemicals |
| Balance of Plant | Water (Demin) | 1.9.2 | Confirm if automated valves are not in position and there is an output into the DCS to show this. Confirm with package supplier if these valves are interlocked. | AECOM | 1 | Verify | No | Closed. Included in the vendor package specification that output of automated valves to trade waste to have an output that can be monitored and alarmed. P&ID -1059 a note has been added to show position indication on the XV's 90GCB01AA962 AND 90GCB01AA043 in DCS. |
| Balance of Plant | Water (Service and Demin) | 1.10.1 | Raise RFI to SH to confirm stainless steel grade required (304 or 316). | AECOM | 1 | Firm | No | Closed. AECOM piping is specified as 316. MHI has put 304 SS on their PIDS for Demin water lines/equipment 316 is more expensive than 304 SS SH confirmed 316 SS is acceptable and has been specified in PMS |
| Balance of Plant | Water (Service and Demin) | 1.10.3 | Determine desired system response in emergency shutdown (from safety perspective). Apply this to all subsystems. Provide a list of impacts of any system shutdowns on ability of GT to operate. | AECOM | 1 | Study | Yes | Closed. Demin package stoppage does not stop GT Apply this to all subsystems |
| Balance of Plant | Water (Service and Demin) | 1.10.4 | Review location of all demin drains to ensure they all go to neutralisation pit. | AECOM | 1 | Verify | No | Closed. P&IDs marked up to show all drains to go to neutralisation pit |
| Balance of Plant | Fire Water | 1.1.5 | Update critical valves to be locked open e.g. for valves on fire fighting system (Show on P&ID). | AECOM | 1 | Firm | No | Closed. Discussion was referring about whether the drain valves on the FW tanks should be locked closed. Fire water supply line valves within the HW metering skid, 90GKB01AA205 and 90GKB01AA008 marked up as locked open (LO) |
| Balance of Plant | Fire Water | 1.1.6 | Confirm the pressure drop to the tank and flowrate meet the requirements of AS2419. | AECOM | 1 | Verify | No | Closed. The worst-case firewater demand scenario was identified following NFPA 15 deluge demand methodology (More conservative than AS2419.1). The maximum demand for the fire pumps is 11,600 L/min. For more details refer to the HPP-AEC_MEC-FP-GEN-REP-0001 Fire Safety Study report. As per AS2419, the minimum filling rate of 5.8 l/s (21 m3/h) is required to fill one of the tanks in 24 hours, while the system has been designed to fill the tanks with 20 l/s (72 m3/h) which is the maximum supply rate to the site. The piping is large enough to fill the tanks in the required time to satisfy AS2419. |
| Balance of Plant | Fire Water | 1.1.7 | Review requirement for nozzle fill point on tanks for emergency tank filling by tanker. | AECOM | 1 | Verify | No | Closed. A 100 NB spare nozzle N15 has been provided as shown on P&ID -1070. As per the Fire Safety Study report HPP-AEC_MEC-FP-GEN-REP-0001, the two firewater tanks will be designed and constructed in accordance with AS 2304 Water storage tanks for fire protection systems. |
| Balance of Plant | Fire Water | 1.1.8 | Confirm that RFS connection standards are met. | AECOM | 1 | Verify | No | Closed. The facility will have two water tanks storing potable and one tank for demineralised water, each of 1,700 m3 working capacity, which NSW RFS will be able to access in the event of responding to a local bushfire event. A spare nozzle has been provided on each tank with a valve and blind flange (for dust protection of the valve internals). The facility will have an adapter that can be fitted to this nozzle that is then suitable for NSW RFS to connect to. Refer to the Fire Safety Study report. |
| Balance of Plant | Fire Water | 1.1.9 | Review need for sample point on firewater system. Review best location for sample point i.e. one on each tank or upstream of fire water pumps. | AECOM | 1 | Verify | No | Closed. SH prefer the ability to sample from each tank. Sample point added on each tank |
| Balance of Plant | Fire Water | 1.1.10 | Review access provisions through tank liner and manhole access. | AECOM | 1 | Study | No | Closed. Standard Fire water tank design as AS2304 specified. Liner will not restrict access for inspection during maintenance |
| Balance of Plant | Fire Water | 1.1.12 | Review tank outlets/connections - all nozzles to be fitted with valves for isolation. | AECOM | 1 | Verify | No | Closed. Isolation valves shown on instrumentation and added downstream of LCVs, relief discharge lines and balance line |
| Balance of Plant | Fire Water | 1.1.13 | Confirm tank bladder is compatible with biocides that may be required for water treatments. | AECOM | 1 | Verify | No | Closed. The fire water tank is not expected to be dosed with algaecides as algae does not grow in dark conditions |
| Balance of Plant | Fire Water | 1.1.14 | Provide description of how the auto fill valve will be maintained, isolated and bypass used. | AECOM | 1 | Firm | No | Closed. Upstream isolation valve has been added to the PID 1070 for both FW tank autofill valves to avoid the need to drain large quantities of water. Description added to Basis of design to describe the reasons why the valve was added e.g. for maintenance of the autofill valve |
| Balance of Plant | Fire Water | 1.2.1 | Review the potential to provide auto fill from site diesel storage tanks to the smaller diesel tank near diesel driven firewater pump. If diesel tank for pump is filled manually consider manual handling requirements of how this tank is filled. | AECOM | 1 | Verify | No | Closed. Diesel tank for FW pump is too far away from diesel area so the diesel tanks will be manually filled. Snowy Hydro to consider handling requirements |
| Balance of Plant | Fire Water | 1.2.2 | Add locked open valve on relief line. Review AS2941 to see if this is permitted | AECOM | 1 | Firm | No | Closed. Valves marked up as locked open. AS2941 to be reviewed |
| Balance of Plant | Fire Water | 1.2.3 | Review the position of balance line to minimise potential of silting in line. Confirm height of line above tank | AECOM | 1 | Verify | No | Closed. Valves marked up as locked open. AS2941 to be reviewed |
| Balance of Plant | Fire Water | 1.2.6 | Review battery system monitoring alarm interface with DCS for monitoring. | AECOM | 1 | Verify | No | Closed. Battery Charger Supply failure has been added to the FW pump data sheet and will alarm to the DCS |
| Balance of Plant | Fire Water | 1.2.7 | Review where the outlet of TRV on firewater pump outlet is to be directed and select a suitable location. | AECOM | 1 | Verify | No | Closed. P&ID marked up with "safe location" to be determined in 3D model |

| | | | | | | | | |
|------------------|------------|-------|---|-------|---|--------|-----|--|
| Balance of Plant | Fire Water | 1.2.8 | Review the potential for embers and overloading the air intake system in the event of a bushfire. | AECOM | 1 | Verify | No | Closed. The firewater tanks provide water to fire pumps. The fire pumps are 100% duty and standby arrangement and in accordance with AS 2941. There will be two diesel driven pumps with one designated as the duty pump and the other as the standby pump. Both pumps are housed in a dedicated Fire Pump Room located adjacent to the fire water tanks and fire appliance hardstand for accessing the tanks suction and system booster assemblies. Air intake in the bushfire scenario has a very low risk of being compromised. |
| Balance of Plant | Oily Water | 1.3.4 | Review management of algae in pit. Include in package spec and discuss potential options with vendors. | AECOM | 1 | Verify | No | Closed. As per current design there is a roof shelter (open sides) over the oily water pit, however this will not prevent sunshine into the pit content and there will be a chance of growing algae. The oily water vendor has not been finalised yet, however in current offer there is coarse filter in the package to capture the large debris and algae. The filter has easy access for cleaning purpose. PDT with High alarm will be added to warn operators to clean the filter. Since there is no continuous source for this pit, we expect to have dry pit for most of the days so algae growth is not expected to be an issue |
| Balance of Plant | Oily Water | 1.3.6 | Review use of stairs instead of ladder into pit. Look at removable type of stairs to prevent fouling of stairs. | AECOM | 1 | Verify | No | Closed. Pit to be maintained annually. An embedded steel rung ladder will be installed for emergency access in and out of the pit. More accessible means for planned entry to the pit have been assessed as outlined below and would be provided in addition to the emergency fixed steel rung ladder. Stairs Stairs offer a viable solution as they provide safe access for both levels of the oily water pit by incorporating a landing for the upper level. The potential ability for the stairs to be hinged at the upper point and be lifted clear of the oily water when not in use is being investigated. This would limit plant growth on the stairs and contact with oily water. |
| Balance of Plant | Oily Water | 1.3.7 | Review requirement for isolation of incoming drains to allow access to pit to provide correct isolation. | AECOM | 1 | Verify | No | Closed. Inlet valve to be provided and access permit to pit to specify that valve is closed as a condition of entry Structural Dwg No : HPP-AEC-CIV-ST-BPS-DRG-5650 |
| Balance of Plant | Oily Water | 1.4.1 | Confirm interface of package with DCS. Determine what information needs to be transferred to DCS. | AECOM | 1 | Verify | No | Closed. Interface with DCS is highly dependent on type of package and equipment inside. For the current selected package the signals would be (to be finalised by vendor): Start/Stop, Status, Common Alarm/Fault, LAH on Decanting tank PDAH on coarse filter and Recycle valve Status. Added to package Specification. |
| Balance of Plant | Oily Water | 1.4.3 | Confirm if piping between filter and pumps and filter is designed for a vacuum conditions. | AECOM | 1 | Verify | No | Closed. Will be finalised by manufacturer Added to package Spec. |
| Balance of Plant | Oily Water | 1.4.4 | Vendor supplier to confirm if oil water separator does not operate for a period of time what (if any) effects this would cause on the reliability of the unit. Specification of package to include mention of extended periods on downtime. | AECOM | 1 | Verify | Yes | Closed. Separator package may need to be run when not required to keep all equipment working properly. Will be finalised by manufacturer. Added to package Spec. |
| Balance of Plant | Oily Water | 1.4.5 | Review potential impacts of winter operation. Include in specification that unit needs to operate during low ambient conditions | AECOM | 1 | Verify | No | Closed. Will be finalised by manufacturer. Added to package Spec to follow project winterisation philosophy. |
| Balance of Plant | Oily Water | 1.4.6 | Review the operational area of the skimmer pit. Consider sloped floor on main pit to concentrate sludge for ease of cleaning and allow oil/ water to be diluted. | AECOM | 1 | Verify | No | Closed. Pit is provided with sloped floor and the inlet is 300mm above the base of pit to allow for sediment/sludge build up. Operational pump stop float switch is 300mm above pit base so that sludge does not enter oily water separator. Periodic maintenance is completed by vacuum truck that will suck sludge from base of pit. Maintenance to be completed regularly to limit sludge build up. |
| Balance of Plant | Oily Water | 1.4.8 | Ensure vent location is at an adequate height to disperse any hazardous vapours. | AECOM | 1 | Verify | No | Closed. Will be finalised by manufacturer. Added to package Spec. |
| Balance of Plant | Oily Water | 1.5.1 | Review oil and diesel vent points in the GT area to ensure no diesel can flow to the stormwater discharge point. All oil vents to drain to oily water system with concrete apron. | AECOM | 1 | Verify | No | Closed. The MHI PIDS were reviewed for vents that could release to the atmosphere. All drain from the fuel oil system either drain to the Fuel oil tank or the oil drain pit. The vent on the fuel oil drain tank vents to an elevated vent 12-15m high with an oil catch pot arrangement to capture small droplets of oil. There is an 100mm overflow on the drain tank that overflows to the oily drain pit (refer to MHI PIDS A-21041/2/3/4/5/6-C) IL: All the stormwater must pass through HumeCeptor which has over 4000 litres of oil containment capacity. Any diesel that bypass OWS inlet will be captured by HumeCeptor |
| Balance of Plant | Oily Water | 1.5.2 | Review requirements for capture during construction for containment of drainage carryover. To be reviewed in CHAIR. | AECOM | 1 | Study | No | Closed. Transfer to CHAIR workshop |

| | | | | | | | | |
|------------------|---------------------|-------|---|-------------|---|--------|-----|--|
| Balance of Plant | Oily Water | 1.6.1 | Confirm if oily water system is considered in fire safety study. | AECOM | 1 | Verify | No | <p>Closed.</p> <p>Yes, it has been considered and regarded as a low consequence risk.</p> <p>Sources of oily water, where there is a credible fire risk have a flame trap at the entry to the oily water drain included in the design.</p> <p>There are no sources of flammable liquid connected to the oily water system, only combustible liquids and oils drained into the oily water pit will be cool or cooled by the water in the pit which is a significant heat sink for the oil.</p> <p>As a combustible liquid these oils do not have a significant vapour above their surface making them difficult to ignite; however, ember attack might cause flame pockets. It is expected such flame pockets would be quenched by the bulk temperature of the compartments in the oily water system.</p> <p>It was considered that the oily water pit is well-separated from other infrastructure and a fire in the oily water pit does not represent a damage risk to other site infrastructure. Damage to equipment and structures in the oily water pit is considered to have very low impact. The density of ember attack, hence heating density, is reduced by the planned roof over the oily water pit system. The entire area of the oily water pit will be accessible with firewater hydrant hoses. After considering the likelihood and consequence no increased fire protection is considered justified.</p> |
| Balance of Plant | Oily Water | 1.6.2 | Review the requirement for monitoring of fire traps liquid level and regular maintenance of fire traps. | AECOM | 1 | Verify | Yes | <p>Closed.</p> <p>David Lockley has provided a flame trap assessment which indicated risk of fire explosion is negligible as concentration of flammable gas is not sufficient for ignition. Temperature of diesel/oily gas not sufficient to ignite.</p> |
| Balance of Plant | Oily Water | 1.6.3 | Review potential to install a smaller initial volume within decanting pit for concentrated spills. Consider interface level detection. Review requirement for detection of high-level oils in the observation pit and how this can be achieved. | AECOM | 1 | Verify | No | <p>Closed.</p> <p>a)The inlet of the main oily water pit contains a deeper section where the floating weir oil skimmer floats on the surface and skims the highest concentration of oil for concentrated spills. The skimmer and OW package operation will be activated by a level switch. Interface detection would not work well in the incoming pit because of significant water level differences.</p> <p>c) Oil/water interface instrument is shown on PID HPP-AEC-MEC-GN-GEN-DRG-1085. Specification for Oily water package has a note added HPP-AEC-MEC-DS-PFS-DST-0036 "The vendor to propose a facility/instrumentation to detect the oil presence at the outlet side of the system in the observation pit in order to switch the package operation shut down the package to decrease the chance of oil escape to clean storm water system."</p> |
| Balance of Plant | Oily Water | 1.6.3 | Review operational response to a high-level oil in the decanting pit. | SNOWY HYDRO | 1 | Study | Yes | |
| Balance of Plant | Oily Water | 1.6.4 | Review location of humeceptor in location to highest flood level. | AECOM | 1 | Verify | No | <p>Closed.</p> <p>The 1 per cent AEP flood level is 9.73 mAHD and the Probable Maximum Flood (PMF) level is 11.71 mAHD (WMAwater, 2010).</p> <p>HumeCeptor outlet invert is 9.99 mAHD so slightly above the 1% AEP Level. In the PMF the outlet is below PMF level, however the flow is from the site to the watercourse so HumeCeptor functions normally.</p> <p>HumeCeptor cannot be raised and capture all site flows, and is above 1% AEP (100yr) level so considered acceptable. No action required</p> |
| Balance of Plant | Oily Water | 1.6.6 | Seek further guidance from SH environmental team on whether a penstock valve is required on humeceptor discharge line to the environment. | SNOWY HYDRO | 1 | Verify | No | |
| Balance of Plant | Trade Waste & Sewer | 1.1.1 | Confirm final pit volume is sufficient to contain all the flows from blade washing and closed loop cooling water volumes. | AECOM | 1 | Verify | No | <p>In progress of being closed.</p> <p>Evaporative cooler blowdown water currently drains to the neutralisation pit downstream of the blade wash pit so is not taken into account in the pit sizing.</p> <p>Offline water maximum water volume with detergent is 1.5m³ (without detergent, maximum volume is 1 m³).</p> <p>Blade washing water does not meet Trade waste specification. Will be removed by truck</p> <p>During on-line washing there is no water drained from the exhaust duct.</p> <p>Current proposal is for 5 m³ pit volume so risk of overflow is negligible. Operations could also provide a vacuum truck during offline washing to further safeguard the environment.</p> <p>During on-line washing there is no water drained from the exhaust duct.</p> <p>Water/air temperature draining out is 525 deg C so piping is designed for 525 deg C. Tank will most likely be concrete.</p> <p>Frequency is more often (TBC) so sizing of the tank will be finalised after information is available.</p> |
| Balance of Plant | Trade Waste & Sewer | 1.1.3 | Determine if the blade washing water with detergent can be disposed to the trade waste (HWC criteria for maximum concentration). When detergent is used for off-line blade washing (approx. once a year) the GT compressor wash pit should be isolated and removed by sucker truck. Test the blade wash water after commissioning to check analysis meets HWC criteria for trade waste. | AECOM | 1 | Study | Yes | <p>Closed.</p> <p>Blade washing with detergent is likely to be infrequent (once a year). MHI confirmed that detergent is used during off-line blade washing. SH confirmed detergent is used for the best clean to remove residue. The wash water is removed by a truck.</p> <p>Blade washing is a supervised procedure.</p> |
| Balance of Plant | Trade Waste & Sewer | 1.1.3 | Confirm the iron concentration in wash water. Is 220 mg/l the normal concentration during off line washing? | MHI | 1 | Verify | No | |
| Balance of Plant | Trade Waste & Sewer | 1.2.1 | Review the neutralisation pit capacity to cater for emergency storage in the event of not having access to pump out to the trade waste. | AECOM | 1 | Verify | No | <p>Closed</p> <p>According to the Trade Waste Pump Station Design Report there is a total available emergency storage capacity of 64.3 kL including the wet well and neutralisation pit that exceeds the two-hour emergency scenario capacity using the peak inflow of 8.9 L/s</p> |

| | | | | | | | | |
|------------------|---------------------|--------|---|-------|---|----------|-----|--|
| Balance of Plant | Trade Waste & Sewer | 1.2.5 | Confirm the impacts of chemicals used in demin plant CIP to neutralisation pit. Confirm if the concentration of COD from the CIP chemicals from the demin plant will be suitable for discharge to trade waste or whether removal by tanker is more appropriate. | AECOM | 1 | Verify | No | In progress of being closed. Awaiting for package supplier design. Volume of CIP water is likely to be small (1-2 m3). HW may sample the waste from time to time. Trade Waste limit on COD is 1500 mg/L. Estimated TDS on reject water is 350-500 ppm based on potable water TDS of 110 ppm and no issue on reject water. In case of high TDS or ions > Hunter spec, it can be diluted in the neutralisation pit or an IBC/drum for demin package neutralisation to be emptied by a truck. |
| Balance of Plant | Trade Waste & Sewer | 1.2.6 | Replace local PI with pressure transmitter downstream of transfer pumps to prove there is no damage to HWC trade waste main from the transfer pump. Review best location for this PT to measure discharge pressure. | AECOM | 1 | Firm | No | Closed. PT with high alarm has been added to the PID at battery limit with the Hunter Water |
| Balance of Plant | Trade Waste & Sewer | 1.2.7 | SDV's downstream of the transfer pumps to HWC line to fail closed. SDV's downstream of the transfer pumps returning to pit fail open to prevent dead heading of pump. | AECOM | 1 | Firm | No | Closed. During discharge to the trade waste both valves can be open to maintain circulation RO moved to the SDV bypass line to have permanent recycle and mixing during the transfer |
| Balance of Plant | Trade Waste & Sewer | 1.2.8 | Consider removal of pump with a roof above the pit | AECOM | 1 | Consider | No | Closed. The roof over the neutralisation pit has been retained in the design and a crawl beam with trolley/chain-block for lifting the pumps out of the pit for maintenance will be provided. |
| Balance of Plant | Trade Waste & Sewer | 1.2.9 | Materials of pit to consider acid and caustic dosing. (Epoxy coating). | AECOM | 1 | Consider | No | Closed Demin Vendor will consider materials for tank The neutralisation of demin "Clean in Place" streams will now be included in the demin package and there will be no dosing of acid and caustic into the pit. |
| Balance of Plant | Trade Waste & Sewer | 1.2.10 | Ensure dosing of acid and caustic is located at opposite end of pump suction and adequate recirculation time to ensure good mixing of neutralisation chemicals. | AECOM | 1 | Verify | Yes | Closed. No longer relevant as there will be no direct dosing into pit. |
| Balance of Plant | Trade Waste & Sewer | 1.3.1 | Include either an alarm for continual operation of the pump (or too frequent operation) or investigate other solutions to reduce overdosing (Review requirement for two pH meters for checking that pH is moving in the expected direction). | AECOM | 1 | Firm | Yes | Closed. The neutralisation of demin "Clean in Place" streams will now be included in the demin package and there will be no dosing of acid and caustic into the pit. |
| Balance of Plant | Trade Waste & Sewer | 1.3.2 | Chemicals to be dosed are TBC. If caustic is used potential for freezing in lines needs to be considered. Include in the package specification the range of ambient temperature. | AECOM | 1 | Study | Yes | Closed. The neutralisation of demin "Clean in Place" streams will now be included in the demin package and there will be no dosing of acid and caustic into the pit. |
| Balance of Plant | Trade Waste & Sewer | 1.3.4 | Review the replacement process for the chemicals (tank or drum) and if minimal contact with the chemical for the operator | AECOM | 2 | Study | No | Closed. Proposed Demin Vendor has been asked to provide the SDS for all chemicals proposed to be used so that SHL can assess and respond appropriately. |
| Balance of Plant | Trade Waste & Sewer | 1.3.7 | Consider the type of acid and potential to vaporise. Dilute sulphuric acid is preferred. | AECOM | 2 | Consider | No | Closed. Proposed Demin Vendor has been asked to provide the SDS for all chemicals proposed to be used so that SHL can assess and respond appropriately. |
| Balance of Plant | Trade Waste & Sewer | 1.3.8 | FS is sometimes included in the line downstream of the PSV to indicate the PSV has lifted. Check the vendor package includes this. | AECOM | 1 | Verify | No | Closed. Dosing will be manually controlled by an operator so the action is no longer relevant |
| Balance of Plant | Trade Waste & Sewer | 1.4.4 | Consider providing a sewer connection in temporary. offices/facilities area. Review potential to use temporary toilet blocks on site. | AECOM | 1 | Consider | No | Closed. Portable toilets are not preferred by SH because of industrial relations issues. Maximum number of people on site is expected to be 50 during a scheduled outage. Consider provision of appropriate temporary facilities, if required, as part of mobilization planning for major outages. A sewer connection has not been included in the design. |
| Balance of Plant | Trade Waste & Sewer | 1.4.5 | Alarms from sewerage pit to DCS so operators are aware of high/low level in sewerage pit when no one on site. | AECOM | 1 | Firm | Yes | Closed. A high high level from the sewage pit will give an alarm in the DCS. HH alarm levels are show on HPP-AEC-CIV-MW-WWS-DRG-2422 and HPP-AEC-CIV-MW-WWS-DRG-2425. |
| Balance of Plant | Trade Waste & Sewer | 1.4.7 | Consider odour from the tank and a filter. | AECOM | 1 | Consider | No | Closed. Usually filters are used on larger municipal facilities. According to the Trade Waste Pump Station Design report: odour release and the build-up of toxic gases such as hydrogen-sulphide was considered in the design. The access covers would provide a seal against egress of gasses, which could cause backpressure on the upstream gravity network and unintended odour release elsewhere on site. A vent pole will be mounted to the adjacent controls and administration building to disperse odour at a 12.5 m height above the finished surface level. |
| Balance of Plant | Trade Waste & Sewer | 1.5.2 | Review application of flushing water to the pit and potential to use potable water and a garden hose | AECOM | 1 | Verify | No | Closed. A connection from service water for flushing purpose has been added to the PID for the sewer pit |
| Balance of Plant | Trade Waste & Sewer | 1.5.4 | Confirm noise limits included in the package specifications | AECOM | 1 | Verify | No | Closed. The pumps are more than 1 km away from residential neighbours. Also, typically these pumps are installed < 10 m away from houses. Therefore, the noise is not an issue and limits have not been specified. |
| Balance of Plant | Trade Waste & Sewer | 1.5.5 | Ensure safety shower is no further than 10 m from chemical storage if dosing chemicals are being decanted | AECOM | 1 | Firm | No | Closed. Location of safety showers positioned as per requirements of AS 4775. Neutralisation of "Clean in Place" streams from demin plants will be done within demin package. There are two safety showers installed at demin package. |