

### Snowy 2.0 - Externally Reported Environmental Incidents and Non-Compliances

Under the Conditions of Approval, issued by the Department, Schedule 4, Condition 12(a), a register of incidents and non-compliances must be made publicly available on the Snowy 2.0 website. The information presented below addresses this requirement.

The register consists of all incidents/non-compliances that were reported to the Department and NPWS as per Schedule 4, Conditions 6 & 7, from the beginning of the 2024/2025 financial year.

Date	Type	Location	Detail
3 July 2024	Incident	Lobs Hole	Talbingo wedge-pit material placed in Pad 50.
9 July 2024	Incident	Lobs Hole	GF01 gully sump leaking.
16 July 2024	Incident	Lobs Hole	Sediment basin overtopping event.
20 July 2024	Incident	Lobs Hole	Sediment-laden water entering Yahoo Gully from F10.5 basin.
20 July 2024	Incident	Lobs Hole, Tantangara	Sediment basin overtopping event.
26 July 2024	Incident	Marica	Sediment basin overtopping event.
27 July 2024	Non-Compliance	Tantangara	Elevated nitrates and total nitrogen at EPL103.
4 August 2024	Non-Compliance	Lobs Hole	Waste management at Lick Hole Gully PSE.
13 August 2024	Incident	Lobs Hole	F5a sediment basin overtopping from watercart irrigation.

18 August 2024	Non-Compliance	Lobs Hole	Missing sample for BOD at EPL10 & EPL11.
26 August 2024	Non-Compliance	Tantangara	Exceedance of BOD following emergency discharge at RO plant.
26 August 2024	Incident	Lobs Hole/Tantangara/Marica	Sediment basin overtopping event.
7 September 2024	Non-Compliance	Tantangara	EIS boundary breach by watercart.
21 September 2024	Non-Compliance	Tantangara	Elevated analytical concentration at EPL69.
25 September 2024	Incident	Lobs Hole	Sediment laden water overtopping from basins F5a and F9.
26 September 2024	Incident	Lobs Hole	Leachate sediment laden water reporting to Yarrangobilly River from EPL84.
26 September 2024	Incident	Tantangara	Sediment basin overtopping event.
27 September 2024	Incident	Marica	EIS boundary encroachment from rock and fill material.
5 October 2024	Incident	Lobs Hole	Sediment laden water reporting to Yarrangobilly River from basin F5a.
12 October 2024	Incident	Lobs Hole	Sediment laden water entering Middle Creek.
16 October 2024	Non-Compliance	Lobs Hole	Discharge of non-compliant water into Talbingo reservoir.
19 October 2024	Incident	Lobs Hole, Marica	Sediment basin overtopping event.
14 November 2024	Incident	Lobs Hole	Sediment laden water reporting to Yarrangobilly River.

26 November 2024	Incident	Lobs Hole	Sediment laden water reporting to Yarrangobilly River at basin F5a.
28 November 2024	Incident	Lobs Hole	Sediment laden water reporting to Yarrangobilly River at basins F5a and F9.
28 November 2024	Incident	Lobs Hole	Sediment laden water reporting to Yarrangobilly River at basins F8 and F8.5.
28 November 2024	Incident	Lobs Hole	Leachate sediment laden water reporting to Yahoo Gully at basin F10.5.
30 November 2024	Incident	Lobs Hole	Sediment laden water reporting to Yarrangobilly River from ECVT turkeys nest and F1 basin.
3 December 2024	Incident	Lobs Hole	Dirty water reporting into Talbingo Reservoir.
6 December 2024	Incident	Lobs Hole	Leachate sediment laden water reporting to Talbingo Reservoir at SB01.
6 December 2024	Incident	Lobs Hole	Sump overtopping.
6 December 2024	Non-Compliance	Lobs Hole	Nutrient exceedance at EPL89.
7 December 2024	Incident	Lobs Hole	Pad 2 basin overtopping to Yarrangobilly River.
7 December 2024	Incident	Lobs Hole	Leachate water reporting to Yarrangobilly River at GF01 gully.
7 December 2024	Incident	Marica	Sediment basin overtopping into drain reporting to Eucumbene River.
12 December 2024	Non-Compliance	Lobs Hole	Exceedance of total nitrogen at EPL57.
2 January 2025	Incident	Lobs Hole	Process water from Pad 2 overtopping into F8.5 basin.

14 January 2025	Incident	Lobs Hole	Greyish coloured run-off beneath Ravine Bay PSE reporting to Talbingo Reservoir.
10 February 2025	Incident	Lobs Hole	F3a, F5a, F8.5, F9 basin overtopping event.
10 February 2025	Incident	Marica	Sediment basin overtopping event.
11 February 2025	Incident	Tantangara	Sediment basin overtopping event.
11 February 2025	Incident	Lobs Hole	Basin and sump overtopping event.
14 February 2025	Incident	Lobs Hole	Treated process water reporting to Yarrangobilly River.
14 February 2025	Incident	Marica	Leachate laden water reporting to ephemeral creek from SPLB01 basin.
14 February 2025	Incident	Lobs Hole	F1 and F3b sediment basin overtopping event.
27 February 2025	Incident	Marica	Wheel wash at Marica gatehouse out of service.